

52 Volume

2.003

TRIBUNAL MARÍTIMO

Anexo D

Processo 19489/01 - P 36

PIRE E GAS

Representado(s):

AUTUAÇÃO

Aos 09 de Agosto de dois mil e 01
a Secretaria do Tribunal Marítimo autua os presentes autos.

Do que fiz este termo

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CUSTÓRIOS

Director - Genl da Secretaria



CERTIDÃO

CERTIFICO que, nesta data, foi arquivado o 3º volume
do processo D. nº 19489103
2- 96

O referido é verdade e dou fê.

Aos 09 de abril de 2003.

É CÓPIA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FIGUEIREDO GUSMÃO
DIRETOR
FÓRUM DE SERVIÇOS JUDICIAIS



Mar 14 08:00:03 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:06 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:00:06 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:07 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:16 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:24 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:25 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:30 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:00:31 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:34 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:00:34 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:43 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:51 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:00:57 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:00:58 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:00:58 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:01 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:01:01 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:10 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:10 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:16 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:21 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:01:30 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:33 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:34 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:39 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:01:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:01:46 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:46 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS ADMINISTRATIVOS



Mar 14 08:01:54 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:01:58 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:02:00 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:04 RTN DISC	2 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:02:04 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:09 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:13 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:02:13 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:02:24 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:02:28 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:02:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:34 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:36 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:02:36 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:02:40 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:02:49 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:02:58 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:03 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:03:04 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:09 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:09 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:12 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:03:12 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:16 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:27 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:33 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:34 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:39 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:03:40 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:03:45 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:03:45 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:03:46 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS FAKENTEL GUSMÃO
DIRETOR
UNSAO DE SERVIDORES CARIOQUAS



Mar 14 08:03:57 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:01 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:06 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:07 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:12 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:04:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:18 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:04:18 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:19 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:19 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:25 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:04:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:33 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:04:34 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:37 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:41 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:42 ALM DISC	1 XZ70004A	F&G
START/START UNACK_ALM		
Mar 14 08:04:42 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:04:42 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:04:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:48 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:04:49 RTN DISC	1 XZ70004A	F&G
NORMA/START ACK_RTN		
Mar 14 08:04:49 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:04:49 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:04:51 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:04:51 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:04:55 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:04:55 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:00 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:05:01 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:05 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:05:06 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:09 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		

NORMA/

STOP/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL



Mar 14 08:05:12 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:18 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:05:22 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:24 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:24 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:28 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:05:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:36 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:40 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:45 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:05:49 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:05:54 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:54 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:05:57 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:05:57 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:06:03 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:06:16 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:06:25 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:06:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:06:34 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:06:39 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:06:43 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:06:57 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:07:03 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:07:10 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:07:12 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:07:15 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:07:16 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:07:24 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:07:33 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:07:37 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:07:42 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		

É Cópia fiel do documento original.

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
DE CONTABILIDADE E GESTÃO DE RECURSOS



Mar 14 08:07:42 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:07:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:07:55 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:08:05 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:08:06 ALM DISC	1 XZ70004A	F&G
START/START UNACK_ALM		
Mar 14 08:08:06 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:08:06 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:08:11 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:08:12 RTN DISC	1 XZ70004A	F&G
NORMA/START ACK_RTN		
Mar 14 08:08:12 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:08:13 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:08:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:08:18 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:08:18 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:08:19 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:08:45 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:03 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:06 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:07 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:12 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:09:13 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:18 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:09:18 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:19 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:24 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:39 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:09:48 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:52 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:09:57 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:10:06 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:10:10 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

NORMA/

JOSE CARLOS MENEZES GUSMÃO
DIRETOR
DEPARTAMENTO DE SERVIÇOS GERAIS



Mar 14 08:10:13 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:10:18 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:10:19 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:10:20 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:10:24 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:10:24 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:10:38 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:10:38 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:10:42 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:10:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:10:46 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:10:55 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:11:00 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:11:04 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:11:09 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:11:13 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:11:17 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:11:21 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:11:22 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:11:27 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:11:27 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:11:33 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:11:40 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:11:58 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:12:03 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:03 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:12:24 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:28 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:12:30 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:12:30 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:34 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:12:34 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		

STOP/

É CÓPIA FEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
OPETON
UNIDADE DE SERVIÇOS GERAIS



Mar 14 08:12:36 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:12:43 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:12:52 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:12:57 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:13:10 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:13:30 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:13:35 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:13:36 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:13:41 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:13:41 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:13:42 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:13:47 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:13:53 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:13:56 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:04 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:14:13 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:14:22 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:31 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:14:35 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:14:36 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:41 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:14:42 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:42 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:14:47 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:14:47 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:52 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:14:57 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:15:00 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:15:03 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:15:12 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:21 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:15:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASSINADO E FISCALIZADO

DATA: 15/03/2013

Mar 14 08:15:25 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:30 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:15:34 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:39 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:15:42 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:15:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:48 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:15:48 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:49 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:15:54 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:15:55 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:16:01 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:16:06 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:16:10 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:16:29 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:16:38 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:16:48 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:16:53 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:16:54 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:16:59 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:16:59 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:17:00 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:17:00 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:17:05 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:17:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:17:18 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:17:36 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:17:36 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:17:41 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:17:50 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:17:54 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:17:55 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:00 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		



É Cópia Fiel do Documento Original

RECEBIMOS DO SENAI CUBANO
 01/07/2017
 ASSINADO POR: [Signature]



Mar 14 08:18:00 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:18:01 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:18:01 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:18:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:25 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:18:34 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:34 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:39 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:18:52 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:54 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:18:58 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:19:00 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:19:05 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:19:05 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:19:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:19:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:19:33 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:19:42 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:19:47 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:19:48 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:19:51 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:19:53 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:19:56 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:00 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:02 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:20:06 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:20:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:12 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:20:12 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:20:14 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:20:15 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:20:20 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:20:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

DESEMPENHO DE SERVIÇO
FELICIDADE

Mar 14 08:20:27 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:36 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:20:45 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:50 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:20:50 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:02 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:03 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:08 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:21:09 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:14 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:21:14 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:18 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:25 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:34 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:39 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:21:48 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:53 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:21:57 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:06 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:22:09 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:22:11 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:15 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:22:15 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:17 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:21 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:22:23 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:22:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:38 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:22:42 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:22:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:22:56 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:23:00 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PAZINTEL OUSATO
DIRETOR
CENTRO DE SERVIÇOS DO CASP/PAJAC



Mar 14 08:23:00 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:23:14 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:23:15 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:23:20 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:23:21 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:23:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:23:26 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:23:26 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:23:27 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:23:45 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:23:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:24:07 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:24:12 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:24:16 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:24:21 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:24:26 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:24:27 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:24:27 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:24:32 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:24:32 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:24:33 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:24:39 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:24:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:25:06 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:25:11 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:25:15 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:25:24 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:25:29 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:25:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:25:35 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:25:36 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:25:41 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:25:41 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PAZINTEL GUERATO
DIRETOR
MUNICÍPIO DE SÃO CARLOS



Mar 14 08:25:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:25:56 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:26:18 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:26:23 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:26:23 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:26:27 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:26:32 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:26:36 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:26:38 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:26:42 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:26:44 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:26:48 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:26:48 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:26:56 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:27:00 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:27:12 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:27:18 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:27:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:27:34 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:27:35 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:27:45 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:27:50 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:27:54 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:27:56 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:28:00 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:28:02 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:28:12 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:28:20 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:28:29 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:28:38 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:28:47 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:28:51 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:28:53 ALM DISC	1 XZ70004A	F&G
START/START UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUZMÁN
DIRETOR
UNIDADE DE SERVIÇOS ADMINISTRATIVOS



Mar 14 08:28:53 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:28:53 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:28:57 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:28:59 RTN DISC	1 XZ70004A	F&G
NORMA/START ACK_RTN		
Mar 14 08:28:59 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:28:59 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:29:00 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:29:05 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:29:05 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:29:32 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:29:36 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:29:50 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:29:50 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:29:54 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:29:59 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:30:00 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:30:05 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:30:06 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:30:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:30:11 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:30:11 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:30:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:30:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:30:32 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:30:35 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:30:39 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:30:44 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:30:45 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:30:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:30:53 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:02 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:05 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

NORMA

STOP/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
LABORATÓRIO DE FÍSICA



Mar 14 08:31:11 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:31:12 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:31:17 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:31:17 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:31:29 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:30 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:35 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:31:41 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:31:41 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:31:45 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:31:51 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:31:53 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:31:57 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:02 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:32:02 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:08 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:12 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:32:12 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:14 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:23 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:24 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:24 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:29 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:32:30 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:35 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:39 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:32:41 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:32:45 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:32:47 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:32:51 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:32:56 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:32:56 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		

É CÔPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUERATO
DIRETOR
DEPARTAMENTO DE DEFESA JURÍDICA



Mar 14 08:33:02 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:02 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:06 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:11 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:33:12 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:21 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:24 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:29 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:33:30 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:30 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:35 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:33:35 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:48 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:33:51 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:53 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:33:57 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:33:59 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:03 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:05 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:09 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:34:20 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:34:21 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:34:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:34:26 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:34:27 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:32 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:34:32 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:33 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:34:33 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:34:38 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

É COPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
CONTEIXA
PROCURADOR ASSOCIADO GONÇALVES



Mar 14 08:34:42 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:35:02 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:35:06 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:35:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:35:12 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:35:12 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:35:14 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:35:15 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:35:15 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:35:20 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:35:41 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:35:45 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:36:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:36:12 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:36:26 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:36:30 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:36:35 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:36:36 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:36:41 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:36:41 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:36:42 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:36:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:37:06 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:09 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:15 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:37:17 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:37:17 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:37:18 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:37:23 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:37:23 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:37:24 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:37:24 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:37:26 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		

NORMA/

STOP/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
DE SERVIÇOS DE TI



Mar 14 08:37:32 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:37:39 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:48 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:37:53 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:37:53 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:54 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:37:59 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:00 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:05 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:38:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:38:14 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:27 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:38:29 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:38:29 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:38:33 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:38:35 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:35 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:39 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:38:39 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:45 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:38:45 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:38:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:38:50 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:38:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:38:59 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:03 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:03 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:39:06 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:08 ALM DISC	1 XZ70004A	F&G
START/START UNACK_ALM		
Mar 14 08:39:08 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:39:08 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		

É Cópia do Documento Original.

JOSE CARLOS PUENTE CUSATO
DIRETOR
CONTROLE DE QUALIDADE



Mar 14 08:39:09 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:14 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:39:15 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:39:15 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:39:20 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:39:20 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:39:39 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:44 RTN DISC	1 XZ70004A	F&G
NORMA/START ACK_RTN		
Mar 14 08:39:44 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:39:44 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:39:45 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:50 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:39:50 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:39:54 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:39:59 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		
Mar 14 08:39:59 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:00 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:40:06 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:40:08 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:11 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:40:15 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:40:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:40:20 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:40:21 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:40:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:24 ALM DISC	1 PS70001	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:40:26 ALM DISC	1 XZ70004A	F&G
START/START UNACK_ALM		
Mar 14 08:40:26 RTN DISC	1 XZ70004B	F&G
STOP ACK_RTN		
Mar 14 08:40:26 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:40:30 ALM DISC	1 XS70004A	F&G
RUNNI/RUNNI UNACK_ALM		
Mar 14 08:40:32 RTN DISC	1 PT70034	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:32 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:40:36 RTN DISC	1 XS70004A	F&G
STOPP/RUNNI ACK_RTN		

STOP/

NORMA/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PINHEIRO GUSMÃO
DIRETOR
GRUPO DE GESTÃO E PLANEJAMENTO



Mar 14 08:40:36 RTN DISC	1 PS70001	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:38 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:40:56 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:41:00 ALM DISC	1 PT70034	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:41:05 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:41:23 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:41:27 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:41:32 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:41:36 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:41:59 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:42:03 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:42:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:42:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:42:35 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:42:39 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:42:44 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:42:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:43:02 RTN DISC	1 XZ70004A	F&G
NORMA/START ACK_RTN		
Mar 14 08:43:02 ALM DISC	1 XZ70004B	F&G
STOP UNACK_ALM		
Mar 14 08:43:02 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:43:06 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:43:15 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:43:23 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:43:29 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:43:30 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:43:33 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:43:42 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:43:47 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:43:56 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:44:00 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:44:23 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:44:27 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:44:32 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		

STOP/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PEREIRA GUSMÃO
DIRETOR
COORDENADOR DE SERVIÇOS DE INTELIGÊNCIA



Mar 14 08:44:45 ALM DISC FAULT/FAULT UNACK_ALM	1 GS16-HCB_F	F&G
Mar 14 08:44:46 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 08:44:47 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:44:50 RTN DISC NORMA/FAULT ACK_RTN	1 GS16-HCB_F	F&G
Mar 14 08:44:54 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:45:05 ALM DISC FAULT/FAULT UNACK_ALM	1 GS16-HCB_F	F&G
Mar 14 08:45:09 RTN DISC NORMA/FAULT ACK_RTN	1 GS16-HCB_F	F&G
Mar 14 08:45:12 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:45:21 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:45:39 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 08:45:48 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 08:45:53 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:45:57 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 08:45:59 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:46:02 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 08:46:03 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:46:06 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:46:11 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:46:15 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:46:26 ALM DISC FAULT/FAULT UNACK_ALM	1 GS16-HCB_F	F&G
Mar 14 08:46:29 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:46:32 RTN DISC NORMA/FAULT ACK_RTN	1 GS16-HCB_F	F&G
Mar 14 08:46:33 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:46:42 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 08:46:47 RTN DISC NORMA/FAULT ACK_RTN	1 GS2405_F	F&G
Mar 14 08:46:56 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:46:59 ALM DISC FAULT/FAULT UNACK_ALM	1 GS16-HCB_F	F&G
Mar 14 08:47:00 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:47:09 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 08:47:12 RTN DISC NORMA/FAULT ACK_RTN	1 GS16-HCB_F	F&G
Mar 14 08:47:20 ALM DISC FAULT/FAULT UNACK_ALM	1 GS16-HCB_F	F&G
Mar 14 08:47:27 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 08:47:30 RTN DISC NORMA/FAULT ACK_RTN	1 GS16-HCB_F	F&G

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:
SILVIO CARLOS FARIAS GUSMÃO
DIRETOR
NÚCLEO DE SERVIÇOS CARTÓGRAFOS



Mar 14 08:47:36 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:47:41 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:47:44 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:47:50 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:47:53 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:48:03 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:48:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:48:17 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:48:20 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:48:23 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:48:35 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:48:39 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:48:45 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:48:50 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:48:54 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:48:59 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:49:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:49:15 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:49:20 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:49:23 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:49:24 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:49:27 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:49:42 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:49:48 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:49:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:49:54 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:49:57 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:50:02 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:50:09 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:50:14 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:50:20 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:50:24 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:50:36 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		


É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FLECHER DOS SANTOS
DIRETOR
DEPARTAMENTO DE SERVIÇOS DE CONTABILIDADE



Mar 14 08:50:41 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:50:50 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:50:53 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:50:53 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:50:54 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:50:57 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:51:01 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:51:03 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:51:08 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:51:14 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:51:19 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:51:21 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:51:26 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:51:30 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:51:35 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:51:44 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:51:48 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:51:59 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:52:03 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:52:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:52:14 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:52:15 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:52:21 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:52:29 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:52:32 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:52:33 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:52:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:52:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:52:57 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:53:14 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:53:17 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:53:19 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:53:21 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS PEREIRA LUS
DIRETOR
CENTRO DE SERVIÇOS COMUNITÁRIOS



JOSE CARLOS FERRAZ DE OLIVEIRA
DIRECTOR
INSTITUTO DE PESQUISA E DESENVOLVIMENTO



Mar 14 08:58:56 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:59:00 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 08:59:05 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 08:59:06 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 08:59:27 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 08:59:32 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:00:17 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:00:19 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:00:22 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:00:26 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:00:31 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:00:40 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:01:02 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:01:07 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:01:11 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:01:16 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:02:14 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:02:18 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:04:02 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:04:07 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:04:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:04:11 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:04:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:04:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:06:16 ALM DISC	1 ZSC70402	F&G
CLOSE/CLOSE UNACK_ALM		
Mar 14 09:06:16 ALM DISC	1 ZSC70403	F&G
CLOSE/CLOSE UNACK_ALM		
Mar 14 09:06:16 ALM DISC	1 ZSO70404	F&G
OPEN UNACK_ALM		
Mar 14 09:06:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:06:22 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:06:31 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:06:35 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:07:47 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:07:51 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

OPEN/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

RUISE CARLOS FOLGEMER DOS SANTOS
DIRETOR
DE PLANO DE SERVIÇOS DE AERONÁUTICA

Mar 14 09:08:18 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:08:23 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:09:04 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:09:08 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:09:17 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:09:22 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:09:44 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:09:49 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:10:11 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:10:16 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:10:29 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:10:35 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:12:22 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:12:26 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:12:58 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:13:02 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:13:40 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:14:02 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:14:11 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:14:14 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:14:19 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:14:20 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:14:23 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:14:34 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:14:38 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:14:52 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:14:56 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:15:22 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:15:26 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:15:58 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:16:07 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:16:16 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:16:20 RTN DISC	2 GS2405_F	F&G
NORMA/FAULT ACK_RTN		



É CÓPIA PIEL DO DOCUMENTO ORIGINAL


JOSE CARLOS FARIAS GUSMÃO
DIRETOR
GRUPO DE SEGURANÇA COMUSIA

Mar 14 09:16:32 RTN DISC	1 ZSC70402	F&G
C/CLOSE ACK_RTN		
Mar 14 09:16:32 RTN DISC	1 ZSC70403	F&G
C/CLOSE ACK_RTN		
Mar 14 09:16:32 RTN DISC	1 ZSO70404	F&G
OPEN ACK_RTN		
Mar 14 09:16:40 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:16:44 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:17:11 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:17:14 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:17:28 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:17:34 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:17:37 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:17:37 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:17:59 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:18:05 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:18:08 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:18:08 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:18:14 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:18:19 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:18:23 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:18:26 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:18:31 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:18:37 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:18:40 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:18:49 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:18:59 ALM DISC	1 GS16-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:19:02 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:19:07 RTN DISC	1 GS16-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:19:07 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:19:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:19:11 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:19:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:19:16 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:19:29 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:19:34 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		

NOT

NOT

NOT O/



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

UNIVERSIDADE DE SÃO PAULO
BIBLIOTECA DE DOCUMENTOS
1541



Mar 14 09:19:35 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:19:43 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:19:47 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:20:23 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:20:28 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:21:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:21:13 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:21:31 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:21:35 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:21:44 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:21:49 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:22:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:22:16 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:22:20 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:22:25 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:23:23 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:23:28 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:23:32 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:23:37 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:23:41 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:23:43 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:24:04 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:24:13 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:24:13 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:24:22 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:24:31 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:24:35 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:24:44 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:24:49 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:24:53 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:24:58 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:25:07 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:25:11 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		

É Cópia fiel do documento original.

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR

17/03/2014 10:00:00



Mar 14 09:25:20 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:25:25 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:25:26 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:25:29 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:25:34 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:25:38 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:25:40 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:25:43 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:25:43 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:25:52 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:25:56 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:26:10 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:26:11 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:26:14 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:26:16 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:26:19 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:26:32 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:26:37 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:26:46 ALM DISC	1 ZSC70402	F&G
CLOSE/CLOSE UNACK_ALM		
Mar 14 09:26:46 ALM DISC	1 ZSC70403	F&G
CLOSE/CLOSE UNACK_ALM		
Mar 14 09:26:46 ALM DISC	1 ZSC70404	F&G
OPEN UNACK_ALM		
Mar 14 09:26:47 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:26:55 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:26:59 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:27:02 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:27:17 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:27:22 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:27:26 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:27:31 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:27:44 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:27:44 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:27:49 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:27:58 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		

OPEN/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FIDELIS GUSMÃO
DELEGADO
DEPARTAMENTO DE SERVIÇOS CARRONAGS



Mar 14 09:28:02 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:28:07 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:28:11 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:28:20 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:28:25 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:28:25 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:28:34 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:28:43 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:28:52 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:28:56 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:28:56 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:01 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:29:05 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:05 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:10 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:29:14 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:29:28 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:32 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:32 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:29:37 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:29:37 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:46 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:29:46 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:30:04 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:30:08 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:30:13 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:30:14 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:30:17 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:30:22 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:30:26 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:30:31 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:30:40 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:30:41 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERREIRA GUANZON
DIRETOR
UNIDADE DE SERVIÇOS DE TI



Mar 14 09:30:44 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 09:30:46 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:30:49 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:30:53 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:30:53 RTN DISC NORMA/FAULT ACK_RTN	1 GS2405_F	F&G
Mar 14 09:31:02 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:31:16 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:31:17 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:31:20 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:31:21 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 09:31:25 RTN DISC NORMA/FAULT ACK_RTN	1 GS2405_F	F&G
Mar 14 09:31:29 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:31:34 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 09:31:38 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:31:38 RTN DISC NORMA/FAULT ACK_RTN	1 GS2405_F	F&G
Mar 14 09:32:01 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 09:32:05 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:32:10 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:32:19 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:32:28 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:32:32 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:32:41 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:32:50 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:32:55 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:32:59 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:33:04 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:33:08 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:33:26 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:33:40 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:33:49 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:33:53 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:34:20 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:35:50 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES
DIRETOR
FABRIL DE BOMBAS E MÁQUINAS



Mar 14 09:35:55 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:35:56 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:35:59 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:36:17 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:36:17 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:36:22 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:36:40 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:36:40 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:36:53 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:36:58 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:37:02 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G
Mar 14 09:37:11 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 09:37:16 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:37:21 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:37:34 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:37:39 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:37:57 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:37:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:38:01 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:38:59 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:39:31 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:39:35 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:39:40 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:39:44 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:40:11 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:40:25 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:40:27 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 09:40:30 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 09:40:34 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:40:43 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:40:48 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G
Mar 14 09:40:52 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCB_F	F&G
Mar 14 09:41:01 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCB_F	F&G

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PAULETAL GUARDO
DIRETOR
CENTRO DE SERVIÇOS DE ATENDIMENTO



Mar 14 09:41:37 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:41:41 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:41:46 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:42:08 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:42:17 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:42:26 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:42:40 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:42:49 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:42:49 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:42:53 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:42:54 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:43:02 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:43:12 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:43:52 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:44:01 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:44:19 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:44:24 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:44:28 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:45:53 RTN DISC	1 GS29-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:45:58 ALM DISC	1 GS29-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:46:16 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:46:21 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:46:43 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:46:52 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:46:52 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:46:54 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:46:57 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:46:58 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:47:01 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:47:10 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:47:19 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:47:28 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:47:33 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS HUGONEL GILBERTO
DIRETOR
CENTRO DE SERVIÇOS DE COMUNICAÇÃO



Mar 14 09:47:33 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:47:42 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:47:46 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:48:22 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:48:22 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:48:26 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:48:27 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:48:31 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:48:31 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:48:40 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:48:44 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:48:53 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:49:12 RTN DISC	1 ZSC70402	F&G
C/CLOSE ACK_RTN		
Mar 14 09:49:12 RTN DISC	1 ZSC70403	F&G
C/CLOSE ACK_RTN		
Mar 14 09:49:12 RTN DISC	1 ZSO70404	F&G
OPEN ACK_RTN		
Mar 14 09:49:13 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:49:52 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:50:10 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:51:04 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:51:22 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:51:27 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:51:27 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:51:31 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:52:57 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:53:10 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:53:15 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:53:33 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:54:00 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:54:04 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:54:13 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:54:22 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:54:36 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:54:40 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		

NOT

NOT

NOT O/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

ROSE CARLOS PIMENTEL GUSMÃO
DIRETOR
COMANDO DE SERVIÇO DE PROTEÇÃO

Mar 14 09:55:16 ALM DISC	1 PT70033	F&G
ALARM/ALARM UNACK_ALM		
Mar 14 09:55:21 RTN DISC	1 PT70033	F&G
NORMA/ALARM ACK_RTN		
Mar 14 09:56:15 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:58:30 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:58:39 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:58:43 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:58:48 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:59:06 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:59:15 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:59:19 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:59:24 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:59:33 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:59:37 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 09:59:42 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 09:59:55 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:00:00 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:00:13 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:00:22 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:00:36 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:00:54 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:01:03 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:01:48 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:01:57 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:02:01 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:06:09 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:06:13 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:08:28 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:08:33 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:10:16 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:10:21 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:12:18 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:12:22 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:12:27 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL CUSATO
 DIRETOR
 CENTRO DE SERVIÇOS COMERCIAIS



Mar 14 10:12:31 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:12:49 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:12:54 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:12:54 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:12:58 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:13:30 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:13:57 ALM DISC FAULT/FAULT UNACK_ALM	1 GS2405_F	F&G
Mar 14 10:14:06 RTN DISC NORMA/FAULT ACK_RTN	1 GS2405_F	F&G
Mar 14 10:14:24 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:14:28 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:14:33 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:14:37 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:14:42 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:15:00 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:15:04 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:15:09 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:15:13 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:15:40 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:15:45 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:15:49 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:15:54 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:16:43 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:17:06 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:17:10 ALM DISC ALARM/ALARM UNACK_ALM	1 PT70033	F&G
Mar 14 10:17:15 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:17:16 RTN DISC NORMA/ALARM ACK_RTN	1 PT70033	F&G
Mar 14 10:17:24 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:17:28 RTN DISC NORMA/FAULT ACK_RTN	1 GS35-HCB_F	F&G
Mar 14 10:17:28 RTN DISC NORMA/FAULT ACK_RTN	1 GS1810_F	F&G
Mar 14 10:17:33 ALM DISC FAULT/FAULT UNACK_ALM	1 GS35-HCB_F	F&G
Mar 14 10:17:46 ALM DISC FAULT/FAULT UNACK_ALM	1 GS1810_F	F&G
Mar 14 10:18:22 RTN DISC NORMA/FAULT ACK_RTN	1 GS29-HCA_F	F&G
Mar 14 10:18:27 ALM DISC FAULT/FAULT UNACK_ALM	1 GS29-HCA_F	F&G

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FIALTEL GUSMÃO
DIRETOR
GESTÃO DE SERVIÇOS CANTERIAS



Mar 14 10:18:58 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:19:07 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:19:25 ALM DISC	1 GS2405_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:19:25 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:19:30 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:19:30 RTN DISC	1 GS2405_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:19:34 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:19:39 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:19:48 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:19:52 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:19:57 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:20:06 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:20:46 RTN DISC	1 GS1810_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:20:51 ALM DISC	1 GS1810_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:21:23 RTN DISC	1 GS29-HCA_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:21:36 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:21:41 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:21:49 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:21:54 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:21:58 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:22:21 ALM DISC	1 GS29-HCA_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:22:21 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:22:48 RTN DISC	1 GS35-HCB_F	F&G
NORMA/FAULT ACK_RTN		
Mar 14 10:22:52 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		
Mar 14 10:23:11 ALM DISC	1 GS35-HCB_F	F&G
FAULT/FAULT UNACK_ALM		

Mar 14 10:24:05 RTN DISC	1 GS35-HCB_F	F&G

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIRES EL GUSMÃO
DIRETOR
CENTRO DE SERVIÇOS PARTICULARES

03

7 4540 2400 (Mar 14 14:47:32 ALM DISC 1 0835-MCB_F F4G) 48 2400 0 SB

105. 08 667 4628 CB

7 4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

00 08 667 4716 CB

7 4716 2400 (Mar 14 14:47:36 RTN DISC 1 0835-MCB_F F4G) 48 2400 0 SB

950 08 667 4804 CB

7 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 08 667 4892 CB

7 4892 2400 (Mar 14 14:47:41 ALM DISC 1 0835-MCB_F F4G) 48 2400 0 SB

1050 08 667 4980 CB

7 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 08 667 5068 CB

7 5068 2400 (Mar 14 14:48:03 ALM DISC 1 0816-MCB_F F4G) 48 2400 0 SB

111 08 667 5156 CB

7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 08 667 5244 CB

7 5244 2400 (Mar 14 14:48:14 RTN DISC 1 0816-MCB_F F4G) 48 2400 0 SB

950 08 667 5332 CB

7 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 08 667 5420 CB

7 5420 2400 (Mar 14 14:48:30 RTN DISC 1 0835-MCB_F F4G) 48 2400 0 SB

950 08 667 5508 CB

7 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 08 667 5596 CB

7 5596 2400 (Mar 14 14:48:54 RTN DISC 1 0827-MCB_F F4G) 48 2400 0 SB

950 08 667 5684 CB

7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 08 667 5772 CB

7 5772 2400 (Mar 14 14:48:57 ALM DISC 1 0835-MCB_F F4G) 48 2400 0 SB

1050 08 667 5860 CB

7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 08 667 5948 CB

7 5948 2400 (Mar 14 14:49:03 ALM DISC 1 0827-MCB_F F4G) 48 2400 0 SB

1050 08 667 6036 CB

7 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 08 667 6124 CB

7 6124 2400 (Mar 14 14:49:12 RTN DISC 1 0827-MCB_F F4G) 48 2400 0 SB

1050 08 667 6212 CB

7 6212 1050 (NORMA/FAULT ACK_RTN) 19 950 0 SB

0C



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PEREIRA GUEIRO
DIRETOR
UNIDADE DE REGISTRO E ARQUIVAMENTO

CB

7 4500 2400 (Mar 14 14:47:33 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4620 CB

7 4620 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

60 88 667 4716 CB

7 4716 2400 (Mar 14 14:47:36 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4804 CB

7 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4892 CB

7 4892 2400 (Mar 14 14:47:41 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4980 CB

7 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB

7 5068 2400 (Mar 14 14:48:09 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 5156 CB

7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB

7 5244 2400 (Mar 14 14:48:14 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 5332 CB

7 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5420 CB

7 5420 2400 (Mar 14 14:48:30 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5508 CB

7 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5596 CB

7 5596 2400 (Mar 14 14:48:54 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 5684 CB

7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB

7 5772 2400 (Mar 14 14:48:57 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 5860 CB

7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB

7 5948 2400 (Mar 14 14:49:03 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 6036 CB

7 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 6124 CB

7 6124 2400 (Mar 14 14:49:12 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 6212 CB

7 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

FC



COPIA DO DOCUMENTO ORIGINAL

JOSE CARLOS M. M. GUSMÃO
DIRETOR
GERENÇÃO DE SERVIÇOS

CB

7 4530 1:00 [Mar 14 14:47:32 ALM DISC 1 GS35-HCB_F PEG] 48 2400 0 SB

1050 48 667 4828 CB

7 4828 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

00 08 667 4716 CB

7 4716 2400 [Mar 14 14:47:36 RTW DISC 1 GS35-HCB_F PEG] 48 2400 0 SB

950 88 667 4804 CB

7 4804 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 4892 CB

7 4892 2400 [Mar 14 14:47:41 ALM DISC 1 GS35-HCB_F PEG] 48 2400 0 SB

1050 88 667 4980 CB

7 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB

7 5068 2400 [Mar 14 14:48:09 ALM DISC 1 GS16-HCB_F PEG] 48 2400 0 SB

1050 88 667 5156 CB

7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB

7 5244 2400 [Mar 14 14:48:14 RTN DISC 1 GS16-HCB_F PEG] 48 2400 0 SB

950 88 667 5332 CB

7 5332 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 5420 CB

7 5420 2400 [Mar 14 14:48:20 RTN DISC 1 GS35-HCB_F PEG] 48 2400 0 SB

950 88 667 5508 CB

7 5508 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 5596 CB

7 5596 2400 [Mar 14 14:48:34 RTN DISC 1 GS27-HCB_F PEG] 48 2400 0 SB

950 88 667 5684 CB

7 5684 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 5772 CB

7 5772 2400 [Mar 14 14:48:57 ALM DISC 1 GS35-HCB_F PEG] 48 2400 0 SB

1050 88 667 5860 CB

7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB

7 5948 2400 [Mar 14 14:49:03 ALM DISC 1 GS27-HCB_F PEG] 48 2400 0 SB

1050 88 667 6036 CB

7 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 6124 CB

7 6124 2400 [Mar 14 14:49:12 RTW DISC 1 GS27-HCB_F PEG] 48 2400 0 SB

1050 88 667 6212 CB

7 6212 1050 (NORMA/FAULT ACK_RTNI 19 950 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

AGE CARLOS HENRIQUE GUARIM
DIRETOR
DIVISÃO DE SERVIÇOS E COMUNICAÇÃO

PageTrailer
PageResources: font Courier
Pag 5 68
Page...sources: (attend)



0 translate
1 18 789 1169 600 SM
0 0 83 83 0 0 0 65/Courier /Font21 ANSIVec ANSIFont Font
81 6006 667 492 255 255 255 0 QB
3 0 20
2400 88 667 492 CB
7 492 2400 (Mar 14 14:49:24 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 540 CB
7 540 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 CB
7 668 2400 (Mar 14 14:49:28 ALM DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1050 88 667 756 CB
7 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
7 844 2400 (Mar 14 14:50:01 ALM DISC 1 GS27-HCA_F FLAG) 48 2400 0 SB

1050 88 667 932 CB
7 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1020 CB
7 1020 2400 (Mar 14 14:50:04 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1950 88 667 1108 CB
7 1108 1950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 CB
7 1196 2400 (Mar 14 14:50:18 ALM DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1050 88 667 1284 CB
7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1372 CB
7 1372 2400 (Mar 14 14:50:23 RTN DISC 1 GS27-HCA_F FLAG) 48 2400 0 SB

950 88 667 1460 CB
7 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1548 CB
7 1548 2400 (Mar 14 14:50:23 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1950 88 667 1636 CB
7 1636 1950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1724 CB
7 1724 2400 (Mar 14 14:50:29 ALM DISC 1 GS27-HCA_F FLAG) 48 2400 0 SB

1050 88 667 1812 CB
7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1900 CB
7 1900 2400 (Mar 14 14:50:42 RTN DISC 1 GS27-HCA_F FLAG) 48 2400 0 SB

950 88 667 1988 CB
7 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MARCEL GUSSATO
DIRETOR
10/04/2014 09:25:14

PageTrailer

PageResources: font Courier

Page 5 86

PageResources: (attend)

0. translate

4 19 799 1169 600 SM
0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font
61 5806 667 492 255 255 255 0 08
0 0 10
2400 88 667 492 CB
7 192 2400 (Mar 14 14:49:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 560 CB
7 580 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 668 CB
7 663 2400 (Mar 14 14:49:24 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 756 CB
7 1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
7 844 2400 (Mar 14 14:50:01 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 932 CB
7 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1020 CB
7 1020 2400 (Mar 14 14:50:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1108 88 667 1108 CB
7 1108 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 1196 CB
7 1196 2400 (Mar 14 14:50:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1284 CB
7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

24 88 667 1372 CB
7 1372 2400 (Mar 14 14:50:23 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 1460 CB
7 1460 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 1548 CB
7 1548 2400 (Mar 14 14:50:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 1636 CB
7 1636 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB

2400 88 667 1724 CB
7 1724 2400 (Mar 14 14:50:29 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 1812 CB
7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

24 88 667 1900 CB
7 1900 2400 (Mar 14 14:50:42 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 1988 CB
7 1988 950 (NORMA/FAULT ACK_RTNI 19 950 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS RIBEIRO GUSMÃO
DIRETOR
11/04/2010 10:00:00

PageTrailer
PageResources: font Courier
Page 3 66
Page, Sources: (attend)



0 translate
4 18 799 1169 600 SM
0 0 83 83 0 0 0 65/Courier /font21 ANSIVec ANSIFont font
81 580 667 492 255 255 255 0 0B
0 0 0C
2:50 88 667 492 0B
7 492 2400 (Mar 14 14:49:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 08 667 580 0B
7 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 0B
7 668 2400 (Mar 14 14:49:28 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 756 0B
7 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
2400 88 667 844 0B
7 844 2400 (Mar 14 14:50:01 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 932 0B
7 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1020 0B
7 1020 2400 (Mar 14 14:50:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1108 0B
7 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 0B
7 1196 2400 (Mar 14 14:50:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1284 0B
7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1372 0B
7 1372 2400 (Mar 14 14:50:23 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 1460 0B
7 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1548 0B
7 1548 2400 (Mar 14 14:50:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 1636 0B
7 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1724 0B
7 1724 2400 (Mar 14 14:50:29 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 1812 0B
7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1900 0B
7 1900 2400 (Mar 14 14:50:42 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

950 88 667 1988 0B
7 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOÃO CARLOS FIDELIS CUNHA
DIRETOR
TRIBUNAL GERAL DO TRABALHO

: 2400 88 667 2076 CB
 7 2076 2400 (May 14 14:50:45 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 1950 88 667 2164 CB
 7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 1000 88 667 2252 CB
 7 2252 2400 (May 14 14:51:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 950 88 667 2340 CB
 7 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 : 2400 88 667 2428 CB
 7 2428 2400 (May 14 14:51:08 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 1050 88 667 2516 CB
 7 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 2400 88 667 2604 CB
 7 2604 2400 (May 14 14:51:32 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
 : 1050 88 667 2692 CB
 7 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 2400 88 667 2780 CB
 7 2780 2400 (May 14 14:51:54 RTN DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
 : 950 88 667 2868 CB
 7 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 : 2400 88 667 2956 CB
 7 2956 2400 (May 14 14:51:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 950 88 667 3044 CB
 7 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 : 2400 88 667 3132 CB
 7 3132 2400 (May 14 14:52:07 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
 : 1050 88 667 3220 CB
 7 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 2400 88 667 3308 CB
 7 3308 2400 (May 14 14:52:10 RTN DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
 : 950 88 667 3396 CB
 7 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 : 2400 88 667 3484 CB
 7 3484 2400 (May 14 14:52:10 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 1050 88 667 3572 CB
 7 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 2400 88 667 3660 CB
 7 3660 2400 (May 14 14:52:25 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
 : 950 88 667 3748 CB
 7 3748 950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 : 2400 88 667 3836 CB
 7 3836 2400 (May 14 14:52:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 : 950 88 667 3924 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUELLAO
 DIRETOR
 CENTRO DE ATENDIMENTO AO CONSUMIDOR



2000 88 667 2075 CB
7 2075 2400 (Mar 14 14:50:45 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 2164 CB
7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2252 2400 (Mar 14 14:51:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2428 2400 (Mar 14 14:51:08 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2604 2400 (Mar 14 14:51:32 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB

2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2780 2400 (Mar 14 14:51:54 RTN DISC 1 GS27-HCA_F F&G) 48 2400 0 SB

2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2956 2400 (Mar 14 14:51:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3132 2400 (Mar 14 14:52:07 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB

3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3308 2400 (Mar 14 14:52:10 RTN DISC 1 GS27-HCA_F F&G) 48 2400 0 SB

3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3484 2400 (Mar 14 14:52:10 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3660 2400 (Mar 14 14:52:25 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB

3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3836 2400 (Mar 14 14:52:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL CUSATO
DIRETOR
FABRIL DE BOMBAS CAMARGO

2400 88 667 2076 CB
 7 2076 2400 (Mar 14 14:50:45 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 2164 CB
 7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1252 2400 (Mar 14 14:51:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2420 88 667 2420 CB
 7 2420 2400 (Mar 14 14:51:09 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2604 2400 (Mar 14 14:51:32 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2780 2400 (Mar 14 14:51:54 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2956 2400 (Mar 14 14:51:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3132 2400 (Mar 14 14:52:07 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3308 2400 (Mar 14 14:52:10 RTN DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3484 2400 (Mar 14 14:52:10 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3660 2400 (Mar 14 14:52:25 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3836 2400 (Mar 14 14:52:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PUENTE GUERRA
 DIRETOR
 DIVISÃO DE GESTÃO DE CONDIÇÕES

3324 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB

4012 2400 (Mar 14 14:52:55 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4100 CB

4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB

4188 2400 (Mar 14 14:53:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4276 CB

4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

4364 2400 (Mar 14 14:53:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB

4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4540 CB

4540 2400 (Mar 14 14:53:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4628 CB

4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4716 CB

4716 2400 (Mar 14 14:53:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4804 CB

4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4892 CB

4892 2400 (Mar 14 14:53:50 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 4980 CB

4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB

5068 2400 (Mar 14 14:53:54 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5156 CB

5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5244 CB

5244 2400 (Mar 14 14:54:03 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5332 CB

5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5420 CB

5420 2400 (Mar 14 14:54:08 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5508 CB

5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5596 CB

5596 2400 (Mar 14 14:54:26 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5684 CB

5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB

5772 2400 (Mar 14 14:54:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

DESEMPENHO FISCAL DO CURSÃO
PROFESSOR
DIRETOR DE ENSINO

3:21 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB

7 4012 2400 (Mar 14 14:52:55 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4100 CB

7 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB

7 4188 2400 (Mar 14 14:53:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4276 CB

7 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

7 4364 2400 (Mar 14 14:53:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB

7 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4540 CB

7 4540 2400 (Mar 14 14:53:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4628 CB

7 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4716 CB

7 4716 2400 (Mar 14 14:53:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4804 CB

7 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4892 CB

7 4892 2400 (Mar 14 14:53:50 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 4980 CB

7 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB

7 5068 2400 (Mar 14 14:53:54 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5156 CB

7 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5244 CB

7 5244 2400 (Mar 14 14:54:03 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5332 CB

7 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5420 CB

7 5420 2400 (Mar 14 14:54:08 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5508 CB

7 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5596 CB

7 5596 2400 (Mar 14 14:54:26 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5684 CB

7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB

7 5772 2400 (Mar 14 14:54:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PEREIRA CUSATO
OAB 112
CARLOS PEREIRA CUSATO

* 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

240 88 667 4012 CB

* 410 2400 (Mar 14 14:52:55 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4100 CB

* 100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB

* 4188 2400 (Mar 14 14:53:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4276 CB

* 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

* 4364 2400 (Mar 14 14:53:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB

* 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4540 CB

* 4540 2400 (Mar 14 14:53:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4628 CB

* 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4716 CB

* 4716 2400 (Mar 14 14:53:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4804 CB

* 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4892 CB

* 4892 2400 (Mar 14 14:53:50 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 4980 CB

* 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB

* 5068 2400 (Mar 14 14:53:54 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5156 CB

* 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5244 CB

* 5244 2400 (Mar 14 14:54:03 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5332 CB

* 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5420 CB

* 5420 2400 (Mar 14 14:54:08 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5508 CB

* 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5596 CB

* 5596 2400 (Mar 14 14:54:26 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5684 CB

* 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB

* 5772 2400 (Mar 14 14:54:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PRADO GUSMÃO
Diretor
LIVRO DE REGISTRO DE ATOS

1050 88 667 5460 CB
 50 050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB
 5948 2400 (Mar 14 14:54:44 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

950 88 667 6036 CB
 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
 6124 2400 (Mar 14 14:54:53 ALM DISC 1 0835-HCB_F P&G) 48 2400 0 SB

1050 87 667 6212 CB
 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

#C

PageTrailer
 Page: 67 67
 PageResources: (atend)

3 translate
 3 14 18 799 1169 600 SX
 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font
 31 5806 667 492 255 255 255 0 CB
 3 5 fC

2400 88 667 452 CB
 452 2400 (Mar 14 14:55:02 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

950 88 667 580 CB
 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 CB
 668 2400 (Mar 14 14:55:15 ALM DISC 1 0835-HCB_F P&G) 48 2400 0 SB

1050 88 667 756 CB
 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
 844 2400 (Mar 14 14:55:30 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

950 88 667 932 CB
 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1020 CB
 1020 2400 (Mar 14 14:55:24 ALM DISC 1 0835-HCB_F P&G) 48 2400 0 SB

1050 88 667 1108 CB
 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1196 CB
 1196 2400 (Mar 14 14:55:30 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

2400 88 667 1284 CB
 1284 2400 (Mar 14 14:55:37 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

2400 88 667 1372 CB
 1372 2400 (Mar 14 14:55:37 RTN DISC 1 0835-HCB_F P&G) 48 2400 0 SB

350 88 667 1460 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASS. CARLOS MACHADO JUNIOR
 CONSULTA
 GERENCIAMENTO DE DOCUMENTOS

1050 88 667 5860 CB
 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB
 2400 (Mar 14 14:54:44 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 6038 CB
 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
 6124 2400 (Mar 14 14:54:53 ALM DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1050 87 667 6212 CB
 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

7C

PageTrailer
 Page: 67 67
 PageResources: {atend}

> translate
 14 18 739 1169 600 SH
 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font
 37 6826 667 492 255 255 255 0 OB
 0 0 1C
 2400 88 667 492 CB
 2400 (Mar 14 14:55:02 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 560 CB
 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 CB
 2400 (Mar 14 14:55:15 ALM DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1050 88 667 756 CB
 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
 2400 (Mar 14 14:55:20 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 932 CB
 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1020 CB
 2400 (Mar 14 14:55:24 ALM DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

1050 88 667 1108 CB
 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1196 CB
 2400 (Mar 14 14:55:30 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 1284 CB
 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1372 CB
 2400 (Mar 14 14:55:37 RTN DISC 1 GS35-HCB_F FLAG) 48 2400 0 SB

950 88 667 1460 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARLOS FERNANDES GOMES
 DIRETOR
 14 DE OUTUBRO DE 2014

1050 88 667 5860 CB
 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3400 58 667 5948 CB
 5948 2400 (Mar 14 14:54:44 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 6036 CB
 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3400 58 667 6124 CB
 6124 2400 (Mar 14 14:54:53 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB

1050 88 667 6212 CB
 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

.C

%ageT: C:\font\font Courier
 %age: 57 67
 %ageResources: (attend)

% translate
 % 14 18 799 1169 600 SM
 % 0 0 83 83 0 0 0 65/Courier /Font21 ANSIVec AMSIFont font
 % 5806 667 492 255 255 255 0 DB
 % 0 CC
 2400 88 667 492 CB
 492 2400 (Mar 14 14:55:02 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 580 CB
 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3400 58 667 668 CB
 668 2400 (Mar 14 14:55:15 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB

1050 88 667 756 CB
 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
 844 2400 (Mar 14 14:55:20 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 932 CB
 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1020 CB
 1020 2400 (Mar 14 14:55:24 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB

1050 88 667 1108 CB
 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1196 CB
 1196 2400 (Mar 14 14:55:30 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 1284 CB
 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1372 CB
 1372 2400 (Mar 14 14:55:37 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 1460 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

Assinatura
 Data: 14/03/2014
 Hora: 14:55:37

7 1160 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1548 CB

7 1548 2400 (Mar 14 14:55:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1636 CB

1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1724 CB

7 1724 2400 (Mar 14 14:56:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 1812 CB

7 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1900 CB

7 1900 2400 (Mar 14 14:56:09 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1988 CB

7 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2076 CB

7 2076 2400 (Mar 14 14:56:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 2164 CB

7 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2252 CB

7 2252 2400 (Mar 14 14:56:36 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 2340 CB

7 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2428 CB

7 2428 2400 (Mar 14 14:57:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 2516 CB

7 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2604 CB

7 2604 2400 (Mar 14 14:57:48 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 2692 CB

7 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2780 CB

7 2780 2400 (Mar 14 14:57:53 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 2868 CB

7 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2956 CB

7 2956 2400 (Mar 14 14:57:57 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 3044 CB

7 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3132 CB

7 3132 2400 (Mar 14 14:58:15 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 3220 CB

7 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3308 CB

7 3308 2400 (Mar 14 14:58:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ALFRE CARLOS PASSETELOUSO
DIRETOR
BRASÃO DE ARMA DO BRASIL



667 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 10 88 667 1548 CB
667 1548 2400 (Mar 14 14:55:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1636 CB
667 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 14:56:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 14:56:09 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 100 88 667 2076 CB
667 2076 2400 (Mar 14 14:56:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2164 CB
667 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 14:56:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2340 CB
667 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 100 88 667 2428 CB
667 2428 2400 (Mar 14 14:57:36 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2516 CB
667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 14:57:48 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2692 CB
667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 14:57:53 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2868 CB
667 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 14:57:57 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3044 CB
667 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 14:58:15 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 14:58:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
DEPARTAMENTO DE RECURSOS HUMANOS

667 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 10 88 667 1548 CB

667 1548 2400 (Mar 14 14:55:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 1636 CB

667 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 1724 CB

667 1724 2400 (Mar 14 14:56:04 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 1812 CB

667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1900 CB

667 1900 2400 (Mar 14 14:56:09 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 1988 CB

667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 2076 CB

667 2076 2400 (Mar 14 14:56:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 2164 CB

667 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 2252 CB

667 2252 2400 (Mar 14 14:56:36 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 2340 CB

667 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 2428 CB

667 2428 2400 (Mar 14 14:57:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 2516 CB

667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 2604 CB

667 2604 2400 (Mar 14 14:57:48 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 2692 CB

667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 2780 CB

667 2780 2400 (Mar 14 14:57:53 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 2868 CB

667 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 2956 CB

667 2956 2400 (Mar 14 14:57:57 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 3044 CB

667 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 3132 CB

667 3132 2400 (Mar 14 14:58:15 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 3220 CB

667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 3308 CB

667 3308 2400 (Mar 14 14:58:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARIMBO PRESSIONAL EM CADA
ORITROR
INSCRIÇÃO DESENVOLVIDA POR SIA/S

gx
gs 1050 88 667 3396 CB
66 196 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 14:58:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 950 88 667 3572 CB
667 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 14:58:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 14:59:09 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 950 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 14:59:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 4100 CB
667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:00:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 950 88 667 4276 CB
6 276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:00:48 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:00:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:01:06 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:01:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 950 88 667 4980 CB
667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 5068 CB
6 5068 2400 (Mar 14 15:01:24 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 5156 CB
667 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS DE OLIVEIRA
DIRETOR
ANEXO 15

gr
gs 1050 88 667 3396 CB
66 196 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 14:58:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
F
gs 950 88 667 3572 CB
667 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 14:58:33 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 14:59:09 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 14:59:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4100 CB
667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:00:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4276 CB
6 276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:00:48 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:00:59 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:01:06 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:01:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4980 CB
667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5068 CB
6 5068 2400 (Mar 14 15:01:24 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5156 CB
667 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS VALENTE QUEIROZ
DIRETOR
DEPARTAMENTO DE CONTABILIDADE

gr
gs 1050 88 667 3396 CB
667 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 14:58:24 RTN DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
[
gs 950 88 667 3572 CB
667 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 14:58:33 ALM DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 1050 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 14:59:03 RTN DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 950 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
g
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 14:59:18 ALM DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 1050 88 667 4100 CB
667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:00:35 RTN DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 950 88 667 4276 CB
667 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:00:48 ALM DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:00:57 RTN DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:01:06 ALM DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:01:11 RTN DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 950 88 667 4980 CB
667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 1050 88 667 5068 CB
667 5068 1050 (Mar 14 15:01:24 ALM DISC 1 GS35-HCB_F F6G) 48 2400 0 SB
gr
gs 2400 88 667 5156 CB
667 5156 2400 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr



É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS FLORENTIN CUSATO
DIRETOR
COORDENADOR DE SERVIÇOS DE CONTABILIDADE

gs 2400 88 667 5244 CB
667 5244 2400 (Mar 14 15:01:38 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gr
gs 950 88 667 5332 CB
667 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 1050 88 667 5420 CB
667 5420 2400 (Mar 14 15:01:47 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gr
gs 1050 88 667 5508 CB
667 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:02:00 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gr
gs 950 88 667 5684 CB
667 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:02:14 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gr
gs 1050 88 667 5860 CB
667 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5948 CB
667 5948 2400 (Mar 14 15:02:28 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gr
gs 950 88 667 6036 CB
667 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 6124 CB
667 6124 2400 (Mar 14 15:02:27 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB
gs
gs 1050 87 667 6212 CB
667 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
RS

1 #C

RJ

% Trailer

%%PageResources: font Courier

%Page: 68 68

%%PageResources: {attend}

SS

0 0 translate

0 0 14 18 799 1169 600 SM

32 0 0 83 83 0 0 0 0 65/Courier /font21 ANSIvec ANSIFont font

3481 5806 667 492 255 255 255 0 0B

0 0 0 fC

gs 2400 88 667 492 CB

667 492 2400 (Mar 14 15:02:32 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

gr

gs 950 88 667 580 CB

667 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 668 CB

667 668 2400 (Mar 14 15:02:36 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

gr

gs 1050 88 667 756 CB

667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 844 CB

667 844 2400 (Mar 14 15:02:41 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MACHADO GUEDES
DIRETOR
DE LOGÍSTICA E SUPRIMENTOS

gs 2400 88 667 5244 CB
667 5244 2400 (Mar 14 15:01:38 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 88 667 5332 CB
667 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 00 88 667 5420 CB
667 5420 2400 (Mar 14 15:01:47 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5508 CB
667 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:02:00 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5684 CB
667 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:02:14 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 88 667 5860 CB
667 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5948 CB
667 5948 2400 (Mar 14 15:02:18 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 6036 CB
667 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 6124 CB
667 6124 2400 (Mar 14 15:02:27 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gs
gs 1050 88 667 6212 CB
667 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
RS

1 HC
SU
%%P trailer
%%PageResources: font Courier
%%Page: 68 68
%%PageResources: {attend}
RS
1 C translate
1 0 14 18 798 1168 600 SM
32 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSI-Font Font
1431 5806 667 492 255 255 255 0 0B
1 0 0 fc
gs 2400 88 667 492 CB
667 492 2400 (Mar 14 15:02:32 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 580 CB
667 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 668 CB
667 668 2400 (Mar 14 15:02:36 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
gs
gs 88 667 756 CB
667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 844 CB
667 844 2400 (Mar 14 15:02:41 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS POTENTIL GUARATO
DIRETOR
CENTRO DE SERVIÇOS CAR-CONAS

gs 2400 88 667 5244 CB
667 5244 2400 (Mar 14 15:01:38 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 2400 88 667 5332 CB
667 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5420 CB
667 5420 2400 (Mar 14 15:01:47 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5508 CB
667 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:02:00 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5684 CB
667 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:02:14 ALM DISC 2 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 2400 88 667 5860 CB
667 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5948 CB
667 5948 2400 (Mar 14 15:02:18 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 6036 CB
667 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 6124 CB
667 6124 2400 (Mar 14 15:02:27 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 87 667 6212 CB
667 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
RS

1 #C
3J
%%P. caller
%%PageResources: font Courier
%%Page: 68 68
%%PageResources: (atend)
%%
) 0 translate
) 0 14 18 799 1169 600 SM
32 0 0 83 83 0 0 0 65/Courier /Font21 ANSIVec ANSIFont font
3481 5806 667 492 255 255 255 0 CB
) 0 0 10
34 2400 88 667 492 CB
667 492 2400 (Mar 14 15:02:32 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 560 CB
667 560 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 668 CB
667 668 2400 (Mar 14 15:02:36 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 756 CB
667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 844 CB
667 844 2400 (Mar 14 15:02:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FIAZENTEL GUARATO
DIRETOR
DE DEFESA CIVIL

gr
gs 950 88 667 932 CB
667 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1020 CB
667 1020 2400 (Mar 14 15:02:45 ALM DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
g
gs 1050 88 667 1108 CB
667 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1198 CB
667 1198 2400 (Mar 14 15:03:12 RTN DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 950 88 667 1284 CB
667 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1372 CB
667 1372 2400 (Mar 14 15:03:17 ALM DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 1050 88 667 1460 CB
667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:03:26 RTN DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 950 88 667 1636 CB
667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:03:30 ALM DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 1050 88 667 1812 CB
667 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:03:35 RTN DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 950 88 667 1988 CB
667 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 88 667 2076 CB
667 2076 2400 (Mar 14 15:03:39 ALM DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 1050 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:04:33 RTN DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:04:42 ALM DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 1050 88 667 2516 CB
667 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 88 667 2604 CB
667 2604 2400 (Mar 14 15:05:45 RTN DISC 1 GS35-HCB_F PEG) 48 2400 0 SB
gr
gs 950 88 667 2692 CB
667 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
CENTRO DE SERVIÇOS AERONÁUTICOS

gr
gs 950 88 667 932 CB
667 2 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1020 CB
667 1020 2400 (Mar 14 15:02:45 ALM DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 1050 88 667 1108 CB
667 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1196 CB
667 1196 2400 (Mar 14 15:03:12 RTN DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 1284 CB
667 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1372 CB
667 1372 2400 (Mar 14 15:03:17 ALM DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 1050 88 667 1460 CB
667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:03:26 RTN DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 1636 CB
667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:03:30 ALM DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:03:35 RTN DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 1988 CB
667 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:03:39 ALM DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 1050 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:04:33 RTN DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:04:42 ALM DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 1050 88 667 2516 CB
667 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:05:45 RTN DISC 1 0835-HCB_F F40) 48 2400 0 SB
gr
gs 950 88 667 2692 CB
667 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr



É Cópia Fiel do Documento Original.

JOSÉ CARLOS HENRIQUE OLIVEIRA
OAB/SP 108.878
DELEGADO DE PROSECUÇÃO GERAL



gr
gs 950 88 667 932 CB
667 930 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1020 CB
667 1020 2400 (Mar 14 15:02:45 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
g
gs 1050 88 667 1108 CB
667 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1196 CB
667 1196 2400 (Mar 14 15:03:12 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1284 CB
667 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1372 CB
667 1372 2400 (Mar 14 15:03:17 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 1460 CB
667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:03:26 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1636 CB
667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:03:30 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 1812 CB
667 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:03:35 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1988 CB
667 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 88 667 2076 CB
667 2076 2400 (Mar 14 15:03:39 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:04:33 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:04:42 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 2516 CB
667 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:05:45 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 2692 CB
667 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MONTIEL GARCIA
PROFESSOR
CARTILHA DE IDENTIFICACAO

gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:05:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 2858 CB
667 2858 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:06:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:06:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 3220 CB
667 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:06:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3396 CB
667 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 15:08:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:08:23 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:08:27 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:08:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4100 CB
667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:09:12 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 4276 CB
667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:09:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4452 CB
667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:09:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 1050 88 667 4628 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
DE REGISTRO E ARQUIVAMENTO

gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:05:59 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:06:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:06:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3220 CB
667 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:06:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3396 CB
667 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 15:08:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:08:23 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:08:27 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:08:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4100 CB
667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:09:22 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4276 CB
667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gx
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:09:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4452 CB
667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gx
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:09:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gx
gs 2400 88 667 4628 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

CARLOS HENRIQUE GUARINI
DIRETOR
DESENVOLVIMENTO

gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:05:59 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:06:03 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 950 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:06:44 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 3220 CB
667 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:08:14 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 950 88 667 3396 CB
667 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 15:08:18 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:08:23 ALM DISC 1 GS2405_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 3748 CB
667 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:08:27 RTN DISC 1 GS2405_F F4G) 48 2400 0 SB
gr
gs 950 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:08:27 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 950 88 667 4100 CB
667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:09:12 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 4276 CB
667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:09:17 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 950 88 667 4452 CB
667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:09:35 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
gr
gs 1050 88 667 4628 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS MAGNÉL GARCÍA
DIRETOR
UNIDAD DE SERVICIOS TÉCNICOS



JOSE CARLOS PINO AL GUZMAN
DIRECTOR
IN CHARGE OF THE CHARGE

\$PageTrailer

PageResources: font Courier;

Page: 59 69

*PageResources: (acend)

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PINEN DEL GUERRA
DIRECTOR
CALLE DE LA GUERRA 1000



JOSE CARLOS PACHEL GARCIA
DIRECTOR
CENTRO DE ESTUDIOS Y CAPACITACION

SS
 0 0 translate
 0 0 18 799 1169 600 SM
 32 0 83 83 0 0 0 65/Courier /font21 ANSIVec ANSIFont font
 3481 5806 667 492 255 255 255 0 08
 0 0 0 fC
 0 00 88 667 492 CB
 667 492 2400 (Mar 14 15:12:03 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 88 667 580 CB
 667 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 668 CB
 667 668 2400 (Mar 14 15:12:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 88 667 756 CB
 667 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 844 CB
 667 844 2400 (Mar 14 15:12:21 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 88 667 932 CB
 667 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 1020 CB
 667 1020 2400 (Mar 14 15:12:44 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 88 667 1108 CB
 667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 1196 CB
 667 1196 2400 (Mar 14 15:13:02 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
 0
 gs 1050 88 667 1284 CB
 667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 1372 CB
 667 1372 2400 (Mar 14 15:13:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 88 667 1460 CB
 667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 1548 CB
 667 1548 2400 (Mar 14 15:13:06 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
 gr
 gs 950 88 667 1636 CB
 667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 1724 CB
 667 1724 2400 (Mar 14 15:13:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 88 667 1812 CB
 667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 1900 CB
 667 1900 2400 (Mar 14 15:13:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 88 667 1988 CB
 667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 2076 CB
 667 2076 2400 (Mar 14 15:13:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 88 667 2164 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNIL GARCIA
 DIRETOR
 DE FISCALIA



SS
0 0 translate
0 0 18 799 1169 600 SM
32 0 , 42 83 0 0 0 65/Courier /font21 ANSIvec ANSIFont font
3481 5806 667 492 255 255 255 0 08
0 0-0 FC
g 00 88 667 492 CB
667 492 2400 (Mar 14 15:12:03 ALM DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 580 CB
667 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 668 CB
667 668 2400 (Mar 14 15:12:08 RTN DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 756 CB
667 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 844 CB
667 844 2400 (Mar 14 15:12:21 ALM DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 932 CB
667 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1020 CB
667 1020 2400 (Mar 14 15:12:44 RTN DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1108 CB
667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1196 CB
667 1196 2400 (Mar 14 15:13:02 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 1284 CB
667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1372 CB
667 1372 2400 (Mar 14 15:13:02 ALM DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 1460 CB
667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:13:06 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1636 CB
667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:13:24 RTN DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:13:42 ALM DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:13:42 RTN DISC 1 GS35-HCE_F P&G) 48 2400 0 SB
gr
gs 950 88 667 2164 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS MAGALHÃES GUSMÃO
DIRETOR
DE DEFESA CIVIL

38
 > 0 translate
 5 0 19 799 1169 600 3K
 32 0 33 83 0 0 0 65/Courier /font21 ANSIvec ANSIFont font
 3401 5806 667 492 255 255 255 0 0B
 0 0 0 fc
 g. 10 08 667 492 CB
 667 492 2400 (Mar 14 15:12:03 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 08 667 580 CB
 667 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 08 667 668 CB
 667 668 2400 (Mar 14 15:12:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 08 667 756 CB
 667 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 08 667 844 CB
 667 844 2400 (Mar 14 15:12:21 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1 08 667 932 CB
 667 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 08 667 1020 CB
 667 1020 2400 (Mar 14 15:12:44 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 08 667 1108 CB
 667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 08 667 1196 CB
 667 1196 2400 (Mar 14 15:13:02 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
 gr
 gs 1050 08 667 1284 CB
 667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 08 667 1372 CB
 667 1372 2400 (Mar 14 15:13:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 08 667 1460 CB
 667 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 08 667 1548 CB
 667 1548 2400 (Mar 14 15:13:06 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
 gr
 gs 950 08 667 1636 CB
 667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 08 667 1724 CB
 667 1724 2400 (Mar 14 15:13:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 08 667 1812 CB
 667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 08 667 1900 CB
 667 1900 2400 (Mar 14 15:13:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 1050 08 667 1988 CB
 667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 08 667 2076 CB
 667 2076 2400 (Mar 14 15:13:47 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 gr
 gs 950 08 667 2164 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL
 JOSÉ CARLOS FERNANDES GIL
 DIRETOR
 07/04/2014 15:13:47



667 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 88 667 2252 CB
667 2400 (Mar 14 15:13:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2340 CB
667 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:13:56 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2516 CB
667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:14:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2692 CB
667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2780 CB
667 2400 (Mar 14 15:15:39 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2868 CB
667 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:15:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3044 CB
667 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:16:15 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:16:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3396 CB
667 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 15:16:29 ALM DISC 2 GS2405_S F&G) 48 2400 0 SB
gr
gs 1050 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:16:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3748 CB
667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:16:33 RTN DISC 1 GS2405_S F&G) 48 2400 0 SB
gr
gs 950 88 667 3924 CB
667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:16:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS HERNÁNDEZ GARCÍA
DIRECTOR
INSTITUTO NACIONAL DE ESTADÍSTICA Y CENSOS

667 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 2252 CB
 667 2252 2400 (Mar 14 15:13:51 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 1050 88 667 2340 CB
 667 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 GR
 GS 2400 88 667 2428 CB
 667 2428 2400 (Mar 14 15:13:56 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 950 88 667 2516 CB
 667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 2604 CB
 667 2604 2400 (Mar 14 15:14:23 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 1050 88 667 2692 CB
 667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 GR
 GS 2400 88 667 2780 CB
 667 2780 2400 (Mar 14 15:15:38 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 950 88 667 2868 CB
 667 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 2956 CB
 667 2956 2400 (Mar 14 15:15:44 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 1050 88 667 3044 CB
 667 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 GR
 GS 2400 88 667 3132 CB
 667 3132 2400 (Mar 14 15:16:15 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 950 88 667 3220 CB
 667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 3308 CB
 667 3308 2400 (Mar 14 15:16:20 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 1050 88 667 3396 CB
 667 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 GR
 GS 2400 88 667 3484 CB
 667 3484 2400 (Mar 14 15:16:29 ALM DISC 1 GS2405_F F4G) 48 2400 0 SB
 GR
 GS 1050 88 667 3572 CB
 667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 GR
 GS 2400 88 667 3660 CB
 667 3660 2400 (Mar 14 15:16:29 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB
 GR
 GS 950 88 667 3748 CB
 667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 3836 CB
 667 3836 2400 (Mar 14 15:16:33 RTN DISC 1 GS2405_F F4G) 48 2400 0 SB
 GR
 GS 950 88 667 3924 CB
 667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 GR
 GS 2400 88 667 4012 CB
 667 4012 2400 (Mar 14 15:16:51 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS GUARINO
 DIRETOR
 DEPARTAMENTO DE INFORMÁTICA



467 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
78 2 88 667 2252 CB
467 2400 (Mar 14 15:13:51 ALM DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 1050 88 667 2340 CB
467 2400 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3X
98 2400 88 667 2428 CB
467 2428 2400 (Mar 14 15:13:56 RTN DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 950 88 667 2516 CB
467 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
98 2400 88 667 2604 CB
467 2604 2400 (Mar 14 15:14:23 ALM DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 1050 88 667 2692 CB
467 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3X
98 2400 88 667 2780 CB
467 2400 (Mar 14 15:15:39 RTN DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 950 88 667 2868 CB
467 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
98 2400 88 667 2956 CB
467 2956 2400 (Mar 14 15:15:44 ALM DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 1050 88 667 3044 CB
467 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3X
98 2400 88 667 3132 CB
467 3132 2400 (Mar 14 15:16:15 RTN DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 950 88 667 3220 CB
467 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
98 2400 88 667 3308 CB
467 3308 2400 (Mar 14 15:16:20 ALM DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 1050 88 667 3396 CB
467 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3X
98 2400 88 667 3484 CB
467 3484 2400 (Mar 14 15:16:29 ALM DISC 1 GS2405_F F43) 48 2400 0 SB
3X
98 1050 88 667 3572 CB
467 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3X
98 2400 88 667 3660 CB
467 3660 2400 (Mar 14 15:16:29 RTN DISC 1 GS35-HCB_F F43) 48 2400 0 SB
3X
98 950 88 667 3748 CB
467 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
98 2400 88 667 3836 CB
467 3836 2400 (Mar 14 15:16:33 RTN DISC 1 GS2405_F F43) 48 2400 0 SB
3X
98 2400 88 667 3924 CB
467 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3X
98 2400 88 667 4012 CB
467 4012 2400 (Mar 14 15:16:51 ALM DISC 1 GS35-HCB_F F43) 48 2400 0 SB

É CÓPIA DE DOCUMENTO ORIGINAL

JOSE CARLOS MONTESINOS
DIRETOR
12/04/2009 13:00:00



15
15 550 88 667 4100 CB
167 550 (FAULT/FAULT) 11 550 0 SB
15
15 500 88 1217 4100 CB
1217 4100 500 (UNACK_ALM) 10 500 0 SB
15
15 2400 88 667 4188 CB
167 4188 2400 (Mar 14 15:16:56 RTN DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 950 88 667 4276 CB
167 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
15
15 2400 88 667 4364 CB
167 4364 2400 (Mar 14 15:17:14 ALM DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 1050 88 667 4452 CB
167 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
15
15 2400 88 667 4540 CB
167 4540 2400 (Mar 14 15:18:21 RTN DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 950 88 667 4628 CB
167 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
15
15 2400 88 667 4716 CB
167 4716 2400 (Mar 14 15:18:26 ALM DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 1050 88 667 4804 CB
167 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
15
15 2400 88 667 4892 CB
167 4892 2400 (Mar 14 15:18:57 RTN DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 950 88 667 4980 CB
167 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
15
15 2400 88 667 5068 CB
167 5068 2400 (Mar 14 15:19:02 ALM DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 88 667 5156 CB
167 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
15
15 2400 88 667 5244 CB
167 5244 2400 (Mar 14 15:19:38 RTN DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 950 88 667 5332 CB
167 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
15
15 2400 88 667 5420 CB
167 5420 2400 (Mar 14 15:19:42 ALM DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 1050 88 667 5508 CB
167 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
15
15 2400 88 667 5596 CB
167 5596 2400 (Mar 14 15:20:23 RTN DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15
15 88 667 5684 CB
167 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
15
15 2400 88 667 5772 CB
167 5772 2400 (Mar 14 15:20:34 ALM DISC 1 GS35-HCB_F F40) 48 2400 0 SB
15

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
LIVRO DE REGISTRO DE ASSINATURAS



TX
38 550 88 667 4100 CB
367 550 (FAULT/FAULT) 11 550 0 SB
TX
38 500 88 1217 4100 CB
367 4100 500 (UNACK_ALM) 10 500 0 SB
TX
38 2400 88 667 4188 CB
367 4188 2400 (Mar 14 15:16:56 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 950 88 667 4276 CB
367 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
TX
38 2400 88 667 4364 CB
367 4364 2400 (Mar 14 15:17:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 1050 88 667 4452 CB
367 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
TX
38 2400 88 667 4540 CB
367 4540 2400 (Mar 14 15:18:21 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 950 88 667 4628 CB
367 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
TX
38 2400 88 667 4716 CB
367 4716 2400 (Mar 14 15:18:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 1050 88 667 4804 CB
367 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
TX
38 2400 88 667 4892 CB
367 4892 2400 (Mar 14 15:18:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 950 88 667 4980 CB
367 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
TX
38 2400 88 667 5068 CB
367 5068 2400 (Mar 14 15:19:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 1050 88 667 5156 CB
367 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
TX
38 2400 88 667 5244 CB
367 5244 2400 (Mar 14 15:19:38 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 950 88 667 5332 CB
367 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
TX
38 2400 88 667 5420 CB
367 5420 2400 (Mar 14 15:19:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 1050 88 667 5508 CB
367 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
TX
38 2400 88 667 5596 CB
367 5596 2400 (Mar 14 15:20:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX
38 1050 88 667 5684 CB
367 5684 1050 (NORMA/FAULT ACK_RTN) 19 950 0 SB
TX
38 2400 88 667 5772 CB
367 5772 2400 (Mar 14 15:20:36 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
TX

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FIALENTEL GUEZANO
DIRETOR
GERENCIAL DE ZONA 13 CANOAS



gr
gs 550 88 667 4100 CB
667 550 (FAULT/FAULT) 11 550 0 SB
gr
gs 500 88 1217 4100 CB
1217 4100 500 (UNACK_ALM) 10 500 0 SB
g
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:16:56 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4276 CB
667 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:17:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:18:21 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:18:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:18:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4980 CB
667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5068 CB
667 5068 2400 (Mar 14 15:19:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5156 CB
667 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5244 CB
667 5244 2400 (Mar 14 15:19:38 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5332 CB
667 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5420 CB
667 5420 2400 (Mar 14 15:19:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5508 CB
667 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:20:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5684 CB
667 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:20:36 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR

:s 1050 88 667 5860 CB
 :67 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 :Y
 :s 24. 88 667 5948 CB
 :67 5948 2400 (Mar 14 15:20:34 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
 :Y
 :s 50 88 667 6036 CB
 :67 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 :Y
 :s 2400 88 667 6124 CB
 :67 6124 2400 (Mar 14 15:20:54 RTN DISC 1 GS15-HCB_F F&G) 48 2400 0 SB
 :Y
 :s 950 87 667 6212 CB
 :67 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 :Y
 :S
 :FC
 :Z
 :PageTrailer
 :PageResources: font Courier
 :via 70 70
 :PageResources: (attend)
 :S
 :C translate
 :C 14 18 799 1159 600 SM
 :2 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font
 :401 5806 667 492 255 255 255 0 DB
 :C 0 fC
 :s 1250 88 667 492 CB
 :67 492 1250 (Mar 14 15:20:59 RTN DISC) 25 1250 0 AB
 :Y
 :s 50 88 1917 492 CB
 :67 492 1150 (1 GS2405_F F&G) 23 1150 0 SA
 :Y
 :s 950 88 667 580 CB
 :67 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 :Y
 :s 2400 88 667 668 CB
 :67 668 2400 (Mar 14 15:20:59 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 :Y
 :s 1014 88 667 756 CB
 :67 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 :Y
 :s 2400 88 667 844 CB
 :67 844 2400 (Mar 14 15:21:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 :Y
 :s 950 88 667 932 CB
 :67 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 :Y
 :s 2400 88 667 1020 CB
 :67 1020 2400 (Mar 14 15:21:08 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 :Y
 :s 1050 88 667 1108 CB
 :67 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 :Y
 :s 2400 88 667 1196 CB
 :67 1196 2400 (Mar 14 15:21:26 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 :Y
 :s 03 667 1284 CB
 :67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 :Y
 :s 2100 88 667 1372 CB
 :67 1372 2400 (Mar 14 15:21:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FREIREL GUERINO
 DIRETOR
 COMISSÃO DE SELEÇÃO DE CANDIDATOS

```

S 1050 88 667 5860 CB
67 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
S 24... 98 667 5948 CB
67 5948 2400 (Mar 14 15:20:54 RW DISC 1 082405_F F&G] 48 2400 0 SB
IF
S 50 48 667 6036 CB
67 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
S 2400 48 667 6124 CB
67 6124 2400 (Mar 14 15:20:54 RTW DISC 1 GS35-HCB_F F&G] 48 2400 0 SB
IF
S 950 87 667 6212 CB
67 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
IF
S

```

```

1 AC
2J
3$PageTrailer
4$PageResources: font Courier
5$Pa 70 70
6$PageResources: (atend)
7$
8J 0 translate
9J 0 14 16 799 1169 600 SM
10J 0 0 83 83 0 0 0 0 65/Courier /Font21 ANSIVec ANSIPont font
11$41 5806 667 492 255 255 255 0 OB
12J 0 0 FC
13$ 1250 88 667 492 CB
14$ 492 1250 (Mar 14 15:20:59 RTN DISC ) 25 1250 0 SB
15$
16J 50 88 1917 492 CB
17$ 1917 492 1150 ( 1 GS2405_F F&G) 23 1150 0 SB
18$
19$ 950 88 667 580 CB
20$ 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
21$
22$ 2400 88 667 668 CB
23$ 668 2400 (Mar 14 15:20:59 ALM DISC 1 GS35-HCB_F FA
24$
25$ 1050 88 667 756 CB
26$ 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
27$
28$ 2400 88 667 844 CB
29$ 844 2400 (Mar 14 15:21:03 RTN DISC 1 GS35-HCB_F FA
30$
31$ 950 88 667 932 CB
32$ 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
33$
34$ 2400 88 667 1020 CB
35$ 1020 2400 (Mar 14 15:21:08 ALM DISC 1 GS35-HCB_F B
36$
37$ 1050 88 667 1108 CB
38$ 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
39$
40$ 2400 88 667 1196 CB
41$ 1196 2400 (Mar 14 15:22:26 RTN DISC 1 GS35-HCB_F I
42$
43$ 98 667 1284 CB
44$ 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
45$
46$ 2400 88 667 1372 CB
47$ 1372 2400 (Mar 14 15:21:44 ALM DISC 1 GS35-HCB_F Y

```

É CÓPIA FEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS FERNÁNDEZ GUSMÁN
DIRETOR
COORDINADOR DE ASESORIA JURÍDICA



48 1050 88 667 5860 CB
167 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
48 2400 88 667 5948 CB
167 5948 2400 (Mar 14 15:20:54 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
IF
48 2400 88 667 6036 CB
167 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
48 2400 88 667 6124 CB
167 6124 2400 (Mar 14 15:20:54 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
IF
48 950 87 667 6212 CB
167 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
IF
48

1 40
23
**PageTrailer
**PageResources: font Courier
40 70 70
**PageResources: (attend)
28
0 0 translate
1 0 14 18 799 1169 600 SM
32 0 0 83 83 0 0 0 65/Courier /font21 ANSIVec ANSIFont font
1481 5806 667 492 255 255 255 0 CB
0 0 0 IC

48 1250 88 667 492 CB
167 492 1250 (Mar 14 15:20:59 RTN DISC) 25 1250 0 SB
IF
48 1250 88 667 492 CB
167 492 1150 (1 GS2405_F F&G) 25 1150 0 SB
IF
48 950 88 667 580 CB
167 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
IF
48 2400 88 667 668 CB
167 668 2400 (Mar 14 15:20:59 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
IF

48 1050 83 667 756 CB
167 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
48 2400 83 667 844 CB
167 844 2400 (Mar 14 15:21:03 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
IF
48 950 88 667 932 CB
167 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
IF
48 2400 88 667 1020 CB
167 1020 2400 (Mar 14 15:21:08 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
IF

48 1050 83 667 1108 CB
167 1108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
IF
48 2400 88 667 1196 CB
167 1196 2400 (Mar 14 15:21:26 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
IF
48 950 88 667 1284 CB
167 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
IF
48 2400 88 667 1372 CB
167 1372 2400 (Mar 14 15:22:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MAGALHAES OLIVEIRA
DIRETOR
ATA DA COMISSÃO DE LICITAÇÃO



Y
Y 1050 88 667 1460 CB
67 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:21:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 551 88 667 1636 CB
67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
Y 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:22:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 1050 88 667 1812 CB
67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 2400 88 667 1900 CB
67 1900 2400 (Mar 14 15:22:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
Y 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:22:28 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
Y 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:22:33 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
Y 950 88 667 2340 CB
67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
Y 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:22:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 1050 88 667 2516 CB
67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 88 667 2604 CB
67 2604 2400 (Mar 14 15:22:47 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 950 88 667 2692 CB
67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
Y 2400 88 667 2780 CB
67 2780 2400 (Mar 14 15:23:14 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
Y 1050 88 667 2868 CB
67 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:23:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
Y 1050 88 667 3044 CB
67 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
Y 88 667 3132 CB
67 3132 2400 (Mar 14 15:23:18 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
Y 950 88 667 3220 CB
67 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FALCÃO
DEPUTADO
Pelo Estado de São Paulo



Y
S 1050 88 667 1460 CB
67 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:21:57 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 950 88 667 1636 CB
67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:22:20 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 1050 88 667 1812 CB
67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 1900 CB
67 1900 2400 (Mar 14 15:22:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:22:29 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:22:33 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 950 88 667 2340 CB
67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:22:42 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 1050 88 667 2516 CB
67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 950 88 667 2604 CB
67 2604 950 (Mar 14 15:23:47 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 950 88 667 2692 CB
67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 2780 CB
67 2780 2400 (Mar 14 15:23:14 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 1050 88 667 2868 CB
67 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:23:14 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3044 CB
67 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3132 CB
67 3132 2400 (Mar 14 15:23:18 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 950 88 667 3220 CB
67 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES CUNHA
DIRETOR
CENTRO DE GESTÃO DE TECNOLOGIA



GR
gs 1050 88 667 1460 CB
667 0 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:21:57 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 950 88 667 1636 CB
667 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
GR
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:22:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 1050 88 667 1812 CB
667 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:22:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
GR
gs 1050 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:22:39 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 950 88 667 2164 CB
667 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
GR
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:22:33 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
GR
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
GR
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:22:42 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 1050 88 667 2516 CB
667 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:22:47 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 950 88 667 2692 CB
667 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
GR
gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:23:14 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
GR
gs 1050 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:23:14 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
GR
gs 1050 88 667 3044 CB
667 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
GR
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:23:18 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
GR
gs 950 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
GR

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MENEZES GUSMÃO
DIRETOR
FABRIL DE DEFESA CIVIL, 1978

gs 2400 08 667 3308 CB
 667 3308 2400 (Mar 14 15:23:18 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 3396 CB
 667 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 100 88 667 3404 CB
 667 3404 2400 (Mar 14 15:23:23 ALM DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 1050 88 667 3572 CB
 667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 3660 CB
 667 3660 2400 (Mar 14 15:23:27 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 3748 CB
 667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 3836 CB
 667 3836 2400 (Mar 14 15:23:32 ALM DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 1050 88 667 3924 CB
 667 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 4012 CB
 667 4012 2400 (Mar 14 15:23:41 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 4100 CB
 667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 4188 CB
 667 4188 2400 (Mar 14 15:23:59 ALM DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 1050 88 667 4276 CB
 667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 4364 CB
 667 4364 2400 (Mar 14 15:23:59 ALM DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 1050 88 667 4452 CB
 667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 4540 CB
 667 4540 2400 (Mar 14 15:24:03 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 4628 CB
 667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 4716 CB
 667 4716 2400 (Mar 14 15:24:08 ALM DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 1050 88 667 4804 CB
 667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 gr
 gs 2400 88 667 4892 CB
 667 4892 2400 (Mar 14 15:24:08 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 4980 CB
 667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 gr
 gs 2400 88 667 5068 CB
 667 5068 2400 (Mar 14 15:24:12 RTN DISC 1 082405_F FLAG) 48 2400 0 SB
 gr
 gs 950 88 667 5156 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MENDES GUERATO
 DIRETOR
 DEPARTAMENTO DE CONTABILIDADE



gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:23:18 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 2400 88 667 3396 CB
667 3396 2400 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3484 CB
667 3484 2400 (Mar 14 15:23:23 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:23:27 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 350 88 667 3748 CB
667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:23:32 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 2400 88 667 3924 CB
667 3924 2400 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:23:41 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 4100 CB
667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:23:59 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 4276 CB
667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:23:59 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:24:03 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:24:09 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:24:09 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 2400 88 667 4980 CB
667 4980 2400 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5068 CB
667 5068 2400 (Mar 14 15:24:12 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 950 88 667 5156 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS FREITAS GUARIM
DIRETOR
DIVISÃO DE GESTÃO DE PROCESSOS



gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:23:18 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3396 CB
667 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3444 CB
667 3444 2400 (Mar 14 15:23:23 ALM DISC 1 GS2405_F F&G) 48 2400 0 SE
gr
gs 1050 88 667 3572 CB
667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 3660 CB
667 3660 2400 (Mar 14 15:23:27 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3748 CB
667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3836 CB
667 3836 2400 (Mar 14 15:23:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3924 CB
667 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:23:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4100 CB
667 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4188 CB
667 4188 2400 (Mar 14 15:23:50 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4276 CB
667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:23:59 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4452 CB
667 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:24:03 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4628 CB
667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:24:08 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4804 CB
667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:24:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4980 CB
667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5068 CB
667 5068 2400 (Mar 14 15:24:12 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5156 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PRADO LACERDA
DIRETOR
EMPRESA DE SERVIÇOS DE TI



667 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 667 5244 CB
667 5244 2400 (Mar 14 15:24:30 ALM DISC 1 GS2405_F P6G) 48 2400 0 SB
gr
gs 1050 88 667 5322 CB
5322 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5420 CB
667 5420 2400 (Mar 14 15:24:35 RTN DISC 1 GS2405_F P6G) 48 2400 0 SB
gr
gs 950 88 667 5502 CB
667 5502 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:25:20 ALM DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 1050 88 667 5684 CB
667 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:25:24 RTN DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 950 88 667 5850 CB
667 5850 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5948 CB
667 5948 2400 (Mar 14 15:25:29 ALM DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 1050 88 667 6036 CB
667 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 6124 CB
667 6124 2400 (Mar 14 15:25:33 RTN DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 950 88 667 6212 CB
667 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 6300 CB
667 6300 2400 (Mar 14 15:25:38 ALM DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 1050 88 667 6388 CB
667 6388 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 6476 CB
667 6476 2400 (Mar 14 15:25:42 RTN DISC 1 GS35-HCB_F P6G) 48 2400 0 SB
gr
gs 950 88 667 6564 CB
667 6564 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

%PageTrailer

%PageResources: font Courier

%Page: 71 71

%PageResources: (xcond)

%S

C translate

. 0 14 18 799 1169 600 SM

2 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec LWSIFont font

481 5806 667 492 255 255 255 0 CB

0 0 50

6 2400 88 667 492 CB

67 492 2400 (Mar 14 15:25:38 ALM DISC 1 GS35-HCB_F P6G) 48 2400 0 SB

7

8 1050 88 667 580 CB

67 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

8

9 2400 88 667 668 CB

67 668 2400 (Mar 14 15:25:42 RTN DISC 1 GS35-HCB_F P6G) 48 2400 0 SB

9

0 950 88 667 756 CB

67 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

0

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PUENTE GUSMÃO
DIRETOR
UNIDADE DE DEFESA JURÍDICA



57 5154 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
JR
YS 2 13 667 5244 CB
567 5154 2400 (Mar 14 15:24:30 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
JR
ZS 1050 88 667 5332 CB
5 332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
JR
ZS 2400 88 667 5420 CB
567 5120 2400 (Mar 14 15:24:35 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
JR
ZS 950 88 667 5508 CB
667 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
JR
ZS 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:25:20 ALM DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 1050 88 667 5684 CB
667 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
JR
ZS 1400 88 667 5772 CB
667 5772 1400 (Mar 14 15:25:24 RTN DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 950 88 667 5860 CB
667 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
JR
ZS 2400 88 667 5948 CB
667 5948 2400 (Mar 14 15:25:29 ALM DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 1050 88 667 6036 CB
667 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
JR
ZS 1050 88 667 6124 CB
667 6124 1050 (Mar 14 15:25:33 RTN DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 950 88 667 6212 CB
667 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
JR
ZS
JR
ZS
%%PageTrailer
%%PageResources: font Courier
%%Page: 71 71
%%PageResources: (atend)
ZS
ZS 0 translate
ZS 0 10 16 799 1169 600 SM
ZS 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIFont font
ZS 1481 5806 667 492 255 255 255 0 DB
ZS 0 0 fC
ZS 2400 88 667 492 CB
667 492 2400 (Mar 14 15:25:38 ALM DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 1050 88 667 580 CB
667 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
ZS
ZS 1050 88 667 668 CB
667 668 1050 (Mar 14 15:25:42 RTN DISC 1 GS25-HCB_F F&G) 48 2400 0 SB
JR
ZS 950 88 667 756 CB
667 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
JR

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARLOS HENRIQUE GOMES
DIRETOR
CENTRO DE ATENDIMENTO AO PACIENTE

57 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 S 2400 88 667 5244 CB
 67 5. 2400 (Mar 14 15:24:30 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
 Y
 S 1050 88 667 5332 CB
 32 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 S 2400 88 667 5420 CB
 67 5420 2400 (Mar 14 15:24:35 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
 Y
 S 950 88 667 5508 CB
 67 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 S 2400 88 667 5596 CB
 67 5596 2400 (Mar 14 15:25:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 1050 88 667 5684 CB
 67 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 S 2400 88 667 5772 CB
 67 2400 (Mar 14 15:25:24 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 950 88 667 5860 CB
 67 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 S 2400 88 667 5948 CB
 67 5948 2400 (Mar 14 15:25:29 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 1050 88 667 6036 CB
 67 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 S 00 88 667 6124 CB
 67 6124 2400 (Mar 14 15:25:33 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 950 87 667 6212 CB
 67 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 S

FC
 J
 %PageTrailer
 %PageResources: font Courier
 %Page: 71 71
 %PageResources: (Intend)
 S
 6 translate
 0 14 18 799 1169 600 SM
 2 0 0 83 83 0 0 0 65/Courier /font21 ANSIVEC ANSIFont font
 482 5906 667 492 255 255 255 0 OB
 0 0 fC
 S 2400 88 667 492 CB
 67 492 2400 (Mar 14 15:25:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 1050 88 667 580 CB
 67 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 S 2400 88 667 668 CB
 67 2400 (Mar 14 15:25:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
 Y
 S 950 88 667 756 CB
 67 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MONTA CUSTO
 DIRETOR
 COMISSÃO DE PROCESSOS



S 2400 88 667 844 CB
67 844 2400 (Mar 14 15:25:51 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 932 CB
67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
S 1020 88 667 1020 CB
67 1020 2400 (Mar 14 15:26:00 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 950 88 667 1108 CB
67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
S 2400 88 667 1196 CB
67 1196 2400 (Mar 14 15:26:18 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 1284 CB
67 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
S 2400 88 667 1372 CB
67 1372 2400 (Mar 14 15:27:12 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 950 88 667 1460 CB
67 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
S 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:28:02 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 1636 CB
67 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
S 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:28:11 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 950 88 667 1812 CB
67 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
S 2400 88 667 1900 CB
67 1900 2400 (Mar 14 15:28:25 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
S 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:28:29 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
S 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:28:38 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 2340 CB
67 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
S 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:28:51 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 950 88 667 2516 CB
67 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
S 2400 88 667 2604 CB
67 2604 2400 (Mar 14 15:28:56 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB
X
S 1050 88 667 2692 CB

JOSÉ CARLOS MAGALHÃES
DIRETOR
UNIDADE DE SERVIÇO DE APOIO À AVIAÇÃO

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS MAGALHÃES
DIRETOR



2 2400 88 667 844 CB
67 844 2400 (Mar 14 15:25:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
V
2 1044 88 667 932 CB
67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
V
2 20 88 667 1020 CB
67 1020 2400 (Mar 14 15:26:00 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 950 88 667 1108 CB
67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
T
2 2400 88 667 1196 CB
67 1196 2400 (Mar 14 15:26:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 1050 88 667 1284 CB
67 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
T
2 2400 88 667 1372 CB
67 1372 2400 (Mar 14 15:27:12 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 20 88 667 1460 CB
67 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
T
2 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:28:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 1050 88 667 1636 CB
67 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
T
2 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:28:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 950 88 667 1812 CB
67 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
T
2 2400 88 667 1900 CB
67 1900 2400 (Mar 14 15:28:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
T
2 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:28:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
T
2 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:28:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 1050 88 667 2340 CB
67 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
T
2 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:28:51 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 950 88 667 2516 CB
67 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
T
2 2400 88 667 2604 CB
67 2604 2400 (Mar 14 15:28:56 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
T
2 1050 88 667 2692 CB

É Cópia fiel do documento original

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
L. 15/03/2014 (15:04:00)



8 2400 88 667 844 CB
67 844 2400 (Mar 14 15:25:51 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 932 CB
67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
8 2400 88 667 1020 CB
67 1020 2400 (Mar 14 15:26:00 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 950 88 667 1108 CB
67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
8 2400 88 667 1196 CB
67 1196 2400 (Mar 14 15:26:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 1284 CB
67 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
8 2400 88 667 1372 CB
67 1372 2400 (Mar 14 15:27:12 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 950 88 667 1460 CB
67 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
8 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:28:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 1636 CB
67 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
8 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:28:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 950 88 667 1812 CB
67 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
8 2400 88 667 1900 CB
67 1900 2400 (Mar 14 15:28:25 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
8 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:28:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
8 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:28:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 2340 CB
67 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
8 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:28:51 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 950 88 667 2516 CB
67 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
8 2400 88 667 2604 CB
67 2604 2400 (Mar 14 15:28:56 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
X
8 1050 88 667 2692 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
DO TRIBUNAL MARÍTIMO



17 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 24 98 667 2780 CB
67 2400 (Mar 14 15:29:00 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 2868 CB
67 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:29:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3044 CB
67 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3132 CB
67 3132 2400 (Mar 14 15:29:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 3220 CB
67 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 3400 88 667 3308 CB
67 3400 (Mar 14 15:29:48 ALM DISC 1 GS35-HCB_F F&G) 48 3400 0 SB
Y
S 1050 88 667 3396 CB
67 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3484 CB
67 3484 2400 (Mar 14 15:30:12 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 3572 CB
67 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 3660 CB
67 3660 2400 (Mar 14 15:30:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3748 CB
67 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3836 CB
67 3836 2400 (Mar 14 15:30:30 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 3924 CB
67 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 4012 CB
67 4012 2400 (Mar 14 15:30:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 4100 CB
67 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 4188 CB
67 4188 2400 (Mar 14 15:30:58 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 4276 CB
67 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 4364 CB
67 4364 2400 (Mar 14 15:31:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 4452 CB
67 4452 950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 4540 CB
67 4540 2400 (Mar 14 15:31:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MANTUEL GUELLIO
DIRETOR
DEPARTAMENTO DE REGISTRO E DOCUMENTAÇÃO



17 2612 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 2780 CB
17 2780 2400 (Mar 14 15:29:00 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 2868 CB
18 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1
18 667 2956 CB
17 2956 2400 (Mar 14 15:29:23 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3044 CB
17 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 3132 CB
17 3132 2400 (Mar 14 15:29:41 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3220 CB
17 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1
18 667 3308 CB
17 3308 2400 (Mar 14 15:29:45 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3396 CB
17 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 3484 CB
17 3484 2400 (Mar 14 15:30:12 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3572 CB
17 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1
18 667 3660 CB
17 3660 2400 (Mar 14 15:30:26 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3748 CB
17 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 3836 CB
17 3836 2400 (Mar 14 15:30:30 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 3924 CB
17 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1
18 667 4012 CB
17 4012 2400 (Mar 14 15:30:35 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 4100 CB
17 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 4188 CB
17 4188 2400 (Mar 14 15:30:58 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 4276 CB
17 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1
18 667 4364 CB
17 4364 2400 (Mar 14 15:31:02 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
1
18 667 4452 CB
17 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
1
18 667 4540 CB
17 4540 2400 (Mar 14 15:31:07 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB

É Cópia Fiel do Documento Original

JOSE CARLOS MONTI GUSMÃO
DIRETOR
12/03/2014 15:00:00



67 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 26 88 667 2760 CB
67 26 2400 (Mar 14 15:29:00 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 250 88 667 2868 CB
67 250 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
S 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:29:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 1050 88 667 3044 CB
67 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 2400 88 667 3132 CB
67 3132 2400 (Mar 14 15:29:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 350 88 667 3220 CB
67 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
S 2400 88 667 3308 CB
67 3308 2400 (Mar 14 15:29:45 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 1050 88 667 3396 CB
67 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 2400 88 667 3484 CB
67 3484 2400 (Mar 14 15:30:12 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 950 88 667 3572 CB
67 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
S 2400 88 667 3660 CB
67 3660 2400 (Mar 14 15:30:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 1050 88 667 3748 CB
67 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 2400 88 667 3836 CB
67 3836 2400 (Mar 14 15:30:30 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 950 88 667 3924 CB
67 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
S 2400 88 667 4012 CB
67 4012 2400 (Mar 14 15:30:35 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 1050 88 667 4100 CB
67 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 2400 88 667 4188 CB
67 4188 2400 (Mar 14 15:30:58 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 950 88 667 4276 CB
67 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
S 2400 88 667 4364 CB
67 4364 2400 (Mar 14 15:31:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
S 950 88 667 4452 CB
67 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
S 2400 88 667 4540 CB
67 4540 2400 (Mar 14 15:31:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS GUSMÃO
DIRETOR
DEPARTAMENTO DE SERVIÇOS DE CONDIÇÃO



3 350 88 667 4628 CB
67 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 3400 88 667 4716 CB
67 3400 2400 (Mar 14 15:31:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 4804 CB
67 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 4892 CB
67 4892 2400 (Mar 14 15:31:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 4980 CB
67 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5068 CB
67 5068 2400 (Mar 14 15:31:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5156 CB
67 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5244 CB
67 5244 2400 (Mar 14 15:32:18 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 5332 CB
67 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5420 CB
67 5420 2400 (Mar 14 15:32:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5508 CB
67 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5596 CB
67 5596 2400 (Mar 14 15:32:36 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 5684 CB
67 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5772 CB
67 5772 2400 (Mar 14 15:32:41 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5860 CB
67 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5948 CB
67 5948 2400 (Mar 14 15:32:45 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 6036 CB
67 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 6124 CB
67 6124 2400 (Mar 14 15:32:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 6212 CB
67 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:



950 88 667 4628 CB
950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 4716 CB
4716 2400 (Mar 14 15:31:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 4804 CB
4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 4892 CB
4892 2400 (Mar 14 15:31:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 4980 CB
4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 5068 CB
5068 2400 (Mar 14 15:31:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 5156 CB
5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5244 CB
5244 2400 (Mar 14 15:32:18 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 5332 CB
5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 5420 CB
5420 2400 (Mar 14 15:32:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 5508 CB
5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5596 CB
5596 2400 (Mar 14 15:32:36 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 5684 CB
5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
1050 88 667 5772 CB
5772 1050 (Mar 14 15:32:41 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
2400 88 667 5860 CB
5860 2400 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5948 CB
5948 2400 (Mar 14 15:33:45 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 6036 CB
6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 6124 CB
6124 2400 (Mar 14 15:33:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 6212 CB
6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FREITAS OLIVEIRA
DIRETOR
COMISSÃO DE GESTÃO DE PROCESSOS



3 950 88 667 4628 CB
57 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 4716 CB
57 4716 2400 (Mar 14 15:32:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 4804 CB
57 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 4832 CB
57 4832 2400 (Mar 14 15:32:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 4900 CB
57 4900 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5068 CB
57 5068 2400 (Mar 14 15:32:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5156 CB
57 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5244 CB
57 5244 2400 (Mar 14 15:32:38 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 5332 CB
57 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5420 CB
57 5420 2400 (Mar 14 15:32:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5506 CB
57 5506 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5596 CB
57 5596 2400 (Mar 14 15:32:36 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 5684 CB
57 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 5772 CB
57 5772 2400 (Mar 14 15:32:41 ALM DISC 2 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 5860 CB
57 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3 2400 88 667 5948 CB
57 5948 2400 (Mar 14 15:32:45 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 950 88 667 6036 CB
57 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3 2400 88 667 6124 CB
57 6124 2400 (Mar 14 15:32:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3 1050 88 667 6212 CB
57 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É Cópia fiel do documento original

Dr. Carlos Magalhães
Diretor
17/03/2014 15:30:00

%Page: 72 73

%Page.resources: (atend)

3

0 1. ...late

0 14 18 799 1169 600 SM

2 0 0 83 83 0 0 0 65/Courier /font21 ANSIVec ANSIFont Cont

1806 667 492 255 255 255 0 CB

0 0 EC

8 2400 88 667 492 CB

67 492 2400 (Mar 14 15:33:49 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 950 88 667 580 CB

67 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

8 2400 88 667 668 CB

67 668 2400 (Mar 14 15:33:58 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1

8 1050 88 667 756 CB

67 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

8 2400 88 667 844 CB

67 844 2400 (Mar 14 15:33:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 1050 88 667 932 CB

67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

8 2400 88 667 1020 CB

67 1020 2400 (Mar 14 15:34:02 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

1

8 950 88 667 1108 CB

67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

8 00 88 667 1196 CB

67 1196 2400 (Mar 14 15:34:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 950 88 667 1284 CB

67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

8 2400 88 667 1372 CB

67 1372 2400 (Mar 14 15:34:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 1050 88 667 1460 CB

67 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

8 3400 88 667 1548 CB

67 1548 2400 (Mar 14 15:34:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 950 88 667 1636 CB

67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

8 2400 88 667 1724 CB

67 1724 2400 (Mar 14 15:34:52 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 1050 88 667 1812 CB

67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

8 2400 88 667 1900 CB

67 1900 2400 (Mar 14 15:35:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

8 1 88 667 1988 CB

67 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

8 2400 88 667 2076 CB

67 2076 2400 (Mar 14 15:35:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO OLIVEIRA
OURET
20140328 15:35:32 163 049

Page: 72 72

PageResources: (attend)

S

5 0. .slare

0 14 18 799 1169 600 SM

2 0 0 83 23 0 0 0 65/Courier /font21 ANSIVec ANSIFont font

1306 667 492 255 255 255 0 0B

3 0 1C

5 2400 88 667 492 CB

67 492 2400 (Mar 14 15:33:49 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 950 88 667 580 CB

67 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

T

5 2400 88 667 668 CB

67 668 2400 (Mar 14 15:33:58 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

T

5 1050 88 667 756 CB

67 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

T

5 2400 88 667 844 CB

67 844 2400 (Mar 14 15:33:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 1050 88 667 932 CB

67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

T

5 2400 88 667 1020 CB

67 1020 2400 (Mar 14 15:34:02 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

T

5 950 88 667 1108 CB

67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

T

5 2400 88 667 1196 CB

67 1196 2400 (Mar 14 15:34:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 950 88 667 1284 CB

67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

T

5 2400 88 667 1372 CB

67 1372 2400 (Mar 14 15:34:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 1050 88 667 1460 CB

67 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

T

5 2400 88 667 1548 CB

67 1548 2400 (Mar 14 15:34:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 950 88 667 1636 CB

67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

T

5 2400 88 667 1724 CB

67 1724 2400 (Mar 14 15:34:52 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 1050 88 667 1812 CB

67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

T

5 2400 88 667 1900 CB

67 1900 2400 (Mar 14 15:35:27 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

T

5 950 88 667 1988 CB

67 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

T

5 2400 88 667 2076 CB

67 2076 2400 (Mar 14 15:35:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MENDONÇA
DIRETOR



C
S 1050 88 667 2164 CB
67 2 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:36:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
C
S 950 88 667 2340 CB
67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
C
S 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:36:17 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
C
S 1050 88 667 2516 CB
67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2604 CB
67 2604 2400 (Mar 14 15:36:49 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 2692 CB
67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 2780 CB
67 2780 2400 (Mar 14 15:36:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 2868 CB
67 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:37:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 3044 CB
67 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 3132 CB
67 3132 2400 (Mar 14 15:37:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3220 CB
67 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3308 CB
67 3308 2400 (Mar 14 15:37:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3396 CB
67 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 3484 CB
67 3484 2400 (Mar 14 15:37:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 3572 CB
67 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 3660 CB
67 3660 2400 (Mar 14 15:37:34 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
S 950 88 667 3748 CB
67 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 3836 CB
67 3836 2400 (Mar 14 15:37:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 3924 CB
67 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS, Juiz de Direito
DIRETOR
DO TRIBUNAL MARÍTIMO



3 1050 88 667 2164 CB
57 1950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3
3 2400 88 667 2252 CB
57 2252 2400 (Mar 14 15:36:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 950 88 667 2340 CB
57 2240 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3
3 2400 88 667 2428 CB
57 2428 2400 (Mar 14 15:36:17 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 1050 88 667 2516 CB
57 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3
3 2400 88 667 2604 CB
57 2604 2400 (Mar 14 15:36:49 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 950 88 667 2692 CB
57 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3
3 2400 88 667 2780 CB
57 2780 2400 (Mar 14 15:36:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 1050 88 667 2868 CB
57 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3
3 2400 88 667 2956 CB
57 2956 2400 (Mar 14 15:37:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 950 88 667 3044 CB
57 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3
3 2400 88 667 3132 CB
57 3132 2400 (Mar 14 15:37:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 1050 88 667 3220 CB
57 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3
3 2400 88 667 3308 CB
57 3308 2400 (Mar 14 15:37:29 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 1050 88 667 3396 CB
57 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3
3 2400 88 667 3484 CB
57 3484 2400 (Mar 14 15:37:39 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 950 88 667 3572 CB
57 3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3
3 2400 88 667 3660 CB
57 3660 2400 (Mar 14 15:37:34 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 950 88 667 3748 CB
57 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
3
3 2400 88 667 3836 CB
57 3836 2400 (Mar 14 15:37:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
3
3 1050 88 667 3924 CB
57 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
3

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GOMES
DIRETOR



1050 88 667 2164 CB
1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 2252 CB
2252 2400 (Mar 14 15:36:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 2340 CB
2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 2428 CB
2428 2400 (Mar 14 15:36:17 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 2516 CB
2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 2604 CB
2604 2400 (Mar 14 15:36:49 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 2692 CB
2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 2780 CB
2780 2400 (Mar 14 15:36:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 2868 CB
2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 2956 CB
2956 2400 (Mar 14 15:37:11 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 3044 CB
3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 3132 CB
3132 2400 (Mar 14 15:37:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 3220 CB
3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 3308 CB
3308 2400 (Mar 14 15:37:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
1050 88 667 3396 CB
3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 3484 CB
3484 2400 (Mar 14 15:37:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 3572 CB
3572 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 3660 CB
3660 2400 (Mar 14 15:37:34 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
950 88 667 3748 CB
3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 3836 CB
3836 2400 (Mar 14 15:37:34 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 3924 CB
3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PIMENTEL CUNHA
DIRETOR
14/03/2014 15:37:34



2400 88 667 4012 CB
167 4012 2400 (Mar 14 15:37:43 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
2400 88 667 4100 CB
167 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 4188 CB
167 4188 2400 (Mar 14 15:37:47 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
2400 88 667 4276 CB
167 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 4364 CB
167 4364 2400 (Mar 14 15:38:14 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 4452 CB
167 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 4540 CB
167 4540 2400 (Mar 14 15:38:28 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 4628 CB
167 4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 4716 CB
167 4716 2400 (Mar 14 15:39:31 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 4804 CB
167 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 4892 CB
167 4892 2400 (Mar 14 15:39:40 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 4980 CB
167 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5068 CB
167 5068 2400 (Mar 14 15:39:44 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 5156 CB
167 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 5244 CB
167 5244 2400 (Mar 14 15:39:58 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 5332 CB
167 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5420 CB
167 5420 2400 (Mar 14 15:40:07 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 5508 CB
167 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 5596 CB
167 5596 2400 (Mar 14 15:40:11 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
2400 88 667 5684 CB
167 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5772 CB
167 5772 2400 (Mar 14 15:40:16 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
2400 88 667 5860 CB

É CÓPIA DO DOCUMENTO ORIGINAL

JOSE CARLOS AGENTIL CURATO
DIRETOR
17/03/2014 15:40:16



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

gs 2400 88 667 4012 CB
667 4012 2400 (Mar 14 15:37:43 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4100 CB
667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 00 88 667 4188 CB
667 4188 2400 (Mar 14 15:37:47 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4276 CB
667 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4364 CB
667 4364 2400 (Mar 14 15:38:14 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4452 CB
667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4540 CB
667 4540 2400 (Mar 14 15:38:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 00 88 667 4628 CB
667 4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 4716 CB
667 4716 2400 (Mar 14 15:39:31 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 4804 CB
667 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 4892 CB
667 4892 2400 (Mar 14 15:39:40 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 4980 CB
667 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5068 CB
667 5068 2400 (Mar 14 15:39:44 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 050 88 667 5156 CB
667 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5244 CB
667 5244 2400 (Mar 14 15:39:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5332 CB
667 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5420 CB
667 5420 2400 (Mar 14 15:40:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 5508 CB
667 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 5596 CB
667 5596 2400 (Mar 14 15:40:11 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 050 88 667 5684 CB
667 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 5772 CB
667 5772 2400 (Mar 14 15:40:16 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 5860 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FALCÃO GOMES
DIRETOR
COMISSÃO DE FISCALIZAÇÃO



667 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 66 667 5948 CB

667 5948 2400 (Mar 14 15:40:20 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 250 88 667 6036 CB

6. 336 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 6124 CB

667 6124 2400 (Mar 14 15:40:29 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 87 667 6212 CB

667 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

RS

1 #C

EJ

%%PageTrailer

%%PageResources: font Courier

%%Font: 73 73

%%Resources: (attend)

SS

0 0 translate

0 0 14 18 799 1169 600 SM

32 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font

3481 5806 667 492 255 255 0 OB

0 0 0 fC

gs 2400 88 667 492 CB

667 492 2400 (Mar 14 15:40:38 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 2050 88 667 580 CB

6. 80 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 668 CB

667 668 2400 (Mar 14 15:42:40 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 756 CB

667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 100 88 667 844 CB

667 844 2400 (Mar 14 15:42:44 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 932 CB

667 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1020 CB

667 1020 2400 (Mar 14 15:43:25 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 1108 CB

667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1196 CB

667 1196 2400 (Mar 14 15:43:34 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 1284 CB

667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 400 88 667 1372 CB

667 1372 2400 (Mar 14 15:43:38 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 1460 CB

667 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PINHEIRO EL GUANO
DIRETOR

14/03/2024 14:03:43

667 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 88 667 5948 CB

667 5948 2400 (Mar 14 15:40:20 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

gr

gs 950 88 667 6036 CB

667 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 6124 CB

667 6124 2400 (Mar 14 15:40:29 RTN DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

gr

gs 950 87 667 6212 CB

667 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

RS

1 #C

BJ

%%PageTrailer

%%PageResources: font Courier

%%Page: 73 73

%%Resources: (atend)

SS

D 0 translate

0 0 14 18 799 1169 600 SM

32 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIFont font

3481 5806 667 492 255 255 255 0 CB

0 0 0 fC

gs 2400 88 667 492 CB

667 492 2400 (Mar 14 15:40:38 ALM DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

gr

gs 1050 88 667 580 CB

667 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 668 CB

667 668 2400 (Mar 14 15:42:40 ALM DISC 1 GS2405_F

FLG) 48 2400 0 SB

gr

gs 1050 88 667 756 CB

667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 844 88 667 844 CB

667 844 2400 (Mar 14 15:42:44 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

gr

gs 950 88 667 932 CB

667 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1020 CB

667 1020 2400 (Mar 14 15:43:25 RTN DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

gr

gs 950 88 667 1108 CB

667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1196 CB

667 1196 2400 (Mar 14 15:43:34 ALM DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

gr

gs 1050 88 667 1284 CB

667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 1372 88 667 1372 CB

667 1372 2400 (Mar 14 15:43:38 RTN DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

gr

gs 950 88 667 1460 CB

667 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES CORREIA
DIRETOR
15/03/2014 14:00:00

667 5868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 88 667 5948 CB

667 5948 2400 (Mar 14 15:40:20 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

gr

gs 250 88 667 6036 CB

6. 136 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 6124 CB

667 6124 2400 (Mar 14 15:40:29 RTN DISC 1 GS26-MCB_F F&G) 48 2400 0 SB

gr

gs 950 87 667 6212 CB

667 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

rs

1 #C

EU

%%PageTrailer

%%PageResources: font Courier

%%PageResources: 73 73

%%Resources: (attend)

SS

0 0 translate

0 0 14 18 799 1169 600 SM

12 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIfont font

3481 5806 667 492 255 255 255 0 QB

0 0 0 fC

gs 2400 88 667 492 CB

667 492 2400 (Mar 14 15:40:38 ALM DISC 1 GS15-MCB_F F&G) 48 2400 0 SB

gr

gs 250 88 667 580 CB

6. 80 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 668 CB

667 668 2400 (Mar 14 15:42:40 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 756 CB

667 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 00 88 667 844 CB

667 844 2400 (Mar 14 15:42:44 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

gr

gs 950 88 667 932 CB

667 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1020 CB

667 1020 2400 (Mar 14 15:43:25 RTN DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 1108 CB

667 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 1196 CB

667 1196 2400 (Mar 14 15:43:34 ALM DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

gr

gs 1050 88 667 1284 CB

667 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 1372 CB

6. 1372 2400 (Mar 14 15:43:38 RTN DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

gr

gs 950 88 667 1460 CB

667 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARLOS FERNANDES
DIRETOR
DE ADMINISTRAÇÃO

gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:43:43 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1548 88 667 1636 CB
667 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 00 88 667 1724 CB
667 1724 2400 (Mar 14 15:43:52 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:43:56 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:44:41 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 0 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:44:46 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:45:35 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 950 88 667 2516 CB
667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:45:44 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 2692 CB
667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:46:16 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:46:20 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
gr
gs 950 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:47:32 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:47:37 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
gr
gs 1050 88 667 3396 CB



É Cópia Fiel do Documento Original

JOSE CARLOS M. S. OLIVEIRA
DIRETOR
CENTRO DE REGISTRO E ARQUIVAMENTO

gs 2400 88 667 1518 CB
667 1518 2400 (Mar 14 15:43:43 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1636 CB
667 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 1724 CB
667 1724 2400 (Mar 14 15:43:52 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:43:56 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:44:41 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 2400 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:44:46 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:45:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gs
gs 950 88 667 2516 CB
667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:45:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2692 CB
667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:46:16 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:46:20 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:47:32 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 2400 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gs
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:47:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 3396 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FANTINEL CUNHA
DEPUTADO GERAL DO TRIBUNAL

gs 2400 88 667 1548 CB
667 1548 2400 (Mar 14 15:43:43 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1636 CB
667 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 1724 88 667 1724 CB
667 1724 2400 (Mar 14 15:43:52 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 1812 CB
667 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 1900 CB
667 1900 2400 (Mar 14 15:43:56 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 1988 CB
667 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2076 CB
667 2076 2400 (Mar 14 15:44:11 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 2164 88 667 2164 CB
667 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2252 CB
667 2252 2400 (Mar 14 15:44:46 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 2340 CB
667 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2428 CB
667 2428 2400 (Mar 14 15:45:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gs
gs 950 88 667 2516 CB
667 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 2604 CB
667 2604 2400 (Mar 14 15:45:44 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2692 CB
667 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gs
gs 2400 88 667 2780 CB
667 2780 2400 (Mar 14 15:46:16 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 1050 88 667 2868 CB
667 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
gr
gs 2400 88 667 2956 CB
667 2956 2400 (Mar 14 15:46:20 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3044 CB
667 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gr
gs 2400 88 667 3132 CB
667 3132 2400 (Mar 14 15:47:32 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 950 88 667 3220 CB
667 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
gs
gs 2400 88 667 3308 CB
667 3308 2400 (Mar 14 15:47:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
gr
gs 2050 88 667 3396 CB



É Cópia fiel do documento original

JOSE CARLOS MANTOUELLI
DIRETOR
DE REGISTRO E ARQUIVAMENTO

667 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 1 00 667 3484 CB

667 3484 2400 (Mar 14 15:47:46 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 2050 00 667 3572 CB

667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 00 667 3660 CB

667 3660 2400 (Mar 14 15:47:50 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 950 00 667 3748 CB

667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 00 667 3836 CB

667 3836 2400 (Mar 14 15:48:17 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 00 667 3924 CB

667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 00 667 4012 CB

667 4012 2400 (Mar 14 15:48:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 00 667 4100 CB

667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 00 667 4188 CB

667 4188 2400 (Mar 14 15:50:29 ALM DISC 1 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 1050 00 667 4276 CB

667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 00 00 667 4364 CB

667 4364 2400 (Mar 14 15:50:34 RTN DISC 1 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 950 00 667 4452 CB

667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 00 667 4540 CB

667 4540 2400 (Mar 14 15:50:50 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 00 667 4628 CB

667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 00 667 4716 CB

667 4716 2400 (Mar 14 15:51:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 00 667 4804 CB

667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 00 667 4892 CB

667 4892 2400 (Mar 14 15:51:31 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 00 667 4980 CB

667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 00 667 5068 CB

667 5068 2400 (Mar 14 15:51:35 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 00 00 667 5156 CB

667 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 00 667 5244 CB

667 5244 2400 (Mar 14 15:51:40 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB



É CÓPIA DE DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GONCALVES
DIRETOR
DE OPERACOES E MANUTENCAO

667 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2 88 667 3484 CB

667 3484 2400 (Mar 14 15:47:46 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 3572 CB

667 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 3660 CB

667 3660 2400 (Mar 14 15:47:50 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 3748 CB

667 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 3836 CB

667 3836 2400 (Mar 14 15:48:17 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 3924 CB

667 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4012 CB

667 4012 2400 (Mar 14 15:48:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4100 CB

667 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 4188 CB

667 4188 2400 (Mar 14 15:50:29 ALM DISC 1 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4276 CB

667 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 4364 CB

667 4364 2400 (Mar 14 15:50:34 RTN DISC 1 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4452 CB

667 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4540 CB

667 4540 2400 (Mar 14 15:50:50 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4628 CB

667 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4716 CB

667 4716 2400 (Mar 14 15:51:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4804 CB

667 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 4892 CB

667 4892 2400 (Mar 14 15:51:31 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4980 CB

667 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 5068 CB

667 5068 2400 (Mar 14 15:51:35 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 2400 88 667 5156 CB

667 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 5244 CB

667 5244 2400 (Mar 14 15:51:40 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO, CUI 110
DIRETOR
CENTRO DE REGISTRO DE MARCAS

567 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2 88 667 2484 CB

567 2400 (Mar 14 15:47:46 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 2050 88 667 2572 CB

567 572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 3660 CB

567 3660 2400 (Mar 14 15:47:50 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 3748 CB

567 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 3836 CB

567 3836 2400 (Mar 14 15:48:17 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 3924 CB

567 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4012 CB

567 4012 2400 (Mar 14 15:48:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4100 CB

567 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 4188 CB

567 4188 2400 (Mar 14 15:50:29 ALM DISC 1 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4276 CB

567 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 00 88 667 4364 CB

567 4364 2400 (Mar 14 15:50:34 RTN DISC 2 GS27-HCA_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4452 CB

567 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4540 CB

567 4540 2400 (Mar 14 15:50:50 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4628 CB

567 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 4716 CB

567 4716 2400 (Mar 14 15:51:22 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 1050 88 667 4804 CB

567 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 4892 CB

567 4892 2400 (Mar 14 15:51:31 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 950 88 667 4980 CB

567 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

gr

gs 2400 88 667 5068 CB

567 5068 2400 (Mar 14 15:51:35 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

gr

gs 00 88 667 5156 CB

567 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

gr

gs 2400 88 667 5244 CB

567 5244 2400 (Mar 14 15:51:40 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FONSECA TELLES
DIRETOR
COORDENADOR DE SERVIÇOS DE CALAGEM

1
 2 950 88 667 5132 CB
 3 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 4
 5 2400 88 667 5420 CB
 6 5420 2400 (Mar 14 15:51:44 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
 7
 8 1050 88 667 5508 CB
 9 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 10
 11 2400 88 667 5596 CB
 12 5596 2400 (Mar 14 15:52:52 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
 13
 14 1050 88 667 5684 CB
 15 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 16
 17 2400 88 667 5772 CB
 18 5772 2400 (Mar 14 15:52:56 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
 19
 20 950 88 667 5860 CB
 21 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 22
 23 2400 88 667 5948 CB
 24 5948 2400 (Mar 14 15:53:46 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
 25
 26 950 88 667 6036 CB
 27 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 28
 29 2400 88 667 6124 CB
 30 6124 2400 (Mar 14 15:54:31 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
 31
 32 1050 87 667 6212 CB
 33 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100

1 20
 2 20
 3 20
 4 20
 5 20
 6 20
 7 20
 8 20
 9 20
 10 20
 11 20
 12 20
 13 20
 14 20
 15 20
 16 20
 17 20
 18 20
 19 20
 20 20
 21 20
 22 20
 23 20
 24 20
 25 20
 26 20
 27 20
 28 20
 29 20
 30 20
 31 20
 32 20
 33 20
 34 20
 35 20
 36 20
 37 20
 38 20
 39 20
 40 20
 41 20
 42 20
 43 20
 44 20
 45 20
 46 20
 47 20
 48 20
 49 20
 50 20
 51 20
 52 20
 53 20
 54 20
 55 20
 56 20
 57 20
 58 20
 59 20
 60 20
 61 20
 62 20
 63 20
 64 20
 65 20
 66 20
 67 20
 68 20
 69 20
 70 20
 71 20
 72 20
 73 20
 74 20
 75 20
 76 20
 77 20
 78 20
 79 20
 80 20
 81 20
 82 20
 83 20
 84 20
 85 20
 86 20
 87 20
 88 20
 89 20
 90 20
 91 20
 92 20
 93 20
 94 20
 95 20
 96 20
 97 20
 98 20
 99 20
 100 20



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GOMES
 DIRETOR
 GERAL DE REGISTRO E ARQUIVOS



Y
s 950 88 667 5332 CB
67 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s 2400 88 667 5420 CB
67 5420 2400 (Mar 14 15:51:44 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
.
s 1050 88 667 5508 CB
67 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
x
s 2400 88 667 5596 CB
67 5596 2400 (Mar 14 15:52:52 ALM DISC 1 GS2405_3 P&G) 48 2400 0 SB
O
s 1050 88 667 5684 CB
67 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
%
s 2400 88 667 5772 CB
67 5772 2400 (Mar 14 15:52:56 RTN DISC 1 GS2405_3 P&G) 48 2400 0 SB
Y
s 950 88 667 5860 CB
67 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
s 2400 88 667 5948 CB
67 5948 2400 (Mar 14 15:53:46 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
Y
s 950 88 667 6036 CB
67 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
s 2400 88 667 6124 CB
67 6124 2400 (Mar 14 15:54:31 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
H
s 1050 87 667 6212 CB
67 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S

: HC
D
-PageTrailer
-PageResources: font Courier
%E 74 74
-PageResources: (acendi)
S
O translate
O 14 18 799 1169 600 SM
2 0 0 83 83 0 0 0 65/Courier /font21 ANSIvec ANSIFont font
481 5806 667 492 255 255 255 0 CB
O 0 0 IC
s 2400 88 667 492 CB
67 492 2400 (Mar 14 15:54:44 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 580 CB
67 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
s 2400 88 667 668 CB
67 668 2400 (Mar 14 15:55:07 ALM DISC 1 GS35 HCB_F P&G) 48 2400 0 SB
Y
s 1050 88 667 756 CB
67 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
s 2400 88 667 844 CB
67 844 2400 (Mar 14 15:55:25 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
Y
s 950 88 667 932 CB

É cópia em DO DOCUMENTO ORIGINAL

JOSE CARLOS F. LUSTO
DIRETOR
10/03/2014 10:00:00

67 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

2 3 18 667 1020 CB

67 2400 2400 (Mar 14 15:56:05 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

2

3 1050 88 667 1108 CB

108 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

4 2400 88 667 1196 CB

67 1196 2400 (Mar 14 15:56:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

5 950 88 667 1284 CB

67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

6 2400 88 667 1372 CB

67 1372 2400 (Mar 14 15:57:04 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

7 1050 88 667 1460 CB

67 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

8 2400 88 667 1548 CB

67 1548 2400 (Mar 14 15:57:53 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

9 950 88 667 1636 CB

67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

10 2400 88 667 1724 CB

67 1724 2400 (Mar 14 15:58:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

11 1050 88 667 1812 CB

67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

12 2400 88 667 1900 CB

67 1900 2400 (Mar 14 15:58:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

13 950 88 667 1988 CB

67 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

14 2400 88 667 2076 CB

67 2076 2400 (Mar 14 15:58:16 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

15 1050 88 667 2164 CB

67 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

16 2400 88 667 2252 CB

67 2252 2400 (Mar 14 15:58:47 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

17 950 88 667 2340 CB

67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

18 2400 88 667 2428 CB

67 2428 2400 (Mar 14 15:59:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

19 1050 88 667 2516 CB

67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

1

20 2400 88 667 2604 CB

67 2604 2400 (Mar 14 15:59:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1

21 950 88 667 2692 CB

67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1

22 2400 88 667 2780 CB

67 2780 2400 (Mar 14 15:59:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FREITAS BRUNO
DIRETOR
ESPECIAL DE PROTOCOLO

67 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 (Mar 14 15:56:05 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 67 1050 88 667 1108 CB
 168 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 67 2400 88 667 1196 CB
 67 1196 2400 (Mar 14 15:56:41 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 950 88 667 1284 CB
 67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 88 667 1372 CB
 67 1372 2400 (Mar 14 15:57:04 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 1050 88 667 1460 CB
 67 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 67 2400 88 667 1548 CB
 67 1548 2400 (Mar 14 15:57:53 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 950 88 667 1636 CB
 67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 88 667 1724 CB
 67 1724 2400 (Mar 14 15:58:02 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 1050 88 667 1812 CB
 67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 67 950 88 667 1900 CB
 67 1900 2400 (Mar 14 15:58:07 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 950 88 667 1988 CB
 67 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 88 667 2076 CB
 67 2076 2400 (Mar 14 15:58:16 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 1050 88 667 2164 CB
 67 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 67 2400 88 667 2252 CB
 67 2252 2400 (Mar 14 15:58:47 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 950 88 667 2340 CB
 67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 88 667 2428 CB
 67 2428 2400 (Mar 14 15:59:23 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 1050 88 667 2516 CB
 67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
 Y
 67 2400 88 667 2604 CB
 67 2604 2400 (Mar 14 15:59:41 RTN DISC 1 GS35-HCE_F F&G) 48 2400 0 SB
 Y
 67 950 88 667 2692 CB
 67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
 Y
 67 2400 88 667 2780 CB
 67 2780 2400 (Mar 14 15:59:50 ALM DISC 1 GS35-HCE_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS TELLES
 DIRETOR
 TRIBUNAL JUIZ DE DIREITO DE FRIBURGO



67 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 37 08 667 1020 CB
67 11 2400 (Mar 14 15:56:05 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 1050 88 667 1108 CB
67 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
S 2400 88 667 1196 CB
67 1196 2400 (Mar 14 15:56:41 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 950 88 667 1284 CB
67 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 2400 88 667 1372 CB
67 1372 2400 (Mar 14 15:57:04 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 1050 88 667 1460 CB
67 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
S 2400 88 667 1548 CB
67 1548 2400 (Mar 14 15:57:53 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 950 88 667 1636 CB
67 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 2400 88 667 1724 CB
67 1724 2400 (Mar 14 15:58:02 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 1050 88 667 1812 CB
67 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
S 950 88 667 1900 CB
67 1900 2400 (Mar 14 15:58:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 950 88 667 1988 CB
67 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 2400 88 667 2076 CB
67 2076 2400 (Mar 14 15:58:16 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 1050 88 667 2164 CB
67 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
S 2400 88 667 2252 CB
67 2252 2400 (Mar 14 15:58:47 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 950 88 667 2340 CB
67 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 2400 88 667 2428 CB
67 2428 2400 (Mar 14 15:59:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 1050 88 667 2516 CB
67 2516 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
S 2400 88 667 2604 CB
67 2604 2400 (Mar 14 15:59:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
S 950 88 667 2692 CB
67 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
S 2400 88 667 2780 CB
67 2780 2400 (Mar 14 15:59:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS F. DE A. C. C. S. S.
DIRETOR
PROCURADOR GERAL DO ESTADO



F
2050 88 667 2868 CB
57 2 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 2956 CB
57 2956 2400 (Mar 14 15:59:55 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
950 88 667 3044 CB
57 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
F
2400 88 667 3132 CB
57 3132 2400 (Mar 14 16:00:31 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
1050 88 667 3220 CB
57 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 3308 CB
57 3308 2400 (Mar 14 16:00:35 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
950 88 667 3396 CB
57 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
F
2400 88 667 3484 CB
57 3484 2400 (Mar 14 16:00:40 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
1050 88 667 3572 CB
57 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 3660 CB
57 3660 2400 (Mar 14 16:00:44 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
950 88 667 3748 CB
57 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
F
2400 88 667 3836 CB
57 3836 2400 (Mar 14 16:00:58 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
1050 88 667 3924 CB
57 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 4012 CB
57 4012 2400 (Mar 14 16:01:07 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
950 88 667 4100 CB
57 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
F
2400 88 667 4188 CB
57 4188 2400 (Mar 14 16:01:16 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB
F
1050 88 667 4276 CB
57 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 4364 CB
57 4364 2400 (Mar 14 16:01:16 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
F
1050 88 667 4452 CB
57 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
F
2400 88 667 4540 CB
57 4540 2400 (Mar 14 16:01:20 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB
F
950 88 667 4628 CB
57 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
F

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTA OLIVEIRA
DIRETOR
DE REGISTRO E ARQUIVO



..
1 1050 88 667 2868 CB
67 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
2 2400 88 667 2956 CB
67 2956 2400 (Mar 14 15:59:55 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
3 950 88 667 3044 CB
67 3044 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
4 2400 88 667 3132 CB
67 3132 2400 (Mar 14 16:00:31 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
5 1050 88 667 3220 CB
67 3220 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
6 2400 88 667 3308 CB
67 3308 2400 (Mar 14 16:00:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
7 950 88 667 3396 CB
67 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
8 2400 88 667 3484 CB
67 3484 2400 (Mar 14 16:00:40 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
9 1050 88 667 3572 CB
67 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
10 2400 88 667 3660 CB
67 3660 2400 (Mar 14 16:00:44 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
11 950 88 667 3748 CB
67 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
12 2400 88 667 3836 CB
67 3836 2400 (Mar 14 16:00:58 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
13 1050 88 667 3924 CB
67 3924 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
14 950 88 667 4012 CB
67 4012 950 (Mar 14 16:01:07 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
15 2400 88 667 4100 CB
67 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
16 2400 88 667 4188 CB
67 4188 2400 (Mar 14 16:01:16 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
.
17 1050 88 667 4276 CB
67 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
18 2400 88 667 4364 CB
67 4364 2400 (Mar 14 16:01:16 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
.
19 1050 88 667 4452 CB
67 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
20 2400 88 667 4540 CB
67 4540 2400 (Mar 14 16:01:20 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
.
21 950 88 667 4628 CB
67 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
22

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS DE ALMEIDA, ESCLTO
DIRETOR
DO TRIBUNAL MARÍTIMO



2 2400 88 667 4716 CB
57 4716 2400 (Mar 14 16:01:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 950 88 667 4804 CB
67 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s 1050 88 667 4892 CB
67 4892 2400 (Mar 14 16:01:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 1050 88 667 4980 CB
67 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
r
s 2400 88 667 5068 CB
67 5068 2400 (Mar 14 16:01:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 950 88 667 5156 CB
67 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s 2400 88 667 5244 CB
67 5244 2400 (Mar 14 16:01:47 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 1050 88 667 5332 CB
67 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
r
s 2400 88 667 5420 CB
67 5420 2400 (Mar 14 16:02:05 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 950 88 667 5508 CB
67 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s 2400 88 667 5596 CB
67 5596 2400 (Mar 14 16:02:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 1050 88 667 5684 CB
67 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
r
s 2400 88 667 5772 CB
67 5772 2400 (Mar 14 16:02:46 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 950 88 667 5860 CB
67 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s 2400 88 667 5948 CB
67 5948 2400 (Mar 14 16:02:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 1050 88 667 6036 CB
67 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
r
s 2400 88 667 6124 CB
67 6124 2400 (Mar 14 16:03:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
r
s 950 88 667 6212 CB
67 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
r
s

1 #C
2 #
3 #Trailer
4 #Resources: font Courier
5 #Page: 75 25
6 #PageResources: (acend)
7 #
8 # translate

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS MENDONÇA GUERATO
DIRETOR
DEPARTAMENTO DE INVESTIGAÇÃO

```

1 %C
2 --
3 %Writer
4 %Resources: font courier
5 %Page: 75 75
6 %PageResources: (atend)
7
8
9 % Translate

```

É CÓPIA FEITA DO DOCUMENTO ORIGINAL.

JOSE CARLOS MATEO CARRER
DIRECTOR
6 MARZO 1983



2 2400 88 667 4716 CB
57 4716 2400 (Mar 14 16:01:29 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 950 3 667 4804 CB
57 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
10 88 667 4892 CB
57 4892 2400 (Mar 14 16:01:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
1 1050 88 667 4980 CB
57 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
3 2400 88 667 5068 CB
57 5068 2400 (Mar 14 16:01:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 950 88 667 5156 CB
57 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
3 2400 88 667 5244 CB
57 5244 2400 (Mar 14 16:01:47 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 1050 88 667 5332 CB
57 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
3 2400 88 667 5420 CB
57 5420 2400 (Mar 14 16:02:05 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 950 88 667 5508 CB
57 5508 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
3 2400 88 667 5596 CB
57 5596 2400 (Mar 14 16:02:32 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 1050 88 667 5684 CB
57 5684 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
3 2400 88 667 5772 CB
57 5772 2400 (Mar 14 16:02:46 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 950 88 667 5860 CB
57 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
3 2400 88 667 5948 CB
57 5948 2400 (Mar 14 16:02:50 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 1050 88 667 6036 CB
57 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Z
3 2400 88 667 6124 CB
57 6124 2400 (Mar 14 16:03:08 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Z
3 950 88 667 6212 CB
57 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Z
3

FC

Trailer

Resources: Font Courier

Page: 75 75

PageResources: (attend)

3

C translate

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MACHADO GONCALVES
DIRETOR
DE REGISTRO E ARQUIVOS



C 14 18 199 1169 600 SM
L 0 0 63 83 0 0 0 0 65/Courier /font21 ANSIVec ANSIfont font
:81 667 492 255 255 255 0 DB
0 0 --
S 2400 88 667 492 CB
17 492 2400 (Mar 14 16:04:07 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

S 1050 88 667 580 CB
17 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 668 CB
17 668 2400 (Mar 14 16:04:34 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 756 CB
17 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 844 CB
17 844 2400 (Mar 14 16:05:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 932 CB
17 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 1020 CB
17 1020 2400 (Mar 14 16:05:05 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 1108 CB
17 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 1196 CB
17 1196 2400 (Mar 14 16:05:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 2400 88 667 1284 CB
17 1284 2400 (Mar 14 16:05:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 2400 88 667 1372 CB
17 1372 2400 (Mar 14 16:05:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 1460 CB
17 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 1548 CB
17 1548 2400 (Mar 14 16:05:55 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 1636 CB
17 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 1724 CB
17 1724 2400 (Mar 14 16:05:59 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 1812 CB
17 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
S 2400 88 667 1900 CB
17 1900 2400 (Mar 14 16:06:13 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 1050 88 667 1988 CB
17 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
S 2400 88 667 2076 CB
17 2076 2400 (Mar 14 16:06:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
S 950 88 667 2164 CB
17 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y

É CÓPIA FEL DO DOCUMENTO ORIGINAL

JOSE CARLOS DE AZEVEDO
DIRETOR
DEPARTAMENTO DE INVESTIGACAO



0 14 13 799 1169 600 SM
1 0 0 01 83 0 0 0 0 65/Courier /font21 ANSIvec ANSIFont font
481 1 667 492 255 255 255 0 0B
0 0 0
s 2400 88 667 492 CB
67 492 2400 (Mar 14 16:04:07 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 1050 88 667 580 CB
67 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
s 2400 88 667 668 CB
67 668 2400 (Mar 14 16:04:34 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 756 CB
67 756 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
s 2400 88 667 844 CB
67 844 2400 (Mar 14 16:05:01 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 1050 88 667 932 CB
67 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
s 2400 88 667 1020 CB
67 1020 2400 (Mar 14 16:05:05 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 1108 CB
67 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
s 2400 88 667 1196 CB
67 1196 2400 (Mar 14 16:05:37 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 1050 88 667 1284 CB
67 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
s 2400 88 667 1372 CB
67 1372 2400 (Mar 14 16:05:42 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 1460 CB
67 1460 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
s 1 88 667 1548 CB
67 1548 2400 (Mar 14 16:05:56 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 1050 88 667 1636 CB
67 1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
s 2400 88 667 1724 CB
67 1724 2400 (Mar 14 16:05:59 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 1812 CB
67 1812 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X
s 2400 88 667 1900 CB
67 1900 2400 (Mar 14 16:06:13 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 1050 88 667 1988 CB
67 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
X
s 2400 88 667 2076 CB
67 2076 2400 (Mar 14 16:06:17 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB
X
s 950 88 667 2164 CB
67 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
X

É CÓPIA DE DOCUMENTO ORIGINAL
DIRETOR
LPO 01 03 01 01 01 01 01 01



Q 14 18 299 1165 600 SM
Q 0 0 83 83 0 0 0 0 65/Courier /font21 ANSIvee ANSIFont font
Q 1 1 667 492 255 255 255 0 0B
Q 0 0 ..
Q 2400 88 667 492 CB
Q 2400 2400 (Mar 14 16:04:07 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q 1050 88 667 500 CB
Q 1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Q
Q 2400 88 667 668 CB
Q 2400 2400 (Mar 14 16:04:34 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 756 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q
Q 2400 88 667 844 CB
Q 2400 2400 (Mar 14 16:05:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 1050 88 667 932 CB
Q 1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Q
Q 2400 88 667 1020 CB
Q 2400 2400 (Mar 14 16:05:05 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 1108 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q
Q 2400 88 667 1196 CB
Q 2400 2400 (Mar 14 16:05:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 1284 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q
Q 2400 88 667 1372 CB
Q 2400 2400 (Mar 14 16:05:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 1460 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q
Q 2400 88 667 1548 CB
Q 2400 2400 (Mar 14 16:05:55 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 1650 88 667 1636 CB
Q 1650 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Q
Q 2400 88 667 1724 CB
Q 2400 2400 (Mar 14 16:05:59 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 1812 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q
Q 2400 88 667 1900 CB
Q 2400 2400 (Mar 14 16:06:13 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 1050 88 667 1988 CB
Q 1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Q
Q 2400 88 667 2076 CB
Q 2400 2400 (Mar 14 16:06:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Q
Q 950 88 667 2164 CB
Q 950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Q

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUERÃO
DIRETOR
RECEBIDO EM 16/03/2014



2400 88 667 2252 CB
17 2252 2400 (Mar 14 16:06:22 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 2340 CB
17 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 2428 CB
17 2428 2400 (Mar 14 16:06:31 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 2516 CB
17 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 2604 CB
17 2604 2400 (Mar 14 16:07:16 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 2692 CB
17 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 2780 CB
17 2780 2400 (Mar 14 16:07:20 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 2868 CB
17 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 2956 CB
17 2956 2400 (Mar 14 16:07:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 3044 CB
17 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 3132 CB
17 3132 2400 (Mar 14 16:07:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 3220 CB
17 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 3308 CB
17 3308 2400 (Mar 14 16:08:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 3396 CB
17 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 3484 CB
17 3484 2400 (Mar 14 16:08:19 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
1050 88 667 3572 CB
17 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 3660 CB
17 3660 2400 (Mar 14 16:08:19 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
950 88 667 3748 CB
17 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 3836 CB
17 3836 2400 (Mar 14 16:08:23 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
50 88 667 3924 CB
17 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
2400 88 667 4012 CB
17 4012 2400 (Mar 14 16:08:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 4100 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MACHADO
DIRETOR
DE REGISTRO E IDENTIFICACAO



8 2400 88 667 2252 CB
57 2252 2400 (Mar 14 16:06:22 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 1050 88 667 2340 CB
57 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
8 2400 88 667 2428 CB
57 2428 2400 (Mar 14 16:06:31 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 950 88 667 2516 CB
57 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
8 2400 88 667 2604 CB
57 2604 2400 (Mar 14 16:07:16 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 1050 88 667 2692 CB
57 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
8 2400 88 667 2780 CB
57 2780 2400 (Mar 14 16:07:20 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 950 88 667 2868 CB
57 2868 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
8 2400 88 667 2956 CB
57 2956 2400 (Mar 14 16:07:38 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 1050 88 667 3044 CB
57 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
8 2400 88 667 3132 CB
57 3132 2400 (Mar 14 16:07:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 950 88 667 3220 CB
57 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
8 2400 88 667 3308 CB
57 3308 2400 (Mar 14 16:08:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 1050 88 667 3396 CB
57 3396 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
8 2400 88 667 3484 CB
57 3484 2400 (Mar 14 16:08:19 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
8 1050 88 667 3572 CB
57 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
Y
8 2400 88 667 3660 CB
57 3660 2400 (Mar 14 16:08:19 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 950 88 667 3748 CB
57 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
8 2400 88 667 3836 CB
57 3836 2400 (Mar 14 16:08:23 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB
Y
8 950 88 667 3924 CB
57 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
Y
8 2400 88 667 4012 CB
57 4012 2400 (Mar 14 16:08:23 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
Y
8 1050 88 667 4100 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUIMARÃES
DIRETOR
DE REGISTRO E ARQUIVOS



7 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

240 88 667 4188 CB

7 4100 2400 (Mar 14 16:08:28 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

450 88 667 4276 CB

7 4500 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

7 4364 2400 (Mar 14 16:08:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB

7 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4540 CB

7 4540 2400 (Mar 14 16:08:55 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4628 CB

7 4628 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4716 CB

7 4716 2400 (Mar 14 16:09:04 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4804 CB

7 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4892 CB

7 4892 2400 (Mar 14 16:09:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4980 CB

7 4980 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5068 CB

7 5068 2400 (Mar 14 16:09:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 5156 CB

7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB

7 5244 2400 (Mar 14 16:10:16 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5332 CB

7 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5420 CB

7 5420 2400 (Mar 14 16:10:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 5508 CB

7 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5596 CB

7 5596 2400 (Mar 14 16:10:25 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5684 CB

7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB

7 5772 2400 (Mar 14 16:10:29 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 5860 CB

7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB

7 5948 2400 (Mar 14 16:10:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

OSÉ CARLOS HENRIQUE GARCIA
DIRETOR
C. 1004 18804 11/11/14 14:03



2 1100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2 667 4188 CB

2 4188 2400 (Mar 14 16:08:28 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

950 66 667 4276 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 66 667 4364 CB

2 4364 2400 (Mar 14 16:08:37 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

1050 66 667 4452 CB

2 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 66 667 4540 CB

2 4540 2400 (Mar 14 16:08:55 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

950 66 667 4628 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 66 667 4716 CB

2 4716 2400 (Mar 14 16:09:04 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

1050 66 667 4804 CB

2 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 66 667 4892 CB

2 4892 2400 (Mar 14 16:09:17 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

950 66 667 4980 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 66 667 5068 CB

2 5068 2400 (Mar 14 16:09:26 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

1050 66 667 5156 CB

2 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 66 667 5244 CB

2 5244 2400 (Mar 14 16:10:16 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

950 66 667 5332 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 66 667 5420 CB

2 5420 2400 (Mar 14 16:10:20 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

1050 66 667 5508 CB

2 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 66 667 5596 CB

2 5596 2400 (Mar 14 16:10:25 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

950 66 667 5684 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 66 667 5772 CB

2 5772 2400 (Mar 14 16:10:29 ALM DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

1050 66 667 5860 CB

2 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 66 667 5948 CB

2 5948 2400 (Mar 14 16:10:43 RTN DISC 1 GS35-HCB_F F4G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES DE ALMEIDA
DIRETOR
DE REGISTRO E ARQUIVO



? 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
240 8 667 4188 CB
1 41 2400 (Mar 14 16:08:28 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
350 88 667 4276 CB
776 950 (NORMA/FAULT ACK_RTIN) 19 950 0 SB
2400 88 667 4364 CB
7 4364 2400 (Mar 14 16:08:37 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1052 83 667 4452 CB
7 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 4540 CB
7 4540 2400 (Mar 14 16:08:55 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
350 88 667 4628 CB
7 4628 950 (NORMA/FAULT ACK_RTIN) 19 950 0 SB
2400 88 667 4716 CB
7 4716 2400 (Mar 14 16:09:04 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 4804 CB
7 4804 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 4892 CB
7 4892 2400 (Mar 14 16:09:17 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
350 88 667 4980 CB
7 4980 950 (NORMA/FAULT ACK_RTIN) 19 950 0 SB
08 80 667 5068 CB
7 5068 2400 (Mar 14 16:09:26 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 5156 CB
7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5244 CB
7 5244 2400 (Mar 14 16:10:16 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
350 88 667 5332 CB
7 5332 950 (NORMA/FAULT ACK_RTIN) 19 950 0 SB
2400 88 667 5420 CB
7 5420 2400 (Mar 14 16:10:20 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
1050 88 667 5508 CB
7 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5596 CB
7 5596 2400 (Mar 14 16:10:25 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
350 88 667 5684 CB
7 5684 950 (NORMA/FAULT ACK_RTIN) 19 950 0 SB
2400 88 667 5772 CB
7 5772 2400 (Mar 14 16:10:29 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB
08 80 667 5860 CB
7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
2400 88 667 5948 CB
7 5948 2400 (Mar 14 16:10:43 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É Cópia Fiel do Documento Original.

JOSE CARLOS HENRIQUE GUIMARAES
DIRETOR
01/04/2014 10:04:00



550 08 667 6036 CB
2 67 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
1 6124 2400 (Mar 14 16:10:47 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB

1050 87 667 6212 CB
1 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

9C

PageTrailer
PageResources: font Courier
Page: 76 76
PageResources: {aread}
:
:
O translate
O 14 18 799 1169 600 SM
2 1 93 0 0 0 0 65/Courier /font21 ANSIVec ANSIFont font
181 584 667 492 254 255 255 0 OB
O 0 fC
2 2400 88 667 492 CB
1 492 2400 (Mar 14 16:10:56 RTN DISC 1 GS15-HCB_F P&G) 48 2400 0 SB

3 950 88 667 580 CB
1 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3 2400 88 667 668 CB
1 668 2400 (Mar 14 16:11:01 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB

3 1050 88 667 756 CB
1 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3 2400 88 667 844 CB
1 844 2400 (Mar 14 16:11:01 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB

3 1050 88 667 932 CB
1 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3 2400 88 667 1020 CB
1 1020 2400 (Mar 14 16:11:05 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB

3 950 88 667 1108 CB
1 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3 2400 88 667 1196 CB
1 1196 2400 (Mar 14 16:11:23 RTN DISC 1 GS35-HCB_F P&G) 48 2400 0 SB

3 950 88 667 1284 CB
1 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3 2400 88 667 1372 CB
1 1372 2400 (Mar 14 16:11:26 ALM DISC 1 GS2405_F P&G) 48 2400 0 SB

3 950 88 667 1460 CB
1 1460 950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3 2400 88 667 1548 CB
1 1548 2400 (Mar 14 16:11:26 ALM DISC 1 GS35-HCB_F P&G) 48 2400 0 SB

3 1050 88 667 1636 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS MANTOVANI CORRÊA
DIRETOR
BRASIL 2000



950 88 667 6036 CB
2 84 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
2 6124 2400 (Mar 14 16:10:47 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 6212 CB
2 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

#C
#PageTrailer
#PageResources: font Courier
#Page: 76 76
#PageResources: (acend)

0 translate
0 14 18 799 1169 600 BM
0 0 0 0 0 0 65/Courier /font21 ANSIvec ANSIfont font
431 5636 667 492 255 255 255 0 CB
0 0 IC

2400 88 667 492 CB
2 492 2400 (Mar 14 16:10:56 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 580 CB
2 580 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 CB
2 668 2400 (Mar 14 16:11:01 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 756 CB
2 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
2 844 2400 (Mar 14 16:11:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 932 CB
2 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1020 CB
2 1020 2400 (Mar 14 16:11:05 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 1108 CB
2 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 CB
2 1196 2400 (Mar 14 16:11:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 1284 CB
2 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1372 CB
2 1372 2400 (Mar 14 16:11:28 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 1460 CB
2 1460 950 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1548 CB
2 1548 2400 (Mar 14 16:11:28 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1636 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GONCALVES
DIRETOR
DE REGISTRO E ARQUIVOS



350 88 667 6036 CB
7 50 450 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
7 5124 2400 (Mar 14 16:10:47 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 6212 CB
7 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

40

PageTrailer
PageResources: font Courier
Page: 76 76
PageResources: (atend)

0 translate
0 14 18 799 1169 600 SM
0 0 0 0 0 65/Courier /font121 ANSIvec ANSIfont font
0 1 6506 667 492 255 255 255 0 OB
0 0 10

2400 88 667 492 CB
7 492 2400 (Mar 14 16:10:56 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 590 CB
7 590 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 668 CB
7 668 2400 (Mar 14 16:11:01 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 756 CB
7 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
7 844 2400 (Mar 14 16:11:01 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 932 CB
7 932 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1020 CB
7 1020 2400 (Mar 14 16:11:05 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 1108 CB
7 1108 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 CB
7 1196 2400 (Mar 14 16:11:23 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 1284 CB
7 1284 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1372 CB
7 1372 2400 (Mar 14 16:11:28 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 1460 CB
7 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1548 CB
7 1548 2400 (Mar 14 16:11:28 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 1636 CB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS HENRIQUE GUIMARAES
OFICIAL
10/01/2014 14:00:00

1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

24 667 1724 CB

1724 2400 (Mar 14 16:11:33 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 2812 CB

312 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1900 CB

1900 2400 (Mar 14 16:12:22 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 1988 CB

1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2076 CB

2076 2400 (Mar 14 16:12:36 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 2164 CB

2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2252 CB

2252 2400 (Mar 14 16:13:11 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 2340 CB

2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2428 CB

2428 2400 (Mar 14 16:13:20 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 2516 CB

2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2604 CB

2604 2400 (Mar 14 16:13:56 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

950 88 667 2692 CB

2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2780 CB

2780 2400 (Mar 14 16:14:05 ALM DISC 1 GS35-HCF_F

F&G) 48 2400 0 SB

1050 88 667 2868 CB

2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2956 CB

2956 2400 (Mar 14 16:14:19 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 3044 CB

3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3132 CB

3132 2400 (Mar 14 16:14:19 RTN DISC 1 GS35-HCD_F

F&G) 48 2400 0 SB

950 88 667 3220 CB

3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3308 CB

3308 2400 (Mar 14 16:14:24 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 3396 CB

3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3484 CB

3484 2400 (Mar 14 16:14:24 ALM DISC 1 GS35-HCI_F

F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PRENTELL GUYVIO
DIRETOR
DEPARTAMENTO DE REGISTRO

* 1638 1650 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

241 667 1724 CB

? 1724 2400 (Mar 14 16:11:33 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

350 88 667 1812 CB

112 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1900 CB

? 1900 2400 (Mar 14 16:12:22 ALM DISC 1 GS2405_F

FLG) 48 2400 0 SB

1050 88 667 1988 CB

? 1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2076 CB

? 2076 2400 (Mar 14 16:12:26 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

950 88 667 2164 CB

? 2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

3410 88 667 2252 CB

? 2252 3400 (Mar 14 16:13:11 ALM DISC 1 GS2405_F

FLG) 48 2400 0 SB

1050 88 667 2340 CB

? 2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2428 CB

? 2428 2400 (Mar 14 16:13:20 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

950 88 667 2516 CB

? 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

05 88 667 2604 CB

? 2604 2400 (Mar 14 16:13:56 RTN DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

950 88 667 2692 CB

? 2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2780 CB

? 2780 2400 (Mar 14 16:14:06 ALM DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

1050 88 667 2868 CB

? 2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2956 CB

? 2956 2400 (Mar 14 16:14:19 ALM DISC 1 GS2405_F

FLG) 48 2400 0 SB

1050 88 667 3044 CB

? 3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3400 88 667 3132 CB

? 3132 2400 (Mar 14 16:14:19 RTN DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB

950 88 667 3220 CB

? 3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3308 CB

? 3308 2400 (Mar 14 16:14:24 RTN DISC 1 GS2405_F

FLG) 48 2400 0 SB

950 88 667 3396 CB

? 3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3484 CB

? 3484 2400 (Mar 14 16:14:24 ALM DISC 1 GS35-HCB_F

FLG) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GOMES
DIRETOR
14 MAR 2014 10:00

1636 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1724 CB

1724 2400 (Mar 14 16:11:33 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 1612 CB

1612 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1900 CB

1900 2400 (Mar 14 16:12:22 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 1988 CB

1988 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2076 CB

2076 2400 (Mar 14 16:12:26 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 2164 CB

2164 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2252 CB

2252 2400 (Mar 14 16:13:11 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 2340 CB

2340 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2428 CB

2428 2400 (Mar 14 16:13:24 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 2516 CB

2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2604 CB

2604 2400 (Mar 14 16:13:56 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

950 88 667 2692 CB

2692 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2780 CB

2780 2400 (Mar 14 16:14:05 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

1050 88 667 2868 CB

2868 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2956 CB

2956 2400 (Mar 14 16:14:19 ALM DISC 1 GS2405_F

F&G) 48 2400 0 SB

1050 88 667 3044 CB

3044 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3132 CB

3132 2400 (Mar 14 16:14:19 RTN DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB

950 88 667 3220 CB

3220 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3308 CB

3308 2400 (Mar 14 16:14:24 RTN DISC 1 GS2405_F

F&G) 48 2400 0 SB

950 88 667 3396 CB

3396 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3484 CB

3484 2400 (Mar 14 16:14:24 ALM DISC 1 GS35-HCB_F

F&G) 48 2400 0 SB



É Cópia fidel do documento original

ASS. CARLOS M. KENTEL, GARCIA
DIRETOR
GABINETE DO DIRETOR



1050 88 667 3572 CB
7 3 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3660 CB
2460 2400 (Mar 14 16:14:28 ALM DISC 1 052405_F F&G) 48 2400 0 SB

1050 88 667 3748 CB
2 2748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3836 CB
27 2836 2400 (Mar 14 16:14:33 RTN DISC 1 052405_F F&G) 48 2400 0 SB

950 88 667 3924 CB
27 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB
67 4012 2400 (Mar 14 16:14:42 RTN DISC 1 0515-HCB_F F&G) 48 2400 0 SB

950 88 667 4100 CB
67 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4188 CB
27 4188 2400 (Mar 14 16:15:00 ALM DISC 1 0515-HCB_F F&G) 48 2400 0 SB

1050 88 667 4276 CB
2 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4364 CB
67 4364 2400 (Mar 14 16:15:13 RTN DISC 1 0515-HCB_F F&G) 48 2400 0 SB

950 88 667 4452 CB
452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4540 CB
67 4540 2400 (Mar 14 16:15:18 ALM DISC 1 0515-HCB_F F&G) 48 2400 0 SB

1050 88 667 4628 CB
67 4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4716 CB
67 4716 2400 (Mar 14 16:15:35 RTN DISC 1 0515-HCB_F F&G) 48 2400 0 SB

950 88 667 4804 CB
67 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4892 CB
67 4892 2400 (Mar 14 16:15:40 ALM DISC 1 0515-HCB_F F&G) 48 2400 0 SB

1050 88 667 4980 CB
67 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB
67 5068 2400 (Mar 14 16:15:20 RTN DISC 1 0515-HCB_F F&G) 48 2400 0 SB

950 88 667 5156 CB
67 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5244 CB
67 5244 2400 (Mar 14 16:16:56 ALM DISC 1 0515-HCB_F F&G) 48 2400 0 SB

1050 88 667 5332 CB
67 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PACHECO
DIRETOR
DE REGISTRO E ARQUIVO



1050 88 667 3572 CB
7 3572 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3660 CB
7 3660 2400 (Mar 14 16:14:28 ALM DISC 1 GS2405_F FLG) 48 2400 0 SB

1050 88 667 3748 CB
7 3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3836 CB
7 3836 2400 (Mar 14 16:14:33 RTN DISC 1 GS2405_F FLG) 48 2400 0 SB

950 88 667 3924 CB
7 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB
7 4012 2400 (Mar 14 16:14:42 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

950 88 667 4100 CB
7 4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4188 CB
7 4188 2400 (Mar 14 16:15:00 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

1050 88 667 4276 CB
7 4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4364 CB
7 4364 2400 (Mar 14 16:15:12 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

950 88 667 4452 CB
7 4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4540 CB
7 4540 2400 (Mar 14 16:15:18 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

1050 88 667 4628 CB
7 4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4716 CB
7 4716 2400 (Mar 14 16:15:35 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

950 88 667 4804 CB
7 4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4892 CB
7 4892 2400 (Mar 14 16:15:40 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

1050 88 667 4980 CB
7 4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB
7 5068 2400 (Mar 14 16:16:20 RTN DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

950 88 667 5156 CB
7 5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5244 CB
7 5244 2400 (Mar 14 16:16:56 ALM DISC 1 GS35-HCB_F FLG) 48 2400 0 SB

1050 88 667 5332 CB
7 5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA DE DOCUMENTO ORIGINAL

JOSÉ CARLOS MONTALVÃO
DIRETOR
DE REGISTRO E ARQUIVO



1050 88 667 3572 CB
1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3660 CB
3660 2400 (Mar 14 16:14:28 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 3748 CB
3748 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 3836 CB
3836 2400 (Mar 14 16:14:33 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 3924 CB
3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB
4012 2400 (Mar 14 16:14:42 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4100 CB
4100 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4188 CB
4188 2400 (Mar 14 16:15:00 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4276 CB
4276 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4364 CB
4364 2400 (Mar 14 16:15:13 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4452 CB
4452 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4540 CB
4540 2400 (Mar 14 16:15:18 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4628 CB
4628 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2 88 667 4716 CB
4716 2400 (Mar 14 16:15:35 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 4804 CB
4804 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4892 CB
4892 2400 (Mar 14 16:15:40 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4980 CB
4980 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5068 CB
5068 2400 (Mar 14 16:16:20 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5156 CB
5156 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

88 667 5244 CB
5244 2400 (Mar 14 16:16:56 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 5332 CB
5332 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PAVANELLO
DIRETOR
16/05/2014



PageTrailer

0 translate

É CÓPIA FEITA DO DOCUMENTO ORIGINAL:



2400 88 667 5420 CB
7 5420 2400 (Mar 14 16:17:10 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5508 CB
7 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5596 CB
7 5596 2400 (Mar 14 16:17:15 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5684 CB
7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB
7 5772 2400 (Mar 14 16:17:28 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 5860 CB
7 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5948 CB
7 5948 2400 (Mar 14 16:17:46 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 6036 CB
7 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 6124 CB
7 6124 2400 (Mar 14 16:18:22 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

950 88 667 6212 CB
7 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

PageTrailer
PageResources: font Courier
Page: 77 77
PageResources: (attend)

0 translate
0 799 1149 600 SM
0 0 83 83 0 0 0 65/Courier /font21 ANSIVec ANSIFont font
01 5206 667 492 255 255 255 0 CB
0 0 fC

2400 88 667 492 CB
7 492 2400 (Mar 14 16:18:27 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 560 CB
7 560 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 668 CB
7 668 2400 (Mar 14 16:19:29 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 756 CB
7 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
7 844 2400 (Mar 14 16:19:34 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 932 CB
7 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1020 CB
7 1020 2400 (Mar 14 16:19:34 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES CUNHA
DIRTOR
01/04/2014 10:00:00

2400 88 667 5420 CB
 7 5420 2400 (Mar 14 16:17:10 ALM DISC 1 082405_F F&G) 48 2400 0 SB

1050 88 667 5508 CB
 7 5508 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

950 88 667 5596 CB
 7 5596 950 (Mar 14 16:17:15 RTN DISC 1 082405_F F&G) 48 2400 0 SB

950 88 667 5684 CB
 7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB
 7 5772 2400 (Mar 14 16:17:28 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 88 667 5860 CB
 7 5860 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5948 CB
 7 5948 2400 (Mar 14 16:17:46 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB

1050 88 667 6036 CB
 7 6036 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 6124 CB
 7 6124 2400 (Mar 14 16:18:22 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB

950 87 667 6212 CB
 7 6212 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

PageTrailer
 PageResources: font Courier
 Page: 77 77
 PageResources: (acend)

Translate
 0 799 1169 600 SM
 0 0 0 0 0 0 0 0 55/Courier /font21 ANSIvec ANSIfont font
 181 5806 667 492 255 255 255 0 0B
 0 0 0C
 2400 88 667 492 CB
 7 492 2400 (Mar 14 16:18:27 ALM DISC 1 0835-HCB_F F&G) 48 2400 0 SB

1050 88 667 580 CB
 7 580 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 668 CB
 7 668 2400 (Mar 14 16:19:29 ALM DISC 1 082405_F F&G) 48 2400 0 SB

1050 88 667 756 CB
 7 756 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 844 CB
 7 844 2400 (Mar 14 16:19:34 RTN DISC 1 082405_F F&G) 48 2400 0 SB

950 88 667 932 CB
 7 932 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1020 CB
 7 1020 2400 (Mar 14 16:19:34 RTN DISC 1 0835-HCB_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES OLIVEIRA
 DIRETOR
 17/03/2014 10:00:00

930 88 667 1108 CB
 7 11 50 (NORMA/FAULT ACK_RTN) 19 950 0 SB

1400 88 667 1196 CB
 7 1196 2400 (Mar 14 16:19:28 ALM DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

1050 88 667 1284 CB
 7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1372 CB
 7 1372 2400 (Mar 14 16:19:58 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1460 CB
 7 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1548 CB
 7 1548 2400 (Mar 14 16:20:07 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1636 CB
 7 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1724 CB
 7 1724 2400 (Mar 14 16:20:30 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1812 CB
 7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1900 CB
 7 1900 2400 (Mar 14 16:20:34 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1988 CB
 7 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2076 CB
 7 2076 2400 (Mar 14 16:20:39 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 2164 CB
 7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2252 CB
 7 2252 2400 (Mar 14 16:20:46 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 2340 CB
 7 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2428 CB
 7 2428 2400 (Mar 14 16:21:09 RTN DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

950 88 667 2516 CB
 7 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2604 CB
 7 2604 2400 (Mar 14 16:21:18 ALM DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

1050 88 667 2692 CB
 7 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2780 CB
 7 2780 2400 (Mar 14 16:21:27 ALM DISC 1 PT70034 F&G) 48 2400 0 SB

1050 88 667 2868 CB
 7 2868 1050 (ALARM/ALARM UNACK_ALM) 21 1050 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PASTORAL
 DIRETOR



950 88 667 1108 CB
7 11 50 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 CB
7 1196 2400 (Mar 14 16:19:38 ALM DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

1050 88 667 1284 CB
7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1372 CB
7 1372 2400 (Mar 14 16:19:58 ALX DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1460 CB
7 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1548 CB
7 1548 2400 (Mar 14 16:20:07 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1636 CB
7 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1724 CB
7 1724 2400 (Mar 14 16:20:30 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1812 CB
7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1900 CB
7 1900 2400 (Mar 14 16:20:34 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1988 CB
7 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2076 CB
7 2076 2400 (Mar 14 16:20:39 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 2164 CB
7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2252 CB
7 2252 2400 (Mar 14 16:20:48 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 2340 CB
7 2340 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2428 CB
7 2428 2400 (Mar 14 16:21:09 RTN DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

950 88 667 2516 CB
7 2516 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2604 CB
7 2604 2400 (Mar 14 16:21:18 ALM DISC 1 GS15-HCB_F F&G) 48 2400 0 SB

1050 88 667 2692 CB
7 2692 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2780 CB
7 2780 2400 (Mar 14 16:21:27 ALM DISC 1 PT70034 F&G) 48 2400 0 SB

1050 88 667 2868 CB
7 2868 1050 (ALARM/ALARM UNACK_ALM) 21 1050 0 SB

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
DO TRIBUNAL MARÍTIMO

950 88 667 1108 CB
 7 1196 2400 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1196 CB
 7 1196 2400 (Mar 14 16:19:38 ALM DISC 1 GS36-HCB_F F&G) 48 2400 0 SB

1050 88 667 1284 CB
 7 1284 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1372 CB
 7 1372 2400 (Mar 14 16:19:58 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1460 CB
 7 1460 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1548 CB
 7 1548 2400 (Mar 14 16:20:07 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1636 CB
 7 1636 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 1724 CB
 7 1724 2400 (Mar 14 16:20:30 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 1812 CB
 7 1812 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 1900 CB
 7 1900 2400 (Mar 14 16:20:34 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 1988 CB
 7 1988 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 2076 CB
 7 2076 2400 (Mar 14 16:20:39 ALM DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

1050 88 667 2164 CB
 7 2164 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 2252 CB
 7 2252 2400 (Mar 14 16:20:48 RTN DISC 1 GS16-HCB_F F&G) 48 2400 0 SB

950 88 667 2340 CB
 7 2340 950 (NORMA/FAULT ACK_RTN) 19 950

2400 88 667 2428 CB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FREITAS GUSMÃO
 DIRETOR
 DEPARTAMENTO DE REGISTRO



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
DEPARTAMENTO DE REGISTRO E TÍTULOS

11 1350 0 SB

240 667 3660 CB
7 3660 2400 (Mar 14 20:56:54 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

350 88 667 3748 CB
7 3748 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3836 CB
7 3836 2400 (Mar 14 20:57:16 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

350 88 667 3924 CB
7 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB
7 4012 2400 (Mar 14 20:57:21 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4100 CB
7 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB
7 4188 2400 (Mar 14 20:57:46 RTN DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

350 88 667 4276 CB
7 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB
7 4364 2400 (Mar 14 20:57:52 ALM DISC 1 GS35-HCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB
7 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

350 88 667 4540 CB
7 4540 3350 (Mar 14 21:03:36 ALM DISC 1 F&G_INH_8867 F&G_INHIBITS ON/) 67 3350 0 SB

600 88 667 4628 CB
7 4628 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4716 CB
7 4716 3350 (Mar 14 21:03:46 ALM DISC 1 F&G_INH_8876 F&G_INHIBITS ON/) 67 3350 0 SB

600 88 667 4804 CB
7 4804 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4892 CB
7 4892 3350 (Mar 14 21:03:57 ALM DISC 1 F&G_INH_8868 F&G_INHIBITS ON/) 67 3350 0 SB

600 88 667 4980 CB
7 4980 600 (ON UNACK_ALM) 12 600 0 SB

2400 88 667 5068 CB
7 5068 2400 (Mar 14 21:05:00 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5156 CB
7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB
7 5244 2400 (Mar 14 21:05:09 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

350 88 667 5332 CB
7 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5420 CB
7 5420 2400 (Mar 14 21:06:52 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB



É Cópia Fiel do Documento Original

JOSE CARLOS MARIANO DE OLIVEIRA
DIRETOR
D. 10/10/2014 10:10:10

11 1050 0 SB

2400 88 667 3650 CB

2400 2400 (Mar 14 20:56:54 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 3748 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3836 CB

2400 2400 (Mar 14 20:57:16 RTN DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

950 88 667 3924 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB

2400 2400 (Mar 14 20:57:21 ALM DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

1050 88 667 4100 CB

1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB

2400 2400 (Mar 14 20:57:48 RTN DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

950 88 667 4276 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

2400 2400 (Mar 14 20:57:52 ALM DISC 1 GS35-MCB_F F&G) 48 2400 0 SB

1050 88 667 4452 CB

1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

3350 88 667 4540 CB

3350 3350 (Mar 14 21:03:36 ALM DISC 1 F&G_INH_8867 F&G_INHIBITS ON/I 67 3350 0 SB

600 88 667 4628 CB

600 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4716 CB

3350 3350 (Mar 14 21:03:46 ALM DISC 1 F&G_INH_8876 F&G_INHIBITS ON/I 67 3350 0 SB

600 88 667 4804 CB

600 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4892 CB

3350 3350 (Mar 14 21:03:57 ALM DISC 1 F&G_INH_8868 F&G_INHIBITS ON/I 67 3350 0 SB

600 88 667 4980 CB

600 600 (ON UNACK_ALM) 12 600 0 SB

2400 88 667 5068 CB

2400 2400 (Mar 14 21:05:00 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB

1050 88 667 5156 CB

1050 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB

2400 2400 (Mar 14 21:05:09 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5332 CB

950 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5420 CB

2400 2400 (Mar 14 21:06:52 ALM DISC 1 GS2405_F F&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MENDONÇA GUSMÃO
DIRETOR
14 DE MARÇO DE 2014

21 1050 0 SB

544 667 3660 CB

7 3660 2400 (Mar 14 20:56:54 RTN DISC 1 082405_F

P&G) 48 2400 0 SB

550 88 667 3748 CB

740 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 3836 CB

7 3836 2400 (Mar 14 20:57:16 RTN DISC 1 082405-F

P&G) 48 2400 0 SB

550 88 667 3924 CB

7 3924 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4012 CB

7 4012 2400 (Mar 14 20:57:21 ALM DISC 1 082405-F

P&G) 48 2400 0 SB

1050 88 667 4100 CB

7 4100 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 4188 CB

7 4188 2400 (Mar 14 20:57:48 RTN DISC 1 082405-F

P&G) 48 2400 0 SB

950 88 667 4276 CB

7 4276 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 4364 CB

7 4364 2400 (Mar 14 20:57:52 ALM DISC 1 082405-F

P&G) 48 2400 0 SB

1050 88 667 4452 CB

7 4452 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

600 88 667 4540 CB

7 4540 3350 (Mar 14 21:03:36 ALM DISC 1 P&G_INH_8860

P&G_INHIBITS

ON/) 67 3350 0 SB

600 88 667 4628 CB

7 4628 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4716 CB

7 4716 3350 (Mar 14 21:03:46 ALM DISC 1 P&G_INH_8876

P&G_INHIBITS

ON/) 67 3350 0 SB

600 88 667 4804 CB

7 4804 600 (ON UNACK_ALM) 12 600 0 SB

3350 88 667 4892 CB

7 4892 3350 (Mar 14 21:03:57 ALM DISC 1 P&G_INH_8888

P&G_INHIBITS

ON/) 67 3350 0 SB

600 88 667 4980 CB

7 4980 600 (ON UNACK_ALM) 12 600 0 SB

2400 88 667 5068 CB

7 5068 2400 (Mar 14 21:05:00 ALM DISC 1 082405_F

P&G) 48 2400 0 SB

1050 88 667 5156 CB

7 5156 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 88 667 5244 CB

7 5244 2400 (Mar 14 21:05:09 RTN DISC 1 082405_F

P&G) 48 2400 0 SB

950 88 667 5332 CB

7 5332 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5420 CB

7 5420 2400 (Mar 14 21:06:52 ALM DISC 1 082405_F

P&G) 48 2400 0 SB



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES
DIRETOR



: 1050 88 667 5508 CB
7 55 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
2400 88 667 5596 CB
7 5596 2400 (Mar 14 21:06:57 RTN DISC 1 GS240S_F F&G) 48 2400 0 SB
.
950 88 667 5684 CB
7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
2400 88 667 5772 CB
7 5772 2400 (Mar 14 21:07:16 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
.
1050 88 667 5860 CB
7 5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
2400 88 667 5948 CB
7 5948 2400 (Mar 14 21:07:21 RTN DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
.
950 88 667 6036 CB
7 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB
.
2400 88 667 6124 CB
7 6124 2400 (Mar 14 21:07:25 ALM DISC 1 GS27-HCA_F F&G) 48 2400 0 SB
.
1050 88 667 6212 CB
7 6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB
.
.
.

PC

,eTrailer

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS M. M. C. C. C.
DIRETOR
C. 11111111111111111111



1050 88 667 5508 CB
7 55 1050 (FAULT/FAULT ONACK_ALM) 21 1050 0 SB

2400 88 667 5596 CB
7 5536 2400 (Mar 14 21:06:57 RTN DISC 1 GS2405_F F&G) 48 2400 0 SB

950 88 667 5684 CB
7 5684 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 5772 CB
7 5772 2400 (Mar 14 21:07:16 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 88 667 5860 CB
7 5860 1050 (FAULT/FAULT ONACK_ALM) 21 1050 0 SB

2400 88 667 5948 CB
7 5948 2400 (Mar 14 21:07:21 RTN DISC 1 GS27-HCA_F B&G) 48 2400 0 SB

950 88 667 6036 CB
7 6036 950 (NORMA/FAULT ACK_RTN) 19 950 0 SB

2400 88 667 6124 CB
7 6124 2400 (Mar 14 21:07:25 ALM DISC 1 GS27-HCB_F F&G) 48 2400 0 SB

1050 87 667 6212 CB
7 6212 1050 (FAULT/FAULT ONACK_ALM) 21 1050 0 SB

PC
...
_otrailer

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO, 02/03/2010
DIRETOR
RECEBIDA EM 02/03/2010



1050 00 667 5500 CB

55 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 00 667 5500 CB

5596 2400 (Mar 14 21:06:57 RTN DISC 1 GS2405_F P&G) 48 2400 0 SB

950 00 667 5600 CB

5604 950 (NORMAL/FAULT ACK_RTN) 19 950 0 SB

2400 00 667 5772 CB

5772 2400 (Mar 14 21:07:16 ALM DISC 2 GS27-HCA_F P&G) 48 2400 0 SB

1050 00 667 5860 CB

5860 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

2400 00 667 5948 CB

5948 2400 (Mar 14 21:07:21 RTN DISC 1 GS27-HCA_F P&G) 48 2400 0 SB

950 00 667 6036 CB

6036 950 (NORMAL/FAULT ACK_RTN) 19 950 0 SB

2400 00 667 6124 CB

6124 2400 (Mar 14 21:07:25 ALM DISC 1 GS27-HCA_F P&G) 48 2400 0 SB

1050 00 667 6212 CB

6212 1050 (FAULT/FAULT UNACK_ALM) 21 1050 0 SB

>C

"

,aTrailer

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

DR. CARLOS MONTIEL DE OLIVEIRA
DIRETOR
14/03/2014



Mar 14 21:07:21 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:07:25 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:07:30 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:07:33 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:07:37 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:00 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:08:04 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:18 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:08:22 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:42 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:08:45 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:45 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:08:51 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:08:54 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:54 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:08:57 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:09:00 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:09:07 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:09:22 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:09:25 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:09:30 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:09:34 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:09:39 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:09:58 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:10:03 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:10:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:10:10 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:12:25 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA DE DOCUMENTO ORIGINAL

JOSE CARLOS PAVANILLO
DIRETOR
10/03/2014



Mar 14 21:12:30 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:13:55 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:14:00 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:14:13 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:14:18 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:14:36 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:14:40 RTN DISC	2 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:14:45 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:14:49 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:14:58 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:15:03 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:15:03 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:15:07 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:15:48 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:15:52 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:17:09 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:17:13 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:17:54 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:17:58 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:18:07 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:18:12 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:18:12 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:18:16 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:18:30 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:18:53 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:18:57 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:19:01 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:19:10 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA DO DOCUMENTO ORIGINAL.

JOSE CARLOS GENTIL GUERATO
OFICINHA
01 MAR 2003 10:00



Mar 14 21:19:33 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:19:37 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:19:42 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:20:13 RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:20:18 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:20:18 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:20:22 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:20:54 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:20:58 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:20:58 RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:21:03 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:21:07 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:21:12 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:21:16 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:21:17 RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:21:21 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:21:30 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:21:39 RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:21:44 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:22:11 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:22:15 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:22:28 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:22:33 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:22:46 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:22:51 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:22:51 RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:22:55 ALM DISC	1	GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:23:13 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				

É CÓPIA DO DOCUMENTO ORIGINAL

JOSE CARLOS MACHADO DE OLIVEIRA
DISC 013
10/03/2014 14:00:00



Mar 14 21:23:18 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:23:18 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 14 21:23:27 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 14 21:23:31 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:23:36 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:23:45 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:23:49 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:24:03 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:24:16 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:24:21 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:24:26 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:24:44 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:24:48 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:24:53 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:25:02 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:25:29 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 14 21:25:33 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 14 21:25:46 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:25:51 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:26:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:26:09 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:26:22 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:26:27 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:27:30 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:27:35 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:27:57 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 21:28:02 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 21:28:11 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
DEPARTAMENTO DE INVESTIGAÇÃO
DE ACIDENTES MARÍTIMOS



Mar 14 21:28:15 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:32:09 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:32:14 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:32:23 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:32:27 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:40:56 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:41:00 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:42:48 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:42:53 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:43:11 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:43:15 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:45:48 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:45:53 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:47:05 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:47:09 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:52:51 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:52:56 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:53:36 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:53:41 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:53:45 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:53:50 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:54:12 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:54:17 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:54:21 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:54:26 RTN DISC	1	GS2405_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 14 21:54:48 ALM DISC	1	GS2405_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:56:15 ALM DISC	1	GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 14 21:56:20 RTN DISC	1	GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES OLIVEIRA
DIRETOR
DE SERVIÇOS DE TRÁFICO



Mar 14 21:56:51 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:57:18 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:57:27 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:57:32 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:59:29 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:59:33 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:59:38 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 21:59:47 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 21:59:56 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:00:59 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:01:30 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:01:44 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:01:53 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:01:57 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:03:05 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:03:09 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:07:03 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:07:08 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:17:34 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:17:43 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:26:47 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:27:05 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:27:26 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:27:46 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:27:50 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:27:50 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:28:04 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:28:32 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

ROSE CARLOS MACHADO
DIRETOR
20/03/2018, 11:05:20



Mar 14 22:28:47 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:28:52 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:28:59 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:29:05 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:29:05 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:29:08 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:29:11 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:29:31 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:29:35 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:29:40 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:30:02 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:30:07 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:30:16 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:30:29 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:31:13 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:31:22 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:31:35 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:32:07 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:32:13 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:32:26 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:32:31 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:33:08 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:33:13 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:33:16 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:33:16 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:33:22 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:33:32 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:33:41 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS HENRIQUE CUNHA
DEPUTADO
P. 10/10/2014 14:11:00



Mar 14 22:33:56 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:33:59 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:33:59 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:34:05 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:34:13 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:34:22 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:34:26 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:34:59 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:35:02 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:35:02 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:35:20 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:36:07 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:36:11 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:36:49 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:36:58 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:37:07 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:37:16 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:37:34 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:37:38 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:37:43 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:37:52 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:38:01 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:38:52 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:38:56 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:39:23 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:39:23 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:39:32 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:39:32 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS M. ASSIS, GCM-10
DEPT-7
01/02/2008 14:43



Mar 14 22:39:41 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:39:46 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:40:07 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:40:14 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:40:14 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:40:20 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:40:20 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:40:23 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:40:23 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:40:34 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:42:13 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:42:17 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:42:28 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:42:50 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:43:04 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:43:08 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:43:17 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:43:25 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:43:25 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:43:28 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:43:58 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:44:16 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:44:20 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:44:34 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:44:38 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:45:54 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:45:58 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:50:05 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASS. CARLOS ALBERTO BUSTAMANTE
DIRETOR
07/03/2014 14:43



Mar 14 22:50:10 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:50:14 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:50:19 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:50:40 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:50:58 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:02 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:03 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:08 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:11 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:12 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:17 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:24 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:24 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:28 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:42 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:51:42 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:46 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:51:58 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:52:03 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:03 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:52:09 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:52:12 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:19 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:52:30 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:34 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:34 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL CUSTODI
DIRETOR
DE VIGILANCIA E FISCALIZACAO



Mar 14 22:52:40 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:52:44 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:52:56 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:01 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:53:07 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:10 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:19 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:53:23 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:53:23 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:23 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:53:26 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:53:29 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:29 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:53:37 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:54:13 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:54:16 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:54:27 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:54:34 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:54:39 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:55:21 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:55:25 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:57:19 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:57:42 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:57:46 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:57:51 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:58:00 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:58:04 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:58:07 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE GUILHERME FERNANDES GARCIA
DIÁRIO 1
DE 1989 2000 1000 1000



Mar 14 22:58:13 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:58:21 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:15 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:59:32 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:32 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:59:41 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:41 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:46 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:59:46 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 22:59:50 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:51 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 22:59:55 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:00:37 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:00:40 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:00:40 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:00:43 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:01:16 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:21 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:01:25 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:01:25 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:28 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:01:31 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:36 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:01:43 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:49 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:55 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:01:58 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:02:04 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASSINADO POR: [Signature]
DESCRIÇÃO: [Text]
DATA: [Text]



Mar 14 23:02:10 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:02:13 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:02:16 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:02:25 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:02:25 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:02:25 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:02:34 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:02:43 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:03:01 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:03:01 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:03:19 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:04:49 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:04:54 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:04:57 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:05:06 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:05:15 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:05:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:05:25 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:05:25 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:05:39 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:05:42 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:05:44 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:05:45 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:05:54 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:06:00 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:06:03 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:06:03 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:06:06 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT

É CÓPIA DE DOCUMENTO ORIGINAL

Assinado por: CARLOS RODRIGUES DE OLIVEIRA
Diretor
14/03/2014



Mar 14 23:06:06 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:06:09 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:06:16 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:07:03 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 14 23:07:07 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 14 23:07:13 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:07:18 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:07:27 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:07:40 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:07:45 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:07:45 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:07:58 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:08:24 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:08:24 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:08:27 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:08:34 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:08:43 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:08:48 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:09:10 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:09:15 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:09:19 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:09:28 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:09:36 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:09:36 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:09:39 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:09:46 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:09:51 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:09:51 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FONSECA, P.º 1.º
DIRETOR
14/03/2014, 14:00:00



Mar 14 23:09:51 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:10:18 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:10:27 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:11:12 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:12:01 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:12:10 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:12:15 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:12:37 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:13:25 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:13:48 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:14:06 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:14:10 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:14:13 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:14:22 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:14:22 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:14:28 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:14:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:14:55 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:15:00 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:15:04 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:15:31 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:15:34 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:15:34 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:15:37 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:15:40 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:15:54 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:16:12 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:16:15 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

É Cópia Fiel do Documento Original

ASSERÇÃO FIEL DO DOCUMENTO ORIGINAL
DIRETOR
17-03-2014 14:00:00



Mar 14 23:16:15 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:16:18 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:16:21 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:16:21 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:16:24 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:16:33 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:16:36 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:16:40 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:16:46 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:16:51 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:17:00 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:17:04 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:17:10 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:17:15 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:17:18 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:17:25 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:17:28 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:17:34 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:17:39 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:17:43 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:17:46 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:17:51 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:17:57 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:18:03 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:18:07 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:18:07 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:18:10 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:18:19 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT

É O ORIGINAL DO DOCUMENTO ORIGINAL

EXECUTIVO DE DIRETORIA
DIRETORIA
UNIDADE DE DIRETORIA



Mar 14 23:18:27 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:18:31 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:18:31 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:18:36 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:18:36 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:18:40 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:18:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:18:54 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:19:06 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:19:06 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:19:09 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:19:12 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:19:15 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:19:31 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:19:34 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:19:43 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:19:43 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:20:06 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:20:27 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:20:55 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:21:09 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:21:12 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:21:12 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:21:21 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:21:27 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:21:31 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:21:40 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:21:52 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

EXATINA EM DO DOCUMENTO ORIGINAL

USE COM O MATERIAL ORIGINAL
DE CADA
E NÃO SE SEPARAR



Mar 14 23:22:07 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:22:12 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:22:12 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:22:15 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:22:18 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 14 23:22:21 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:22:25 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:22:31 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 14 23:22:31 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:22:37 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:22:40 ALM DISC UNACK_ALM	1 XS70317A	F&G	RUNNI/RUNNI
Mar 14 23:22:52 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:22:52 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:22:57 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:22:57 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:23:01 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:23:10 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:23:15 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:23:15 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:23:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:23:19 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:23:24 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:24:00 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:24:09 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:24:45 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:24:49 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:24:54 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:24:57 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARLOS HENRIQUE OLIVEIRA
08/07/23
11/08/2023 14:00:00



É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS TAVARES DE OLIVEIRA
CORRETO
07/05/2011



Mar 14 23:24:57 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:25:03 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:25:03 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:25:07 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:25:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:25:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:25:13 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:25:16 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:25:16 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:25:30 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:25:34 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:25:43 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:25:48 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:25:48 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:25:51 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:25:57 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:26:01 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:26:06 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:26:10 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:26:15 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:26:15 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:26:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:26:33 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:26:37 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:27:22 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:27:31 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:27:40 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:27:45 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE UNOS FOLIOS DO DOCUMENTO
DIRETOR
10/03/2014 10:00:00



Mar 14 23:27:54 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:28:03 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:28:12 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:28:16 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:28:48 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:28:52 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:30:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:30:54 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:31:12 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:31:16 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:31:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:31:34 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:31:57 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:32:02 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:32:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:32:11 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:32:15 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:32:20 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:35:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:35:11 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:35:20 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:35:24 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:35:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:35:56 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:38:30 RTN DISC	1 XS70317A	F&G	NOT R/RUNNI
ACK_RTN			
Mar 14 23:40:44 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:40:48 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:41:11 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MONTIEL
ONEN
12/03/2014



Mar 14 23:41:15 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:42:49 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:42:54 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:43:21 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:43:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:43:35 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:43:44 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:44:06 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:44:33 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:44:42 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:44:47 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:44:47 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:44:51 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:44:54 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:45:09 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:45:09 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:45:23 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:45:32 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:45:41 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:45:50 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:46:26 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:46:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:46:35 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:47:02 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:47:20 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:47:42 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:47:56 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:48:09 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CANOES PARA O DESPACHO
DESPACHO
20/03/2014 14:00:00



Mar 14 23:48:27 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:48:32 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:48:41 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:48:41 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:48:45 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:48:50 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:48:54 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:49:17 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:49:20 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:49:35 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:49:38 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:49:44 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:50:02 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:50:06 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:50:18 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:50:32 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:50:38 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:50:42 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:50:50 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:50:54 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:50:54 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:51:05 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:51:14 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:51:18 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:51:23 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:51:27 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:51:30 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:51:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É COPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FARIAS DE OLIVEIRA
DIRETOR
11/03/2014 14:00



Mar 14 23:51:33 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:51:36 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:52:30 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:52:45 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:52:53 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:52:57 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:53:06 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 14 23:53:06 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:53:23 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:53:29 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:53:33 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:53:33 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:53:36 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:53:36 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:53:42 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:53:42 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:53:47 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:53:50 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:53:50 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:53:59 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:54:18 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 14 23:54:18 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 14 23:54:21 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 14 23:54:21 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 14 23:54:24 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 14 23:54:30 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 14 23:54:41 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 14 23:54:51 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT

É Cópia Fiel do Documento Original

JOSÉ CARLOS FERNANDES LOPES
DIRETOR
LIVRO 18.11.2013 13:43



Mar 14 23:55:00 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:55:05 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:55:14 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:55:18 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:55:50 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:55:53 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:55:53 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:55:56 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:55:56 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:02 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:11 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:15 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:15 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:20 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:20 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:23 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:23 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:26 ALM DISC	1 GS27-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:33 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:38 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:38 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:42 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:47 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:56:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:56:56 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 14 23:57:09 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 14 23:57:14 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

ASSINADO E CARIMBADO
OK
14/03/2014 14:03



Mar 14 23:57:18 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 14 23:57:29 RTN DISC	1 GS27-HCA_F	F&G
ACK_RTN		
Mar 14 23:57:42 ALM DISC	1 GS27-HCA_F	F&G
UNACK_ALM		
Mar 14 23:57:47 RTN DISC	1 GS27-HCA_F	F&G
ACK_RTN		
Mar 14 23:57:51 ALM DISC	1 GS27-HCA_F	F&G
UNACK_ALM		
Mar 14 23:58:08 RTN DISC	1 GS29-HCB_F	F&G
ACK_RTN		
Mar 14 23:58:14 RTN DISC	1 GS27-HCA_F	F&G
ACK_RTN		
Mar 14 23:58:17 ALM DISC	1 GS29-HCB_F	F&G
UNACK_ALM		
Mar 14 23:58:23 ALM DISC	1 GS27-HCA_F	F&G
UNACK_ALM		
Mar 14 23:59:24 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 14 23:59:29 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:01:26 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:01:35 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:01:39 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:01:44 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:02:15 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:02:20 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:02:47 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:02:51 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:03:15 RTN DISC	1 GS16-HCB_F	F&G
ACK_RTN		
Mar 15 00:03:20 ALM DISC	1 GS16-HCB_F	F&G
UNACK_ALM		
Mar 15 00:03:45 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:03:50 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:04:03 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:04:08 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:04:35 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		
Mar 15 00:04:39 RTN DISC	1 GS2405_F	F&G
ACK_RTN		
Mar 15 00:05:15 ALM DISC	1 GS2405_F	F&G
UNACK_ALM		

NORMA/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

NORMA/FAULT

FAULT/FAULT

FAULT/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

NORMA/FAULT

FAULT/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

NORMA/FAULT

FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

Associação dos Marinheiros e
Diretor
Câmara de Defesa da Marinha



Mar 15 00:05:20 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:05:47 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:05:51 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:07:53 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:07:57 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:11:20 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:11:24 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:11:50 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:12:03 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:12:15 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:12:16 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:12:21 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:12:24 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:12:35 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:12:43 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:13:12 RTN DISC	1 GS29-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:13:17 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:13:21 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:13:21 ALM DISC	1 GS29-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:13:44 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:13:48 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:13:57 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:14:02 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:14:08 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:14:33 ALM DISC	2 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:14:38 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:14:42 ALM DISC	2 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:14:47 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

1705
Tribunal Marítimo



Mar 15 00:14:51 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:14:51 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:14:54 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:15:11 RTN DISC ACK_RTN	2 GS27-HCA_F	F&G	NORMA/FAULT
Mar 15 00:15:23 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:15:23 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 15 00:15:28 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:15:28 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 15 00:15:37 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 15 00:15:46 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:15:50 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:15:59 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:16:03 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:16:09 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 15 00:16:14 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:16:23 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 15 00:17:09 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:17:27 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:17:45 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:18:03 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:18:11 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:18:20 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 15 00:18:29 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:19:23 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 15 00:19:27 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:19:32 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT
Mar 15 00:19:36 RTN DISC ACK_RTN	1 GS16-HCB_F	F&G	NORMA/FAULT
Mar 15 00:20:35 ALM DISC UNACK_ALM	1 GS16-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASSINADO E CARIMBADO
02/03/2015 14:11:10

Mar 15 00:20:39 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:21:10 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:21:14 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:21:23 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:21:32 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:21:52 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:21:56 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:22:11 ALM DISC	1 PS70001	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:22:12 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:22:17 ALM DISC	1 XS70004A	F&G	RUNNI/RUNNI
UNACK_ALM			
Mar 15 00:22:17 ALM DISC	1 XS70519C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 00:22:17 ALM DISC	1 XS70581	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:22:31 ALM DISC	1 XS70519B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 00:22:31 RTN DISC	1 XS70519C	F&G	NORMA/LOW S
ACK_RTN			
Mar 15 00:22:31 ALM DISC	1 XS70520C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 00:22:32 RTN DISC	1 XZ70004B	F&G	NORMA/ STOP
ACK_RTN			
Mar 15 00:22:32 ALM DISC	1 XS70701	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XS70704	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XZ70519	F&G	START/START
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53044	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53047	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53051	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XCV53004	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XZ70520	F&G	START/START
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53017	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53020	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 XV53023	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

~~ASÍ CARLOS FERNÁNDEZ GARCÍA~~



Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS20-HCA	F&G	HIGH/ HIGH
Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS20-HCB	F&G	HIGH/ HIGH
Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS52-HCA	F&G	HIGH/ HIGH
Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS52-HCB	F&G	HIGH/ HIGH
Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS20-HCA_HH	F&G	HIGH /HIGH
Mar 15 00:22:33 ALM DISC UNACK_ALM	1 GS20-HCB_HH	F&G	HIGH /HIGH
Mar 15 00:22:34 ALM DISC UNACK_ALM	1 GS52-HCA_HH	F&G	HIGH /HIGH
Mar 15 00:22:34 ALM DISC UNACK_ALM	1 GS52-HCB_HH	F&G	HIGH /HIGH
Mar 15 00:22:36 ALM DISC UNACK_ALM	1 MA04024	F&G	ALARM/ALARM
Mar 15 00:22:49 RTN DISC ACK_RTN	1 ZSC70569A	F&G	NOT C/CLOSE
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 ZSO70569B	F&G	OPEN/ OPEN
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 ZSO70570B	F&G	OPEN/ OPEN
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 XS70520B	F&G	HIGH /HIGH
Mar 15 00:22:49 RTN DISC ACK_RTN	1 XS70520C	F&G	NORMA/LOW S
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 ZSC70038	F&G	CLOSE/CLOSE
Mar 15 00:22:49 RTN DISC ACK_RTN	1 ZSO53002	F&G	CLOSE/ OPEN
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 F&G_INH_8775	F&G_INHIBITS	ON/ ON
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 XV70038A	F&G	OPEN/ OPEN
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 XV70570A	F&G	CLOSE/CLOSE
Mar 15 00:22:49 ALM DISC UNACK_ALM	1 XV70570A-VD	F&G	DISCR/DISCR
Mar 15 00:22:50 ALM DISC UNACK_ALM	1 XCV53002	F&G	ENERG/ENERG
Mar 15 00:22:50 RTN DISC ACK_RTN	1 GS21-HCA_F	F&G	NORMA/FAULT
Mar 15 00:22:50 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:22:51 ALM DISC UNACK_ALM	1 GS19-HCB	F&G	HIGH/ HIGH
Mar 15 00:22:51 RTN DISC ACK_RTN	1 GS20-HCB	F&G	NORMA/ HIGH
Mar 15 00:22:51 ALM DISC UNACK_ALM	1 GS19-HCA	F&G	HIGH/ HIGH
Mar 15 00:22:51 ALM DISC UNACK_ALM	1 GS2903	F&G	HIGH/ HIGH
Mar 15 00:22:52 RTN DISC ACK_RTN	1 GS20-HCB_HH	F&G	NORMA/HIGH

É COPIA DE DOCUMENTO ORIGINAL

Assinado e rubricado pelo
Diretor
em 15/03/2015 às 14h30



Mar 15 00:22:54 ALM DISC UNACK_ALM	1 SD07030	F&G	ALARM/ALARM
Mar 15 00:22:54 ALM DISC UNACK_ALM	1 SD04020	F&G	ALARM/ALARM
Mar 15 00:22:54 ALM DISC UNACK_ALM	1 SD04022	F&G	ALARM/ALARM
Mar 15 00:22:54 ALM DISC UNACK_ALM	1 SD04023	F&G	ALARM/ALARM
Mar 15 00:22:59 ALM DISC UNACK_ALM	1 F&G_INH_8765	F&G_INHIBITS	ON/ ON
Mar 15 00:22:59 ALM DISC UNACK_ALM	1 XV70039A	F&G	OPEN/ OPEN
Mar 15 00:22:59 ALM DISC UNACK_ALM	1 XCV53004-VD	F&G	DISCR/DISCR
Mar 15 00:23:00 RTN DISC ACK_RTN	1 XZ70519	F&G	NORMA/START
Mar 15 00:23:00 RTN DISC ACK_RTN	1 XV53044	F&G	DE-EN/ENERG
Mar 15 00:23:00 RTN DISC ACK_RTN	1 XV53047	F&G	DE-EN/ENERG
Mar 15 00:23:00 RTN DISC ACK_RTN	1 XV53051	F&G	DE-EN/ENERG
Mar 15 00:23:01 RTN DISC ACK_RTN	1 XCV53004	F&G	DE-EN/ENERG
Mar 15 00:23:01 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:23:02 RTN DISC ACK_RTN	1 GS20-HCA	F&G	NORMA/ HIGH
Mar 15 00:23:02 ALM DISC UNACK_ALM	1 GS19-HCB_HH	F&G	HIGH /HIGH
Mar 15 00:23:02 RTN DISC ACK_RTN	1 GS20-HCA_HH	F&G	NORMA/HIGH
Mar 15 00:23:02 ALM DISC UNACK_ALM	1 GS19-HCA_HH	F&G	HIGH /HIGH
Mar 15 00:23:02 RTN DISC ACK_RTN	1 GS52-HCA_HH	F&G	NORMA/HIGH
Mar 15 00:23:02 ALM DISC UNACK_ALM	1 GS2903_HH	F&G	HIGH /HIGH
Mar 15 00:23:15 ALM DISC UNACK_ALM	1 XS70010A	F&G	RUNNI/RUNNI
Mar 15 00:23:15 ALM DISC UNACK_ALM	1 XS70011A	F&G	RUNNI/RUNNI
Mar 15 00:23:16 RTN DISC ACK_RTN	1 ZSC70570A	F&G	NOT C/CLOSE
Mar 15 00:23:16 RTN DISC ACK_RTN	1 ZSO70038	F&G	NOT O/ OPEN
Mar 15 00:23:16 RTN DISC ACK_RTN	1 ZSO70039	F&G	NOT O/ OPEN
Mar 15 00:23:16 ALM DISC UNACK_ALM	1 ZSC70039	F&G	CLOSE/CLOSE
Mar 15 00:23:16 ALM DISC UNACK_ALM	1 XV70042A	F&G	OPEN/ OPEN
Mar 15 00:23:16 RTN DISC ACK_RTN	1 XV70033A	F&G	NORMA/ OPEN
Mar 15 00:23:16 RTN DISC ACK_RTN	1 XV70570A	F&G	NORMA/CLOSE

Enviado al Jefe de Oficina ORIGINAL

SE CARLOS HERNANDEZ
DIRECTOR
3



Mar 15 00:23:16 ALM DISC UNACK_ALM	1 XV70043A	F&G	OPEN/ OPEN
Mar 15 00:23:16 RTN DISC ACK_RTN	1 XV70039A	F&G	NORMA/ OPEN
Mar 15 00:23:16 RTN DISC ACK_RTN	1 XV70570A-VD	F&G	NORMA/DISCR
Mar 15 00:23:17 ALM DISC UNACK_ALM	1 XS70702	F&G	ALARM/ALARM
Mar 15 00:23:17 ALM DISC UNACK_ALM	1 XS72009	F&G	ALARM/ALARM
Mar 15 00:23:17 ALM DISC UNACK_ALM	1 XS72008	F&G	ALARM/ALARM
Mar 15 00:23:17 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:23:18 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 00:23:18 ALM DISC UNACK_ALM	1 PT70032	F&G	ALARM/ALARM
Mar 15 00:23:18 ALM DISC UNACK_ALM	1 GS52-HCA_HH	F&G	HIGH /HIGH
Mar 15 00:23:19 RTN DISC ACK_RTN	1 GS2903_HH	F&G	NORMA/HIGH
Mar 15 00:23:21 ALM DISC UNACK_ALM	1 SD07032	F&G	ALARM/ALARM
Mar 15 00:23:34 RTN DISC ACK_RTN	1 ZSO70042	F&G	NOT O/ OPEN
Mar 15 00:23:34 ALM DISC UNACK_ALM	1 ZSC70042	F&G	CLOSE/CLOSE
Mar 15 00:23:34 RTN DISC ACK_RTN	1 ZSO70043	F&G	NOT O/ OPEN
Mar 15 00:23:34 ALM DISC UNACK_ALM	1 ZSC70043	F&G	CLOSE/CLOSE
Mar 15 00:23:34 ALM DISC UNACK_ALM	1 F&G_INH_8791	F&G_INHIBITS	ON/ ON
Mar 15 00:23:34 RTN DISC ACK_RTN	1 XV70042A	F&G	NORMA/ OPEN
Mar 15 00:23:34 RTN DISC ACK_RTN	1 XV70043A	F&G	NORMA/ OPEN
Mar 15 00:23:35 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 15 00:23:36 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 00:23:36 ALM DISC UNACK_ALM	1 PT70030	F&G	ALARM/ALARM
Mar 15 00:23:37 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:23:37 RTN DISC ACK_RTN	1 GS19-HCB	F&G	NORMA/ HIGH
Mar 15 00:23:37 RTN DISC ACK_RTN	1 GS19-HCA	F&G	NORMA/ HIGH
Mar 15 00:23:37 RTN DISC ACK_RTN	1 GS2903	F&G	NORMA/ HIGH
Mar 15 00:23:37 RTN DISC ACK_RTN	1 GS19-HCB_HH	F&G	NORMA/HIGH
Mar 15 00:23:37 RTN DISC ACK_RTN	1 GS19-HCA_HH	F&G	NORMA/HIGH

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

SAE CARLOS FERNANDES CARDOSO
DIRETOR
DE ATENDIMENTO AO USUÁRIO



Mar 15 00:23:50 ALM DISC UNACK_ALM	1 F&G_INH_8752	F&G_INHIBITS	ON/ ON
Mar 15 00:23:51 ALM DISC UNACK_ALM	1 GS2904	F&G	HIGH/ HIGH
Mar 15 00:23:52 RTN DISC ACK_RTN	1 GS52-HCB_HH	F&G	NORMA/HIGH
Mar 15 00:24:05 ALM DISC UNACK_ALM	1 GS47-HCA	F&G	HIGH/ HIGH
Mar 15 00:24:05 ALM DISC UNACK_ALM	1 GS47-HCB	F&G	HIGH/ HIGH
Mar 15 00:24:05 RTN DISC ACK_RTN	1 GS2904	F&G	NORMA/ HIGH
Mar 15 00:24:05 ALM DISC UNACK_ALM	1 GS52-HCB_HH	F&G	HIGH /HIGH
Mar 15 00:24:07 RTN DISC ACK_RTN	1 SD07030	F&G	NORMA/ALARM
Mar 15 00:24:07 RTN DISC ACK_RTN	1 SD07032	F&G	NORMA/ALARM
Mar 15 00:24:11 ALM DISC UNACK_ALM	1 XV70569B	F&G	OPEN/ OPEN
Mar 15 00:24:11 ALM DISC UNACK_ALM	1 XV70570B	F&G	OPEN/ OPEN
Mar 15 00:24:13 ALM DISC UNACK_ALM	1 GS47-HCC	F&G	HIGH/ HIGH
Mar 15 00:24:13 RTN DISC ACK_RTN	1 GS47-HCA	F&G	NORMA/ HIGH
Mar 15 00:24:14 RTN DISC ACK_RTN	1 SD04020	F&G	NORMA/ALARM
Mar 15 00:24:14 RTN DISC ACK_RTN	1 SD04022	F&G	NORMA/ALARM
Mar 15 00:24:14 RTN DISC ACK_RTN	1 SD04023	F&G	NORMA/ALARM
Mar 15 00:24:14 RTN DISC ACK_RTN	1 MA04024	F&G	NORMA/ALARM
Mar 15 00:24:17 ALM DISC UNACK_ALM	1 ZSC70569A	F&G	CLOSE/CLOSE
Mar 15 00:24:17 ALM DISC UNACK_ALM	1 ZSC70570A	F&G	CLOSE/CLOSE
Mar 15 00:24:19 RTN DISC ACK_RTN	1 GS47-HCB	F&G	NORMA/ HIGH
Mar 15 00:24:32 RTN DISC ACK_RTN	1 ZSO70569B	F&G	NOT O/ OPEN
Mar 15 00:24:32 RTN DISC ACK_RTN	1 XV70569B	F&G	NORMA/ OPEN
Mar 15 00:24:32 ALM DISC UNACK_ALM	1 XV70570B-VD	F&G	DISCR/DISCR
Mar 15 00:24:34 RTN DISC ACK_RTN	1 GS47-HCC	F&G	NORMA/ HIGH
Mar 15 00:24:34 RTN DISC ACK_RTN	1 GS52-HCB	F&G	NORMA/ HIGH
Mar 15 00:24:34 RTN DISC ACK_RTN	1 GS52-HCA_HH	F&G	NORMA/HIGH
Mar 15 00:24:34 RTN DISC ACK_RTN	1 GS52-HCB_HH	F&G	NORMA/HIGH
Mar 15 00:24:47 RTN DISC ACK_RTN	1 ZSO70570B	F&G	NOT O/ OPEN

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE QUALQUER FERRAMENTA DE
DIGITALIZAÇÃO
DE DOCUMENTOS



Mar 15 00:24:47 RTN DISC	1	XV70570B	F&G	NORMA/ OPEN
ACK_RTN				
Mar 15 00:24:47 RTN DISC	1	XV70570B-VD	F&G	NORMA/DISCR
ACK_RTN				
Mar 15 00:24:49 RTN DISC	1	XS70701	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:24:49 RTN DISC	1	XS70702	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:24:49 RTN DISC	1	XS70704	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:24:49 RTN DISC	1	XS72009	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:24:49 RTN DISC	1	XS72008	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:24:49 ALM DISC	1	PT70032_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 00:24:50 RTN DISC	1	GS52-HCA	F&G	NORMA/ HIGH
ACK_RTN				
Mar 15 00:25:33 ALM DISC	1	SD04022	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	ZSO70569B	F&G	OPEN/ OPEN
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	ZSO70570B	F&G	OPEN/ OPEN
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	ZSO70571B	F&G	OPEN/ OPEN
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	ZSO70572B	F&G	OPEN/ OPEN
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	XV70569A	F&G	CLOSE/CLOSE
UNACK_ALM				
Mar 15 00:25:46 ALM DISC	1	XV70570A	F&G	CLOSE/CLOSE
UNACK_ALM				
Mar 15 00:25:48 ALM DISC	3	SD07032	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:48 ALM DISC	1	SD04023	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:48 ALM DISC	1	MA04024	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:52 RTN DISC	1	ZSC70569A	F&G	NOT C/CLOSE
ACK_RTN				
Mar 15 00:25:52 RTN DISC	1	ZSC70571A	F&G	NOT C/CLOSE
ACK_RTN				
Mar 15 00:25:52 RTN DISC	1	XV70569A	F&G	NORMA/CLOSE
ACK_RTN				
Mar 15 00:25:52 RTN DISC	1	XV70571A	F&G	NORMA/CLOSE
ACK_RTN				
Mar 15 00:25:52 ALM DISC	1	XV70570A-VD	F&G	DISCR/DISCR
UNACK_ALM				
Mar 15 00:25:52 RTN DISC	1	XV70571A-VD	F&G	NORMA/DISCR
ACK_RTN				
Mar 15 00:25:53 ALM DISC	1	XS70701	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:53 ALM DISC	1	XS70704	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:25:58 RTN DISC	1	ZSC70572A	F&G	NOT C/CLOSE
ACK_RTN				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

RECEBUEMOS
O DIA 15/03/2015
AS 14:00 HORAS



Mar 15 00:25:58 RTN DISC ACK_RTN	1 XV70572A	F&G	NORMA/CLOSE
Mar 15 00:25:58 RTN DISC ACK_RTN	1 XV70572A-VD	F&G	NORMA/DISCR
Mar 15 00:26:01 RTN DISC ACK_RTN	1 SD07032	F&G	NORMA/ALARM
Mar 15 00:26:04 RTN DISC ACK_RTN	1 ZSC70570A	F&G	NOT C/CLOSE
Mar 15 00:26:04 RTN DISC ACK_RTN	1 XV70570A	F&G	NORMA/CLOSE
Mar 15 00:26:04 RTN DISC ACK_RTN	1 XV70570A-VD	F&G	NORMA/DISCR
Mar 15 00:26:12 RTN DISC ACK_RTN	1 SD04022	F&G	NORMA/ALARM
Mar 15 00:26:12 RTN DISC ACK_RTN	1 SD04023	F&G	NORMA/ALARM
Mar 15 00:26:12 RTN DISC ACK_RTN	1 MA04024	F&G	NORMA/ALARM
Mar 15 00:26:24 ALM DISC UNACK_ALM	1 ZSC70569A	F&G	CLOSE/CLOSE
Mar 15 00:26:24 ALM DISC UNACK_ALM	1 ZSC70570A	F&G	CLOSE/CLOSE
Mar 15 00:26:25 ALM DISC UNACK_ALM	1 XV70569B	F&G	OPEN/ OPEN
Mar 15 00:26:25 ALM DISC UNACK_ALM	1 XV70570B	F&G	OPEN/ OPEN
Mar 15 00:26:29 RTN DISC ACK_RTN	1 ZSO70569B	F&G	NOT O/ OPEN
Mar 15 00:26:29 RTN DISC ACK_RTN	1 XV70569B	F&G	NORMA/ OPEN
Mar 15 00:26:29 ALM DISC UNACK_ALM	1 XV70570B-VD	F&G	DISCR/DISCR
Mar 15 00:26:32 ALM DISC UNACK_ALM	1 SD07030	F&G	ALARM/ALARM
Mar 15 00:26:36 RTN DISC ACK_RTN	1 XS70701	F&G	NORMA/ALARM
Mar 15 00:26:37 RTN DISC ACK_RTN	1 XS70704	F&G	NORMA/ALARM
Mar 15 00:26:37 RTN DISC ACK_RTN	2 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:26:39 ALM DISC UNACK_ALM	1 SD07032	F&G	ALARM/ALARM
Mar 15 00:26:51 ALM DISC UNACK_ALM	1 ZSO70569B	F&G	OPEN/ OPEN
Mar 15 00:26:52 ALM DISC UNACK_ALM	1 LS70301	F&G	ALARM/ALARM
Mar 15 00:26:52 ALM DISC UNACK_ALM	1 XV70569A	F&G	CLOSE/CLOSE
Mar 15 00:26:52 ALM DISC UNACK_ALM	1 XV70570A	F&G	CLOSE/CLOSE
Mar 15 00:26:52 RTN DISC ACK_RTN	1 XV70570B	F&G	NORMA/ OPEN
Mar 15 00:26:52 RTN DISC ACK_RTN	1 XV70570B-VD	F&G	NORMA/DISCR
Mar 15 00:26:56 RTN DISC ACK_RTN	1 ZSC70569A	F&G	NOT C/CLOSE

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTA GOMES
DEPUTADO
21/07/2014 14:00:00



Mar 15 00:26:56 RTN DISC	1 XV70569A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 00:27:01 ALM DISC	1 XV70570A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 00:27:02 ALM DISC	1 XS70701	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:27:02 ALM DISC	1 XS70704	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:27:02 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:27:08 RTN DISC	1 ZSC70570A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 00:27:08 RTN DISC	1 XV70570A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 00:27:08 RTN DISC	1 XV70570A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 00:27:38 ALM DISC	1 MA04024	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:27:43 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:27:44 ALM DISC	1 GS52-HCB	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 00:27:56 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:27:58 RTN DISC	1 GS52-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 00:28:05 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:28:08 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:28:11 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:28:11 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:28:16 RTN DISC	1 MA04024	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:28:19 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:28:29 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:28:34 ALM DISC	1 GS21-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:28:46 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:28:50 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:29:41 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:29:42 ALM DISC	1 MA04024	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:29:45 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:29:59 ALM DISC	1 PS70103	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:30:28 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASS. CARLOS F. DE VIL. 20
DIKE
6/12/2014 11:11:43



Mar 15 00:30:32 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:31:16 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:31:20 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:31:29 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:31:34 RTN DISC	1 MA04024	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:31:38 RTN DISC	1 SD07030	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:31:38 RTN DISC	1 SD07032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:31:50 ALM DISC	1 ZSC70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 00:31:50 ALM DISC	1 ZSC70570A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 00:31:50 ALM DISC	1 XV70569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:31:50 ALM DISC	1 XV70570B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:31:52 RTN DISC	1 XS70701	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:31:52 RTN DISC	1 XS70704	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:31:52 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:31:59 RTN DISC	1 ZSO70569B	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 00:31:59 RTN DISC	1 XV70569B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 00:31:59 ALM DISC	1 XV70570B-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 00:32:11 RTN DISC	1 ZSO70570B	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 00:32:11 RTN DISC	1 XV70570B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 00:32:11 RTN DISC	1 XV70570B-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 00:32:16 ALM DISC	1 PS70105	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:32:20 ALM DISC	1 PS70108	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:32:20 ALM DISC	1 XV70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 00:32:20 ALM DISC	1 XV70570A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 00:32:22 ALM DISC	1 XS70701	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:32:22 ALM DISC	1 XS70704	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:32:22 ALM DISC	1 SOV70123	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:32:22 ALM DISC	1 SOV70126	F&G	OPEN/ OPEN
UNACK_ALM			

É Cópia do Documento Original

SE CARLOS ALBERTO L. GONCALVES
PRESIDENTE
DO TRIBUNAL MARÍTIMO



Mar 15 00:32:22 RTN DISC	1 SOV70123_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:32:22 RTN DISC	1 SOV70126_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:32:26 ALM DISC	1 ZS070569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:32:26 ALM DISC	1 ZS070570B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:32:31 RTN DISC	1 ZSC70569A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 00:32:31 RTN DISC	1 XV70569A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 00:32:35 ALM DISC	1 XV70570A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 00:32:40 ALM DISC	1 PT70030_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:32:40 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:32:42 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:32:46 RTN DISC	1 ZSC70570A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 00:32:46 RTN DISC	1 XV70570A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 00:32:46 RTN DISC	1 XV70570A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 00:32:58 ALM DISC	1 MA04024	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:33:10 RTN DISC	1 PS70105	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:33:11 ALM DISC	1 XS70702	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:33:11 ALM DISC	1 XS72009	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:33:11 ALM DISC	1 XS72008	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:33:11 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:33:14 ALM DISC	1 SD07032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:33:46 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:33:49 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:33:49 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:34:01 RTN DISC	1 SD07032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:34:06 RTN DISC	1 MA04024	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:34:17 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:34:22 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:34:25 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CUIDADO PARA NÃO
DANIFICAR
O DOCUMENTO



Mar 15 00:34:25 RTN DISC	1 GS2405_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:34:34 RTN DISC	1 GS2305_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:34:43 ALM DISC	1 GS2305_F	F&G	FAULT/ FAULT
UNACK_ALM			
Mar 15 00:34:49 ALM DISC	1 PT70007	F&G	ALARM/ ALARM
UNACK_ALM			
Mar 15 00:34:49 ALM DISC	1 PT70034	F&G	ALARM/ ALARM
UNACK_ALM			
Mar 15 00:35:04 ALM DISC	1 ZSC70569A	F&G	CLOSE/ CLOSE
UNACK_ALM			
Mar 15 00:35:04 ALM DISC	1 ZSC70570A	F&G	CLOSE/ CLOSE
UNACK_ALM			
Mar 15 00:35:04 ALM DISC	1 XV70569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:35:04 ALM DISC	1 XV70570B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:35:17 ALM DISC	1 XV70569A	F&G	CLOSE/ CLOSE
UNACK_ALM			
Mar 15 00:35:17 RTN DISC	1 XV70569B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 00:35:17 ALM DISC	1 XV70570A	F&G	CLOSE/ CLOSE
UNACK_ALM			
Mar 15 00:35:17 RTN DISC	1 XV70570B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 00:35:19 RTN DISC	1 GS26-HCB_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:35:23 RTN DISC	1 ZSC70569A	F&G	NOT C/ CLOSE
ACK_RTN			
Mar 15 00:35:24 RTN DISC	1 XV70569A	F&G	NORMA/ CLOSE
ACK_RTN			
Mar 15 00:35:25 ALM DISC	1 GS26-HCB_F	F&G	FAULT/ FAULT
UNACK_ALM			
Mar 15 00:35:28 ALM DISC	1 SD07032	F&G	ALARM/ ALARM
UNACK_ALM			
Mar 15 00:35:31 RTN DISC	1 ZSC70570A	F&G	NOT C/ CLOSE
ACK_RTN			
Mar 15 00:35:31 RTN DISC	1 XV70570A	F&G	NORMA/ CLOSE
ACK_RTN			
Mar 15 00:35:33 ALM DISC	1 MA04024	F&G	ALARM/ ALARM
UNACK_ALM			
Mar 15 00:35:44 RTN DISC	2 PT70030_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:35:44 RTN DISC	1 GS26-HCB_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:35:44 RTN DISC	1 GS2305_F	F&G	NORMA/ FAULT
ACK_RTN			
Mar 15 00:35:47 ALM DISC	1 GS26-HCB_F	F&G	FAULT/ FAULT
UNACK_ALM			
Mar 15 00:35:55 ALM DISC	1 SD07033	F&G	ALARM/ ALARM
UNACK_ALM			
Mar 15 00:36:07 ALM DISC	1 PT70030_F	F&G	FAULT/ FAULT
UNACK_ALM			
Mar 15 00:36:07 ALM DISC	1 GS2305_F	F&G	FAULT/ FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ASS: CARLOS FERNANDO ALMEIDA
DIRETOR
por: [assinatura]



Mar 15 00:36:13 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:36:16 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:36:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:36:22 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:36:29 RTN DISC ACK_RTN	1 GS27-HCA_F	F&G	NORMA/FAULT
Mar 15 00:36:32 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:36:35 ALM DISC UNACK_ALM	1 SD07030	F&G	ALARM/ALARM
Mar 15 00:36:38 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:36:41 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:36:46 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 00:36:46 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:36:56 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 00:37:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:37:07 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:37:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:37:10 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:37:16 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:37:20 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:37:40 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:37:44 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:38:13 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 00:38:19 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:38:46 ALM DISC UNACK_ALM	1 PS70105	F&G	ALARM/ALARM
Mar 15 00:38:47 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:01 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 00:39:01 ALM DISC UNACK_ALM	2 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:39:04 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:39:16 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE COM OS PARÂMETROS
DIREÇÃO
DE MANEIRA CORRETA



Mar 15 00:39:16 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:39:22 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:39:22 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:39:25 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 00:39:28 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:28 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:39:37 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:39:40 RTN DISC ACK_RTN	1 PS70103	F&G	NORMA/ALARM
Mar 15 00:39:40 RTN DISC ACK_RTN	1 ZSC70140	F&G	NOT O/ OPEN
Mar 15 00:39:41 ALM DISC UNACK_ALM	1 ZSC70131_F	F&G	FAULT/FAULT
Mar 15 00:39:41 ALM DISC UNACK_ALM	1 ZS0701	F&G	ON/ ON
Mar 15 00:39:42 RTN DISC ACK_RTN	1 X270520	F&G	NORMA/START
Mar 15 00:39:42 RTN DISC ACK_RTN	1 XCV53002	F&G	DE-EN/ENERG
Mar 15 00:39:42 RTN DISC ACK_RTN	1 GS18-HCB_F	F&G	NORMA/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS29-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS32-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS44-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS54-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS52-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS54-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS40-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS50-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS52-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS31-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:42 ALM DISC UNACK_ALM	1 GS45-HCA_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS DE SOUZA
DIRTOR
10/05/2010 10:10

Mar 15 00:39:42	ALM DISC	1 GS50-HCB_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1808_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1703_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1312_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS69-HCA_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1804_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 MD-TX15-HC_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1811_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1813_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1704_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 MD-TX69-HC_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1322_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:42	ALM DISC	1 GS1323_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 GS1324_F	F&G	FAULT/FAULT	
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 ZS0605-06	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 ZS0702-03	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0715-16	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0601-02	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0717-19	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0603-05	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 SPARE_d9953_RTU	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0701-02	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 SPARE_d9960_RTU	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0720-21	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0722	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 SPARE_d9964_RTU	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0501-03	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:43	ALM DISC	1 PB0801-04	F&G	ON/	ON
UNACK_ALM					

É CÓPIA FIEL DO DOCUMENTO ORIGINAL



Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d9974_RTU	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0550-53	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0650	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0651	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0652	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0653	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0750	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0751	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0752	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0753	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0754	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0755	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0756	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0757	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0758	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0759	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PB0760	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	2 PB0761	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PSH54250203	F&G	HIGH/	HIGH
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 PSH54250213	F&G	HIGH/	HIGH
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d10021_RT	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d10022_RT	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d10023_RT	F&G	ON/	ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SY54250202	F&G	ENERG/	ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SY54250205	F&G	ENERG/	ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SY54250206	F&G	ENERG/	ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SY54250209	F&G	ENERG/	ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0704	F&G	ON/	ON

É CÓPIA DE DO DOCUMENTO ORIGINAL.

Ass: CARLOS F. P. ...
DIR: ...
...



Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0705	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 KA0702	F&G	ENERG/ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0706	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0707	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0708	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 KA0703	F&G	ENERG/ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0709	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0734	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0735	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0736	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 KA0713	F&G	ENERG/ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0741	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0737	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0738	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0739	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0740	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 KA0714	F&G	ENERG/ENERG
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d9361_RTU	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d9362_RTU	F&G	ON/ ON
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d10176_RT	F&G	FAULT/FAULT
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 SPARE_d10177_RT	F&G	FAULT/FAULT
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 YA0506_F	F&G	FAULT/FAULT
Mar 15 00:39:43 ALM DISC UNACK_ALM	1 GS53-HCB	F&G	HIGH/ HIGH
Mar 15 00:39:45 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 00:39:45 RTN DISC ACK_RTN	1 YA0704	F&G	OFF/ ON
Mar 15 00:39:45 RTN DISC ACK_RTN	1 YA0705	F&G	OFF/ ON
Mar 15 00:39:45 RTN DISC ACK_RTN	1 YA0707	F&G	OFF/ ON
Mar 15 00:39:45 RTN DISC ACK_RTN	1 YA0708	F&G	OFF/ ON

É CÓPIA DO DOCUMENTO ORIGINAL

JOSE CARLOS P. SANTOS
DIRETOR

15/03/2015 14:00



Mar 15 00:39:45 RTN DISC	1 YA0734	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:45 RTN DISC	1 YA0735	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:45 RTN DISC	1 YA0737	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:45 RTN DISC	1 YA0738	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:45 RTN DISC	1 YA0739	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:46 ALM DISC	1 MA07037	F&G	ALARM/ALARM	
UNACK_ALM				
Mar 15 00:39:46 ALM DISC	1 MA07006	F&G	ALARM/ALARM	
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0704	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0705	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0707	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0708	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0734	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0735	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0737	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0738	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:48 ALM DISC	1 YA0739	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:51 RTN DISC	1 YA0704	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0705	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0707	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0708	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0734	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0735	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0737	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0738	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:51 RTN DISC	1 YA0739	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:39:54 ALM DISC	1 YA0704	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:54 ALM DISC	1 YA0705	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:39:54 ALM DISC	1 YA0707	F&G	ON/	ON
UNACK_ALM				

É COPIA DE DOCUMENTO ORIGINAL

RECEBUE EN LA SECRETARIA
DE LA FISCALIA
EL 15/03/2015 A LAS 14:00 HRS



Mar 15 00:39:54 ALM DISC	1	YA0708	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:54 ALM DISC	1	YA0734	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:54 ALM DISC	1	YA0735	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:54 ALM DISC	1	YA0737	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:54 ALM DISC	1	YA0738	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:54 ALM DISC	1	YA0739	F&G	ON/	ON
UNACK_ALM					
Mar 15 00:39:56 RTN DISC	1	WWStatPortTGPr	\$System	HEALT/FAILE	
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0704	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0705	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0707	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0708	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0734	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0735	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0737	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0738	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:57 RTN DISC	1	YA0739	F&G	OFF/	ON
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	PS70103	F&G	ALARM/ALARM	
UNACK_ALM					
Mar 15 00:39:58 RTN DISC	1	XS70004A	F&G	STOPP/RUNNI	
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	XS70004C	F&G	TRIPP/TRIPP	
UNACK_ALM					
Mar 15 00:39:58 RTN DISC	1	XS70010A	F&G	NORMA/RUNNI	
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	XS70010C	F&G	TRIPP/TRIPP	
UNACK_ALM					
Mar 15 00:39:58 RTN DISC	1	XS70011A	F&G	NORMA/RUNNI	
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	XS70011C	F&G	TRIPP/TRIPP	
UNACK_ALM					
Mar 15 00:39:58 RTN DISC	1	XS70519B	F&G	NORMA/HIGH	
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	XS70519D	F&G	TRIPP/TRIPP	
UNACK_ALM					
Mar 15 00:39:58 ALM DISC	1	XS70012C	F&G	TRIPP/TRIPP	
UNACK_ALM					
Mar 15 00:39:58 RTN DISC	1	XS70520B	F&G	NORMA/HIGH	
ACK_RTN					
Mar 15 00:39:58 ALM DISC	1	XS70520D	F&G	TRIPP/TRIPP	
UNACK_ALM					

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS F. GENTIL GREGO
DIRETOR
DE REGISTRO E ARQUIVO



Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XS70013C	F&G	TRIPP/TRIPP
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70042B	F&G	CLOSE/CLOSE
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70569B	F&G	OPEN/ OPEN
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70570B	F&G	OPEN/ OPEN
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70044B	F&G	CLOSE/CLOSE
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70043B	F&G	CLOSE/CLOSE
Mar 15 00:39:58 RTN DISC ACK_RTN	1 XCV53004-VD	F&G	NORMA/DISCR
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70569B-VD	F&G	DISCR/DISCR
Mar 15 00:39:58 ALM DISC UNACK_ALM	1 XV70570B-VD	F&G	DISCR/DISCR
Mar 15 00:39:59 RTN DISC ACK_RTN	1 XV53017	F&G	DE-EN/ENERG
Mar 15 00:39:59 RTN DISC ACK_RTN	1 XV53020	F&G	DE-EN/ENERG
Mar 15 00:39:59 RTN DISC ACK_RTN	1 XV53023	F&G	DE-EN/ENERG
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 XY54231402	F&G	ALARM/ALARM
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 GS21-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 GS18-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 GS08-HCB_F	F&G	FAULT/FAULT
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 00:39:59 ALM DISC UNACK_ALM	1 GS53-HCB_F	F&G	FAULT/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS29-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS32-HCB_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS44-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS29-HCB_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS37-HCB_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS40-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS31-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS45-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 MD-TX16-HC_F	F&G	FAULT/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1808_F	F&G	NORMA/FAULT

É COPIA FIEL DO DOCUMENTO ORIGINAL
DESEMPENHO DE DEVERES
DESEMPENHO DE DEVERES



Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1703_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1312_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS69-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 MD-TX15-HC_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1811_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1813_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1704_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 MD-TX69-HC_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1322_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1323_F	F&G	NORMA/FAULT
Mar 15 00:40:00 RTN DISC ACK_RTN	1 GS1324_F	F&G	NORMA/FAULT
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0704	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0705	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0707	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0708	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0734	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0735	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0737	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0738	F&G	ON/ ON
Mar 15 00:40:00 ALM DISC UNACK_ALM	1 YA0739	F&G	ON/ ON
Mar 15 00:40:01 RTN DISC ACK_RTN	1 GS53-HCB	F&G	NORMA/ HIGH
Mar 15 00:40:02 ALM DISC UNACK_ALM	1 SD09003	F&G	ALARM/ALARM
Mar 15 00:40:02 ALM DISC UNACK_ALM	1 MA16002	F&G	ALARM/ALARM
Mar 15 00:40:02 ALM DISC UNACK_ALM	1 MA07020	F&G	ALARM/ALARM
Mar 15 00:40:02 ALM DISC UNACK_ALM	1 SD07043	F&G	ALARM/ALARM
Mar 15 00:40:02 ALM DISC UNACK_ALM	1 MA07126	F&G	ALARM/ALARM
Mar 15 00:40:03 RTN DISC ACK_RTN	1 YA0704	F&G	OFF/ ON

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FERREIRA GOMES
DIRETOR
14/03/2015



Mar 15 00:40:03 RTN DISC	1 YA0705	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0707	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0708	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0734	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0735	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0737	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0738	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:03 RTN DISC	1 YA0739	F&G	OFF/	ON
ACK_RTN				
Mar 15 00:40:06 ALM DISC	1 YA0704	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0705	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0707	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0708	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0734	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0735	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0737	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0738	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:06 ALM DISC	1 YA0739	F&G	ON/	ON
UNACK_ALM				
Mar 15 00:40:14 RTN DISC	1 XS70004C	F&G	NORMA/TRIPP	
ACK_RTN				
Mar 15 00:40:14 RTN DISC	1 XS70010C	F&G	NORMA/TRIPP	
ACK_RTN				
Mar 15 00:40:14 ALM DISC	1 ZSC70569A	F&G	CLOSE/CLOSE	
UNACK_ALM				
Mar 15 00:40:14 ALM DISC	1 ZSC70570A	F&G	CLOSE/CLOSE	
UNACK_ALM				
Mar 15 00:40:14 ALM DISC	1 XS70519C	F&G	LOW S/LOW S	
UNACK_ALM				
Mar 15 00:40:14 RTN DISC	1 XS70519D	F&G	NORMA/TRIPP	
ACK_RTN				
Mar 15 00:40:14 RTN DISC	1 XS70012C	F&G	NORMA/TRIPP	
ACK_RTN				
Mar 15 00:40:14 ALM DISC	1 ZSO70042	F&G	OPEN/ OPEN	
UNACK_ALM				
Mar 15 00:40:14 ALM DISC	1 ZSO70043	F&G	OPEN/ OPEN	
UNACK_ALM				
Mar 15 00:40:14 RTN DISC	1 XV70042B	F&G	NORMA/CLOSE	
ACK_RTN				
Mar 15 00:40:14 RTN DISC	1 XV70044B	F&G	NORMA/CLOSE	
ACK_RTN				

COPIA DEL DOCUMENTO ORIGINAL

JOSE CARLOS HERNANDEZ
DIRECTOR
13



Mar 15 00:40:16 ALM DISC	1 X270519	F&G	START/START
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 XV53044	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 XV53047	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 XV53051	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 PT70034_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1709_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS68-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1708_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1703_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1312_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS69-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 MD-TX15-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 MD-TX69-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1322_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:16 ALM DISC	1 GS1324_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD07094	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD07112	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD07115	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD09000	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD09004	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD06061	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:40:19 ALM DISC	1 SD07005	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA DE UM DOCUMENTO ORIGINAL

ASSINADO POR: [Assinatura]
[Assinatura]



Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07007	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07021	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07046	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD04022	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07104	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07106	F&G	ALARM/ALARM
Mar 15 00:40:19 ALM DISC UNACK_ALM	1 SD07120	F&G	ALARM/ALARM
Mar 15 00:40:23 ALM DISC UNACK_ALM	1 PS70104	F&G	ALARM/ALARM
Mar 15 00:40:23 RTN DISC ACK_RTN	1 ZSO70569B	F&G	NOT O/ OPEN
Mar 15 00:40:23 RTN DISC ACK_RTN	1 ZSC70043	F&G	NOT C/CLOSE
Mar 15 00:40:23 RTN DISC ACK_RTN	1 XV70569B	F&G	NORMA/ OPEN
Mar 15 00:40:23 RTN DISC ACK_RTN	1 XV70569B-VD	F&G	NORMA/DISCR
Mar 15 00:40:25 ALM DISC UNACK_ALM	1 SOV70120	F&G	OPEN/ OPEN
Mar 15 00:40:25 ALM DISC UNACK_ALM	1 SOV70121	F&G	OPEN/ OPEN
Mar 15 00:40:25 ALM DISC UNACK_ALM	1 SOV70122	F&G	OPEN/ OPEN
Mar 15 00:40:25 ALM DISC UNACK_ALM	1 SOV70124	F&G	OPEN/ OPEN
Mar 15 00:40:25 ALM DISC UNACK_ALM	1 XCV53004	F&G	ENERG/ENERG
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS2401_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	2 GS1502_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS68-HCB_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	2 GS1801_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	2 GS1708_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS1703_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS1312_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS69-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 MD-TX15-HC_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 MD-TX69-HC_F	F&G	NORMA/FAULT

É CÓPIA DE UM DOCUMENTO ORIGINAL

USE CUIDADO PARA NÃO PERDÊ-LO
DATA: 15/03/2015
HORARIO: 14:23



Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS1322_F	F&G	NORMA/FAULT
Mar 15 00:40:25 RTN DISC ACK_RTN	1 GS1324_F	F&G	NORMA/FAULT
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 SD09005	F&G	ALARM/ALARM
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 SD07080	F&G	ALARM/ALARM
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 HD07081	F&G	ALARM/ALARM
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 SD07082	F&G	ALARM/ALARM
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 SD07083	F&G	ALARM/ALARM
Mar 15 00:40:28 ALM DISC UNACK_ALM	1 SD07124	F&G	ALARM/ALARM
Mar 15 00:40:40 RTN DISC ACK_RTN	1 ZSO70570B	F&G	NOT O/ OPEN
Mar 15 00:40:40 ALM DISC UNACK_ALM	1 XS70519B	F&G	HIGH /HIGH
Mar 15 00:40:40 RTN DISC ACK_RTN	1 XS70519C	F&G	NORMA/LOW S
Mar 15 00:40:40 RTN DISC ACK_RTN	1 XV70570B	F&G	NORMA/ OPEN
Mar 15 00:40:40 RTN DISC ACK_RTN	1 XV70570B-VD	F&G	NORMA/DISCR
Mar 15 00:40:41 RTN DISC ACK_RTN	1 SOV70120_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 SOV70121_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 SOV70122_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 SOV70124_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 PT70034_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 PT70030_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 GS08-HCB_F	F&G	NORMA/FAULT
Mar 15 00:40:41 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 GS68-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 GS1709_F	F&G	NORMA/FAULT
Mar 15 00:40:41 RTN DISC ACK_RTN	1 GS67-HCA_F	F&G	NORMA/FAULT
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07035	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07036	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07070	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07073	F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

USE CARLOS FERNANDES
DATA 10/03/2010
10:00:00



Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07075	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07079	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07116	F&G	ALARM/ALARM
Mar 15 00:40:44 ALM DISC UNACK_ALM	1 SD07117	F&G	ALARM/ALARM
Mar 15 00:40:49 ALM DISC UNACK_ALM	1 SD07072	F&G	ALARM/ALARM
Mar 15 00:40:52 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:40:53 ALM DISC UNACK_ALM	1 SD07038	F&G	ALARM/ALARM
Mar 15 00:40:53 ALM DISC UNACK_ALM	1 HD07074	F&G	ALARM/ALARM
Mar 15 00:40:53 ALM DISC UNACK_ALM	1 SD07077	F&G	ALARM/ALARM
Mar 15 00:41:05 ALM DISC UNACK_ALM	1 XCV53004-VD	F&G	DISCR/DISCR
Mar 15 00:41:07 RTN DISC ACK_RTN	1 XZ70519	F&G	NORMA/START
Mar 15 00:41:07 RTN DISC ACK_RTN	1 XV53044	F&G	DE-EN/ENERG
Mar 15 00:41:07 RTN DISC ACK_RTN	1 XV53047	F&G	DE-EN/ENERG
Mar 15 00:41:07 RTN DISC ACK_RTN	1 XV53051	F&G	DE-EN/ENERG
Mar 15 00:41:07 RTN DISC ACK_RTN	1 XCV53004	F&G	DE-EN/ENERG
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70007_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70034_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70030_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70035_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70031_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70037_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 PT70033_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS1705_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS1706_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS1707_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS1711_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS1712_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 SPARE_d11607_F&	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

2023-03-15 14:00:00
00000000000000000000
00000000000000000000



Mar 15 00:41:07 ALM DISC	1 GS2802_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS07-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS09-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS11-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 SPARE_d11612_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS19-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS23-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS26-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 SPARE_d11617_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS2301_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS07-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS09-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS11-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS14G-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS16-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 SPARE_d11626_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS20-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS22-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS24-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS2801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS06-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS08-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS10-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 SPARE_d11636_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS15-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:41:07 ALM DISC	1 GS18-HCC_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MACHADO
DIRETOR
15/03/2015 14:30



Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS20-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS22-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS24-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS27-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS29-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS32-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS37-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS39-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS44-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS56A-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS50-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS29-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS35-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:07 ALM DISC UNACK_ALM	1 GS44-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS56B-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS63-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS33-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS40-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS42-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS47-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS63-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2902_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS31-HCA_F	F&G	FAULT/FAULT

É COPIA DE DOCUMENTO ORIGINAL

SECRETARIA DE SEGURANÇA PÚBLICA
DEPARTAMENTO DE TRÁFICO DE VEÍCULOS
15/03/2018 14:00:00



Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS33-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS38-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS40-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS45-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS47-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS55A-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1316_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2903_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1501_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1503_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS67-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS68-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2306_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2401_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1709_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2904_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2906_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS67-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS68-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2804_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS2403_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1808_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1703_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 MD-TX68-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1312_F	F&G	FAULT/FAULT
Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1306_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL


Doc 00108-000000000000
DISET 1
01/03/2015 15:00



Mar 15 00:41:08 ALM DISC UNACK_ALM	1 GS1315_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1309_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS69-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS70-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 MD-TX15-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1811_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1813_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1704_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 MD-TX69-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS69-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS72-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS72-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1322_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1323_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS1324_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 GS2404_F	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11799_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11800_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11801_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11802_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11803_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11804_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11805_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11806_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11807_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11808_F&	F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11809_F&	F&G	FAULT/FAULT

É Cópia Fiel do Documento Original:

ROSE CARLOS FERNANDES
DISC
11/03/2015



Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11810_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11811_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11812_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11813_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11814_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11815_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11816_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11818_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11819_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11820_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11821_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11852_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11853_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11854_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11855_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11856_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11858_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11859_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11860_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11861_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11862_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	2 SPARE_d11863_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11864_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11865_F& F&G	FAULT/FAULT
Mar 15 00:41:09 ALM DISC UNACK_ALM	1 SPARE_d11866_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUIMARÃES
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11867_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11868_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11869_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11870_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11871_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11872_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11873_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11874_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11875_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11876_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11877_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11878_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11879_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11880_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11881_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11882_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11883_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11884_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11885_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11886_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11887_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11888_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11889_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11890_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11891_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11900_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11901_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11902_F& F&G	FAULT/FAULT

É CÓPIA DO DOCUMENTO ORIGINAL


JOSÉ CARLOS PIMENTEL GUARÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11903_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11904_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11905_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11906_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11907_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11908_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11909_F& F&G	FAULT/FAULT
Mar 15 00:41:10 ALM DISC UNACK_ALM	1 SPARE_d11910_F& F&G	FAULT/FAULT
Mar 15 00:41:11 ALM DISC UNACK_ALM	1 SPARE_d11911_F& F&G	FAULT/FAULT
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70030 F&G	NORMA/ALARM
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70031 F&G	NORMA/ALARM
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70032 F&G	NORMA/ALARM
Mar 15 00:41:11 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 00:41:11 ALM DISC UNACK_ALM	1 PT70316 F&G	ALARM/ALARM
Mar 15 00:41:11 ALM DISC UNACK_ALM	1 SD07034 F&G	ALARM/ALARM
Mar 15 00:41:11 ALM DISC UNACK_ALM	1 SD06060 F&G	ALARM/ALARM
Mar 15 00:41:22 ALM DISC UNACK_ALM	1 PS70102 F&G	ALARM/ALARM
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS2803_F F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS06-HCB_F F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS08-HCB_F F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS10-HCB_F F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 SPARE_d11647_F& F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS15-HCB_F F&G	FAULT/FAULT
Mar 15 00:41:23 ALM DISC UNACK_ALM	1 GS17-HCA_F F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS27-HCB_F F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 SPARE_d11651_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIQUETEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1710_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS14F-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS15-HCC_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS17-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS19-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS23-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 SPARE_d11659_F&	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS28-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS36-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS38-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS43-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS45-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS47-HCC_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS55B-HC_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1301_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1317_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS2302_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS28-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS34-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS36-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS41-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1302_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1318_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1814_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS2303_F	F&G	FAULT/FAULT

É Cópia do documento original

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS32-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS34-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS39-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS51-HCB_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1303_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS60-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1801_F	F&G	FAULT/FAULT
Mar 15 00:41:24 ALM DISC UNACK_ALM	1 GS1812_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1806_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1701_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1310_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1304_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1313_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1307_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1319_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS71-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1802_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1805_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1708_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1807_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1702_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1311_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1305_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1314_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1308_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS1320_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS70-HCA_F	F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 GS71-HCB_F	F&G	FAULT/FAULT

É CÓPIA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUERÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11822_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11823_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11824_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11825_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11826_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11827_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11829_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11830_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11831_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11832_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11834_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11835_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11836_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11837_F& F&G	FAULT/FAULT
Mar 15 00:41:25 ALM DISC UNACK_ALM	1 SPARE_d11838_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11839_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11840_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11841_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11842_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11843_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11844_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11845_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11846_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11847_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11848_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11849_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11850_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11892_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11893_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11894_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11895_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11896_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11897_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11898_F& F&G	FAULT/FAULT
Mar 15 00:41:26 ALM DISC UNACK_ALM	1 SPARE_d11899_F& F&G	FAULT/FAULT
Mar 15 00:41:26 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD07078 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD04013 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD04014 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD07008 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD04020 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD07068 F&G	ALARM/ALARM
Mar 15 00:41:28 ALM DISC UNACK_ALM	1 SD07121 F&G	ALARM/ALARM
Mar 15 00:41:34 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 00:41:35 ALM DISC UNACK_ALM	1 SD07015 F&G	ALARM/ALARM
Mar 15 00:41:35 ALM DISC UNACK_ALM	1 SD07041 F&G	ALARM/ALARM
Mar 15 00:41:35 ALM DISC UNACK_ALM	1 SD07042 F&G	ALARM/ALARM
Mar 15 00:41:35 ALM DISC UNACK_ALM	1 SD07101 F&G	ALARM/ALARM
Mar 15 00:41:44 ALM DISC UNACK_ALM	1 SD07125 F&G	ALARM/ALARM
Mar 15 00:41:53 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 00:41:53 ALM DISC UNACK_ALM	1 PT70031 F&G	ALARM/ALARM
Mar 15 00:41:55 ALM DISC UNACK_ALM	1 SD07016 F&G	ALARM/ALARM
Mar 15 00:41:55 ALM DISC UNACK_ALM	1 HD07084 F&G	ALARM/ALARM
Mar 15 00:41:55 ALM DISC UNACK_ALM	1 SD07086 F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 00:41:59 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:41:59 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:01 ALM DISC	1 SD07088	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:01 ALM DISC	1 SD07089	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:01 ALM DISC	1 SD07127	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:05 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:42:05 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:42:05 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:42:07 ALM DISC	1 SD07017	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:07 ALM DISC	1 SD07128	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:10 ALM DISC	1 XZ70010A	F&G	START/START
UNACK_ALM			
Mar 15 00:42:14 ALM DISC	1 SD07044	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:17 RTN DISC	1 XZ70010A	F&G	NORMA/START
ACK_RTN			
Mar 15 00:42:17 ALM DISC	1 XV70040A	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:42:20 ALM DISC	1 SD07014	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:20 ALM DISC	1 SD07129	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:23 ALM DISC	1 ZSC70040	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 00:42:25 ALM DISC	1 XV53017	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:42:25 ALM DISC	1 XV53020	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:42:25 ALM DISC	1 XV53023	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 00:42:26 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:31 ALM DISC	1 PS70303	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:42:31 RTN DISC	1 ZSC70040	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 00:42:31 RTN DISC	1 XV70040A	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 00:42:32 RTN DISC	1 XV53017	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 00:42:32 RTN DISC	1 XV53020	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 00:42:32 RTN DISC	1 XV53023	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 00:42:34 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
COMISSÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 00:42:34 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:42:40 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:42:40 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:42:41 ALM DISC	2	SD04017	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:42:41 ALM DISC	1	SD07045	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:42:46 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:42:50 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:42:55 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:01 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:01 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:01 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:05 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:05 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:05 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:08 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:13 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:19 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:19 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:19 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:19 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:23 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:23 RTN DISC	2	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:23 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:23 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:26 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:31 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 00:43:35 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 00:43:40 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				

SECRETARIA DE DEFESA NACIONAL
JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:43:46 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:43:46 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:43:46 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:43:50 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:43:50 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:43:50 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:44:11 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:44:16 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:44:20 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:44:25 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11607_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11612_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 GS14G-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11626_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11636_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11799_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11800_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11801_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11802_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11803_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11804_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11805_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11806_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11807_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11808_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11809_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11810_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:44:43 RTN DISC	1 SPARE_d11811_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11812_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11813_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11814_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11815_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11816_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11818_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11819_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11820_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11821_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11856_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11861_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11868_F& F&G	NORMA/FAULT
Mar 15 00:44:43 RTN DISC ACK_RTN	1 SPARE_d11882_F& F&G	NORMA/FAULT
Mar 15 00:44:44 RTN DISC ACK_RTN	1 SPARE_d11907_F& F&G	NORMA/FAULT
Mar 15 00:44:44 RTN DISC ACK_RTN	1 SPARE_d11908_F& F&G	NORMA/FAULT
Mar 15 00:44:44 RTN DISC ACK_RTN	1 SPARE_d11909_F& F&G	NORMA/FAULT
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70007 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70030 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70031 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70032 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 00:44:44 ALM DISC UNACK_ALM	1 PT70033 F&G	ALARM/ALARM
Mar 15 00:44:45 RTN DISC ACK_RTN	1 PT70316 F&G	NORMA/ALARM
Mar 15 00:44:47 ALM DISC UNACK_ALM	1 SPARE_d11607_F& F&G	FAULT/FAULT
Mar 15 00:44:47 ALM DISC UNACK_ALM	1 SPARE_d11612_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIENDEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CONTÁBILIS



Mar 15 00:44:47 ALM DISC UNACK_ALM	1 GS14G-HC_F	F&G	FAULT/FAULT
Mar 15 00:44:47 ALM DISC UNACK_ALM	1 SPARE_d11626_F&	F&G	FAULT/FAULT
Mar 15 00:44:47 ALM DISC UNACK_ALM	1 SPARE_d11636_F&	F&G	FAULT/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS2803_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS06-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS08-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS10-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 SPARE_d11647_F&	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS15-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS17-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 SPARE_d11651_F&	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1710_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS14F-HC_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS15-HCC_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS17-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS19-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS23-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 SPARE_d11659_F&	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS28-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS36-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS38-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS45-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS47-HCC_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS55B-HC_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1301_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1317_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS2302_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS BUENDEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAS



Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS28-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS34-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS36-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS41-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS43-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1302_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1814_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS2303_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS32-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS51-HCB_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1303_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS60-HCA_F	F&G	NORMA/FAULT
Mar 15 00:44:48 RTN DISC ACK_RTN	1 GS1802_F	F&G	NORMA/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11799_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11800_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11801_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11802_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11803_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11804_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11805_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11806_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11807_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11808_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11809_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11810_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	2 SPARE_d11811_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11812_F&	F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11813_F&	F&G	FAULT/FAULT

É CÓPIA DE DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIAS



Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11814_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11815_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11816_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11818_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11819_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11820_F& F&G	FAULT/FAULT
Mar 15 00:44:49 ALM DISC UNACK_ALM	1 SPARE_d11821_F& F&G	FAULT/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11822_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11823_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11824_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11825_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11826_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11827_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11829_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11830_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11831_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11832_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11834_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11835_F& F&G	NORMA/FAULT
Mar 15 00:44:49 RTN DISC ACK_RTN	1 SPARE_d11836_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11837_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11838_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11839_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11840_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11841_F& F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11842_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11843_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11844_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11845_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11846_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11847_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11848_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11849_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11850_F& F&G	NORMA/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11856_F& F&G	FAULT/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11861_F& F&G	FAULT/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11868_F& F&G	FAULT/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11882_F& F&G	FAULT/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11892_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11893_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11894_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11895_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11896_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11897_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11898_F& F&G	NORMA/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 SPARE_d11899_F& F&G	NORMA/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11907_F& F&G	FAULT/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11908_F& F&G	FAULT/FAULT
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 SPARE_d11909_F& F&G	FAULT/FAULT
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70030 F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS FONSECA GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIS



Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70032	F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:44:50 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 00:44:50 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS2803_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS06-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS08-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS10-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 SPARE_d11647_F&	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS15-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS17-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 SPARE_d11651_F&	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS1710_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS14F-HC_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS15-HCC_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS17-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS19-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS23-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 SPARE_d11659_F&	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS28-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS36-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS38-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS45-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS47-HCC_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS55B-HC_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS1301_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS1317_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 00:44:52 ALM DISC UNACK_ALM	1 GS2302_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS28-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS34-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS36-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS41-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS1302_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS1814_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS2303_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS32-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS51-HCB_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS1303_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS60-HCA_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 GS1802_F	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11822_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11823_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11824_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11825_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11826_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11827_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11829_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11830_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11831_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11832_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11834_F&	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAS



Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11835_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11836_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11837_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11838_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11839_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11840_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11841_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11842_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11843_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11844_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11845_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11846_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11847_F& F&G	FAULT/FAULT
Mar 15 00:44:53 ALM DISC UNACK_ALM	1 SPARE_d11848_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11849_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11850_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11892_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11893_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11894_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11895_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11896_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11897_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11898_F& F&G	FAULT/FAULT
Mar 15 00:44:54 ALM DISC UNACK_ALM	1 SPARE_d11899_F& F&G	FAULT/FAULT
Mar 15 00:45:23 RTN DISC ACK_RTN	2 PT70316 F&G	NORMA/ALARM
Mar 15 00:45:28 ALM DISC UNACK_ALM	1 PT70316 F&G	ALARM/ALARM
Mar 15 00:47:49 ALM DISC UNACK_ALM	1 SD06006 F&G	ALARM/ALARM
Mar 15 00:48:55 ALM DISC UNACK_ALM	1 SD07122 F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:49:17 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:49:22 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:49:35 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:49:40 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:31 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:31 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:31 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:31 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:31 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:35 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:35 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:40 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:40 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:44 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:44 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:44 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:44 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:44 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:49 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:49 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:49 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:49 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:49 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:53 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:53 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:53 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:53 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:50:53 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA DE DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:50:58 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:58 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:58 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:58 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:50:58 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:02 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:02 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:02 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:02 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:02 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:07 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:07 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:07 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:07 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:07 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:11 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:11 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:11 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:11 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:11 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:16 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:16 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:16 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:16 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:16 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:20 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:20 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:20 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
PREFEITO
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:51:20 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:20 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:25 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:25 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:25 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:25 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:25 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:29 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:29 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:29 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:29 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:29 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:34 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:34 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:34 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:38 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:38 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:38 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:41 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:46 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:52 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:52 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:51:52 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:56 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:56 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:51:56 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:01 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:01 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			

É Cópia Fiel do Documento Original

JOSÉ CARLOS FONSECA, GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Timestamp	Event	Count	PT	Category	Status
Mar 15 00:52:01	ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:01	ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:01	RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:05	RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:05	RTN DISC	1	PT70031	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:05	RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:06	RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:06	ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:10	ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:10	ALM DISC	1	PT70031	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:10	ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:10	RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:14	RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:14	RTN DISC	1	PT70031	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:14	RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:15	ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:19	ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:19	ALM DISC	1	PT70031	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:19	ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:19	ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:19	RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:23	RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:23	RTN DISC	1	PT70031	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:23	RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:23	RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN					
Mar 15 00:52:23	ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:28	ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM					
Mar 15 00:52:28	ALM DISC	1	PT70031	F&G	ALARM/ALARM
UNACK_ALM					

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 00:52:28 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:28 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:28 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:32 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:32 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:32 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:32 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:32 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:37 ALM DISC	1 PS70101	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:38 ALM DISC	1 SOV70119	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 00:52:38 RTN DISC	1 SOV70119_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:52:39 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:52:39 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:52:39 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:52:40 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:52:40 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:43 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:52:43 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:52:43 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:52:43 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:52:44 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:44 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:52:47 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:52:49 RTN DISC	1 PT70035.	F&G
ACK_RTN		
Mar 15 00:52:49 RTN DISC	1 PT70031	F&G
ACK_RTN		
Mar 15 00:52:49 RTN DISC	1 PT70037	F&G
ACK_RTN		
Mar 15 00:52:49 RTN DISC	1 PT70033	F&G
ACK_RTN		
Mar 15 00:52:49 ALM DISC	1 PT70316	F&G
UNACK_ALM		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11823_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11825_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11828_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11832_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11833_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11834_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11835_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11838_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11842_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11846_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11847_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11848_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11850_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11851_F& F&G	
ACK_RTN		
Mar 15 00:52:52 RTN DISC	1 SPARE_d11857_F& F&G	
ACK_RTN		
Mar 15 00:52:53 ALM DISC	1 PT70035	F&G
UNACK_ALM		
Mar 15 00:52:53 ALM DISC	1 PT70031	F&G
UNACK_ALM		
Mar 15 00:52:53 ALM DISC	1 PT70037	F&G
UNACK_ALM		
Mar 15 00:52:53 ALM DISC	1 PT70033	F&G
UNACK_ALM		
Mar 15 00:52:53 RTN DISC	1 PT70316	F&G
ACK_RTN		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11823_F& F&G	
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	2 SPARE_d11825_F& F&G	
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11828_F& F&G	
UNACK_ALM		

NORMA/ALARM

NORMA/ALARM

NORMA/ALARM

NORMA/ALARM

ALARM/ALARM

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

NORMA/FAULT

ALARM/ALARM

ALARM/ALARM

ALARM/ALARM

ALARM/ALARM

NORMA/ALARM

FAULT/FAULT

FAULT/FAULT

FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 00:52:56 ALM DISC	1 SPARE_d11832_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11833_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11834_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11835_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11838_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	2 SPARE_d11842_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:56 ALM DISC	1 SPARE_d11846_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:57 ALM DISC	1 SPARE_d11847_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:57 ALM DISC	1 SPARE_d11848_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:57 ALM DISC	1 SPARE_d11850_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:57 ALM DISC	1 SPARE_d11851_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:57 ALM DISC	1 SPARE_d11857_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 00:52:58 RTN DISC	1 PT70035 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:52:58 RTN DISC	1 PT70031 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:52:58 RTN DISC	1 PT70037 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:52:58 RTN DISC	1 PT70033 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:52:58 ALM DISC	1 PT70316 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:02 ALM DISC	1 PT70035 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:02 ALM DISC	1 PT70031 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:02 ALM DISC	1 PT70037 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:02 ALM DISC	1 PT70033 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:02 RTN DISC	1 PT70316 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:53:07 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:07 RTN DISC	1 PT70037 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:53:11 RTN DISC	1 PT70034 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:53:11 ALM DISC	1 PT70037 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 00:53:16 RTN DISC	1 PT70035 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 00:53:16 RTN DISC	2 PT70031 F&G	NORMA/ALARM
ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:53:16 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:16 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:16 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:20 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 RTN DISC	2 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:25 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:29 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:29 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:29 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:29 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:29 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:34 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:34 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:34 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:34 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:34 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:38 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:38 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:38 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			

É Cópia fiel do documento original.



Mar 15 00:53:38 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:38 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:41 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:53:41 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:53:41 RTN DISC	1 SPARE_d11865_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:53:43 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:43 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:46 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:53:46 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:53:46 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:53:46 ALM DISC	1 SPARE_d11865_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:53:47 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:47 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:50 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:53:52 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:53:56 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:53:56 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:01 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:01 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:01 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:01 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:01 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:01 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:05 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:05 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:05 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:05 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:05 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL



Mar 15 00:54:07 ALM DISC	1 SD05117	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:19 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:19 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:19 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:20 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:20 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:23 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:23 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:25 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:25 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:28 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:28 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:28 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:29 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:29 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:32 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:32 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:32 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:34 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:34 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:37 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:37 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:38 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:38 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:41 RTN DISC	1 SPARE_d11815_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:41 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:41 RTN DISC	1 SPARE_d11847_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:54:41 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS PUENTE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:54:43 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:46 ALM DISC	1 SPARE_d11815_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:46 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:46 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:46 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:46 ALM DISC	1 SPARE_d11847_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:54:47 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:47 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:47 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:47 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:47 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:48 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:48 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:54:52 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:52 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:52 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:52 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:54:56 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:01 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:05 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:08 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:08 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:10 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:10 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:10 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:13 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:13 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:13 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DEBETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:55:14 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:14 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:15 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:17 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:19 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:19 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:19 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:22 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:22 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:23 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:23 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:25 ALM DISC	1 SD05126	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:25 ALM DISC	1 SD06015	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:28 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:29 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:29 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:32 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:32 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:33 RTN DISC	1 SPARE_d11847_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:34 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:34 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:34 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:37 RTN DISC	1 LS70301	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:39 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:39 ALM DISC	1 SPARE_d11847_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:44 RTN DISC	1 SPARE_d11815_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:45 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:46 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIAS



Mar 15 00:55:46 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:46 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:49 ALM DISC	1 SPARE_d11815_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:49 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:49 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:50 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:53 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:54 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:55:55 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:55:58 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:58 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:55:59 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:55:59 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:03 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:03 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:04 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:04 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:07 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:07 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:07 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:08 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:08 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:08 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:10 ALM DISC	1 SD07103	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:13 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:14 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:14 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:14 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:56:17 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:19 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:19 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:19 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:22 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:23 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:23 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:23 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:26 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:28 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:28 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:28 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:28 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:28 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:28 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:31 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:32 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:32 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:32 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:32 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:32 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:32 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:35 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:35 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:35 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:37 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:37 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:37 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 15 00:56:40 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:40 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:40 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:41 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:41 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:41 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:44 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:44 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:46 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:46 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:46 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:49 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:56:50 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:55 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:56:58 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:56:59 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:56:59 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 00:57:04 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:04 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:04 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:07 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:08 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:08 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:08 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:08 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:11 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:11 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:11 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL



Mar 15 00:57:11 RTN DISC	1 SPARE_d11847_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:13 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:13 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:13 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 00:57:16 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:16 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:16 ALM DISC	1 SPARE_d11847_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:17 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:17 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 00:57:20 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:22 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 00:57:25 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:29 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:29 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:29 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:32 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:34 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:34 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:34 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:37 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:38 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:38 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:38 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:38 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:39 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:43 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:43 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:43 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 15 00:57:43 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:43 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:47 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:47 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:47 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:47 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:57:50 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:52 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:52 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:52 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:52 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:57:55 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:57:55 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:57:59 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:58:04 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:07 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:58:10 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:58:10 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:58:14 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:14 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:15 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:19 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:58:19 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:58:19 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:58:23 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:23 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:58:26 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:58:28 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.
JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:58:28 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:58:32 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:58:33 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 00:58:33 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:58:33 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 00:58:35 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 00:58:37 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 00:58:37 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 00:58:37 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:58:37 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 00:58:40 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 00:58:41 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:58:42 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 00:58:42 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:58:42 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 00:58:44 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 00:58:46 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 00:58:46 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 00:58:46 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:58:46 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 00:58:51 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:58:51 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 00:58:51 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:58:51 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 00:58:51 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 00:58:52 ALM DISC UNACK_ALM	1 SD09002	F&G	ALARM/ALARM
Mar 15 00:58:55 RTN DISC ACK_RTN	1 SPARE_011817_F&	F&G	NORMA/FAULT
Mar 15 00:58:56 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:58:56 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 00:58:56 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:58:56 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 00:58:56 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 00:59:00 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 00:59:01 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:59:01 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:59:04 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 00:59:04 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 00:59:05 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 00:59:05 ALM DISC UNACK_ALM	1 PT70032	F&G	ALARM/ALARM
Mar 15 00:59:05 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:59:09 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 00:59:09 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 00:59:09 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 00:59:09 RTN DISC ACK_RTN	1 SPARE_d11851_F&	F&G	NORMA/FAULT
Mar 15 00:59:09 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 00:59:10 RTN DISC ACK_RTN	1 PT70032	F&G	NORMA/ALARM
Mar 15 00:59:13 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 00:59:13 ALM DISC UNACK_ALM	1 SPARE_d11851_F&	F&G	FAULT/FAULT
Mar 15 00:59:13 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 00:59:17 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 00:59:17 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 00:59:21 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 00:59:22 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 00:59:22 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 00:59:25 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 00:59:25 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT

É COPIA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIENDEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:59:26 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:26 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:30 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:59:30 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 00:59:31 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:31 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:34 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 00:59:35 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:35 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:35 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:35 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:35 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:40 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:40 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:40 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:40 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:44 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:44 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:44 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:44 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:49 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:53 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:53 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:53 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 00:59:58 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:58 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 00:59:58 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:02 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:00:02 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:02 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:02 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:02 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:07 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:07 ALM DISC	2 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:07 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:07 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:07 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:11 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:11 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:11 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:11 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:11 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:16 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:16 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:16 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:16 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:16 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:20 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:20 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:20 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:25 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:25 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:25 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:29 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:29 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:29 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTA GUIMARÃES
DIRETOR
DIVISÃO DE SERVIÇOS



Mar 15 01:00:29 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:29 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:34 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:34 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:34 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:34 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:34 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:38 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:38 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:38 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:38 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:38 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:43 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:47 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:52 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:52 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:52 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:52 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:00:52 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:00:56 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:01 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:05 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:10 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:11 ALM DISC	1 SD05125	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:16 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:16 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:16 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:16 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
COMISSÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:01:16 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:20 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:20 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:21 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:21 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:21 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:25 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:25 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:25 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:25 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:25 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:28 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:01:29 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:30 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:32 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:01:34 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:34 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:34 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:34 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:38 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:39 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:43 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:43 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA DE UM DOCUMENTO ORIGINAL
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:01:43 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:48 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:48 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:48 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:52 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:52 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:52 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:52 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:01:52 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:57 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:57 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:57 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:57 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:01:57 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:01 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:01 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:01 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:01 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:01 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:02:05 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:02:05 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:02:05 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:02:05 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:02:05 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:09 RTN DISC	1 SPARE_011833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:02:10 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:10 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:02:13 RTN DISC	1 SPARE_011817_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:02:13 RTN DISC	1 SPARE_d11828_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:02:13 ALM DISC	1 SPARE_d11833_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:14 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:14 ALM DISC	1 PT70035 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:14 ALM DISC	1 PT70037 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:18 ALM DISC	1 SPARE_d11828_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:18 RTN DISC	1 SPARE_d11833_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:02:18 RTN DISC	1 SPARE_d11851_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:02:18 RTN DISC	1 SPARE_d11857_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:02:19 RTN DISC	1 PT70034 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:22 ALM DISC	1 SPARE_d11833_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:22 ALM DISC	1 SPARE_d11851_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:22 ALM DISC	1 SPARE_d11857_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:23 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:23 ALM DISC	1 PT70032 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:27 ALM DISC	1 SPARE_d11817_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:28 RTN DISC	1 PT70034 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:28 RTN DISC	1 PT70035 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:28 RTN DISC	1 PT70031 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:28 RTN DISC	1 PT70032 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:28 RTN DISC	1 PT70037 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:31 RTN DISC	1 SPARE_d11817_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:02:32 ALM DISC	1 PT70035 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:32 ALM DISC	1 PT70031 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:32 ALM DISC	1 PT70037 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:02:36 ALM DISC	1 SPARE_d11817_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:02:37 RTN DISC	1 PT70035 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:02:38 ALM DISC	1 SD07114 F&G	ALARM/ALARM
UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:03:09 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:03:09 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:03:14 ALM DISC UNACK_ALM	1 SPARE_d11810_F& F&G	FAULT/FAULT
Mar 15 01:03:14 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:03:14 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:03:16 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:03:16 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:03:19 ALM DISC UNACK_ALM	1 XS70004B F&G	LOCAL/LOCAL
Mar 15 01:03:20 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:03:20 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:03:22 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:03:22 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:03:22 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:03:26 ALM DISC UNACK_ALM	1 XS70004A F&G	RUNNI/RUNNI
Mar 15 01:03:28 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:03:29 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:03:34 RTN DISC ACK_RTN	1 SPARE_d11810_F& F&G	NORMA/FAULT
Mar 15 01:03:34 RTN DISC ACK_RTN	1 SPARE_d11815_F& F&G	NORMA/FAULT
Mar 15 01:03:34 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:03:34 RTN DISC ACK_RTN	1 SPARE_d11818_F& F&G	NORMA/FAULT
Mar 15 01:03:34 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:03:34 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:03:34 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:03:35 ALM DISC UNACK_ALM	1 PT70007 F&G	ALARM/ALARM
Mar 15 01:03:35 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:03:35 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:03:35 ALM DISC UNACK_ALM	1 PT70032 F&G	ALARM/ALARM
Mar 15 01:03:38 ALM DISC UNACK_ALM	1 SPARE_d11810_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS PIMENTE/GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:03:38 ALM DISC UNACK_ALM	1 SPARE_d11815_F& F&G	FAULT/FAULT
Mar 15 01:03:38 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:03:39 ALM DISC UNACK_ALM	1 SPARE_d11818_F& F&G	FAULT/FAULT
Mar 15 01:03:39 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:03:40 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 01:03:40 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:03:40 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:03:40 RTN DISC ACK_RTN	1 PT70032 F&G	NORMA/ALARM
Mar 15 01:03:43 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:03:43 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:03:43 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:03:44 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:03:47 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:03:47 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:03:47 RTN DISC ACK_RTN	1 SPARE_d11846_F& F&G	NORMA/FAULT
Mar 15 01:03:47 RTN DISC ACK_RTN	1 SPARE_d11847_F& F&G	NORMA/FAULT
Mar 15 01:03:48 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:03:48 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:03:49 ALM DISC UNACK_ALM	1 GS53-HCA F&G	HIGH/ HIGH
Mar 15 01:03:52 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:03:52 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:03:52 ALM DISC UNACK_ALM	1 SPARE_d11846_F& F&G	FAULT/FAULT
Mar 15 01:03:52 ALM DISC UNACK_ALM	1 SPARE_d11847_F& F&G	FAULT/FAULT
Mar 15 01:03:52 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:03:52 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:03:53 RTN DISC ACK_RTN	1 GS53-HCA F&G	NORMA/ HIGH
Mar 15 01:03:56 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:03:56 RTN DISC ACK_RTN	1 SPARE_d11846_F& F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:03:57 RTN DISC ACK_RTN	1 SPARE_d11847_F& F&G	NORMA/FAULT
Mar 15 01:03:57 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:03:57 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:03:59 RTN DISC ACK_RTN	1 SPARE_d11810_F& F&G	NORMA/FAULT
Mar 15 01:04:01 ALM DISC UNACK_ALM	1 PT70007 F&G	ALARM/ALARM
Mar 15 01:04:01 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:04:01 ALM DISC UNACK_ALM	1 PT70032 F&G	ALARM/ALARM
Mar 15 01:04:04 ALM DISC UNACK_ALM	1 SPARE_d11810_F& F&G	FAULT/FAULT
Mar 15 01:04:04 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:04:04 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:04:04 ALM DISC UNACK_ALM	1 SPARE_d11846_F& F&G	FAULT/FAULT
Mar 15 01:04:04 ALM DISC UNACK_ALM	1 SPARE_d11847_F& F&G	FAULT/FAULT
Mar 15 01:04:05 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 01:04:05 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:04:05 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:04:06 RTN DISC ACK_RTN	1 PT70032 F&G	NORMA/ALARM
Mar 15 01:04:08 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:04:08 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:04:09 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:04:09 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:04:09 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:04:10 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:04:13 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:04:13 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:04:13 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:04:16 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:04:16 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:04:16 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 01:04:16 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:04:17 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:04:20 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:04:22 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:04:25 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:04:25 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:04:25 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:04:28 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:04:28 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:04:31 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:04:32 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:04:33 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:04:35 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:04:37 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:04:37 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:04:40 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:04:40 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:04:42 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:04:42 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:04:45 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:04:45 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:04:45 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:04:46 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:04:46 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:04:46 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:04:49 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:04:49 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:04:49 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:04:49 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:04:49 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:04:51 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:04:51 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:04:51 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:04:54 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:04:54 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:04:54 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:04:54 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:04:55 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:04:55 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:04:55 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:04:55 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:04:55 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:05:09 ALM DISC	1 PSL54231304	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:05:10 ALM DISC	1 XY54231302	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:05:10 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:05:12 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:12 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:12 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:12 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:12 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:05:19 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:19 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:19 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:05:24 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:05:31 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:05:31 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
Tribunal de Segurança Marítima



Mar 15 01:05:31 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:05:31 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 01:05:31 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:05:36 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:05:37 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:05:42 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:05:42 RTN DISC ACK_RTN	1 SPARE_d11851_F&	F&G	NORMA/FAULT
Mar 15 01:05:42 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:05:43 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:05:48 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:05:48 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:05:48 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:05:48 ALM DISC UNACK_ALM	1 SPARE_d11851_F&	F&G	FAULT/FAULT
Mar 15 01:05:48 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:05:49 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:05:54 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:05:54 RTN DISC ACK_RTN	1 SPARE_d11851_F&	F&G	NORMA/FAULT
Mar 15 01:05:54 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:05:55 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:05:55 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:06:00 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:06:00 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:06:00 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:06:00 ALM DISC UNACK_ALM	1 SPARE_d11851_F&	F&G	FAULT/FAULT
Mar 15 01:06:00 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:06:06 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:06:07 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:06:07 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM

É Cópia fiel do documento original.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 01:06:12 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:06:12 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:06:12 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:06:13 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:06:13 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:06:17 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:06:17 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:06:19 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:06:24 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:06:24 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:06:25 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:06:25 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:06:25 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:06:29 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:06:29 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:06:31 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:06:31 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:06:31 RTN DISC ACK_RTN	1 PT70031 F&G	NORMA/ALARM
Mar 15 01:06:31 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:06:35 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:06:35 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:06:35 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:06:36 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:06:37 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:06:37 ALM DISC UNACK_ALM	1 PT70031 F&G	ALARM/ALARM
Mar 15 01:06:37 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:06:41 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:06:41 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PAZINTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:06:41 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:06:41 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:06:43 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:06:47 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:06:47 ALM DISC UNACK_ALM	1 SPARE_d11833_F& F&G	FAULT/FAULT
Mar 15 01:06:47 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:06:48 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:06:49 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:06:49 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:06:52 ALM DISC UNACK_ALM	1 GS53-HCA_F F&G	FAULT/FAULT
Mar 15 01:06:52 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:06:52 ALM DISC UNACK_ALM	1 SPARE_d11851_F& F&G	FAULT/FAULT
Mar 15 01:06:52 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:06:53 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:06:56 RTN DISC ACK_RTN	1 GS53-HCA_F F&G	NORMA/FAULT
Mar 15 01:06:56 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:06:58 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:07:02 ALM DISC UNACK_ALM	1 A_4BAT F&G	ALARM/ALARM
Mar 15 01:07:05 RTN DISC ACK_RTN	1 PT70031 F&G	NORMA/ALARM
Mar 15 01:07:05 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:07:06 RTN DISC ACK_RTN	1 PT70033 F&G	NORMA/ALARM
Mar 15 01:07:06 ALM DISC UNACK_ALM	1 PT70316 F&G	ALARM/ALARM
Mar 15 01:07:08 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:07:10 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:07:10 ALM DISC UNACK_ALM	1 PT70035 F&G	ALARM/ALARM
Mar 15 01:07:10 ALM DISC UNACK_ALM	1 PT70031 F&G	ALARM/ALARM
Mar 15 01:07:10 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:07:10 ALM DISC UNACK_ALM	1 PT70033 F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:07:10 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:07:13 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:07:13 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:07:14 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:07:17 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:07:18 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:07:18 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:07:20 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:07:22 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:07:25 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:07:25 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:07:26 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:07:27 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:07:29 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:07:30 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:07:30 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:07:30 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:07:31 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:07:31 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:07:43 ALM DISC UNACK_ALM	1 XS70010A	F&G	RUNNI/RUNNI
Mar 15 01:07:43 ALM DISC UNACK_ALM	1 XS70010B	F&G	LOCAL/LOCAL
Mar 15 01:07:43 ALM DISC UNACK_ALM	1 PSL54231204	F&G	ALARM/ALARM
Mar 15 01:07:43 ALM DISC UNACK_ALM	1 XV70042B	F&G	CLOSE/CLOSE
Mar 15 01:07:45 RTN DISC ACK_RTN	1 PT70034_F	F&G	NORMA/FAULT
Mar 15 01:07:45 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:07:45 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:07:45 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:07:46 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:07:46 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:07:46 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:07:49 ALM DISC UNACK_ALM	1 SD06063	F&G	ALARM/ALARM
Mar 15 01:07:52 RTN DISC ACK_RTN	1 ZSC70042	F&G	NOT C/CLOSE
Mar 15 01:07:54 ALM DISC UNACK_ALM	1 XY54231202	F&G	ALARM/ALARM
Mar 15 01:07:54 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:07:54 RTN DISC ACK_RTN	1 SPARE_d11846_F&	F&G	NORMA/FAULT
Mar 15 01:07:55 ALM DISC UNACK_ALM	1 PT70032	F&G	ALARM/ALARM
Mar 15 01:07:58 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:07:58 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:07:58 ALM DISC UNACK_ALM	1 SPARE_d11846_F&	F&G	FAULT/FAULT
Mar 15 01:07:58 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:08:00 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:08:00 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:08:00 RTN DISC ACK_RTN	1 PT70032	F&G	NORMA/ALARM
Mar 15 01:08:03 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:08:03 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:08:03 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:08:04 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:08:07 ALM DISC UNACK_ALM	1 XV70042A-VD	F&G	DISCR/DISCR
Mar 15 01:08:09 ALM DISC UNACK_ALM	1 PT70034_F	F&G	FAULT/FAULT
Mar 15 01:08:09 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:08:09 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:08:09 RTN DISC ACK_RTN	1 SPARE_d11851_F&	F&G	NORMA/FAULT
Mar 15 01:08:09 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:08:10 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:08:13 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:08:13 ALM DISC UNACK_ALM	1 SPARE_d11851_F&	F&G	FAULT/FAULT

É CÓPIA FEITA DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAS



Mar 15 01:08:13 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:08:15 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:08:15 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:08:15 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 01:08:19 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:08:19 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:08:19 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 01:08:24 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:08:24 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 01:08:24 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 01:08:28 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:08:28 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:08:28 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 01:08:33 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:08:33 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 01:08:37 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:08:37 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:08:42 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 01:08:45 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:08:46 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 01:08:46 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:08:49 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:08:49 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:08:51 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:08:51 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:08:51 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:08:54 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:08:55 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:08:55 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:08:55 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:08:55 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:08:55 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:08:55 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:08:58 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:08:59 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:08:59 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:08:59 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:08:59 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:09:03 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:04 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:04 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:07 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:07 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:07 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:08 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:09:08 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:09:12 RTN DISC	1 XS70010A	F&G	NORMA/RUNNI
ACK_RTN			
Mar 15 01:09:12 RTN DISC	1 XV70042A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 01:09:13 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:13 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:13 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:14 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:28 RTN DISC	1 XS70010B	F&G	NORMA/LOCAL
ACK_RTN			
Mar 15 01:09:28 ALM DISC	1 XS70012B	F&G	LOCAL/LOCAL
UNACK_ALM			
Mar 15 01:09:28 RTN DISC	1 XV70042B	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 01:09:30 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
NÃO DE SER ARQUIVADO



Mar 15 01:09:30 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:30 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:31 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:31 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:44 ALM DISC	1 XS70012A	F&G	RUNNI/RUNNI
UNACK_ALM			
Mar 15 01:09:44 ALM DISC	1 XV70044B	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:09:46 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:46 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:46 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:47 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:09:53 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:09:53 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:55 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:09:59 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:09:59 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:10:01 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:10:01 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:10:01 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:10:05 ALM DISC	1 XV70044A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:10:07 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:10:10 ALM DISC	1 SD06055	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:10:16 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:10:16 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:10:16 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:10:16 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:10:20 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:10:21 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:10:27 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DE SERVIÇOS CARTORIAIS



Mar 15 01:10:27 ALM DISC UNACK_ALM	1 SPARE_d11851_F&	F&G	FAULT/FAULT
Mar 15 01:10:27 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:10:28 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:10:28 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:10:28 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:10:28 ALM DISC UNACK_ALM	2 PT70037	F&G	ALARM/ALARM
Mar 15 01:10:33 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:10:34 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:10:34 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:10:34 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:10:39 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:10:39 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:10:40 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:10:43 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:10:43 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:10:45 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:10:45 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:10:45 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 01:10:48 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:10:49 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:10:49 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:10:49 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:10:49 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 01:10:52 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:11:31 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 01:11:36 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:11:40 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:11:40 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PINHEIRO GUSMÃO
DIRETOR
DEPARTAMENTO DE SERVIÇOS CONTÁBILIS



Mar 15 01:12:10 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:12:12 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:12 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:12 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:12 RTN DISC	2 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:16 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:16 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:16 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:16 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:20 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:20 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:20 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:20 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:21 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:25 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:25 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:25 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:25 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:30 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:30 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:30 RTN DISC	2 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:34 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:34 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:34 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:12:38 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:38 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:38 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:12:43 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS POINTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:12:43 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:12:43 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:12:47 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:12:47 RTN DISC	1	PT70031	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:12:52 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:12:52 ALM DISC	1	PT70031	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:12:53 ALM DISC	1	SD06065	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:12:58 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:12:58 RTN DISC	1	PT70031	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:12:58 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:01 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:13:02 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:03 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:03 ALM DISC	1	PT70031	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:03 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:05 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:13:07 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:07 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:07 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:07 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:11 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:12 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:12 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:12 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:16 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:16 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:13:16 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:13:16 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PEREIRA GUSMÃO
DIR.



Mar 15 01:13:16 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:19 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:19 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:21 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:21 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:24 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:24 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:24 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:25 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:25 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:27 ALM DISC	1 SD06014	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:30 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:30 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:31 RTN DISC	1 PT70031	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:31 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:34 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:36 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:36 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:36 ALM DISC	1 PT70031	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:36 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:40 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:40 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:40 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:40 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:45 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:45 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:45 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:45 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:13:48 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:48 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:49 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:49 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:49 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:49 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:52 RTN DISC	1 GS19-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:52 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:52 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:13:54 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:54 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:54 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:13:57 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:57 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:57 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:57 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:13:58 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:13:58 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:01 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:01 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:01 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:01 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:03 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:03 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:03 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:06 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:06 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:06 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS MONTIEL GUERRA
DIRETOR
CENTRO DE PESQUISA E DESENVOLVIMENTO



Mar 15 01:14:06 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:07 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:07 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:07 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:10 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:10 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:10 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:10 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:10 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:12 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:12 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:15 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:15 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:15 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:15 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:16 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:16 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:14:19 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:19 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:19 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:19 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:19 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:14:21 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:21 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:14:24 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:24 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:24 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:14:25 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			

COPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 01:14:25 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:14:28 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:14:28 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:14:28 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:14:30 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:14:34 RTN DISC ACK_RTN	1 XS70012A	F&G	NORMA/RUMNI
Mar 15 01:14:34 RTN DISC ACK_RTN	1 XV70044A-VD	F&G	NORMA/DISCR
Mar 15 01:14:36 ALM DISC UNACK_ALM	1 GS19-HCB_F	F&G	FAULT/FAULT
Mar 15 01:14:37 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:14:37 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:14:37 RTN DISC ACK_RTN	1 PT70031	F&G	NORMA/ALARM
Mar 15 01:14:37 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:14:37 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 01:14:40 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:14:40 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:14:42 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:14:42 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:14:42 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:14:42 ALM DISC UNACK_ALM	1 PT70031	F&G	ALARM/ALARM
Mar 15 01:14:42 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:14:42 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:14:45 RTN DISC ACK_RTN	1 GS19-HCB_F	F&G	NORMA/FAULT
Mar 15 01:14:45 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:14:45 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:14:45 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:14:46 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:14:46 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:14:49 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PEREIRA GUESSÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 01:14:49 RTN DISC	1 SPARE_d11828_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:14:49 ALM DISC	1 SPARE_d11857_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:14:51 ALM DISC	1 PT70007 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:14:51 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:14:54 ALM DISC	1 SPARE_d11817_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:14:54 ALM DISC	1 SPARE_d11828_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:14:55 RTN DISC	1 PT70007 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:14:55 RTN DISC	1 PT70034 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:14:58 RTN DISC	1 SPARE_d11817_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:14:58 RTN DISC	1 SPARE_d11828_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:00 ALM DISC	1 PT70007 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:15:00 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:15:03 ALM DISC	1 SPARE_d11817_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:03 ALM DISC	1 SPARE_d11828_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:03 RTN DISC	1 SPARE_d11833_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:03 RTN DISC	1 SPARE_d11857_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:04 RTN DISC	1 PT70007 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:15:04 RTN DISC	1 PT70034 F&G	NORMA/ALARM
ACK_RTN		
Mar 15 01:15:07 RTN DISC	1 SPARE_d11817_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:07 RTN DISC	1 SPARE_d11828_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:07 ALM DISC	1 SPARE_d11833_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:07 ALM DISC	1 SPARE_d11857_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:09 ALM DISC	1 PT70007 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:15:09 ALM DISC	1 PT70034 F&G	ALARM/ALARM
UNACK_ALM		
Mar 15 01:15:12 ALM DISC	1 SPARE_d11817_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:12 ALM DISC	1 SPARE_d11828_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:15:12 RTN DISC	1 SPARE_d11833_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:15:12 RTN DISC	1 SPARE_d11857_F& F&G	NORMA/FAULT
ACK_RTN		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS PIMENTEL GUEDES
OAB 11.111



Mar 15 01:15:13 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:15:13 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:15:16 RTN DISC ACK_RTN	2 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:15:16 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:15:16 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:15:16 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:15:18 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:15:18 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:15:21 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:15:21 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:15:21 RTN DISC ACK_RTN	1 SPARE_d11833_F&	F&G	NORMA/FAULT
Mar 15 01:15:21 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:15:22 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:15:25 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:15:25 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:15:25 ALM DISC UNACK_ALM	1 SPARE_d11833_F&	F&G	FAULT/FAULT
Mar 15 01:15:25 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:15:27 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:15:27 ALM DISC UNACK_ALM	1 PT70030	F&G	ALARM/ALARM
Mar 15 01:15:30 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:15:30 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:15:31 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:15:31 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:15:31 RTN DISC ACK_RTN	2 PT70030	F&G	NORMA/ALARM
Mar 15 01:15:34 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:15:34 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:15:35 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:15:35 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:15:39 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:15:39 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:15:39 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:15:40 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 01:15:40 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:15:43 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:15:43 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:15:43 ALM DISC UNACK_ALM	1 SPARE_d11857_F& F&G	FAULT/FAULT
Mar 15 01:15:44 ALM DISC UNACK_ALM	1 PT70007 F&G	ALARM/ALARM
Mar 15 01:15:44 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:15:48 ALM DISC UNACK_ALM	1 SPARE_d11817_F& F&G	FAULT/FAULT
Mar 15 01:15:48 ALM DISC UNACK_ALM	1 SPARE_d11828_F& F&G	FAULT/FAULT
Mar 15 01:15:49 RTN DISC ACK_RTN	1 PT70007 F&G	NORMA/ALARM
Mar 15 01:15:49 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:15:49 RTN DISC ACK_RTN	1 PT70035 F&G	NORMA/ALARM
Mar 15 01:15:49 RTN DISC ACK_RTN	1 PT70037 F&G	NORMA/ALARM
Mar 15 01:15:53 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:15:54 RTN DISC ACK_RTN	1 PT70033 F&G	NORMA/ALARM
Mar 15 01:15:54 ALM DISC UNACK_ALM	1 PT70316 F&G	ALARM/ALARM
Mar 15 01:15:58 RTN DISC ACK_RTN	1 PT70034 F&G	NORMA/ALARM
Mar 15 01:15:58 ALM DISC UNACK_ALM	1 PT70037 F&G	ALARM/ALARM
Mar 15 01:15:58 ALM DISC UNACK_ALM	1 PT70033 F&G	ALARM/ALARM
Mar 15 01:15:58 RTN DISC ACK_RTN	1 PT70316 F&G	NORMA/ALARM
Mar 15 01:16:01 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:16:01 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:16:02 ALM DISC UNACK_ALM	1 PT70007 F&G	ALARM/ALARM
Mar 15 01:16:03 ALM DISC UNACK_ALM	1 PT70034 F&G	ALARM/ALARM
Mar 15 01:16:03 ALM DISC UNACK_ALM	1 PT70030 F&G	ALARM/ALARM

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:16:03 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:16:03 ALM DISC UNACK_ALM	1 PT70032	F&G	ALARM/ALARM
Mar 15 01:16:06 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:16:06 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:16:06 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:16:07 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:16:07 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:16:07 RTN DISC ACK_RTN	1 PT70030	F&G	NORMA/ALARM
Mar 15 01:16:07 RTN DISC ACK_RTN	1 PT70032	F&G	NORMA/ALARM
Mar 15 01:16:10 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:16:10 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:16:10 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:16:12 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:16:15 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:16:15 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:16:15 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT
Mar 15 01:16:16 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:16:19 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:16:19 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:16:19 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:16:21 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:16:21 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:16:24 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:16:24 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:16:25 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:16:25 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:16:28 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:16:28 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL!

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:16:30 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:30 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:33 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:33 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:33 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:33 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:34 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:16:34 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:16:34 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:16:37 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:37 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:37 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:39 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:39 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:39 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:42 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:42 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:43 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:16:43 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:16:46 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:46 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:46 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:48 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:48 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:51 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:51 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:16:51 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:52 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			

É Cópia fiel do documento original

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
ÁREA DE SERVIÇOS CARTORIAIS



Mar 15 01:16:54 ALM DISC	1 SD06005	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:16:57 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:16:57 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:01 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:01 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:01 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:04 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:04 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:07 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:07 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:07 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:10 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:10 RTN DISC	1 SPARE_d11840_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:10 RTN DISC	1 SPARE_d11846_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:10 RTN DISC	1 SPARE_d11847_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:10 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:10 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:12 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:12 ALM DISC	1 PT70030	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:12 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:15 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:15 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:15 ALM DISC	1 SPARE_d11840_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:15 ALM DISC	1 SPARE_d11846_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:15 ALM DISC	1 SPARE_d11847_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:15 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:15 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:16 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 01:17:16 RTN DISC	1 PT70030	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:16 RTN DISC	1 PT70032	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:19 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:19 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:19 RTN DISC	1 SPARE_d11833_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:19 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:19 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:21 ALM DISC	1 PT70007	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:24 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:24 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:24 ALM DISC	1 SPARE_d11833_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:24 RTN DISC	1 SPARE_d11851_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:24 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:25 RTN DISC	1 PT70007	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:28 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:28 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:28 ALM DISC	1 SPARE_d11851_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:28 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:30 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:30 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:30 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:33 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:17:34 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:34 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:34 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:17:34 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:17:37 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:17:39 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			

É CÚPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
COMISSÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:17:39 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:17:39 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:17:39 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 01:17:42 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:17:43 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:17:43 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:17:43 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:17:43 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:17:46 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:17:48 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:17:48 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:17:48 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:17:48 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:17:51 RTN DISC ACK_RTN	1 SPARE_d11817_F&	F&G	NORMA/FAULT
Mar 15 01:17:51 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:17:52 RTN DISC ACK_RTN	1 PT70007	F&G	NORMA/ALARM
Mar 15 01:17:52 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:17:52 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:17:52 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:17:54 ALM DISC UNACK_ALM	1 SD07048	F&G	ALARM/ALARM
Mar 15 01:17:57 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 01:17:57 ALM DISC UNACK_ALM	1 SPARE_d11828_F&	F&G	FAULT/FAULT
Mar 15 01:17:58 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:17:58 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:18:01 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 01:18:01 ALM DISC UNACK_ALM	1 SPARE_d11817_F&	F&G	FAULT/FAULT
Mar 15 01:18:01 RTN DISC ACK_RTN	1 SPARE_d11828_F&	F&G	NORMA/FAULT
Mar 15 01:18:01 RTN DISC ACK_RTN	1 SPARE_d11857_F&	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 01:18:03 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:06 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:06 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:06 ALM DISC	1 SPARE_d11857_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:09 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:10 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:13 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:13 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:15 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:15 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:15 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:18 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:19 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:19 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:19 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:21 ALM DISC	1 SD07100	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:25 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:28 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:28 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:30 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:30 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:18:33 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:33 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:34 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:34 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:18:37 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:18:37 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:18:39 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:18:39 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:42 ALM DISC	1	GS19-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:18:42 ALM DISC	1	SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:18:43 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:43 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:43 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:43 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:43 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:46 RTN DISC	1	GS19-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:18:48 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:48 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:48 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:48 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:48 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:51 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:18:52 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:52 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:52 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:52 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:18:55 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:18:57 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:57 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:18:57 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:00 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:01 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:01 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:01 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:04 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS POIRETEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:19:06 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:06 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:06 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:06 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:09 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:10 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:10 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:10 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:10 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:13 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:19:15 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:15 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:15 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:18 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:19 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:19 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:19 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:22 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:19:24 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:24 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:24 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:24 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:27 ALM DISC	1	GS19-HCB_F	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:19:27 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:28 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:28 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:28 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:28 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				

É CÔPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:19:31 RTN DISC	1	GS19-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:31 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:19:33 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:33 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:33 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:33 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:37 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:37 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:37 RTN DISC	1	PT70033	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:37 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:42 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:42 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:42 ALM DISC	1	PT70033	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:42 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:45 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:46 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:46 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:46 RTN DISC	1	PT70037	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:46 ALM DISC	1	PT70316	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:49 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				
Mar 15 01:19:51 RTN DISC	1	PT70034	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:51 RTN DISC	1	PT70035	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:51 ALM DISC	1	PT70037	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:51 RTN DISC	1	PT70316	F&G	NORMA/ALARM
ACK_RTN				
Mar 15 01:19:54 RTN DISC	1	SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:19:55 ALM DISC	1	PT70034	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:55 ALM DISC	1	PT70035	F&G	ALARM/ALARM
UNACK_ALM				
Mar 15 01:19:58 ALM DISC	1	SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:19:58 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:00 RTN DISC	3 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:03 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:03 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:04 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:04 RTN DISC	1 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:04 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:07 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:09 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:09 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:09 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:12 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:13 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:13 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:13 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:16 ALM DISC	2 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:16 RTN DISC	2 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:18 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:18 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:18 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:18 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:21 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:21 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:22 ALM DISC	3 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:22 RTN DISC	2 PT70037	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:22 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:22 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:25 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:20:25 RTN DISC	1 SPARE_d11828_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:27 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:27 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:27 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:30 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:30 ALM DISC	1 SPARE_d11828_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:31 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:31 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:31 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:31 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:34 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:36 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:36 RTN DISC	1 PT70035	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:36 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:36 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:39 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:40 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:40 ALM DISC	1 PT70035	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:40 ALM DISC	1 PT70316	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:43 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:45 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:45 ALM DISC	1 PT70037	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:45 RTN DISC	1 PT70316	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:20:48 RTN DISC	1 SPARE_d11817_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:49 ALM DISC	1 PT70034	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:20:52 ALM DISC	1 SPARE_d11817_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:20:52 RTN DISC	1 SPARE_d11857_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:20:54 RTN DISC	1 PT70034	F&G	NORMA/ALARM
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:20:57 ALM DISC UNACK_ALM	1 SPARE_d11857_F&	F&G	FAULT/FAULT
Mar 15 01:20:58 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:20:58 RTN DISC ACK_RTN	1 PT70035	F&G	NORMA/ALARM
Mar 15 01:20:58 RTN DISC ACK_RTN	1 PT70037	F&G	NORMA/ALARM
Mar 15 01:20:58 RTN DISC ACK_RTN	1 PT70033	F&G	NORMA/ALARM
Mar 15 01:20:58 ALM DISC UNACK_ALM	1 PT70316	F&G	ALARM/ALARM
Mar 15 01:21:03 RTN DISC ACK_RTN	1 PT70034	F&G	NORMA/ALARM
Mar 15 01:21:03 ALM DISC UNACK_ALM	1 PT70037	F&G	ALARM/ALARM
Mar 15 01:21:03 ALM DISC UNACK_ALM	1 PT70033	F&G	ALARM/ALARM
Mar 15 01:21:03 RTN DISC ACK_RTN	1 PT70316	F&G	NORMA/ALARM
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70007_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70034_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70030_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70035_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70031_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70032_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70037_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 PT70033_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS1705_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS1706_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS1707_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS1711_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS1712_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 SPARE_d11607_F&	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS2802_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS07-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS09-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:06 RTN DISC ACK_RTN	1 GS11-HCA_F	F&G	NORMA/FAULT

É Cópia do Documento Original.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:21:06 RTN DISC	1 SPARE_d11612_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS21-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS23-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS26-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 SPARE_d11617_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS2301_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS07-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS09-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS11-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:06 RTN DISC	1 GS14G-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS16-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 SPARE_d11626_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS16-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS20-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS22-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS24-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS2801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS06-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	2 GS08-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS10-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 SPARE_d11636_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS15-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	2 GS18-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS20-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS22-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS24-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:07 RTN DISC	1 GS27-HCA_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS POZENTEL GUSMÃO
DIRETOR
DEPARTAMENTO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS37-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS44-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS56A-HC_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS60-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS44-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS56B-HC_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS63-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS33-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS47-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS63-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS2902_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS38-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS40-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS45-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS47-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS1316_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS2903_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS1501_F	F&G	NORMA/FAULT
Mar 15 01:21:07 RTN DISC ACK_RTN	1 GS1503_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS67-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS68-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS2306_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS2401_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS1709_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS2904_F	F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 GS2906_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS PAGNIEL GUSMÃO
DIRETOR
SERV. DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:21:08 RTN DISC	1	GS1502_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS67-HCA_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS68-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS2804_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS2905_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS2403_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS1315_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS1309_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS70-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS72-HCA_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS72-HCB_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	GS2404_F	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11799_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11800_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11801_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11802_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11803_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11804_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11805_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11806_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11807_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11808_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11809_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11810_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11811_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11812_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11813_F&	F&G	NORMA/FAULT
ACK_RTN				
Mar 15 01:21:08 RTN DISC	1	SPARE_d11814_F&	F&G	NORMA/FAULT
ACK_RTN				

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 01:21:08 RTN DISC ACK_RTN	1 SPARE_d11815_F& F&G	NORMA/FAULT
Mar 15 01:21:08 RTN DISC ACK_RTN	1 SPARE_d11816_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11817_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11818_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11819_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11820_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11821_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11851_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11852_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11853_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11854_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11855_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11856_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11857_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11858_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11859_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11860_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11861_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11862_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11863_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11864_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11865_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11866_P& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11867_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11868_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11869_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11870_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11871_F& F&G	NORMA/FAULT

É Cópia fiel do documento original.

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11872_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11873_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11874_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11875_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11876_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11877_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11878_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11879_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11880_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11881_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11882_F& F&G	NORMA/FAULT
Mar 15 01:21:09 RTN DISC ACK_RTN	1 SPARE_d11883_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11884_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11885_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11886_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11887_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11888_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11889_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11890_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11891_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11900_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11901_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11902_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11903_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11904_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11905_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11906_F& F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11907_F& F&G	NORMA/FAULT

É Cópia Fiel do Documento Original
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11908_F&	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11909_F&	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11910_F&	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 SPARE_d11911_F&	F&G	NORMA/FAULT
Mar 15 01:21:10 ALM DISC UNACK_ALM	1 PT70007	F&G	ALARM/ALARM
Mar 15 01:21:10 ALM DISC UNACK_ALM	1 PT70034	F&G	ALARM/ALARM
Mar 15 01:21:10 ALM DISC UNACK_ALM	1 PT70030	F&G	ALARM/ALARM
Mar 15 01:21:10 ALM DISC UNACK_ALM	1 PT70035	F&G	ALARM/ALARM
Mar 15 01:21:10 ALM DISC UNACK_ALM	1 PT70032	F&G	ALARM/ALARM
Mar 15 01:21:10 RTN DISC ACK_RTN	1 GS2803_F	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 GS06-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 GS08-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:10 RTN DISC ACK_RTN	1 GS10-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 SPARE_d11647_F&	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS15-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS17-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS27-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 SPARE_d11651_F&	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1710_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS14F-HC_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS15-HCC_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS17-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS19-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS23-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 SPARE_d11659_F&	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS28-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS36-HCA_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS38-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS43-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS45-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS47-HCC_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS55B-HC_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1301_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1317_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS2302_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS28-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS34-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS36-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS41-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS43-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1302_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1318_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS1814_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS2303_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS32-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS34-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS39-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:11 RTN DISC ACK_RTN	1 GS51-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:12 RTN DISC ACK_RTN	1 GS1303_F	F&G	NORMA/FAULT
Mar 15 01:21:12 RTN DISC ACK_RTN	1 GS60-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:12 RTN DISC ACK_RTN	1 GS29-HCA_F	F&G	NORMA/FAULT
Mar 15 01:21:12 RTN DISC ACK_RTN	1 GS32-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:12 RTN DISC ACK_RTN	1 GS39-HCB_F	F&G	NORMA/FAULT
Mar 15 01:21:12 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS MOURA DE OLIVEIRA
DEPUTADO
PÚBLICO DE SÃO PAULO



Mar 15 01:21:12	RTN DISC	1	GS29-HCB_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS35-HCA_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS37-HCB_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS42-HCA_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS2901_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS35-HCB_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS40-HCA_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS42-HCB_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS31-HCA_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS33-HCB_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS55A-HC_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1801_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1812_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1806_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1701_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1310_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1304_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1313_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1307_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1319_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS71-HCA_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1802_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1805_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1708_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1807_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1702_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1311_F	F&G	NORMA/FAULT
ACK RTN					
Mar 15 01:21:12	RTN DISC	1	GS1305_F	F&G	NORMA/FAULT
ACK RTN					

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.



Mar 15 01:21:12 RTN DISC	1 GS1314_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:12 RTN DISC	1 GS1308_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:12 RTN DISC	1 GS1320_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:12 RTN DISC	1 GS70-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:12 RTN DISC	1 GS71-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:12 RTN DISC	1 GS1808_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1703_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1312_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1306_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1321_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS69-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 MD-TX15-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1811_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1813_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1704_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 MD-TX69-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS69-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1322_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1323_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 GS1324_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11822_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11823_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11824_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11825_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11826_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:13 RTN DISC	1 SPARE_d11827_F&	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAF



Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11828_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11829_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11830_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11831_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11832_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11833_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11834_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11835_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11836_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11837_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11838_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11839_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11840_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11841_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11842_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11843_F& F&G	NORMA/FAULT
Mar 15 01:21:13 RTN DISC ACK_RTN	1 SPARE_d11844_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11845_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11846_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11847_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11848_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11849_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11850_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11892_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11893_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11894_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11895_F& F&G	NORMA/FAULT
Mar 15 01:21:14 RTN DISC ACK_RTN	1 SPARE_d11896_F& F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUEDES
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFAS



Mar 15 01:21:14 RTN DISC	1 SPARE_d11897_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:14 RTN DISC	1 SPARE_d11898_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:14 RTN DISC	1 SPARE_d11899_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:15 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:21:19 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:21:24 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:21:46 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:21:51 ALM DISC	1 PT70032_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:21:51 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:24:19 RTN DISC	1 PT70033	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:24:24 ALM DISC	1 PT70033	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:24:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:24:55 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:26:18 ALM DISC	1 ZSC70044	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:26:31 ALM DISC	1 XS70012A	F&G	RUNNI/RUNNI
UNACK_ALM			
Mar 15 01:26:36 RTN DISC	1 XS70012A	F&G	NORMA/RUNNI
ACK_RTN			
Mar 15 01:26:40 RTN DISC	1 ZSC70044	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 01:26:46 ALM DISC	1 ZSC70044	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:26:55 RTN DISC	1 ZSO70044	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:27:12 ALM DISC	1 ZSO70044	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:27:19 RTN DISC	1 ZSC70044	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 01:31:46 RTN DISC	1 XS70011C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:31:46 ALM DISC	1 XS70520C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 01:31:46 RTN DISC	1 XS70520D	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:31:46 RTN DISC	1 XS70013C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:31:46 RTN DISC	1 XV70043B	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 01:32:00 ALM DISC	1 ZSO70569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:32:00 ALM DISC	1 ZSO70570B	F&G	OPEN/ OPEN
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS DE SOUZA
PROCURADOR
MARITIMO E COMERCIAL



Mar 15 01:32:00 ALM DISC	1 XS70520B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 01:32:00 RTN DISC	1 XS70520C	F&G	NORMA/LOW S
ACK_RTN			
Mar 15 01:32:00 ALM DISC	1 XV70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:32:00 ALM DISC	1 XV70570A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:32:07 RTN DISC	1 ZSC70569A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 01:32:07 RTN DISC	1 XV70569A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 01:32:12 ALM DISC	1 XV70570A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:32:30 RTN DISC	1 XS70004A	F&G	STOPP/RUMNI
ACK_RTN			
Mar 15 01:32:30 ALM DISC	1 XS70004C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XS70010C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XS70011C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 RTN DISC	1 XS70519B	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 01:32:30 ALM DISC	1 XS70519D	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XS70012C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 RTN DISC	1 XS70520B	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 01:32:30 ALM DISC	1 XS70520D	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XS70013C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XV70042B	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XV70569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:32:30 RTN DISC	1 XV70570A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 01:32:30 ALM DISC	1 XV70570B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:32:30 ALM DISC	1 XV70043B	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:32:30 RTN DISC	1 XCV53004-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 01:32:30 RTN DISC	1 XV70570A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 01:32:40 ALM DISC	1 XV70569B-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:32:40 ALM DISC	1 XV70570B-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:32:54 RTN DISC	1 SPARE_d11511_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:32:54 RTN DISC	1 SPARE_d11517_F&	F&G	NORMA/FAULT
ACK_RTN			

É Cópia fiel do documento original.

JOSE CARLOS PINHEIRO GOMES
07/07/2011
DIVISÃO DE RESERVA DE COMANDANTES



Mar 15 01:32:54 RTN DISC	1 SPARE_d11518_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:32:54 RTN DISC	1 SPARE_d11519_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:00 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:00 ALM DISC	1 SPARE_d11517_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:00 ALM DISC	1 SPARE_d11518_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:09 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:18 RTN DISC	1 SPARE_d11517_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:18 RTN DISC	1 SPARE_d11518_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:21 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:21 ALM DISC	1 SPARE_d11517_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:21 ALM DISC	1 SPARE_d11518_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:21 ALM DISC	1 SPARE_d11519_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:27 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:27 RTN DISC	1 SPARE_d11519_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:30 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:30 ALM DISC	1 SPARE_d11519_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:37 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:41 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:55 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:55 RTN DISC	1 SPARE_d11519_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:33:58 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:33:58 ALM DISC	1 SPARE_d11519_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:34:04 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:34:07 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:34:13 RTN DISC	1 SPARE_d11511_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:34:13 RTN DISC	1 SPARE_d11519_F& F&G	NORMA/FAULT
ACK_RTN		
Mar 15 01:34:16 ALM DISC	1 SPARE_d11511_F& F&G	FAULT/FAULT
UNACK_ALM		
Mar 15 01:34:16 ALM DISC	1 SPARE_d11519_F& F&G	FAULT/FAULT
UNACK_ALM		

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSE CARLOS MENDONÇA GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:34:27 RTN DISC ACK_RTN	1 SPARE_d11511_F& F&G	NORMA/FAULT
Mar 15 01:34:27 RTN DISC ACK_RTN	1 SPARE_d11519_F& F&G	NORMA/FAULT
Mar 15 01:34:30 ALM DISC UNACK_ALM	1 SPARE_d11511_F& F&G	FAULT/FAULT
Mar 15 01:34:30 ALM DISC UNACK_ALM	1 SPARE_d11519_F& F&G	FAULT/FAULT
Mar 15 01:34:36 RTN DISC ACK_RTN	1 SPARE_d11511_F& F&G	NORMA/FAULT
Mar 15 01:34:39 ALM DISC UNACK_ALM	1 SPARE_d11511_F& F&G	FAULT/FAULT
Mar 15 01:34:42 RTN DISC ACK_RTN	1 SPARE_d11511_F& F&G	NORMA/FAULT
Mar 15 01:34:42 RTN DISC ACK_RTN	1 SPARE_d11517_F& F&G	NORMA/FAULT
Mar 15 01:34:42 RTN DISC ACK_RTN	1 SPARE_d11518_F& F&G	NORMA/FAULT
Mar 15 01:34:42 RTN DISC ACK_RTN	1 SPARE_d11519_F& F&G	NORMA/FAULT
Mar 15 01:34:45 ALM DISC UNACK_ALM	1 SPARE_d11511_F& F&G	FAULT/FAULT
Mar 15 01:34:45 ALM DISC UNACK_ALM	1 SPARE_d11517_F& F&G	FAULT/FAULT
Mar 15 01:34:45 ALM DISC UNACK_ALM	1 SPARE_d11518_F& F&G	FAULT/FAULT
Mar 15 01:34:45 ALM DISC UNACK_ALM	1 SPARE_d11519_F& F&G	FAULT/FAULT
Mar 15 01:34:45 ALM DISC UNACK_ALM	1 GS2405_F F&G	FAULT/FAULT
Mar 15 01:34:48 RTN DISC ACK_RTN	1 GS2405_F F&G	NORMA/FAULT
Mar 15 01:34:51 RTN DISC ACK_RTN	1 SPARE_d11518_F& F&G	NORMA/FAULT
Mar 15 01:34:51 RTN DISC ACK_RTN	1 SPARE_d11519_F& F&G	NORMA/FAULT
Mar 15 01:34:54 ALM DISC UNACK_ALM	1 SPARE_d11518_F& F&G	FAULT/FAULT
Mar 15 01:34:54 ALM DISC UNACK_ALM	1 SPARE_d11519_F& F&G	FAULT/FAULT
Mar 15 01:35:00 RTN DISC ACK_RTN	1 SPARE_d11518_F& F&G	NORMA/FAULT
Mar 15 01:35:00 RTN DISC ACK_RTN	1 SPARE_d11519_F& F&G	NORMA/FAULT
Mar 15 01:35:03 ALM DISC UNACK_ALM	1 SPARE_d11518_F& F&G	FAULT/FAULT
Mar 15 01:35:03 ALM DISC UNACK_ALM	1 SPARE_d11519_F& F&G	FAULT/FAULT
Mar 15 01:35:09 RTN DISC ACK_RTN	1 SPARE_d11519_F& F&G	NORMA/FAULT
Mar 15 01:35:12 ALM DISC UNACK_ALM	1 SPARE_d11519_F& F&G	FAULT/FAULT
Mar 15 01:36:15 ALM DISC UNACK_ALM	1 GS2405_F F&G	FAULT/FAULT
Mar 15 01:36:19 RTN DISC ACK_RTN	1 GS2405_F F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS RIBEIRO ASSIS
Data: 05/03/2015



Mar 15 01:36:33 RTN DISC	1 SPARE_d11511_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:36:33 RTN DISC	1 SPARE_d11517_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:36:33 RTN DISC	1 SPARE_d11518_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:36:33 RTN DISC	1 SPARE_d11519_F&	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:36:36 ALM DISC	1 SPARE_d11511_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:36:36 ALM DISC	1 SPARE_d11517_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:36:36 ALM DISC	1 SPARE_d11518_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:36:36 ALM DISC	1 SPARE_d11519_F&	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:36:36 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:36:48 RTN DISC	1 XS70004C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:36:48 ALM DISC	1 ZSC70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:36:48 RTN DISC	1 ZSO70569B	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:36:48 ALM DISC	1 XS70519C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 01:36:48 RTN DISC	1 XS70519D	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:36:48 RTN DISC	1 XS70012C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 01:36:48 RTN DISC	1 XV70569B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 01:36:48 RTN DISC	1 XV70569B-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 01:36:49 ALM DISC	1 XZ70519	F&G	START/START
UNACK_ALM			
Mar 15 01:36:49 ALM DISC	1 XV53044	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:36:49 ALM DISC	1 XV53047	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:36:49 ALM DISC	1 XV53051	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:36:49 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:36:57 ALM DISC	1 XS70519B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 01:36:57 RTN DISC	1 XS70519C	F&G	NORMA/LOW S
ACK_RTN			
Mar 15 01:37:08 ALM DISC	1 WWStatPortTGSec	\$\$System	FAILE/FAILE
UNACK_ALM			
Mar 15 01:37:09 RTN DISC	1 ZSO70570B	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:37:09 RTN DISC	1 XV70570B	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 01:37:09 RTN DISC	1 XV70570B-VD	F&G	NORMA/DISCR
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS POMERLE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 15 01:37:10 ALM DISC	1 XCV53004	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:37:24 ALM DISC	1 XCV53004-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:39:01 RTN DISC	1 XZ70519	F&G	NORMA/START
ACK_RTN			
Mar 15 01:39:02 RTN DISC	1 XV53044	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:39:02 RTN DISC	1 XV53047	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:39:02 RTN DISC	1 XV53051	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:39:02 RTN DISC	1 XCV53004	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:39:02 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:39:06 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:41:16 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:41:21 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:42:12 RTN DISC	1 VWStatPortTGSec \$System		HEALT/FAILE
ACK_RTN			
Mar 15 01:43:36 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:43:40 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:43:43 ALM DISC	1 ZSC70044	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:43:43 ALM DISC	1 PSL54231404	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:43:52 RTN DISC	1 ZSO70044	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:44:07 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:44:10 ALM DISC	1 ZSO70044	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:44:12 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:44:25 ALM DISC	1 PSL54231504	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:44:31 RTN DISC	1 ZSO70044	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:44:46 ALM DISC	1 ZSO70044	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:44:54 RTN DISC	1 ZSO70044	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:45:01 ALM DISC	1 ZSO70044	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 01:45:09 RTN DISC	1 ZSC70044	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 01:45:29 ALM DISC	1 PSL54231104	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:48:23 RTN DISC	1 XS70519B	F&G	NORMA/HIGH
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
PROFESSOR
UNIAO DE SERVICOS CARTEIRAS



Mar 15 01:48:23 RTN DISC	1 XCV53004-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 01:48:24 ALM DISC	1 XZ70519	F&G	START/START
UNACK_ALM			
Mar 15 01:48:24 ALM DISC	1 XV53044	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:48:24 ALM DISC	1 XV53047	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:48:24 ALM DISC	1 XV53051	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 01:48:24 ALM DISC	1 XY54231102	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:48:24 ALM DISC	1 XY54231502	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 01:48:38 ALM DISC	1 XS70519C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 01:48:51 ALM DISC	1 XS70519B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 01:48:51 RTN DISC	1 XS70519C	F&G	NORMA/LOW S
ACK_RTN			
Mar 15 01:49:08 ALM DISC	1 XCV53004-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 01:49:31 RTN DISC	1 XZ70519	F&G	NORMA/START
ACK_RTN			
Mar 15 01:49:31 RTN DISC	1 XV53044	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:49:31 RTN DISC	1 XV53047	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:49:31 RTN DISC	1 XV53051	F&G	DE-EN/ENERG
ACK_RTN			
Mar 15 01:49:31 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:49:36 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:49:54 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:49:58 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:50:57 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:51:02 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:53:21 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:53:26 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:53:30 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:53:34 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:54:30 ALM DISC	1 GS53-HCB	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 01:54:30 ALM DISC	1 GS53-HCB_HH	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 01:54:33 RTN DISC	1 GS53-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 01:54:41 ALM DISC	1 GS53-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:55:03 RTN DISC	1 GS53-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:55:11 RTN DISC	1 GS53-HCB_HH	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 01:55:37 RTN DISC	1 ZS0605-06	F&G	OFF/ ON
ACK_RTN			
Mar 15 01:55:45 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:55:46 RTN DISC	1 GS53-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 01:55:50 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:55:52 ALM DISC	1 ZS0605-06	F&G	ON/ ON
UNACK_ALM			
Mar 15 01:56:07 RTN DISC	1 ZS0605-06	F&G	OFF/ ON
ACK_RTN			
Mar 15 01:56:40 ALM DISC	1 ZSC70044	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 01:56:56 RTN DISC	1 ZSO70044	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 01:57:06 RTN DISC	1 XS70702	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:57:06 RTN DISC	1 XS72009	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:57:06 RTN DISC	1 XS72008	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:57:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:57:11 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 01:58:50 RTN DISC	1 XS70701	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:58:50 RTN DISC	1 XS70704	F&G	NORMA/ALARM
ACK_RTN			
Mar 15 01:58:50 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 01:58:54 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:02:06 ALM DISC	1 GS53-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:03:15 RTN DISC	1 XS70011C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 02:03:15 ALM DISC	1 ZSO70569B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:03:15 ALM DISC	1 XS70520B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 02:03:15 RTN DISC	1 XS70520D	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 02:03:15 ALM DISC	1 XV70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 02:03:15 ALM DISC	1 XV70570A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 02:03:15 RTN DISC	1 XV70043B	F&G	NORMA/CLOSE
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 02:03:26 RTN DISC	1 ZSC70569A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 02:03:26 ALM DISC	1 ZS070570B	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:03:26 RTN DISC	1 XV70569A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 02:03:26 ALM DISC	1 XV70570A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 02:03:38 ALM DISC	1 XS70011A	F&G	RUMNI/RUMNI
UNACK_ALM			
Mar 15 02:03:38 ALM DISC	1 ZS0702-03	F&G	ON/ ON
UNACK_ALM			
Mar 15 02:03:38 RTN DISC	1 ZSC70570A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 02:03:38 RTN DISC	1 XV70570A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 02:03:38 ALM DISC	1 XV70043A	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:03:38 RTN DISC	1 XV70570A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 02:03:39 ALM DISC	1 XZ70520	F&G	START/START
UNACK_ALM			
Mar 15 02:03:39 ALM DISC	1 XV53017	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:03:39 ALM DISC	1 XV53020	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:03:39 ALM DISC	1 XV53023	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:03:39 ALM DISC	1 XCV53002	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:03:39 RTN DISC	1 GS18-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:03:44 ALM DISC	1 ZSC70043	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 02:03:45 ALM DISC	1 GS18-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:03:50 RTN DISC	1 ZS070043	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:03:50 RTN DISC	1 XV70043A	F&G	NORMA/ OPEN
ACK_RTN			
Mar 15 02:04:27 RTN DISC	1 XS70011A	F&G	NORMA/RUMNI
ACK_RTN			
Mar 15 02:04:27 ALM DISC	1 XS70011C	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 02:04:27 ALM DISC	1 ZSC70569A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 02:04:27 ALM DISC	1 ZSC70570A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 02:04:27 RTN DISC	1 XS70520B	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 02:04:27 ALM DISC	1 XS70520D	F&G	TRIPP/TRIPP
UNACK_ALM			
Mar 15 02:04:27 ALM DISC	1 ZS070043	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:04:27 ALM DISC	1 XV70569B	F&G	OPEN/ OPEN
UNACK_ALM			

É Cópia fiel do documento original
JOSÉ CARLOS RIDENTE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 02:04:27 ALM DISC UNACK_ALM	1 XV70570B	F&G	OPEN/ OPEN
Mar 15 02:04:27 ALM DISC UNACK_ALM	1 XV70043B	F&G	CLOSE/CLOSE
Mar 15 02:04:36 RTN DISC ACK_RTN	1 ZSO70569B	F&G	NOT O/ OPEN
Mar 15 02:04:36 RTN DISC ACK_RTN	1 ZSC70043	F&G	NOT C/CLOSE
Mar 15 02:04:36 RTN DISC ACK_RTN	1 XV70569B	F&G	NORMA/ OPEN
Mar 15 02:04:36 ALM DISC UNACK_ALM	1 XV70570B-VD	F&G	DISCR/DISCR
Mar 15 02:04:50 RTN DISC ACK_RTN	1 ZSO70570B	F&G	NOT O/ OPEN
Mar 15 02:04:50 RTN DISC ACK_RTN	1 XV70570B	F&G	NORMA/ OPEN
Mar 15 02:04:50 RTN DISC ACK_RTN	1 XV70570B-VD	F&G	NORMA/DISCR
Mar 15 02:05:02 RTN DISC ACK_RTN	1 X270520	F&G	NORMA/START
Mar 15 02:05:02 RTN DISC ACK_RTN	1 XV53017	F&G	DE-EN/ENERG
Mar 15 02:05:02 RTN DISC ACK_RTN	1 XV53020	F&G	DE-EN/ENERG
Mar 15 02:05:02 RTN DISC ACK_RTN	1 XV53023	F&G	DE-EN/ENERG
Mar 15 02:05:02 RTN DISC ACK_RTN	1 XCV53002	F&G	DE-EN/ENERG
Mar 15 02:05:02 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:05:06 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:05:33 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:05:33 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:05:36 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:05:39 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:05:42 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:05:47 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:05:47 RTN DISC ACK_RTN	1 GS53-HCB_F	F&G	NORMA/FAULT
Mar 15 02:05:57 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:06:02 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:06:32 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:06:36 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:06:41 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT

É Cópia fiel do documento original.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:06:45 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:06:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:06:56 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:07:03 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:07:14 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:07:17 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:07:17 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:07:39 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:07:44 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:07:48 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:07:48 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:09:24 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:09:29 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:09:47 RTN DISC	1 XS70010C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 02:09:47 RTN DISC	1 XV70042B	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 02:10:47 RTN DISC	1 XS70013C	F&G	NORMA/TRIPP
ACK_RTN			
Mar 15 02:11:24 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:11:29 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:11:38 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:11:42 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:11:56 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:12:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:12:11 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:12:36 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:12:36 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:12:42 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:13:23 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:13:27 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 02:13:32 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:13:36 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:13:39 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:14:41 ALM DISC UNACK_ALM	1 GS53-HCB	F&G	HIGH/ HIGH
Mar 15 02:15:11 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:15:15 ALM DISC UNACK_ALM	1 GS07-HCA_F	F&G	FAULT/FAULT
Mar 15 02:15:15 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:16:35 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:16:44 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:18:00 ALM DISC UNACK_ALM	1 GS2305_F	F&G	FAULT/FAULT
Mar 15 02:18:18 RTN DISC ACK_RTN	1 GS2305_F	F&G	NORMA/FAULT
Mar 15 02:19:15 ALM DISC UNACK_ALM	1 GS53-HCB_HH	F&G	HIGH /HIGH
Mar 15 02:19:32 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:19:36 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:20:09 RTN DISC ACK_RTN	1 GS07-HCA_F	F&G	NORMA/FAULT
Mar 15 02:20:11 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 02:20:14 ALM DISC UNACK_ALM	1 ZS0702-03	F&G	ON/ ON
Mar 15 02:20:20 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 02:20:26 ALM DISC UNACK_ALM	1 ZS0702-03	F&G	ON/ ON
Mar 15 02:20:32 RTN DISC ACK_RTN	1 ZS0701	F&G	OFF/ ON
Mar 15 02:20:41 ALM DISC UNACK_ALM	1 ZS0701	F&G	ON/ ON
Mar 15 02:22:48 ALM DISC UNACK_ALM	1 GS53-HCB_F	F&G	FAULT/FAULT
Mar 15 02:23:41 ALM DISC UNACK_ALM	1 GS07-HCA_F	F&G	FAULT/FAULT
Mar 15 02:23:59 RTN DISC ACK_RTN	1 ZS0701	F&G	OFF/ ON
Mar 15 02:24:14 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 02:24:15 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 02:24:15 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:24:20 ALM DISC UNACK_ALM	1 ZS0702-03	F&G	ON/ ON

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUERÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 02:24:20 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:24:24 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:24:29 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:24:39 RTN DISC	1 GS07-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:24:44 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:24:48 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:24:53 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:24:54 ALM DISC	1 GS07-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:24:54 ALM DISC	1 MD-TX15-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:25:00 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:25:05 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:25:06 RTN DISC	1 GS07-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:25:14 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:25:17 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:25:17 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:25:18 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:25:27 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:25:28 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:25:36 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:25:41 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:25:49 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:25:50 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:25:55 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:26:11 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:26:13 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:26:14 ALM DISC	1 GS52-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 02:26:20 RTN DISC	1 GS52-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 02:26:25 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FONSECA GUESSAO
CORRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 02:26:34 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:26:41 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:26:47 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:27:00 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:27:05 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:27:06 RTN DISC	1 GS53-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 02:27:06 RTN DISC	1 GS53-HCB_HH	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 02:27:11 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:27:12 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:27:18 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:27:24 RTN DISC	1 GS41-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:27:24 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:27:30 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:27:35 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:27:39 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:27:42 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:27:47 ALM DISC	1 GS41-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:27:47 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:27:51 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:27:56 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:28:00 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:28:02 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:28:11 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:28:12 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:28:17 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:28:27 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:28:36 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:28:41 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:28:46 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:28:49 ALM DISC	1 GS52-HCB	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 02:28:52 ALM DISC	1 GS07-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:28:53 RTN DISC	1 GS52-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 02:28:56 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:28:56 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:28:58 ALM DISC	1 GS52-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 02:29:01 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:29:01 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:29:02 RTN DISC	1 GS52-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 02:29:05 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:29:05 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:29:08 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:29:22 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:29:31 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:29:35 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:29:56 RTN DISC	1 XS70519B	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 02:29:56 ALM DISC	1 XS70519C	F&G	LOW S/LOW S
UNACK_ALM			
Mar 15 02:29:56 RTN DISC	1 XCV53004-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 02:29:58 ALM DISC	1 XZ70519	F&G	START/START
UNACK_ALM			
Mar 15 02:29:58 ALM DISC	1 XV53044	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:29:58 ALM DISC	1 XV53047	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:29:58 ALM DISC	1 XV53051	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:29:58 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:30:09 ALM DISC	1 XS70519B	F&G	HIGH /HIGH
UNACK_ALM			
Mar 15 02:30:09 RTN DISC	1 XS70519C	F&G	NORMA/LOW S
ACK_RTN			
Mar 15 02:30:11 ALM DISC	1 XCV53004	F&G	ENERG/ENERG
UNACK_ALM			
Mar 15 02:30:11 RTN DISC	1 PT70032_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSEF CARLOS DE MORAES GUEDES
ENFERM
FARMACIA - FARMACIA



Mar 15 02:30:11 RTN DISC ACK_RTN	1 GS52-HCA_F	F&G	NORMA/FAULT
Mar 15 02:30:24 ALM DISC UNACK_ALM	1 GS52-HCA_F	F&G	FAULT/FAULT
Mar 15 02:30:36 ALM DISC UNACK_ALM	1 XCV53004-VD	F&G	DISCR/DISCR
Mar 15 02:30:38 RTN DISC ACK_RTN	1 PT70030	F&G	NORMA/ALARM
Mar 15 02:30:51 ALM DISC UNACK_ALM	1 PT70030	F&G	ALARM/ALARM
Mar 15 02:31:20 RTN DISC ACK_RTN	1 XZ70519	F&G	NORMA/START
Mar 15 02:31:20 RTN DISC ACK_RTN	1 XV53044	F&G	DE-EN/ENERG
Mar 15 02:31:20 RTN DISC ACK_RTN	1 XV53047	F&G	DE-EN/ENERG
Mar 15 02:31:20 RTN DISC ACK_RTN	1 XV53051	F&G	DE-EN/ENERG
Mar 15 02:31:20 RTN DISC ACK_RTN	1 XCV53004	F&G	DE-EN/ENERG
Mar 15 02:31:20 ALM DISC UNACK_ALM	1 PT70032_F	F&G	FAULT/FAULT
Mar 15 02:31:20 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 02:32:46 RTN DISC ACK_RTN	1 GS07-HCA_F	F&G	NORMA/FAULT
Mar 15 02:33:05 ALM DISC UNACK_ALM	1 LS70301	F&G	ALARM/ALARM
Mar 15 02:33:59 RTN DISC ACK_RTN	1 GS41-HCB_F	F&G	NORMA/FAULT
Mar 15 02:35:13 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:35:17 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:37:20 ALM DISC UNACK_ALM	1 XS70519A	F&G	LOCAL/LOCAL
Mar 15 02:37:20 RTN DISC ACK_RTN	1 XS70519B	F&G	NORMA/HIGH
Mar 15 02:37:20 RTN DISC ACK_RTN	1 XCV53004-VD	F&G	NORMA/DISCR
Mar 15 02:38:20 ALM DISC UNACK_ALM	1 PT70034_F	F&G	FAULT/FAULT
Mar 15 02:38:20 ALM DISC UNACK_ALM	1 PT70030_F	F&G	FAULT/FAULT
Mar 15 02:38:20 ALM DISC UNACK_ALM	1 GS41-HCB_F	F&G	FAULT/FAULT
Mar 15 02:38:29 RTN DISC ACK_RTN	1 GS41-HCB_F	F&G	NORMA/FAULT
Mar 15 02:38:49 RTN DISC ACK_RTN	1 PT70034_F	F&G	NORMA/FAULT
Mar 15 02:38:49 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:38:58 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:39:19 ALM DISC UNACK_ALM	1 GS41-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:39:23 RTN DISC	1 GS41-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:39:28 ALM DISC	1 GS41-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:39:37 RTN DISC	1 GS41-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:41:20 RTN DISC	1 PT70030_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:41:20 ALM DISC	1 GS41-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:41:37 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:41:55 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:42:13 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:42:17 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:42:19 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:42:19 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:42:23 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:42:34 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:42:40 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:42:46 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:43:13 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:43:59 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:44:04 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:44:28 ALM DISC	1 GS16-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:45:07 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:45:16 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:45:20 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:45:29 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:45:34 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:46:28 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:46:32 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:46:46 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:46:50 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			

É COPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS FARIAS GUSMÃO
DEPUTADO
CIVIL DO ESTADO DE SÃO PAULO



Mar 15 02:46:50 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:47:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:47:04 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 02:47:04 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:47:08 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:47:11 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:47:13 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 02:47:13 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:47:17 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:47:19 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 02:47:44 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:47:53 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:47:58 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:48:02 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:48:07 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:48:11 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:48:20 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:48:35 RTN DISC ACK_RTN	1 LS70301	F&G	NORMA/ALARM
Mar 15 02:48:52 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:48:55 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:48:56 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:49:10 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:49:10 RTN DISC ACK_RTN	1 XS70519A	F&G	NORMA/LOCAL
Mar 15 02:49:10 ALM DISC UNACK_ALM	1 XS70519C	F&G	LOW S/LOW S
Mar 15 02:49:11 ALM DISC UNACK_ALM	1 XZ70519	F&G	START/START
Mar 15 02:49:11 ALM DISC UNACK_ALM	1 XV53044	F&G	ENERG/ENERG
Mar 15 02:49:11 ALM DISC UNACK_ALM	1 XV53047	F&G	ENERG/ENERG
Mar 15 02:49:11 ALM DISC UNACK_ALM	1 XV53051	F&G	ENERG/ENERG

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:49:11 ALM DISC UNACK_ALM	1 GS1811_F	F&G	FAULT/FAULT
Mar 15 02:49:25 ALM DISC UNACK_ALM	1 XS70519B	F&G	HIGH /HIGH
Mar 15 02:49:25 RTN DISC ACK_RTN	1 XS70519C	F&G	NORMA/LOW S
Mar 15 02:49:26 ALM DISC UNACK_ALM	1 XCV53004	F&G	ENERG/ENERG
Mar 15 02:49:26 RTN DISC ACK_RTN	1 PT70032_F	F&G	NORMA/FAULT
Mar 15 02:49:28 RTN DISC ACK_RTN	1 PT70030	F&G	NORMA/ALARM
Mar 15 02:49:28 RTN DISC ACK_RTN	1 PT70032	F&G	NORMA/ALARM
Mar 15 02:49:47 ALM DISC UNACK_ALM	1 XCV53004~VD	F&G	DISCR/DISCR
Mar 15 02:50:13 RTN DISC ACK_RTN	1 XZ70519	F&G	NORMA/START
Mar 15 02:50:13 RTN DISC ACK_RTN	1 XV53044	F&G	DE-EN/ENERG
Mar 15 02:50:13 RTN DISC ACK_RTN	1 XV53047	F&G	DE-EN/ENERG
Mar 15 02:50:13 RTN DISC ACK_RTN	1 XV53051	F&G	DE-EN/ENERG
Mar 15 02:50:13 RTN DISC ACK_RTN	1 XCV53004	F&G	DE-EN/ENERG
Mar 15 02:50:13 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 02:50:17 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 02:50:26 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 02:50:31 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:50:35 ALM DISC UNACK_ALM	1 GS1812_F	F&G	FAULT/FAULT
Mar 15 02:50:49 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:50:53 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:51:07 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:51:11 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:51:23 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:51:25 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 02:51:29 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:51:34 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:51:38 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:51:44 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PAEDEL GUSMÃO
DIRETOR
COMISSÃO DE SERVIÇOS CARTORIAIS



Mar 15 02:51:50 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:51:55 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:51:59 RTN DISC	1 GS31-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:52:02 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:52:04 ALM DISC	1 GS31-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:52:08 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:52:13 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:52:23 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:52:28 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:52:32 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:52:41 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:52:50 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:52:55 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:52:55 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:52:58 RTN DISC	1 GS31-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:52:58 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:07 ALM DISC	1 GS31-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:11 RTN DISC	1 GS31-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:11 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:17 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:22 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:31 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:35 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:35 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:38 ALM DISC	1 GS54-HCB	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 02:53:41 ALM DISC	1 GS31-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:41 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:41 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:53:41 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:49 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:53:52 RTN DISC	1 GS54-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 02:53:55 ALM DISC	1 ZSC70140	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:53:56 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:53:56 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:01 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:54:02 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:02 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:07 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:54:08 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:11 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:11 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:11 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:20 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:54:22 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:26 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:54:28 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:28 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:34 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:54:38 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:43 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:54:53 ALM DISC	1 LS70301	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 02:54:59 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:55:04 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:55:10 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:55:10 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:55:10 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 02:55:14 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 02:55:14 RTN DISC ACK_RTN	1 GS52-HCA_F	F&G	NORMA/FAULT
Mar 15 02:55:14 RTN DISC ACK_RTN	1 GS52-HCB_F	F&G	NORMA/FAULT
Mar 15 02:55:22 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 02:55:22 ALM DISC UNACK_ALM	1 GS52-HCA_F	F&G	FAULT/FAULT
Mar 15 02:55:22 ALM DISC UNACK_ALM	1 GS52-HCB_F	F&G	FAULT/FAULT
Mar 15 02:55:25 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 02:55:31 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:55:32 RTN DISC ACK_RTN	1 GS52-HCA_F	F&G	NORMA/FAULT
Mar 15 02:55:37 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:55:47 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:55:52 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:55:53 RTN DISC ACK_RTN	1 GS52-HCB_F	F&G	NORMA/FAULT
Mar 15 02:55:59 ALM DISC UNACK_ALM	1 GS52-HCB_F	F&G	FAULT/FAULT
Mar 15 02:56:05 RTN DISC ACK_RTN	1 GS52-HCB_F	F&G	NORMA/FAULT
Mar 15 02:56:11 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:56:16 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:56:26 ALM DISC UNACK_ALM	1 GS52-HCB_F	F&G	FAULT/FAULT
Mar 15 02:56:40 RTN DISC ACK_RTN	1 GS52-HCB_F	F&G	NORMA/FAULT
Mar 15 02:56:44 ALM DISC UNACK_ALM	1 GS52-HCA_F	F&G	FAULT/FAULT
Mar 15 02:56:44 ALM DISC UNACK_ALM	1 GS52-HCB_F	F&G	FAULT/FAULT
Mar 15 02:56:52 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 02:56:55 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:57:04 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:57:08 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:57:13 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:57:17 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:57:19 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFOS



Mar 15 02:57:23 RTN DISC	1 2SC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:57:28 RTN DISC	1 GS31-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:57:41 ALM DISC	1 2SC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:57:50 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:57:59 ALM DISC	1 GS31-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:02 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:58:07 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:58:20 ALM DISC	1 2SC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:58:22 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:22 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:26 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:58:28 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:28 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:37 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:37 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:40 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:43 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 02:58:44 RTN DISC	1 GS31-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:44 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:49 RTN DISC	1 2SC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 02:58:50 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:58:50 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:59 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:58:59 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:59:02 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:59:02 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 02:59:05 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 02:59:08 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 02:59:11 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 02:59:11 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 02:59:11 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 02:59:14 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 02:59:16 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 02:59:16 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 02:59:22 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 02:59:26 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 02:59:28 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 02:59:28 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 02:59:32 ALM DISC UNACK_ALM	1 PSL54231804	F&G	ALARM/ALARM
Mar 15 02:59:34 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 02:59:38 RTN DISC ACK_RTN	1 PSL54231804	F&G	NORMA/ALARM
Mar 15 02:59:40 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 02:59:40 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 02:59:53 RTN DISC ACK_RTN	1 GS54-HCB_F	F&G	NORMA/FAULT
Mar 15 02:59:58 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:00:10 ALM DISC UNACK_ALM	1 GS54-HCB_F	F&G	FAULT/FAULT
Mar 15 03:00:10 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:00:13 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:00:17 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:00:22 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:00:26 RTN DISC ACK_RTN	1 GS54-HCB_F	F&G	NORMA/FAULT
Mar 15 03:00:29 ALM DISC UNACK_ALM	1 GS54-HCB_F	F&G	FAULT/FAULT
Mar 15 03:00:37 ALM DISC UNACK_ALM	1 GS51-HCB_F	F&G	FAULT/FAULT
Mar 15 03:00:40 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:00:44 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:01:22 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PUENTE GUEMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFAS



Mar 15 03:01:26 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 03:01:37 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:01:40 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 03:01:46 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:01:50 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 03:01:52 RTN DISC ACK_RTN	1 GS31-HCB_F	F&G	NORMA/FAULT
Mar 15 03:01:52 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 03:01:58 ALM DISC UNACK_ALM	1 GS31-HCB_F	F&G	FAULT/FAULT
Mar 15 03:02:01 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:02:05 ALM DISC UNACK_ALM	1 ZS0702-03	F&G	ON/ ON
Mar 15 03:02:05 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:02:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:02:13 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:02:19 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 03:02:35 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:02:40 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:02:44 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:02:49 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:02:53 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:02:53 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 03:02:56 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:02:56 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:02:59 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 03:03:02 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:03:07 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:03:13 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:03:12 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 03:03:16 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 03:03:16 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 03:03:16 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:03:20 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:03:21 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:03:25 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:03:34 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:03:34 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 03:03:47 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:03:52 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:03:56 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:04:01 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:04:05 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:04:32 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:04:37 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:04:50 RTN DISC ACK_RTN	1 ZS0702-03	F&G	OFF/ ON
Mar 15 03:04:56 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:04:59 ALM DISC UNACK_ALM	1 ZS0702-03	F&G	ON/ ON
Mar 15 03:05:01 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:05:05 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:05:07 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:05:07 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:05:13 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:05:19 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:05:19 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:05:25 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:05:32 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:05:40 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:05:40 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS MUMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 03:05:44 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:05:53 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:05:53 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:05:58 ALM DISC UNACK_ALM	1 GS37-HCA_F	F&G	FAULT/FAULT
Mar 15 03:05:58 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:06:02 RTN DISC ACK_RTN	1 GS37-HCA_F	F&G	NORMA/FAULT
Mar 15 03:06:03 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:06:03 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:06:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:06:13 ALM DISC UNACK_ALM	1 GS1503_F	F&G	FAULT/FAULT
Mar 15 03:06:16 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:06:16 RTN DISC ACK_RTN	1 GS1503_F	F&G	NORMA/FAULT
Mar 15 03:06:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:06:25 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:06:30 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:06:48 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:06:51 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:06:52 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:06:57 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:07:01 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:07:10 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 03:07:14 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:07:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:07:19 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 03:07:23 ALM DISC UNACK_ALM	1 GS37-HCA_F	F&G	FAULT/FAULT
Mar 15 03:07:28 RTN DISC ACK_RTN	1 GS37-HCA_F	F&G	NORMA/FAULT
Mar 15 03:07:33 ALM DISC UNACK_ALM	1 GS37-HCA_F	F&G	FAULT/FAULT
Mar 15 03:07:37 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 03:07:37 ALM DISC	1 GS1503_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:07:40 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:07:46 RTN DISC	1 GS1503_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:07:46 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:07:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:07:56 ALM DISC	1 GS1503_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:07:59 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:04 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:08 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:14 RTN DISC	1 GS1503_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:22 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:26 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:35 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:40 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:46 ALM DISC	1 GS1503_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:49 RTN DISC	1 GS1503_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:55 ALM DISC	1 GS1503_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:08:55 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:08:58 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:09:04 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:09:08 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:09:16 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:09:22 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:09:22 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:09:28 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:09:39 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:09:43 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS POMERLE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 03:09:48 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:09:49 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:09:55 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:10:00 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:10:01 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:10:01 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:10:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:10:16 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:10:25 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:10:42 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:10:46 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:11:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:11:08 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:11:17 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:11:22 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:11:26 ALM DISC ONACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:11:28 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:11:32 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:11:37 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:11:38 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:11:44 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:11:53 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:11:58 ALM DISC UNACK_ALM	1 GS1312_F	F&G	FAULT/FAULT
Mar 15 03:12:04 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:12:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:12:15 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:12:16 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:12:25 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓFIAS



Mar 15 03:12:27 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:12:27 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:12:33 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:12:37 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:12:39 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:12:43 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:12:45 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:12:49 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:12:54 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:12:58 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:13:03 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:13:04 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:13:04 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:13:10 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:13:16 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:13:21 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:13:32 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:13:37 ALM DISC UNACK_ALM	1 PSL54231004	F&G	ALARM/ALARM
Mar 15 03:13:38 ALM DISC UNACK_ALM	1 XY54231002	F&G	ALARM/ALARM
Mar 15 03:13:38 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:13:38 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 03:13:38 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:13:38 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 03:13:43 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:13:44 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:13:44 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 03:13:58 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:14:02 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN

É Cópia fiel do documento original

JOSÉ CARLOS POTENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 03:14:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:14:04 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:14:04 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 03:14:08 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:14:08 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 03:14:08 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 03:14:13 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:14:13 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 03:14:16 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:14:17 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:14:17 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 03:14:22 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 03:14:26 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:14:31 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:14:40 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:14:44 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:14:53 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:15:03 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:15:12 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:15:12 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:15:16 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:15:18 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:15:18 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:15:22 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:15:33 ALM DISC UNACK_ALM	1 GS41-HCA_F	F&G	FAULT/FAULT
Mar 15 03:15:39 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:15:39 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 03:15:42 RTN DISC ACK_RTN	1 GS41-HCA_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

DEPARTAMENTO DE
INVESTIGAÇÃO



Mar 15 03:15:42 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:15:45 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:15:52 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:06 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:16:24 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:28 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:37 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:16:37 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:44 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:16:44 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:48 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:16:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:16:53 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:17:00 ALM DISC	1 GS60-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:00 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:17:00 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:04 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:04 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:08 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:17:10 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:17:19 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:17:22 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:25 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:17:26 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:17:35 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:42 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:17:44 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:17:45 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 03:17:47 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:17:50 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 03:18:03 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:18:07 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:18:18 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:18:25 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:18:25 ALM DISC UNACK_ALM	1 GS1709_F	F&G	FAULT/FAULT
Mar 15 03:18:28 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:18:34 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:18:36 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:18:36 RTN DISC ACK_RTN	1 GS1709_F	F&G	NORMA/FAULT
Mar 15 03:18:39 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:18:40 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:18:45 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:18:51 ALM DISC UNACK_ALM	1 GS36-HCA_F	F&G	FAULT/FAULT
Mar 15 03:18:51 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:18:54 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:18:54 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:19:00 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:19:01 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:19:01 ALM DISC UNACK_ALM	1 GS2901_F	F&G	FAULT/FAULT
Mar 15 03:19:01 ALM DISC UNACK_ALM	1 GS1709_F	F&G	FAULT/FAULT
Mar 15 03:19:06 ALM DISC UNACK_ALM	1 ZSL54231405	F&G	ALARM/ALARM
Mar 15 03:19:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:19:10 RTN DISC ACK_RTN	1 GS2901_F	F&G	NORMA/FAULT
Mar 15 03:19:19 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:19:24 ALM DISC UNACK_ALM	1 ZSL54231406	F&G	ALARM/ALARM
Mar 15 03:19:33 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PARENTAL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 03:19:46 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:19:48 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:19:48 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:19:52 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:19:53 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:19:53 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:20:15 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:20:19 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:20:26 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:20:26 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:20:28 ALM DISC	1 GS07-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:20:28 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:20:32 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:20:34 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:20:40 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:20:40 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:20:44 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:21:12 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:21:15 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:21:15 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:21:24 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:21:33 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:21:37 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:21:42 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:21:46 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:21:48 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:21:52 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:21:52 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 15 03:21:54 RTN DISC ACK_RTN	1 GS07-HCA_F	F&G	NORMA/FAULT
Mar 15 03:21:58 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:22:00 RTN DISC ACK_RTN	1 GS42-HCA_F	F&G	NORMA/FAULT
Mar 15 03:22:06 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:22:10 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:22:12 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:22:16 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:22:18 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:22:24 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:22:25 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:22:36 RTN DISC ACK_RTN	1 GS2401_F	F&G	NORMA/FAULT
Mar 15 03:22:43 ALM DISC UNACK_ALM	1 GS07-HCA_F	F&G	FAULT/FAULT
Mar 15 03:23:00 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:23:04 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:23:15 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:23:16 ALM DISC UNACK_ALM	1 GS2401_F	F&G	FAULT/FAULT
Mar 15 03:23:21 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:23:40 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:23:46 RTN DISC ACK_RTN	1 GS1503_F	F&G	NORMA/FAULT
Mar 15 03:23:49 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:23:49 RTN DISC ACK_RTN	1 GS35-HCB_F	F&G	NORMA/FAULT
Mar 15 03:24:07 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:24:07 ALM DISC UNACK_ALM	1 GS1503_F	F&G	FAULT/FAULT
Mar 15 03:24:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:24:13 RTN DISC ACK_RTN	1 GS1503_F	F&G	NORMA/FAULT
Mar 15 03:24:18 ALM DISC UNACK_ALM	1 GS1503_F	F&G	FAULT/FAULT
Mar 15 03:24:21 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 03:24:43 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CANTONAIS



Mar 15 03:24:43 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:24:43 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:24:46 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:06 ALM DISC	1 XS70519A	F&G	LOCAL/LOCAL
UNACK_ALM			
Mar 15 03:25:06 RTN DISC	1 XS70519B	F&G	NORMA/HIGH
ACK_RTN			
Mar 15 03:25:06 RTN DISC	1 XCV53004-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 03:25:07 ALM DISC	1 PT70032	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 03:25:15 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:25:16 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:16 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:18 ALM DISC	1 PT70030	F&G	ALARM/ALARM
UNACK_ALM			
Mar 15 03:25:22 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:30 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:25:31 ALM DISC	1 PT70032_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:31 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:40 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:25:42 RTN DISC	1 GS07-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:42 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:42 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:48 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:48 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:48 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:25:52 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:25:55 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:26:03 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:26:03 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:26:06 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:26:06 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			

ECÓPIA EM DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 03:26:07 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:26:07 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:26:13 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:26:13 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:26:19 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:26:24 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:26:51 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:12 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:16 RTN DISC	1 GS36-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:16 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:28 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:28 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:34 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:37 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:42 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:42 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:48 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:27:49 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:27:49 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:27:55 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:01 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:01 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:06 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:06 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:06 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:12 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:15 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:18 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 03:28:19 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:24 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:28:25 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:25 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:33 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:28:34 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:40 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:45 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:45 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:45 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:28:48 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:28:51 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:00 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:00 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:06 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:10 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:10 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:15 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:24 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:29:25 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:30 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:29:33 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:36 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:29:37 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:42 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:29:43 ALM DISC	1 GS2405_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:29:43 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:29:49 RTN DISC	1 GS2405_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS POMENEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CÍVILS



Mar 15 03:29:49 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:29:49 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:29:54 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:29:58 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:30:03 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT
Mar 15 03:30:03 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:30:07 RTN DISC ACK_RTN	1 GS18-HCA_F	F&G	NORMA/FAULT
Mar 15 03:30:07 ALM DISC UNACK_ALM	1 GS68-HCA_F	F&G	FAULT/FAULT
Mar 15 03:30:07 RTN DISC ACK_RTN	1 GS2401_F	F&G	NORMA/FAULT
Mar 15 03:30:07 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:30:13 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT
Mar 15 03:30:13 ALM DISC UNACK_ALM	1 GS36-HCA_F	F&G	FAULT/FAULT
Mar 15 03:30:13 ALM DISC UNACK_ALM	1 GS2401_F	F&G	FAULT/FAULT
Mar 15 03:30:13 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:30:18 RTN DISC ACK_RTN	1 GS18-HCA_F	F&G	NORMA/FAULT
Mar 15 03:30:18 RTN DISC ACK_RTN	1 GS2401_F	F&G	NORMA/FAULT
Mar 15 03:30:25 RTN DISC ACK_RTN	1 GS37-HCB_F	F&G	NORMA/FAULT
Mar 15 03:30:30 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:30:34 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT
Mar 15 03:30:34 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:30:37 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:30:39 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:30:39 RTN DISC ACK_RTN	1 GS37-HCB_F	F&G	NORMA/FAULT
Mar 15 03:30:43 RTN DISC ACK_RTN	1 ZSC70121	F&G	NOT O/ OPEN
Mar 15 03:30:45 ALM DISC UNACK_ALM	2 GS45-HCB_F	F&G	FAULT/FAULT
Mar 15 03:30:45 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:30:51 ALM DISC UNACK_ALM	1 GS1801_F	F&G	FAULT/FAULT
Mar 15 03:30:55 RTN DISC ACK_RTN	1 GS1801_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 03:31:04 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:31:04 ALM DISC UNACK_ALM	1 GS1801_F	F&G	FAULT/FAULT
Mar 15 03:31:07 RTN DISC ACK_RTN	1 GS1801_F	F&G	NORMA/FAULT
Mar 15 03:31:10 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:31:10 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:31:18 ALM DISC UNACK_ALM	1 GS17-HCB_F	F&G	FAULT/FAULT
Mar 15 03:31:18 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:31:21 RTN DISC ACK_RTN	1 GS17-HCB_F	F&G	NORMA/FAULT
Mar 15 03:31:24 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:31:24 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:31:31 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:31:31 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:31:31 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:31:45 ALM DISC UNACK_ALM	1 GS1801_F	F&G	FAULT/FAULT
Mar 15 03:31:49 ALM DISC UNACK_ALM	1 GS2405	F&G	HIGH/ HIGH
Mar 15 03:31:54 ALM DISC UNACK_ALM	1 GS42-HCB_F	F&G	FAULT/FAULT
Mar 15 03:31:54 RTN DISC ACK_RTN	1 GS1801_F	F&G	NORMA/FAULT
Mar 15 03:31:55 RTN DISC ACK_RTN	1 GS2405	F&G	NORMA/ HIGH
Mar 15 03:31:58 ALM DISC UNACK_ALM	1 GS17-HCB_F	F&G	FAULT/FAULT
Mar 15 03:31:58 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:31:58 ALM DISC UNACK_ALM	1 GS1708_F	F&G	FAULT/FAULT
Mar 15 03:32:09 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:32:10 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:32:16 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:32:27 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:32:28 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:32:28 RTN DISC ACK_RTN	1 GS2405_F	F&G	NORMA/FAULT
Mar 15 03:32:30 ALM DISC UNACK_ALM	1 GS2405	F&G	HIGH/ HIGH

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE PAULO MONTENEGRO
INSTRUTOR DE DEFESA



Mar 15 03:32:34 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:32:36 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:32:36 ALM DISC UNACK_ALM	1 GS2405_F	F&G	FAULT/FAULT
Mar 15 03:32:36 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:32:37 RTN DISC ACK_RTN	1 GS2405	F&G	NORMA/ HIGH
Mar 15 03:32:43 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:32:52 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:32:57 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:32:57 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:33:00 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:33:00 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:33:00 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:33:03 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:33:03 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:33:06 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:33:06 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:33:09 RTN DISC ACK_RTN	1 GS17-HCB_F	F&G	NORMA/FAULT
Mar 15 03:33:09 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:33:09 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:33:12 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:33:16 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:33:18 ALM DISC UNACK_ALM	1 GS53-HCA	F&G	HIGH/ HIGH
Mar 15 03:33:22 RTN DISC ACK_RTN	1 GS53-HCA	F&G	NORMA/ HIGH
Mar 15 03:33:27 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:33:31 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:33:33 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:33:37 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:33:39 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS FERREIRA GOMES
DEPUTADO
JOSÉ CARLOS FERREIRA GOMES



Mar 15 03:33:39 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:33:40 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 03:33:46 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:33:46 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:33:46 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:33:46 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:33:51 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:33:52 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:33:52 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:33:52 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:33:52 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:33:54 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 03:33:58 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:34:12 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:34:25 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:34:30 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:34:34 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:34:39 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:34:42 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:34:51 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:35:07 RTN DISC	1 GS1708_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:35:10 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:35:15 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:35:16 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 03:35:19 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 03:35:24 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 03:35:28 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:35:30 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.
JOSE CARLOS PIMENTEL GUSMÃO
OFICIA
COMISSÃO DE SEBASTIÃO CARVALHOS



Mar 15 03:35:33 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:35:33 ALM DISC UNACK_ALM	1 GS1708_F	F&G	FAULT/FAULT
Mar 15 03:35:36 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:35:42 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:35:45 RTN DISC ACK_RTN	1 GS49-HCB_F	F&G	NORMA/FAULT
Mar 15 03:35:45 ALM DISC UNACK_ALM	1 GS1502_F	F&G	FAULT/FAULT
Mar 15 03:35:51 RTN DISC ACK_RTN	1 GS1502_F	F&G	NORMA/FAULT
Mar 15 03:35:54 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:35:54 ALM DISC UNACK_ALM	1 GS49-HCB_F	F&G	FAULT/FAULT
Mar 15 03:35:55 ALM DISC UNACK_ALM	1 GS53-HCA	F&G	HIGH/ HIGH
Mar 15 03:36:01 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:36:06 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:36:09 RTN DISC ACK_RTN	1 ZSC70139	F&G	NOT O/ OPEN
Mar 15 03:36:10 RTN DISC ACK_RTN	1 GS1708_F	F&G	NORMA/FAULT
Mar 15 03:36:15 ALM DISC UNACK_ALM	1 ZSC70139	F&G	OPEN/ OPEN
Mar 15 03:36:25 RTN DISC ACK_RTN	1 GS52-HCA_F	F&G	NORMA/FAULT
Mar 15 03:36:30 RTN DISC ACK_RTN	1 GS52-HCB_F	F&G	NORMA/FAULT
Mar 15 03:36:33 ALM DISC UNACK_ALM	1 GS1708_F	F&G	FAULT/FAULT
Mar 15 03:36:54 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:36:55 ALM DISC UNACK_ALM	1 GS54-HCB	F&G	HIGH/ HIGH
Mar 15 03:37:00 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:37:09 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:37:12 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:37:16 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:37:21 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:37:30 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:37:31 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:37:39 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS FREIRE GUSMÃO
ESCRITÓRIO
CAMIÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 03:37:52 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:37:54 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:37:54 RTN DISC	1 MD-TX16-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:37:58 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:38:00 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:00 ALM DISC	1 MD-TX16-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:09 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:38:10 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:38:10 ALM DISC	1 GS17-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:12 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 03:38:12 RTN DISC	1 GS54-HCB	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 03:38:16 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:38:18 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:18 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:22 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:38:24 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:33 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:38:34 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:34 RTN DISC	1 GS1503_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:38:39 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:38:40 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:38:40 ALM DISC	1 GS1503_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:48 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:38:49 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:38:49 RTN DISC	1 GS1503_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:00 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:39:04 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:39:06 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
CARLOS FERNANDO GUSMÃO
DIRETOR
GRANDE DE SENHA DO CASP/2012



Mar 15 03:39:06 RTN DISC	1 GS54-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:06 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:10 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:13 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:21 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:21 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:24 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:27 ALM DISC	1 GS07-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:30 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:33 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:39 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:45 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:45 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:39:49 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:49 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:39:58 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:40:00 ALM DISC	1 GS53-HCA	F&G	HIGH/ HIGH
UNACK_ALM			
Mar 15 03:40:03 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:40:03 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:40:06 RTN DISC	1 GS52-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:40:10 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:40:15 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:40:25 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:40:30 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:40:34 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:40:36 RTN DISC	1 GS52-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:40:40 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:40:40 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			

É Cópia fiel do documento original.

JOSE CARLOS FERNANDA CUSMAO
DIRETOR
GERENTE DE SERVIÇOS JURÍDICOS



Mar 15 03:40:45 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:40:54 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:40:58 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:41:03 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:41:09 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:41:13 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:41:15 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:41:19 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:22 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:41:22 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:28 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:31 ALM DISC	1 GS52-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:31 ALM DISC	1 GS54-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:31 ALM DISC	1 GS52-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:33 RTN DISC	1 GS53-HCA	F&G	NORMA/ HIGH
ACK_RTN			
Mar 15 03:41:36 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:43 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:41:46 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:41:49 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:41:58 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:42:04 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:42:07 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:42:13 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:42:18 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:42:27 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:42:27 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:42:37 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:42:37 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARTÓGRAFOS



Mar 15 03:42:42 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:42:46 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:42:48 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:42:52 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:42:57 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:42:58 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:42:58 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:04 RTN DISC	1 GS07-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:04 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:04 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:05 ALM DISC	1 GS1502_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:09 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:43:10 RTN DISC	1 GS1502_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:16 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:16 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:22 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:22 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:27 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:27 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:46 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:43:51 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:51 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:43:54 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:00 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:00 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:03 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:03 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:06 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É Cópia fiel do documento original.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CANTORIAS



Mar 15 03:44:10 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:13 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:44:15 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:21 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:21 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:25 ALM DISC	1 GS16-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:25 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:25 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:34 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:44:39 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:44:49 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:44:52 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:44:54 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:44:58 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:45:03 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:45:07 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:45:12 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:45:16 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:45:21 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:45:22 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:45:36 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:45:49 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:45:58 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:46:03 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:46:06 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:46:10 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:46:15 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:46:21 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É Cópia do documento original
JOSE MARCELO DE OLIVEIRA
2015
UNIDADE DE SERVIÇOS JURÍDICOS



Mar 15 03:46:34 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:46:36 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:46:36 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:46:36 ALM DISC UNACK_ALM	1 GS1503_F	F&G	FAULT/FAULT
Mar 15 03:46:42 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:46:42 RTN DISC ACK_RTN	1 GS1503_F	F&G	NORMA/FAULT
Mar 15 03:46:46 RTN DISC ACK_RTN	1 ZSC70131	F&G	NOT O/ OPEN
Mar 15 03:46:48 RTN DISC ACK_RTN	1 GS40-HCA_F	F&G	NORMA/FAULT
Mar 15 03:46:51 ALM DISC UNACK_ALM	1 GS40-HCA_F	F&G	FAULT/FAULT
Mar 15 03:47:03 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:47:03 RTN DISC ACK_RTN	1 GS40-HCA_F	F&G	NORMA/FAULT
Mar 15 03:47:06 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:47:06 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:47:09 ALM DISC UNACK_ALM	1 GS40-HCA_F	F&G	FAULT/FAULT
Mar 15 03:47:13 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:47:18 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:47:18 RTN DISC ACK_RTN	1 GS37-HCB_F	F&G	NORMA/FAULT
Mar 15 03:47:21 ALM DISC UNACK_ALM	1 GS37-HCB_F	F&G	FAULT/FAULT
Mar 15 03:47:21 ALM DISC UNACK_ALM	1 MD-TX68-HC_F	F&G	FAULT/FAULT
Mar 15 03:47:24 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:47:28 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:47:28 RTN DISC ACK_RTN	1 GS53-HCA_F	F&G	NORMA/FAULT
Mar 15 03:47:31 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:47:34 RTN DISC ACK_RTN	1 MD-TX68-HC_F	F&G	NORMA/FAULT
Mar 15 03:47:37 ALM DISC UNACK_ALM	1 ZSC70131	F&G	OPEN/ OPEN
Mar 15 03:47:39 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:47:43 ALM DISC UNACK_ALM	1 GS53-HCA_F	F&G	FAULT/FAULT
Mar 15 03:47:43 ALM DISC UNACK_ALM	1 GS1801_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PEREIRA CAUSAO
(RECEBER)
UNSAO DE MONTAGEM E MANUTENCAO



Mar 15 03:47:46 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:47:57 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:04 ALM DISC	1 ZSC70131_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:48:07 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:48:12 ALM DISC	1 PB0701-02_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:48:12 RTN DISC	1 ZSC70131_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:15 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:48:19 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:22 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:48:22 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:48:24 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:36 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:48:37 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:48:42 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:48:43 RTN DISC	1 GS53-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:48 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:48:49 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:48:49 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:48:57 ALM DISC	1 ZSC70131	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:49:01 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:49:06 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:06 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:18 ALM DISC	1 GS53-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:18 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:49:22 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:25 RTN DISC	1 ZSC70131	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:49:27 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:31 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			

É CÓPIA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GOMES
DIRETOR
DIVISÃO DE SERVIÇOS CANTORIAS



Mar 15 03:49:33 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:49:42 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:49:42 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:51 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:49:51 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:00 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:50:05 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:09 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:50:09 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:50:14 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:14 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:16 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:50:22 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:31 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:39 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:39 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:50:52 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:50:54 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:50:54 ALM DISC	1 GS1801_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:51:03 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:51:07 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:51:09 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:51:13 ALM DISC	1 ZSC70139	F&G	OPEN/ OPEN
UNACK_ALM			
Mar 15 03:51:15 RTN DISC	1 GS36-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:51:19 RTN DISC	1 ZSC70139	F&G	NOT O/ OPEN
ACK_RTN			
Mar 15 03:51:21 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:51:28 ALM DISC	1 GS36-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:51:34 ALM DISC	1 GS49-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 03:51:34 ALM DISC	1 GS37-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:52:00 RTN DISC	1 GS36-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:03 RTN DISC	1 PB0701-02_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:07 ALM DISC	1 PB0701-02_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:52:39 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:52:44 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:47 RTN DISC	1 GS49-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:51 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:52:56 RTN DISC	1 GS16-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:56 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:56 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:59 RTN DISC	1 GS37-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:52:59 ALM DISC	1 GS40-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:02 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:05 RTN DISC	1 GS40-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:05 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:09 ALM DISC	1 GS16-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:09 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:09 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:15 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:20 RTN DISC	1 GS16-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:33 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:33 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:36 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:53:42 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:53:46 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:54:00 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:54:04 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÔPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PEREIRA GUSMÃO
PRESIDENTE
DIVISÃO DE SERVIÇOS JURÍDICOS



Mar 15 03:54:09 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:54:09 ALM DISC	1 GS2401_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:54:18 RTN DISC	1 GS2401_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:54:22 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:54:22 RTN DISC	1 GS1801_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:54:25 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:54:25 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:06 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:55:10 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:10 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:13 RTN DISC	1 GS42-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:13 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:55:19 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:27 RTN DISC	1 GS45-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:55:53 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:55:57 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:56:11 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:56:20 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:56:33 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:56:38 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:56:50 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:56:54 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:56:59 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:57:09 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:57:13 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:57:22 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 03:57:27 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 03:57:45 ALM DISC	1 GS18-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			

É Cópia fiel do documento original

JOSE CARLOS M. DE LIMA
PRESIDENTE
CORPAC 15/03/2015 15:00:00



Mar 15 03:58:06 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 03:58:12 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:58:16 RTN DISC ACK_RTN	2 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:58:21 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 03:58:57 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 03:59:11 RTN DISC ACK_RTN	1 GS18-HCA_F	F&G	NORMA/FAULT
Mar 15 03:59:23 RTN DISC ACK_RTN	1 GS42-HCA_F	F&G	NORMA/FAULT
Mar 15 04:00:21 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 04:00:45 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT
Mar 15 04:00:45 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 04:00:58 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 04:01:16 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 04:01:24 RTN DISC ACK_RTN	1 GS42-HCA_F	F&G	NORMA/FAULT
Mar 15 04:01:29 RTN DISC ACK_RTN	1 GS18-HCA_F	F&G	NORMA/FAULT
Mar 15 04:01:29 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 04:01:29 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 04:01:35 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 04:01:38 RTN DISC ACK_RTN	1 GS42-HCA_F	F&G	NORMA/FAULT
Mar 15 04:01:38 ALM DISC UNACK_ALM	1 GS2905_F	F&G	FAULT/FAULT
Mar 15 04:01:48 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 04:01:48 RTN DISC ACK_RTN	1 GS2905_F	F&G	NORMA/FAULT
Mar 15 04:01:53 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 04:01:56 ALM DISC UNACK_ALM	1 GS42-HCA_F	F&G	FAULT/FAULT
Mar 15 04:02:11 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT
Mar 15 04:02:29 ALM DISC UNACK_ALM	1 GS26-HCB_F	F&G	FAULT/FAULT
Mar 15 04:02:33 RTN DISC ACK_RTN	1 GS26-HCB_F	F&G	NORMA/FAULT
Mar 15 04:02:56 RTN DISC ACK_RTN	1 GS18-HCA_F	F&G	NORMA/FAULT
Mar 15 04:03:00 ALM DISC UNACK_ALM	1 GS18-HCA_F	F&G	FAULT/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS DE MENDONÇA GONÇALVES
CORRETOR
DIVISÃO DE REGISTRO E SERVIÇOS CARTÓGRAFOS



Mar 15 04:03:27 RTN DISC	1 GS18-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:03:49 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:03:55 RTN DISC	1 GS17-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:04:03 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:04:17 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:04:44 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:05:02 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:05:06 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:05:26 ALM DISC	1 GS17-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:05:42 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:05:47 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:05:47 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:05:50 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:05:54 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:05:59 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:05 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:09 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:14 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:14 RTN DISC	1 GS17-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:17 ALM DISC	1 GS26-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:17 ALM DISC	1 GS2905_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:20 ALM DISC	1 GS17-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:20 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:23 RTN DISC	1 GS26-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:27 RTN DISC	1 GS2905_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:30 ALM DISC	1 GS42-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:06:35 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:39 RTN DISC	1 GS42-HCA_F	F&G	NORMA/FAULT
ACK_RTN			

ECUAFEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS MENDES LIMA
19/03/2016
CNSÃO DE SERVIDORES



Mar 15 04:06:51 RTN DISC	1 GS17-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:06:51 ALM DISC	1 MD-TX68-HC_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:07:02 RTN DISC	1 MD-TX68-HC_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:11:38 ALM DISC	1 ZSC70572A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 04:11:38 ALM DISC	1 XV70572A	F&G	CLOSE/CLOSE
UNACK_ALM			
Mar 15 04:11:50 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:11:53 ALM DISC	1 XV70572A-VD	F&G	DISCR/DISCR
UNACK_ALM			
Mar 15 04:11:54 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:12:12 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:12:17 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:12:21 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:12:29 RTN DISC	1 GS1812_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:12:35 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:12:48 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:12:54 RTN DISC	1 GS67-HCA_P	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:13:02 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:13:06 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:13:11 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:13:15 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:13:20 ALM DISC	1 GS2901_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:13:29 RTN DISC	1 GS2901_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:13:32 RTN DISC	1 GS1708_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:13:35 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:13:50 ALM DISC	1 GS1708_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:14:35 RTN DISC	1 GS1708_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:15:00 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:15:24 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:15:29 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PEREIRA MACHADO
JUIZ DE DIREITO
DIVISÃO DE SERVIÇOS JUDICIAIS



Mar 15 04:15:33 ALM DISC	1 GS1708_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:15:41 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:15:45 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:15:56 RTN DISC	1 GS21-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:16:00 ALM DISC	1 GS21-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:16:09 RTN DISC	1 GS21-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:16:14 ALM DISC	1 GS21-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:16:14 RTN DISC	1 GS1708_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:16:26 RTN DISC	1 GS21-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:16:26 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:16:29 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:16:32 ALM DISC	1 GS21-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:16:50 RTN DISC	1 GS21-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:12 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:17 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:17:21 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:35 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:17:42 RTN DISC	1 GS67-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:47 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:17:51 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:17:56 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:56 RTN DISC	1 GS67-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:17:56 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:18:02 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:18:06 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:18:15 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:18:18 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:18:32 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PRINDEL GUSMÃO
CRISTINA
DIVISÃO DE SERVIÇOS CÍVIS



Mar 15 04:18:41 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:18:45 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:19:03 ALM DISC	1 GS68-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:19:17 RTN DISC	1 GS68-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:19:17 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:19:33 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:19:38 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:19:41 RTN DISC	1 ZSC70572A	F&G	NOT C/CLOSE
ACK_RTN			
Mar 15 04:19:41 RTN DISC	1 XV70572A	F&G	NORMA/CLOSE
ACK_RTN			
Mar 15 04:19:41 RTN DISC	1 XV70572A-VD	F&G	NORMA/DISCR
ACK_RTN			
Mar 15 04:19:45 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:19:50 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:19:53 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:20:03 ALM DISC	1 GS1311_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:20:11 RTN DISC	1 GS67-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:20:21 RTN DISC	1 GS1311_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:20:27 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:20:32 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:21:50 ALM DISC	1 GS67-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:22:08 RTN DISC	1 GS67-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:22:38 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:23:00 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:23:27 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:23:32 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:23:59 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:24:08 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:24:21 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:24:24 RTN DISC	1 GS43-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PEREIRA LIMA
JESUITA
LIVRO DE REGISTRO



Mar 15 04:24:24 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:24:33 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:24:38 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:24:51 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:24:51 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:24:57 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:25:05 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:25:05 ALM DISC	1 GS43-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:25:05 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:25:14 RTN DISC	1 GS43-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:25:32 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:25:36 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:26:36 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:26:41 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:26:50 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:26:54 ALM DISC	1 GS35-HCB_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:26:57 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:26:57 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:03 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:27:06 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:24 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:27:24 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:30 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:27:33 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:33 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:36 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:27:51 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:27:51 RTN DISC	1 GS35-HCB_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 04:27:54 RTN DISC ACK_RTN	1 GS41-HCA_F	F&G	NORMA/FAULT
Mar 15 04:27:57 ALM DISC UNACK_ALM	1 GS35-HCB_F	F&G	FAULT/FAULT
Mar 15 04:28:06 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:28:14 ALM DISC UNACK_ALM	1 GS41-HCA_F	F&G	FAULT/FAULT
Mar 15 04:28:23 RTN DISC ACK_RTN	1 GS41-HCA_F	F&G	NORMA/FAULT
Mar 15 04:28:32 ALM DISC UNACK_ALM	1 GS41-HCA_F	F&G	FAULT/FAULT
Mar 15 04:28:41 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 04:28:45 RTN DISC ACK_RTN	1 GS43-HCB_F	F&G	NORMA/FAULT
Mar 15 04:29:17 ALM DISC UNACK_ALM	1 GS1320_F	F&G	FAULT/FAULT
Mar 15 04:29:21 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 04:29:21 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:29:24 RTN DISC ACK_RTN	1 GS1320_F	F&G	NORMA/FAULT
Mar 15 04:29:27 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:29:30 RTN DISC ACK_RTN	1 GS43-HCB_F	F&G	NORMA/FAULT
Mar 15 04:29:36 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:29:41 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:29:45 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:30:22 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:30:57 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:31:02 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:31:20 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:31:24 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:31:38 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:31:45 ALM DISC UNACK_ALM	1 GS43-HCB_F	F&G	FAULT/FAULT
Mar 15 04:31:50 RTN DISC ACK_RTN	1 GS43-HCB_F	F&G	NORMA/FAULT
Mar 15 04:31:50 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT
Mar 15 04:31:56 ALM DISC UNACK_ALM	1 GS1804_F	F&G	FAULT/FAULT
Mar 15 04:32:00 RTN DISC ACK_RTN	1 GS1804_F	F&G	NORMA/FAULT

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FUMIEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS GERAIS



Mar 15 04:32:05 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:32:23 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:32:32 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:32:41 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:32:57 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:32:58 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:33:08 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:33:17 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:33:22 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:33:35 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:33:38 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:33:38 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:33:51 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:00 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:34:18 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:29 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:34:32 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:34:32 RTN DISC	1 GS1312_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:32 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:38 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:34:41 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:41 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:51 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:34:56 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:34:59 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:35:08 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:35:54 ALM DISC	1 GS1312_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:35:59 RTN DISC	1 GS1312_F	F&G	NORMA/FAULT
ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL
JOSÉ CARLOS PRADO DE OLIVEIRA
TITULAR
UNIDADE DE SERVIÇOS DE CONTABILIDADE



Mar 15 04:36:52 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:36:56 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:37:15 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:37:20 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:37:50 ALM DISC	1 GS41-HCA_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:37:59 RTN DISC	1 GS41-HCA_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:38:17 RTN DISC	1 2S0702-03	F&G	OFF/ ON
ACK_RTN			
Mar 15 04:38:18 ALM DISC	1 GS1321_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:39:49 ALM DISC	1 GS1804_F	F&G	FAULT/FAULT
UNACK_ALM			
Mar 15 04:39:53 RTN DISC	1 GS1804_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:42:43 RTN DISC	1 GS2305_F	F&G	NORMA/FAULT
ACK_RTN			
Mar 15 04:42:47 ALM DISC	1 GS2305_F	F&G	FAULT/FAULT
UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS FREITAS GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIS



Mar 14 08:01:09 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:01:12 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:03:04 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:03:07 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:05:40 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:05:49 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:12:40 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:12:43 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:22:01 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:22:13 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:33:49 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:34:16 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:34:49 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:35:22 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:35:25 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:35:49 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:35:55 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:36:04 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:36:16 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:36:19 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:36:25 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:36:28 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:38:16 RTN DISC	1 ZSL53360101	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 08:38:37 ALM DISC	1 ZSH53360101	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 08:42:40 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:45:04 RTN DISC	1 ZSH53360101	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 08:45:25 ALM DISC	1 ZSL53360101	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 08:45:43 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:45:52 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:48:04 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:50:50 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 08:53:13 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 08:53:34 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSE CARLOS FONSECA GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 14 08:58:01 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:00:34 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:06:19 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:07:46 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:08:13 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:09:02 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:11:50 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:12:16 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:13:01 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:13:19 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:13:31 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:13:37 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:14:30 ALM DISC	1 XSI2230130	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 09:14:30 ALM DISC	1 RTU2_INH_8075	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:14:33 ALM DISC	1 RTU2_INH_8076	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:14:39 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:14:45 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:15:30 ALM DISC	1 RTU2_INH_8067	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:15:45 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:15:48 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:15:48 ALM DISC	1 RTU2_INH_8068	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:15:51 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:15:54 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:15:57 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:16:03 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:16:10 ALM DISC	1 XSI2230340	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 09:16:10 ALM DISC	1 RTU2_INH_8174	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:16:55 ALM DISC	1 RTU2_INH_8072	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 09:18:07 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:18:53 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:18:55 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 09:19:14 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 09:19:28 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
COMISSÃO DE SERVIÇOS CARTORÁRIOS



Mar 14 09:19:31 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:21:37 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:21:52 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:24:01 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:24:04 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:24:13 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:24:16 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:24:31 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:24:58 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:25:01 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:26:19 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:26:25 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:26:56 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:26:58 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:29:02 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:29:04 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:30:13 RTN DISC	1 PSL112230131	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:32:23 RTN DISC	1 PSL112230748	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:32:34 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:32:40 RTN DISC	1 PSL112230341	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:32:40 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:32:46 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:32:55 RTN DISC	1 PSL112230340	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:33:19 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:33:22 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:33:31 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:33:57 ALM DISC	1 PSL112230241	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:33:57 RTN DISC	1 PSHH12230243	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:33:57 RTN DISC	1 XS12230240	RTU2
EN/ENERG ACK_RTN		
Mar 14 09:34:00 ALM DISC	1 PSL112230240	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:34:21 ALM DISC	1 PSHH12230309	RTU2
ALARM/ALARM UNACK_ALM		
Mar 14 09:34:54 RTN DISC	1 PSHH12230309	RTU2
NORMA/ALARM ACK_RTN		
Mar 14 09:35:01 ALM DISC	1 PSL112230131	RTU2
ALARM/ALARM UNACK_ALM		

DE-

É COPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FONSEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRÁFICOS



Mar 14 09:35:33 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:37:12 RTN DISC ON ACK_RTN	1 RTU2_INH_8067	RTU2_INHIBITS	OFF/
Mar 14 09:37:36 RTN DISC ON ACK_RTN	1 RTU2_INH_8174	RTU2_INHIBITS	OFF/
Mar 14 09:37:57 RTN DISC ON ACK_RTN	1 RTU2_INH_8066	RTU2_INHIBITS	OFF/
Mar 14 09:38:27 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:38:57 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL12230648	RTU2	
Mar 14 09:38:57 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:39:09 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:39:21 RTN DISC ON ACK_RTN	1 RTU2_INH_8071	RTU2_INHIBITS	OFF/
Mar 14 09:39:27 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:39:30 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:39:45 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:40:00 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:41:42 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:41:57 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:42:09 ALM DISC ON UNACK_ALM	1 RTU2_INH_8173	RTU2_INHIBITS	ON/
Mar 14 09:42:37 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230240	RTU2	
Mar 14 09:42:38 ALM DISC ON UNACK_ALM	1 RTU2_INH_8065	RTU2_INHIBITS	ON/
Mar 14 09:43:12 RTN DISC EN/ENERG ACK_RTN	1 XS12230240	RTU2	DE-
Mar 14 09:43:12 RTN DISC ON ACK_RTN	1 RTU2_INH_8065	RTU2_INHIBITS	OFF/
Mar 14 09:43:18 RTN DISC ON ACK_RTN	1 RTU2_INH_8173	RTU2_INHIBITS	OFF/
Mar 14 09:54:46 RTN DISC LOW ACK_RTN	1 TSL151350006	RTU6	NORMA/
Mar 14 09:56:12 RTN DISC NORMA/ALARM ACK_RTN	1 LSL12330205	RTU2	
Mar 14 09:57:28 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 09:57:30 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 09:59:06 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:00:24 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:00:42 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:00:45 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:01:12 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:01:15 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:02:18 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:02:24 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	

É CÓPIA FEL DO DOCUMENTO ORIGINAL:
JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 14 10:02:51 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:03:00 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:03:12 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:03:15 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:04:21 ALM DISC	1 RTU2_INH_8053	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 10:04:28 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:04:30 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:04:44 ALM DISC	1 SY12330202	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 10:04:57 RTN DISC	1 ZSL12330202	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:05:18 ALM DISC	1 ZSH12330202	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:05:24 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:05:42 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:07:09 ALM DISC	1 LSL12330205	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:07:21 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:07:27 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:07:48 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:07:51 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:09:33 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:10:06 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:11:33 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:11:39 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:11:49 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:11:57 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:12:03 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:12:10 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:14:54 RTN DISC	1 ZSL53360101	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:15:15 ALM DISC	1 ZSH53360101	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:15:30 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:15:36 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:21:12 RTN DISC	1 ZSH53360101	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:21:37 ALM DISC	1 ZSL53360101	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 10:25:15 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:25:18 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			

É Cópia Fiel do Documento Original:

JOSÉ CARLOS PINHEIRO RIBEIRO
PROFESSOR
COMISSÃO DE SERVIÇOS JURÍDICOS



Mar 14 10:31:36 RTN DISC ON ACK_RTN	1 RTU2_INH_8055	RTU2_INHIBITS	OFF/
Mar 14 10:31:39 RTN DISC ON ACK_RTN	1 RTU2_INH_8158	RTU2_INHIBITS	OFF/
Mar 14 10:33:59 RTN DISC EN/ENERG ACK_RTN	1 SY12330202	RTU2	DE-
Mar 14 10:34:29 RTN DISC OPEN ACK_RTN	1 ZSH12330202	RTU2	NOT O/
Mar 14 10:34:32 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:34:35 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:34:50 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL12330202	RTU2	
Mar 14 10:37:17 RTN DISC ON ACK_RTN	1 RTU2_INH_8053	RTU2_INHIBITS	OFF/
Mar 14 10:38:59 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:39:05 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:44:59 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:45:06 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:47:02 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:47:05 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:47:20 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:49:58 ALM DISC OPEN UNACK_ALM	1 ZSO41373	RTU2	OPEN/
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH51240006	RTU2	
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL51240005	RTU2	
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 LSL51240001	RTU2	
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH51240052	RTU2	
Mar 14 10:49:58 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL51250105	RTU2	
Mar 14 10:49:58 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL51250205	RTU2	
Mar 14 10:49:58 ALM DISC OPEN UNACK_ALM	1 ZSH51250305	RTU2	OPEN/
Mar 14 10:49:58 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL51250305	RTU2	
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230109	RTU2	
Mar 14 10:49:58 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230209	RTU2	
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 TY51240012B	RTU2	DE-
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 SY51250105	RTU2	DE-
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 SY51250205	RTU2	DE-
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 XS51240012	RTU2	DE-
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 XS51240032	RTU2	DE-
Mar 14 10:49:58 RTN DISC EN/ENERG ACK_RTN	1 XS51240022	RTU2	DE-
Mar 14 10:50:10 RTN DISC OPEN ACK_RTN	1 ZSO41373	RTU2	

É O ORIGINAL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 14 10:50:10 RTN DISC	1 PSHH51240006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 LSL51240001	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 PSHH51240052	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 ZSH51250105	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 ZSL51250105	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 ZSH51250205	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 ZSH51250305	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 ZSL51250305	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 PSHH12230109	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:50:10 RTN DISC	1 PSHH12230209	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:50:37 ALM DISC	1 RTU2_INH_8081	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSO41373	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 PSHH51240006	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 LSL51240001	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 PSHH51240052	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSH51250105	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSL51250105	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSH51250205	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSH51250305	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 ZSL51250305	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 PSHH12230109	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:50:46 ALM DISC	1 PSHH12230209	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 10:51:11 RTN DISC	1 ZSO41373	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 PSHH51240006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 LSL51240001	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 PSHH51240052	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 ZSH51250105	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 ZSL51250105	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 ZSH51250205	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 ZSH51250305	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 ZSL51250305	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 PSHH12230109	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 10:51:11 RTN DISC	1 PSHH12230209	RTU2	
NORMA/ALARM ACK_RTN			

É Cópia fiel do documento original



Mar 14 10:51:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XS51240012	RTU2	
Mar 14 10:51:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XS51240032	RTU2	
Mar 14 10:51:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XS51240022	RTU2	
Mar 14 10:51:11 ALM DISC ON UNACK_ALM	1 RTU2_INH_8082	RTU2_INHIBITS	ON/
Mar 14 10:51:59 ALM DISC ON UNACK_ALM	1 RTU2_INH_8312	RTU2_INHIBITS	ON/
Mar 14 10:52:05 RTN DISC NORMA/ALARM ACK_RTN	1 PSL51240005	RTU2	
Mar 14 10:52:09 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL51240005	RTU2	
Mar 14 10:52:17 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:52:26 ALM DISC ALARM/ALARM UNACK_ALM	1 PSHH12230309	RTU2	
Mar 14 10:52:30 RTN DISC NORMA/ALARM ACK_RTN	1 PSHH12230309	RTU2	
Mar 14 10:52:47 RTN DISC NORMA/ALARM ACK_RTN	1 PSL51240005	RTU2	
Mar 14 10:53:08 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL51240005	RTU2	
Mar 14 10:53:12 RTN DISC ON ACK_RTN	1 RTU2_INH_8312	RTU2_INHIBITS	OFF/
Mar 14 10:53:33 RTN DISC NORMA/ALARM ACK_RTN	1 PSL51240005	RTU2	
Mar 14 10:53:56 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL51240005	RTU2	
Mar 14 10:54:29 RTN DISC NORMA/ALARM ACK_RTN	1 PSL51240005	RTU2	
Mar 14 10:54:50 ALM DISC ALARM/ALARM UNACK_ALM	1 LSL12330105	RTU2	
Mar 14 11:01:44 RTN DISC ON ACK_RTN	1 RTU2_INH_8082	RTU2_INHIBITS	OFF/
Mar 14 11:01:50 RTN DISC ON ACK_RTN	1 RTU2_INH_8081	RTU2_INHIBITS	OFF/
Mar 14 11:04:26 RTN DISC STOPP/RUNNI ACK_RTN	1 XB-149BS	RTU3	
Mar 14 11:15:57 ALM DISC LOW UNACK_ALM	1 TSLL51350006	RTU6	LOW/
Mar 14 11:36:51 RTN DISC NORMA/ALARM ACK_RTN	1 LSL12330105	RTU2	
Mar 14 12:17:47 ALM DISC ENERG/ENERG UNACK_ALM	1 SY51250105	RTU2	
Mar 14 12:17:53 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL51250105	RTU2	
Mar 14 12:18:02 RTN DISC C/CLOSE ACK_RTN	1 ZSL51250105	RTU2	NOT
Mar 14 12:18:08 ALM DISC OPEN UNACK_ALM	1 ZSH51250105	RTU2	OPEN/
Mar 14 12:18:12 ALM DISC ENERG/ENERG UNACK_ALM	1 SY51250205	RTU2	
Mar 14 12:18:24 RTN DISC C/CLOSE ACK_RTN	1 ZSL51250205	RTU2	NOT
Mar 14 12:18:36 ALM DISC OPEN UNACK_ALM	1 ZSH51250205	RTU2	OPEN/
Mar 14 12:26:55 RTN DISC LOW ACK_RTN	1 TSLL51350006	RTU6	NORMA/
Mar 14 12:44:08 RTN DISC OPEN ACK_RTN	1 ZSH51250205	RTU2	NOT O/
Mar 14 12:44:08 RTN DISC EN/ENERG ACK_RTN	1 SY51250205	RTU2	DE
Mar 14 12:44:11 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL51250205	RTU2	

É COPIA FIEL DO DOCUMENTO ORIGINAL
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 14 12:44:42 ALM DISC	1 SY51250205	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 12:44:54 RTN DISC	1 ZSL51250205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 12:45:09 ALM DISC	1 ZSH51250205	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 12:55:54 RTN DISC	1 ZSL12330205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 13:01:21 ALM DISC	1 ZSL12330205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 13:12:40 RTN DISC	1 ZSL12330205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 13:12:46 RTN DISC	1 ZSL53360101	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 13:13:07 ALM DISC	1 ZSH53360101	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 13:16:01 ALM DISC	1 ZSL12330205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 13:20:01 RTN DISC	1 ZSH53360101	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 13:20:25 ALM DISC	1 ZSL53360101	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 13:45:37 RTN DISC	1 ZSL12330205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 13:57:05 ALM DISC	1 ZSL12330205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 14:04:37 ALM DISC	1 PSHH12230309	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 14 14:05:46 RTN DISC	1 PSHH12230309	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 14:14:49 RTN DISC	1 LSL45514	RTU2	
NORMA/ALARM ACK_RTN			
Mar 14 15:13:17 RTN DISC	1 ZSL12330205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 15:13:20 ALM DISC	1 ZSL12330205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 15:26:29 RTN DISC	1 ZSL12330205	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 15:26:38 ALM DISC	1 ZSL12330205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 14 16:36:06 RTN DISC	1 VE-006STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 14 16:36:14 ALM DISC	1 VE-006STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 14 16:59:58 ALM DISC	1 XS12230230	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 16:59:58 ALM DISC	1 RTU2_INH_8077	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 17:29:11 RTN DISC	1 ZSL53360101	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 14 17:29:32 ALM DISC	1 ZSH53360101	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 14 17:31:54 ALM DISC	1 XS51250001	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 14 17:31:54 ALM DISC	1 RTU2_INH_8084	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 14 17:32:53 RTN DISC	1 XS51250001	RTU2	
EN/ENERG ACK_RTN			
Mar 14 17:32:53 RTN DISC	1 RTU2_INH_8084	RTU2_INHIBITS	OFF/
ON ACK_RTN			
Mar 14 17:35:38 RTN DISC	1 ZSH53360101	RTU2	NOT O/
OPEN ACK_RTN			
Mar 14 17:35:46 ALM DISC	1 XB-148AS	RTU4	
RUNNI/RUNNI UNACK_ALM			
Mar 14 17:36:02 ALM DISC	1 LSL45514	RTU2	
ALARM/ALARM UNACK_ALM			

É COPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PEREIRA GUZMÁN
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS



Mar 14 17:36:02 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL53360101	RTU2	
Mar 14 17:36:03 RTN DISC STOPP/RUNNI ACK_RTN	1 XB-149AS	RTU1	
Mar 14 17:49:59 ALM DISC RUNNI/RUNNI UNACK_ALM	1 XB-144BS	RTU3	
Mar 14 17:52:02 RTN DISC STOPP/RUNNI ACK_RTN	1 XB-144BS	RTU3	
Mar 14 18:05:29 ALM DISC ALARM/ALARM UNACK_ALM	1 LSHH12330102	RTU2	
Mar 14 18:12:11 ALM DISC ON UNACK_ALM	1 RTU2_INH_8055	RTU2_INHIBITS	ON/
Mar 14 18:12:17 ALM DISC ON UNACK_ALM	1 RTU2_INH_8158	RTU2_INHIBITS	ON/
Mar 14 18:25:16 RTN DISC EN/ENERG ACK_RTN	1 SY12230150	RTU2	DE-
Mar 14 18:25:20 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230341	RTU2	
Mar 14 18:25:20 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230331	RTU2	
Mar 14 18:25:20 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230154	RTU2	
Mar 14 18:25:20 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230254	RTU2	
Mar 14 18:25:20 RTN DISC EN/ENERG ACK_RTN	1 SY12230250	RTU2	DE-
Mar 14 18:25:20 RTN DISC EN/ENERG ACK_RTN	1 XS12230230	RTU2	DE-
Mar 14 18:25:21 RTN DISC EN/ENERG ACK_RTN	1 XS12230330	RTU2	DE-
Mar 14 18:25:21 RTN DISC EN/ENERG ACK_RTN	1 XS12230130	RTU2	DE-
Mar 14 18:25:21 RTN DISC EN/ENERG ACK_RTN	1 XS12230340	RTU2	DE-
Mar 14 18:25:41 RTN DISC OPEN ACK_RTN	1 ZSH12230250	RTU2	NOT O/
Mar 14 18:25:44 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL12230250	RTU2	
Mar 14 18:25:47 ALM DISC ALARM/ALARM UNACK_ALM	1 FSL112230340	RTU2	
Mar 14 18:26:03 RTN DISC OPEN ACK_RTN	1 ZSH12230150	RTU2	NOT O/
Mar 14 18:27:38 ALM DISC ON UNACK_ALM	1 RTU2_INH_8089	RTU2_INHIBITS	ON/
Mar 14 18:27:48 ALM DISC ON UNACK_ALM	1 RTU2_INH_8090	RTU2_INHIBITS	ON/
Mar 14 18:28:04 ALM DISC ENERG/ENERG UNACK_ALM	1 SY12230150	RTU2	
Mar 14 18:28:09 ALM DISC OPEN UNACK_ALM	1 ZSH12230150	RTU2	OPEN/
Mar 14 18:28:09 ALM DISC ENERG/ENERG UNACK_ALM	1 SY12230350	RTU2	
Mar 14 18:28:22 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230230	RTU2	
Mar 14 18:28:22 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230130	RTU2	
Mar 14 18:28:22 ALM DISC ON UNACK_ALM	1 RTU2_INH_8091	RTU2_INHIBITS	
Mar 14 18:28:26 ALM DISC ENERG/ENERG UNACK_ALM	1 SY12230250	RTU2	
Mar 14 18:28:30 RTN DISC C/CLOSE ACK_RTN	1 ZSL12230250	RTU2	NOT
Mar 14 18:28:35 ALM DISC OPEN UNACK_ALM	1 ZSH12230250	RTU2	OPEN/
Mar 14 18:28:52 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230330	RTU2	

COPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PRUDENTE GUSMÃO
DELEGADO
CISSÃO DE SERVIÇOS CARTORÁRIOS



Mar 14 18:28:52 ALM DISC ON UNACK_ALM	1 RTU2_INH_8080	RTU2_INHIBITS	ON/
Mar 14 18:29:01 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230331	RTU2	
Mar 14 18:29:55 ALM DISC ON UNACK_ALM	1 RTU2_INH_8174	RTU2_INHIBITS	ON/
Mar 14 18:30:08 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230340	RTU2	
Mar 14 18:30:08 ALM DISC ON UNACK_ALM	1 RTU2_INH_8067	RTU2_INHIBITS	ON/
Mar 14 18:30:29 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230341	RTU2	
Mar 14 18:30:32 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230341	RTU2	
Mar 14 18:30:39 RTN DISC OPEN ACK_RTN	1 VE-006STS	RTU1	CLOSE/
Mar 14 18:30:44 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230341	RTU2	
Mar 14 18:31:00 RTN DISC NORMA/ALARM ACK_RTN	1 FSL112230340	RTU2	
Mar 14 18:31:02 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230341	RTU2	
Mar 14 18:31:05 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230331	RTU2	
Mar 14 18:31:05 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230154	RTU2	
Mar 14 18:31:05 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230254	RTU2	
Mar 14 18:31:23 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230154	RTU2	
Mar 14 18:31:26 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL112230254	RTU2	
Mar 14 18:31:38 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230254	RTU2	
Mar 14 18:31:42 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230154	RTU2	
Mar 14 18:31:47 RTN DISC ON ACK_RTN	1 RTU2_INH_8174	RTU2_INHIBITS	OFF/
Mar 14 18:32:26 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230341	RTU2	
Mar 14 18:32:26 RTN DISC NORMA/ALARM ACK_RTN	1 PSL112230331	RTU2	
Mar 14 18:33:19 ALM DISC OPEN UNACK_ALM	1 VE-006STS	RTU1	OPEN/
Mar 14 18:44:35 RTN DISC ON ACK_RTN	1 RTU2_INH_8090	RTU2_INHIBITS	OFF/
Mar 14 18:53:08 RTN DISC ON ACK_RTN	1 RTU2_INH_8089	RTU2_INHIBITS	OFF/
Mar 14 18:53:11 RTN DISC ON ACK_RTN	1 RTU2_INH_8091	RTU2_INHIBITS	OFF/
Mar 14 18:55:00 RTN DISC ON ACK_RTN	1 RTU2_INH_8067	RTU2_INHIBITS	OFF/
Mar 14 18:55:17 RTN DISC ON ACK_RTN	1 RTU2_INH_8074	RTU2_INHIBITS	OFF/
Mar 14 18:55:38 RTN DISC ON ACK_RTN	1 RTU2_INH_8072	RTU2_INHIBITS	OFF/
Mar 14 19:12:02 RTN DISC STOPP/RUNNI ACK_RTN	1 XB-148AS	RTU4	
Mar 14 19:56:51 RTN DISC NORMA/ALARM ACK_RTN	1 LSL112330205	RTU2	
Mar 14 22:21:03 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360015	RTU2	
Mar 14 22:21:03 ALM DISC ON UNACK_ALM	1 RTU2_INH_8109	RTU2_INHIBITS	ON/
Mar 14 22:22:17 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360025	RTU2	

É Cópia do Documento Original

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 14 22:22:17 ALM DISC ON UNACK_ALM	1	RTU2_INH_8110	RTU2_INHIBITS	ON/
Mar 14 22:30:18 RTN DISC OPEN ACK_RTN	1	XV-65002S	RTU1	CLOSE/
Mar 14 22:47:03 RTN DISC EN/ENERG ACK_RTN	1	XS53360025	RTU2	DE-
Mar 14 22:47:03 RTN DISC ON ACK_RTN	1	RTU2_INH_8110	RTU2_INHIBITS	OFF/
Mar 14 22:48:18 ALM DISC ON UNACK_ALM	1	RTU2_INH_8342	RTU2_INHIBITS	ON/
Mar 14 22:48:30 RTN DISC ON ACK_RTN	1	RTU2_INH_8342	RTU2_INHIBITS	OFF/
Mar 14 23:18:58 ALM DISC ON UNACK_ALM	1	RTU2_INH_8053	RTU2_INHIBITS	ON/
Mar 14 23:19:41 ALM DISC ENERG/ENERG UNACK_ALM	1	SY12330202	RTU2	
Mar 14 23:19:54 RTN DISC C/CLOSE ACK_RTN	1	ZSL12330202	RTU2	NOT
Mar 14 23:20:15 ALM DISC OPEN UNACK_ALM	1	ZSH12330202	RTU2	OPEN/
Mar 14 23:28:47 ALM DISC ALARM/ALARM UNACK_ALM	1	LSLL12330205	RTU2	
Mar 14 23:51:31 RTN DISC EN/ENERG ACK_RTN	1	SY12330202	RTU2	DE-
Mar 14 23:51:31 RTN DISC ON ACK_RTN	1	RTU2_INH_8053	RTU2_INHIBITS	OFF/
Mar 14 23:51:55 RTN DISC OPEN ACK_RTN	1	ZSH12330202	RTU2	NOT O/
Mar 14 23:52:19 ALM DISC CLOSE/CLOSE UNACK_ALM	1	ZSL12330202	RTU2	
Mar 14 23:56:34 ALM DISC RUNNI/RUNNI UNACK_ALM	1	XB-149AS	RTU1	
Mar 15 00:21:53 ALM DISC ALARM/ALARM UNACK_ALM	1	LSHH52527	RTU2	
Mar 15 00:21:53 RTN DISC NORMA/ALARM ACK_RTN	1	LSLL45514	RTU2	
Mar 15 00:22:03 RTN DISC OPEN ACK_RTN	1	VE-006STS	RTU1	CLOSE/
Mar 15 00:22:07 RTN DISC OPEN ACK_RTN	1	VE-010STS	RTU1	CLOSE/
Mar 15 00:22:07 ALM DISC TRIP UNACK_ALM	1	XB-269A	RTU1	TRIP/
Mar 15 00:22:07 ALM DISC TRIP UNACK_ALM	1	XB-263D	RTU1	TRIP/
Mar 15 00:22:07 ALM DISC TRIP UNACK_ALM	1	XA-280A	RTU1	TRIP/
Mar 15 00:22:07 ALM DISC TRIP UNACK_ALM	1	XE-159AA	RTU1	TRIP/
Mar 15 00:22:07 ALM DISC TRIP UNACK_ALM	1	XE-159AB	RTU1	TRIP/
Mar 15 00:22:07 ALM DISC FAULT/FAULT UNACK_ALM	1	VE-010STS_F	RTU1	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XB-149B	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XB-148D	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XB-144B	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	TG3FUEL SOV2	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XV-59012	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XV-59013	RTU3	TRIP/
Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1	XV-59018	RTU3	TRIP/

É Cópia do Documento Original

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTOGRAFICOS

Mar 15 00:22:10 ALM DISC TRIP UNACK_ALM	1 XA-428B	RTU3
Mar 15 00:22:11 RTN DISC OPEN ACK_RTN	1 VE-002STS	RTU1
Mar 15 00:22:11 RTN DISC STOPP/RUNNI ACK_RTN	1 XB-149AS	RTU1
Mar 15 00:22:11 RTN DISC NORMA/FAULT ACK_RTN	1 TG3FUELSOV2_F	RTU3
Mar 15 00:22:11 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-684HA	RTU4
Mar 15 00:22:11 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-678D	RTU4
Mar 15 00:22:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XB-148A	RTU4
Mar 15 00:22:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XB-148C	RTU4
Mar 15 00:22:11 ALM DISC ENERG/ENERG UNACK_ALM	1 XV-59023	RTU4
Mar 15 00:22:12 ALM DISC ENERG/ENERG UNACK_ALM	1 XV-59024	RTU4
Mar 15 00:22:12 ALM DISC ENERG/ENERG UNACK_ALM	1 XV-59027	RTU4
Mar 15 00:22:12 ALM DISC ENERG/ENERG UNACK_ALM	1 XV-59028	RTU4
Mar 15 00:22:12 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-684JA	RTU4
Mar 15 00:22:12 RTN DISC EN/ENERG ACK_RTN	1 DF-5251-09	RTU4
Mar 15 00:22:12 RTN DISC EN/ENERG ACK_RTN	1 DF-5251-10	RTU4
Mar 15 00:22:14 ALM DISC RUNNI/RUNNI UNACK_ALM	1 XV-59024S	RTU4
Mar 15 00:22:14 RTN DISC OPEN ACK_RTN	1 DF-5251-09S	RTU4
Mar 15 00:22:14 RTN DISC NORMA/FAULT ACK_RTN	1 YB-684JA_F	RTU4
Mar 15 00:22:15 ALM DISC DISCR/DISCR UNACK_ALM	1 XV-59003_VD	RTU1
Mar 15 00:22:21 ALM DISC DISCR/DISCR UNACK_ALM	1 DF-5251-10S_D	RTU4
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS42591	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS42593	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS42595	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS42597	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS42599	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52751	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52570	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52721	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52580	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52717	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52725	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52747	RTU2
Mar 15 00:22:24 RTN DISC EN/ENERG ACK_RTN	1 XS52755	RTU2

TRIP/
CLOSE/



DE-

DE-

CLOSE/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

DE-

DE-

DE-

JOSÉ CARLOS PINHEIRO GUERAO
DE DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-



Mar 15 00:22:27 ALM DISC	1 XB-265U	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-268K	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-268B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-263S	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-264G	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-266B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-266A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-265R	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-262M	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-266F	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-276B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-274B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-149A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-143A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-148B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-144A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-146A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XE-146D	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XB-146B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 SPARE_d9058_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 SPARE_d9059_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 FZ-002QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 FZ-005QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 FZ-006QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 FZ-001QBA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XM-275AB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XM-275BA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XA-277	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XV-65002	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XV-59003	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XV-59007	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XV-59008	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:27 ALM DISC	1 XV-59009	RTU1	TRIP/
TRIP UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSÉ CARLOS PUELTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:22:27	ALM DISC	1	XV-59010	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	XV-59032	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	SPARE_d9079_RTU	RTU1	ON/
ON UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	XS51400101	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	XS51400102	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	XS51400103	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:27	ALM DISC	1	XA-275B1	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XA-275B2	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263G	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-266C	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263J	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-262B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263L	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-262D	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265M	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265D	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263P	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-267R	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-264A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263N	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-262F	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-264B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-267F	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-266H	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263E	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-263B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-262A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265Q	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-265P	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	VE-025-028GS	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:22:28	ALM DISC	1	XB-276A	RTU3	TRIP/
TRIP UNACK_ALM					

É Cópia do documento original.

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SEMEIOS CARTÓGRAFOS



Mar 15 00:22:28 ALM DISC	1 XE-159BA	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:28 ALM DISC	1 XB-185	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:28 ALM DISC	1 XB-146C	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:28 ALM DISC	1 XV-65004	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XV-59019	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XV-59020	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XV-59021	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XV-59033	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XA-275C1	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XA-275C2	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 XM-568	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684AA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684CA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684TA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 SPARE_d9004_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 SPARE_d9005_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-678A	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-678C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684P	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684Q	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684BA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684DA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 RTN DISC	1 SPARE_d9013_RTU	RTU4	OFF/
ON ACK_RTN			
Mar 15 00:22:29 ALM DISC	1 YA-678E	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 RTN DISC	1 SPARE_d9015_RTU	RTU4	OFF/
ON ACK_RTN			
Mar 15 00:22:29 ALM DISC	1 YB-684R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:29 ALM DISC	1 YB-684S	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:30 ALM DISC	1 YB-684NA	RTU4	
ON UNACK_ALM			
Mar 15 00:22:30 RTN DISC	1 DF-5251-03	RTU4	
EN/ENERG ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 DF-5251-04	RTU4	
EN/ENERG ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 DF-5251-05	RTU4	
EN/ENERG ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 DF-5251-06	RTU4	
EN/ENERG ACK_RTN			

É Cópia fiel do documento original.

JOSE CARLOS FERNANDES GUSMÃO
ON DIRETOR
UNSAO DE SERVICOS CARTORARIAS

DE-

DE-

DE-

DE-



Mar 15 00:22:30 ALM DISC	1 XL51113039R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:30 ALM DISC	1 XL51114039R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:30 RTN DISC	1 XB-267E_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 XB-185_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 XV-65004_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:30 RTN DISC	1 XV-59020_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-017STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-069STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-035STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-002GSS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-072STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-018STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-064STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-014STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-041STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-042STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-072STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-076STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 VE-013GSS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:31 ALM DISC	1 XV-65002S	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:22:31 RTN DISC	1 XB-268K_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 XB-266B_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 XB-266P_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 XB-146A_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:31 RTN DISC	1 XB-146B_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:22:32 RTN DISC	1 DF-5251-03S	RTU4	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:32 RTN DISC	1 DF-5251-06S	RTU4	CLOSE/
OPEN ACK_RTN			
Mar 15 00:22:32 ALM DISC	1 SPARE_d9157_RTU	RTU4	
FAULT/FAULT UNACK_ALM			
Mar 15 00:22:32 ALM DISC	1 SPARE_d9159_RTU	RTU4	
FAULT/FAULT UNACK_ALM			
Mar 15 00:22:34 RTN DISC	1 VE-034STS	RTU3	
OPEN ACK_RTN			
Mar 15 00:22:34 RTN DISC	1 VE-027STS	RTU3	
OPEN ACK_RTN			
Mar 15 00:22:34 RTN DISC	1 VE-030STS	RTU3	
OPEN ACK_RTN			
Mar 15 00:22:34 RTN DISC	1 VE-015STS	RTU3	
OPEN ACK_RTN			

É Cópia Fiel do Documento Original.

CLOSE/

CLOSE/

CLOSE/

JOSÉ CARLOS PAGANELLO GUSMÃO
CARIÓTIPO
CARIÓTIPO DE SÍNDROME DE DOWN



Mar 15 00:22:34 RTN DISC 1 VE-009STS RTU3
OPEN ACK_RTN
Mar 15 00:22:34 RTN DISC 1 VE-066STS RTU3
OPEN ACK_RTN
Mar 15 00:22:34 RTN DISC 1 VE-062STS RTU3
OPEN ACK_RTN
Mar 15 00:22:34 RTN DISC 1 VE-061STS RTU3
OPEN ACK_RTN
Mar 15 00:22:34 RTN DISC 1 VE-036STS RTU3
OPEN ACK_RTN
Mar 15 00:22:34 RTN DISC 1 VE-067STS RTU3
OPEN ACK_RTN
Mar 15 00:22:35 ALM DISC 1 VE-033STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-006GSS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-007GSS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-031STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-005GSS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-012GSS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-019STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-011STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-086STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-075STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-100STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-099STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-101STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-009GSS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-047STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 VE-160STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 XB-146B_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 XV-65002_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 XV-59008_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 ALM DISC 1 XV-59009_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:22:35 RTN DISC 1 SPARE_G9635_RTU RTU4
ON ACK_RTN
Mar 15 00:22:38 ALM DISC 1 YB-684TAS_D RTU4
DISCR/DISCR UNACK_ALM
Mar 15 00:22:38 ALM DISC 1 YB-684NAS_D RTU4
DISCR/DISCR UNACK_ALM
Mar 15 00:22:38 ALM DISC 1 DF-5251-04S_D RTU4
DISCR/DISCR UNACK_ALM
Mar 15 00:22:38 ALM DISC 1 SPARE_d8828_RTU RTU4
DISCR/DISCR UNACK_ALM
Mar 15 00:22:44 RTN DISC 1 SPARE_d9636_RTU RTU4
ON ACK_RTN
Mar 15 00:22:44 RTN DISC 1 SPARE_d8828_RTU RTU4
NORMA/DISCR ACK_RTN

CLOSE/

CLOSE/

CLOSE/

CLOSE/

CLOSE/

CLOSE/

OFF/

É COPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS
OFF/



Mar 15 00:22:56 ALM DISC	1 XL51113039N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:22:58 ALM DISC	1 ESD-LVL2_RTU3	RTU3	
ALARM/ALARM UNACK_ALM			
Mar 15 00:22:59 RTN DISC	1 SY60250301	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY51350001	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 TY51350004B	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY51350002	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 PY51350027B	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 TY51350020B	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY51350006	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY51250004	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY51250005	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12101321	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12101322	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100521	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100522	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100221	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100222	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100421	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12100422	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12102221	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 SY12102222	RTU6	DE-
EN/ENERG ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS12105003	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS12105012	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS12230180	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS60250301	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250302	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250311	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250321	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250401	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250411	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250421	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68250711	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 RTN DISC	1 XS68251111	RTU6	
NORMA/TRIPP ACK_RTN			

É CÓPIA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:22:59 RTN DISC	1 XS68251121	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 00:22:59 ALM DISC	1 ESD-LVL4_RTU6	RTU6	ON/
ON UNACK_ALM			
Mar 15 00:23:00 ALM DISC	1 HS12003333	RTU4	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:00 RTN DISC	1 SY12101721	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:00 ALM DISC	1 XS72009	RTU4	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:00 RTN DISC	1 DF-5251-07	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:00 RTN DISC	1 DF-5251-08	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:00 RTN DISC	1 SY12100002	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:00 RTN DISC	1 XS12230380	RTU5	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:00 ALM DISC	1 ESD-LVL2_RTU5	RTU5	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:02 RTN DISC	1 VE-023GSS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:02 RTN DISC	1 VE-016GSS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:02 RTN DISC	1 VE-046STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:03 ALM DISC	1 XB-263T	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-262K	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-263U	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-262L	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-263Q	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-262H	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-265J	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-264E	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-267A	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-266E	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-268G	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-268F	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XB-143B	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 TG3FUELSOV1	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 XS51400005	RTU3	
TRIP UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 SPARE_09097_RTU	RTU3	
ON UNACK_ALM			
Mar 15 00:23:03 RTN DISC	1 DF-5251-07S	RTU4	
OPEN ACK_RTN			
Mar 15 00:23:03 ALM DISC	1 DF-5251-08_F	RTU4	
FAULT/FAULT UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12100222	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12102222	RTU6	OPEN/
OPEN UNACK_ALM			

É CÓPIA DO DOCUMENTO ORIGINAL

ON/
JOSE CARLOS FONSECA GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CASTROVIANOS



Mar 15 00:23:03 ALM DISC	1 ZSH12100422	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12100521	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12100522	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12101321	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 ALM DISC	1 ZSH12101322	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 RTN DISC	1 ZSL12101322	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:03 RTN DISC	1 ZSL51350002	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:03 RTN DISC	1 ZSL51250004	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:03 ALM DISC	1 ZSH51250005	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 RTN DISC	1 ZSL51250005	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:03 ALM DISC	1 ZSH68250301	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:03 RTN DISC	1 ZSL68250301	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:04 RTN DISC	1 XB-268G_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:23:04 RTN DISC	1 XB-143B_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 00:23:04 ALM DISC	1 PSL112330113	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:04 ALM DISC	1 PSL112330213	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:05 ALM DISC	1 PSL112230341	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:05 ALM DISC	1 PSL112230331	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH51250105	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 RTN DISC	1 ZSH51250205	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL51250205	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230101	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL12230201	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230102	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 RTN DISC	1 ZSH12230111	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL12230111	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230201	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL12230201	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230202	RTU2	
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL12230202	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230211	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:05 ALM DISC	1 ZSL12230211	RTU2	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:23:05 RTN DISC	1 ZSH12230105	RTU2	NOT O/
OPEN ACK_RTN			

É Cópia fiel do documento original

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
CISSÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:23:06 RTN DISC	1 SY12230105	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230305	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230108	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230109	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS42033	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS42036	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SPARE_d9089_RTN	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230205	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230208	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230209	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY53360001	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 BDV30033A	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 BDV30331A	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 ESDV30001A	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 ESDV30007	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 ESDV30048A	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 ESDV30307	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 ESDV30601A	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SOV30070	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SOV30370	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XY53360101B	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230101	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230102	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230111	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230201	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230202	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY12230211	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY51250105	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SY51250205	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS43150	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS53360041	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS53360103	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS53360113	RTU2	DE-
EN/ENERG ACK_RTN			

É CÓPIA DE DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR

CIVIL DE SERVIÇOS CARTORARIOS



Mar 15 00:23:06 RTN DISC	1 XS53360202	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS53360212	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 SPARE_d9208_RTN	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS30130	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS12230230	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:06 RTN DISC	1 XS12230280	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230308	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230330	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230540	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230740	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12330011	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12330031	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS53360010	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230130	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230309	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230340	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12230640	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12330001	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS12330021	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS53360015	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 XS54120013	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 ZSL12100222	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 ALM DISC	1 ZSH12101721	RTU5	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 ZSH12102221	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:07 RTN DISC	1 ZSL12102222	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 ALM DISC	1 ZSH12100421	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:07 RTN DISC	1 ZSL12100422	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 ZSL12100521	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 ZSL12100522	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 RTN DISC	1 ZSL12101321	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:07 ALM DISC	1 SY12100221_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY12100421_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY12100521_VD	RTU6	
DISCR/DISCR UNACK_ALM			

É COPIA FIEL DO ORIGINAL
DESAO DE SERVAÇOS CARTORARIOS



Mar 15 00:23:07 ALM DISC	1 SY12100522_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY12101321_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY12102221_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY12102222_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SYS1350001_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 SY51350006_VD	RTU6	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 ZSH12330207	RTU2	ON/
ON UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 PSL12230154	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:07 ALM DISC	1 PSL12230254	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:23:07 RTN DISC	1 ZSH12230250	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:08 RTN DISC	1 ZSL12101721	RTU5	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:08 RTN DISC	1 VE-023STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:09 ALM DISC	1 ZSH12100221	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:09 RTN DISC	1 ZSL12100221	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 ZSL12102221	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 ZSL12100421	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 00:23:09 ALM DISC	1 ZSH51350006	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:09 RTN DISC	1 SY12100521_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 SY12100522_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 SY12101321_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 SY12102221_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:09 RTN DISC	1 SY12102222_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:10 ALM DISC	1 XB-263C	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:10 ALM DISC	1 XB-265G	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:10 ALM DISC	1 XB-265C	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XB-264C	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XB-265E	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XB-264D	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 VE-019GS	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XB-268H	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XA-280B	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XA-275A1	RTU1	
TRIP UNACK_ALM			
Mar 15 00:23:11 ALM DISC	1 XA-275A2	RTU1	
TRIP UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FERNANDES GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARTÓGRAFOS

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/



Message	Count	RTU	Status
Mar 15 00:23:13 RTN DISC C/CLOSE ACK_RTN	1	ZSL51350006	RTU6
Mar 15 00:23:13 RTN DISC NORMA/DISCR ACK_RTN	1	SY12100221_VD	RTU6
Mar 15 00:23:13 RTN DISC NORMA/DISCR ACK_RTN	1	SY12100421_VD	RTU6
Mar 15 00:23:14 RTN DISC NORMA/ALARM ACK_RTN	1	HS12003333	RTU4
Mar 15 00:23:14 RTN DISC TRIP ACK_RTN	1	XS51110021	RTU5
Mar 15 00:23:14 RTN DISC NORMA/ALARM ACK_RTN	1	HS12003333-F	RTU4
Mar 15 00:23:14 RTN DISC TRIP ACK_RTN	1	XS51110025	RTU5
Mar 15 00:23:14 RTN DISC TRIP ACK_RTN	1	XS51110031	RTU5
Mar 15 00:23:14 RTN DISC TRIP ACK_RTN	1	XS51110035	RTU5
Mar 15 00:23:15 RTN DISC OPEN ACK_RTN	1	VE-024GSS	RTU1
Mar 15 00:23:15 ALM DISC ALARM/ALARM UNACK_ALM	1	PSLL51240005	RTU2
Mar 15 00:23:15 RTN DISC OPEN ACK_RTN	1	VE-038STS	RTU1
Mar 15 00:23:15 RTN DISC OPEN ACK_RTN	1	VE-043STS	RTU1
Mar 15 00:23:15 ALM DISC OPEN UNACK_ALM	1	XV-59007S	RTU1
Mar 15 00:23:15 RTN DISC NORMA/FAULT ACK_RTN	1	XB-143A_F	RTU1
Mar 15 00:23:15 ALM DISC CLOSE/CLOSE UNACK_ALM	1	ZSL12230250	RTU2
Mar 15 00:23:15 RTN DISC OPEN ACK_RTN	1	ZSH12330205	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	ESDV41342	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	ESDV41353	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	KS89021	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS80901	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS80923	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS80924	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS89022	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	SY51250010	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS60132	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS60131	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS60108	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	SOV41346	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	SOV41366	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS51240012	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS51240032	RTU2
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1	XS60130	RTU2

NOT

NORMA/

NORMA/

NORMA/

NORMA/

CLOSE/

CLOSE/

CLOSE/

OPEN/

NOT O/

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

É CÓPIA DO DOCUMENTO ORIGINAL

JOSE CARLOS FERNANDES GUSMÃO
DIRETOR
DIVISÃO DE REGISTRO E CARTÓGRAFIA

DE-

DE-

DE-



Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS51250031	RTU2	DE-
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS89001	RTU2	DE-
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS89002	RTU2	DE-
Mar 15 00:23:15 ALM DISC ENERG/ENERG UNACK_ALM	1 XS72002	RTU2	
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS51210001	RTU2	DE-
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS51240022	RTU2	DE-
Mar 15 00:23:15 RTN DISC EN/ENERG ACK_RTN	1 XS51250041	RTU2	DE-
Mar 15 00:23:17 RTN DISC LOW ACK_RTN	1 PSL151110028	RTU5	NORMA/
Mar 15 00:23:17 RTN DISC LOW ACK_RTN	1 PSL151110038	RTU5	NORMA/
Mar 15 00:23:17 RTN DISC EN/ENERG ACK_RTN	1 SY12100011	RTU5	DE-
Mar 15 00:23:17 RTN DISC EN/ENERG ACK_RTN	1 SY12100021	RTU5	DE-
Mar 15 00:23:18 RTN DISC OPEN ACK_RTN	1 ZS041342	RTU2	NOT O/
Mar 15 00:23:18 RTN DISC OPEN ACK_RTN	1 ZS041353	RTU2	NOT O/
Mar 15 00:23:18 RTN DISC OPEN ACK_RTN	1 ZSH12230150	RTU2	NOT O/
Mar 15 00:23:18 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-008STS_VD	RTU1	
Mar 15 00:23:18 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-004STS_VD	RTU1	
Mar 15 00:23:19 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-022STS_VD	RTU1	
Mar 15 00:23:19 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-024STS_VD	RTU1	
Mar 15 00:23:19 ALM DISC DISCR/DISCR UNACK_ALM	1 XV-59007_VD	RTU1	
Mar 15 00:23:24 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSC41353	RTU2	
Mar 15 00:23:24 ALM DISC ALARM/ALARM UNACK_ALM	1 FSL112230340	RTU2	
Mar 15 00:23:26 ALM DISC ALARM/ALARM UNACK_ALM	1 HS12003333	RTU4	
Mar 15 00:23:26 ALM DISC DISCR/DISCR UNACK_ALM	1 SY12100002_VD	RTU5	
Mar 15 00:23:26 ALM DISC ALARM/ALARM UNACK_ALM	1 HS12003333-F	RTU4	
Mar 15 00:23:26 RTN DISC NORMA/ALARM ACK_RTN	1 XS72009	RTU4	
Mar 15 00:23:26 RTN DISC NORMA/ALARM ACK_RTN	1 ESD-LVL2_RTU5	RTU5	
Mar 15 00:23:26 RTN DISC TRIP ACK_RTN	1 XB-263C	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-265G	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-265C	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-264C	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-265E	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-264D	RTU1	NORMA/
Mar 15 00:23:27 RTN DISC TRIP ACK_RTN	1 XB-262M	RTU1	NORMA/

É COPIA FIEL DO DOCUMENTO ORIGINAL



Mar 15 00:23:27 RTN DISC	1 VE-019GS	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XB-268H	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 FZ-001QBA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XM-275AB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XM-275BA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59003	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59007	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59008	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59009	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59010	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XV-59032	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XA-280B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XA-275A1	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 XA-275A2	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-008STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-004STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-022STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-024STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-075STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-101STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-009GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VE-047STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 VB-160STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PMY12100202	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PWY12100203	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 AMY12100204	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 AWY12100205	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PMY12102202	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PWY12102203	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 AMY12102204	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 AWY12102205	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PMY12100502	RTU6	
EN/ENERG ACK_RTN			
Mar 15 00:23:27 RTN DISC	1 PWY12100503	RTU6	
EN/ENERG ACK_RTN			

É CÓPIA DE DO DOCUMENTO ORIGINAL:

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-

DE-



Mar 15 00:23:27 RTN DISC EN/ENERG ACK_RTN	1 AMY12100504	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 AWY12100505	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 PMY12101302	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 PWY12101303	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 AMY12101304	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 AWY12101305	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 PMY12100402	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 PWY12100403	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 AMY12100404	RTU6	DE-
Mar 15 00:23:28 RTN DISC EN/ENERG ACK_RTN	1 AWY12100405	RTU6	DE-
Mar 15 00:23:28 RTN DISC NORMA/DISCR ACK_RTN	1 SY51350006_VD	RTU6	
Mar 15 00:23:28 RTN DISC ON ACK_RTN	1 ESD-LVL4_RTU6	RTU6	OFF/
Mar 15 00:23:28 RTN DISC NORMA/ALARM ACK_RTN	1 ESD-LVL2_RTU3	RTU3	
Mar 15 00:23:29 RTN DISC NORMA/ALARM ACK_RTN	1 HS12003333	RTU4	
Mar 15 00:23:29 ALM DISC OPEN UNACK_ALM	1 ZSH12100021	RTU5	OPEN/
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684AA	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684TA	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684N	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684P	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684Q	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684BA	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684DA	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YA-678E	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684R	RTU4	DE-
Mar 15 00:23:29 RTN DISC EN/ENERG ACK_RTN	1 YB-684S	RTU4	DE-
Mar 15 00:23:29 RTN DISC ON ACK_RTN	1 YB-684NA	RTU4	DE-EN/
Mar 15 00:23:29 RTN DISC NORMA/DISCR ACK_RTN	1 YB-684TAS_D	RTU4	
Mar 15 00:23:29 RTN DISC NORMA/DISCR ACK_RTN	1 YB-684NAS_D	RTU4	
Mar 15 00:23:30 ALM DISC TRIP UNACK_ALM	1 XS12230380	RTU5	
Mar 15 00:23:30 ALM DISC OPEN UNACK_ALM	1 VE-024GSS	RTU1	
Mar 15 00:23:31 ALM DISC OPEN UNACK_ALM	1 VE-038STS	RTU1	OPEN/
Mar 15 00:23:31 ALM DISC OPEN UNACK_ALM	1 VE-076STS	RTU1	OPEN/
Mar 15 00:23:31 ALM DISC OPEN UNACK_ALM	1 VE-013GSS	RTU1	OPEN/

É CÓPIA FEITA DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
TRIP DIRETOR
CNSÃO DE SERVIÇOS CARTÓGRAFOS



Mar 15 00:23:31 ALM DISC FAULT/FAULT UNACK_ALM	1 XB-266F_F	RTU1
Mar 15 00:23:31 ALM DISC FAULT/FAULT UNACK_ALM	1 XB-143A_F	RTU1
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS89021	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS80901	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS80923	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS80924	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XSB9022	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS30133	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS42195	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS42200	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS42205	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 SPARE_d9056_RTU	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS30135	RTU2
Mar 15 00:23:31 ALM DISC ENERG/ENERG UNACK_ALM	1 XS60132	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS43160	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS60131	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS42033	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS42036	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 SPARE_d9089_RTU	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS60108	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS43150	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360041	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360103	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360113	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360202	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS53360212	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 SPARE_d9208_RTU	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS30130	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 SOV41346	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	2 SOV41366	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230280	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230540	RTU2
Mar 15 00:23:32 ALM DISC ENERG/ENERG UNACK_ALM	1 XS12230740	RTU2

É CÓPIA DE UM DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL RUSINO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:23:32 ALM DISC	1 XS12330031	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS60130	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS53360010	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS89001	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS89002	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 RTN DISC	1 XS72002	RTU2
EN/ENERG ACK_RTN		
Mar 15 00:23:32 ALM DISC	1 XS12230640	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS12330001	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS51210001	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS51250041	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS53360015	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS54120013	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 00:23:32 RTN DISC	1 PSHH51350025	RTU6
HIGH ACK_RTN		
Mar 15 00:23:32 ALM DISC	1 XS12105003	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS12105012	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS12230180	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS68250301	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS68250302	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:32 ALM DISC	1 XS68250311	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68250321	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68250401	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68250411	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68250421	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68250711	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68251111	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 XS68251121	RTU6
TRIPP/TRIPP UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 VE-023GSS	RTU3
OPEN UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 VE-046STS	RTU3
OPEN UNACK_ALM		
Mar 15 00:23:33 ALM DISC	1 VE-062STS	RTU3
OPEN UNACK_ALM		
Mar 15 00:23:33 RTN DISC	1 XB-263T	RTU3
TRIP ACK_RTN		
Mar 15 00:23:33 RTN DISC	1 XB-262K	RTU3
TRIP ACK_RTN		
Mar 15 00:23:33 RTN DISC	1 XB-263U	RTU3
TRIP ACK_RTN		
Mar 15 00:23:33 RTN DISC	1 XB-262L	RTU3
TRIP ACK_RTN		

DE-

NORMA/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

OPEN/
JOSE CARLOS RIBEIRO GUSMÃO
OPERADOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS
OPEN/

NORMA/

NORMA/

NORMA/

NORMA/

Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-263Q	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-262H	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-265J	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-264E	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-267A	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-266E	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-268C	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-268F	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-265B	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-264B	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 VE-025-028GS	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-276A	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XB-143B	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 TG3FUELSOV1	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XS51400005	RTU3	NORMA/
Mar 15 00:23:33 RTN DISC ON ACK_RTN	2 SPARE_d9097_RTU	RTU3	OFF/
Mar 15 00:23:33 RTN DISC TRIP ACK_RTN	1 XM-568	RTU3	NORMA/
Mar 15 00:23:34 ALM DISC FAULT/FAULT UNACK_ALM	1 XB-268G_F	RTU3	
Mar 15 00:23:34 ALM DISC FAULT/FAULT UNACK_ALM	1 XB-143B_F	RTU3	
Mar 15 00:23:41 RTN DISC C/CLOSE ACK_RTN	1 ZSL12100021	RTU5	NOT
Mar 15 00:23:43 ALM DISC TRIP UNACK_ALM	1 XB-262M	RTU1	TRIP/
Mar 15 00:23:43 ALM DISC TRIP UNACK_ALM	1 XV-59007	RTU1	TRIP/
Mar 15 00:23:43 ALM DISC TRIP UNACK_ALM	1 XV-59008	RTU1	TRIP/
Mar 15 00:23:43 ALM DISC TRIP UNACK_ALM	1 XV-59009	RTU1	TRIP/
Mar 15 00:23:44 ALM DISC TRIP UNACK_ALM	1 XB-265B	RTU3	TRIP/
Mar 15 00:23:44 ALM DISC TRIP UNACK_ALM	1 XB-264B	RTU3	TRIP/
Mar 15 00:23:44 ALM DISC TRIP UNACK_ALM	1 VE-025-028GS	RTU3	TRIP/
Mar 15 00:23:44 ALM DISC TRIP UNACK_ALM	1 XB-276A	RTU3	TRIP/
Mar 15 00:23:44 ALM DISC TRIP UNACK_ALM	1 XM-568	RTU3	TRIP/
Mar 15 00:23:44 ALM DISC DISCR/DISCR UNACK_ALM	1 SY12100011_VD	RTU5	
Mar 15 00:23:45 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-684AA	RTU4	
Mar 15 00:23:45 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-684TA	RTU4	
Mar 15 00:23:45 ALM DISC ENERG/ENERG UNACK_ALM	1 YB-684N	RTU4	



É COPIA DO DOCUMENTO ORIGINAL
 JOSE CARLOS MENDES GUSMÃO
 DIRETOR
 DIVISÃO DE SERVIÇOS CARTOGRAFIAIS



Mar 15 00:23:45 ALM DISC	1 YB-684P	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YB-684Q	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YB-684BA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	2 YB-684DA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YA-678E	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YB-684R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YB-684S	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:23:45 ALM DISC	1 YB-684NA	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:23:46 RTN DISC	1 XB-266F_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:23:47 ALM DISC	1 ZSH51350001	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:23:49 RTN DISC	1 VE-062STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:50 ALM DISC	1 XV-59023S_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:50 ALM DISC	1 XV-59024S_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:50 ALM DISC	1 XV-59027S_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:50 ALM DISC	1 XV-59028S_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:51 ALM DISC	1 VE-009GSS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:51 ALM DISC	1 VE-047STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:53 ALM DISC	1 YB-684TAS_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:53 ALM DISC	1 YB-684NAS_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 FZ-001QBA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 XM-275AB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 XM-275BA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 XV-59003	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 XV-59010	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:55 ALM DISC	1 XV-59032	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:23:58 RTN DISC	1 ZSH12230109	RTU2	NOT O/
OPEN ACK_RTN			
Mar 15 00:23:59 RTN DISC	1 VE-076STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:23:59 RTN DISC	1 VE-013GSS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:24:02 ALM DISC	1 RTU5_INH_8215	RTU5_INHIBITS	ON/
ON UNACK_ALM			
Mar 15 00:24:03 ALM DISC	1 VE-075STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:24:03 ALM DISC	1 VE-101STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:24:03 ALM DISC	1 VE-160STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:24:07 RTN DISC	1 XB-265U	RTU1	
TRIP ACK_RTN			

É COPIA DO DOCUMENTO ORIGINAL


JOSE CARLOS POSENTIL GUSMÃO
DIRETOR
NORMAS E SERVIÇOS DE CARTOGRAFIA



Mar 15 00:24:07 RTN DISC	1 XB-268K	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-268B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-263S	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-264G	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-266B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-266A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-265R	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-262M	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-266F	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-276B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-274B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-149A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-143A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-148B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-144A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-146A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-146D	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 XB-146B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 SPARE_d9058_RTU	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 SPARE_d9059_RTU	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 FZ-002QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:07 RTN DISC	1 FZ-005QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 FZ-006QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 FZ-001QBA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XM-275AB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XM-275BA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XA-277	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-65002	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-59003	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-59007	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-59008	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-59009	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XV-59010	RTU1	NORMA/
TRIP ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

SECRETARIA DE SEGURANÇA
DIRETORIA DE SERVIÇOS CANTORIAS



Mar 15 00:24:08 RTN DISC	1 XV-59032	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 SPARE_d9079_RTN	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XA-275B1	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 XA-275B2	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-033STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-006GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-007GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-031STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-005GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-012GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-019STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-011STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-086STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-075STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-100STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-099STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-101STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-009GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-047STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	1 VE-160STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 RTN DISC	2 XB-146B_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:24:08 ALM DISC	1 RTU5_INH_8216	RTU5_INHIBITS	ON/
ON UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-069STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-071STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-014STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-072STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-076STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 VE-013GSS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 XB-268K_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:11 ALM DISC	2 XB-266B_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 XB-266F_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:11 ALM DISC	2 XB-146A_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:11 ALM DISC	1 XB-146B_F	RTU1	
FAULT/FAULT UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-684AA	RTU4	DE-
Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-684CA	RTU4	DE-
Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-684HA	RTU4	DE-
Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-684TA	RTU4	DE-
Mar 15 00:24:11 RTN DISC ON ACK_RTN	1 SPARE_d9004_RTN	RTU4	OFF/
Mar 15 00:24:11 RTN DISC ON ACK_RTN	1 SPARE_d9005_RTN	RTU4	OFF/
Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-678A	RTU4	DE-
Mar 15 00:24:11 RTN DISC EN/ENERG ACK_RTN	1 YB-678C	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684N	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684P	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684Q	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684BA	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684DA	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YA-678E	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-678D	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684R	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684S	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 XB-148A	RTU4	DE-
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 XB-148C	RTU4	DE-
Mar 15 00:24:12 RTN DISC ON ACK_RTN	1 YB-684NA	RTU4	DE-EN/
Mar 15 00:24:12 RTN DISC EN/ENERG ACK_RTN	1 YB-684JA	RTU4	DE-
Mar 15 00:24:12 RTN DISC NORMA/DISC ACK_RTN	1 YB-684TAS_D	RTU4	
Mar 15 00:24:12 RTN DISC NORMA/DISC ACK_RTN	1 YB-684NAS_D	RTU4	
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-263G	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-266C	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-263J	RTU3	
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-262B	RTU3	
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-263L	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-262D	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-265M	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-265D	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-263P	RTU3	NORMA/
Mar 15 00:24:12 RTN DISC TRIP ACK_RTN	1 XB-267E	RTU3	NORMA/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

NORMA/
NORMA/
JOSE CARLOS POMANTE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:24:12 RTN DISC	1 XB-265A	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-264A	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-263N	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-262F	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-265B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-264B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-267F	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-266H	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-263E	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-263B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-262A	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-265Q	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-265P	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 VE-025-028GS	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-276A	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XE-159BA	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:12 RTN DISC	1 XB-149B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XB-148D	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XB-144B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XB-185	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XB-146C	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XA-275C1	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XA-275C2	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XA-428B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 RTN DISC	1 XM-568	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:24:13 ALM DISC	1 XB-267E_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:13 ALM DISC	1 XB-185_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:14 ALM DISC	1 YB-684JA_F	RTU4	
FAULT/FAULT UNACK_ALM			
Mar 15 00:24:15 ALM DISC	1 XS51240012	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 00:24:15 ALM DISC	1 XS51240032	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 00:24:15 ALM DISC	1 XS51240022	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 00:24:15 ALM DISC	1 RTU2_INH_8082	RTU2_INHIBITS	ON/
ON UNACK_ALM			
Mar 15 00:24:18 ALM DISC	1 VE-027STS	RTU3	OPEN/
OPEN UNACK_ALM			

É Cópia do documento original.

JOSÉ CARLOS FACENTE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓRIOS



Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-009STS	RTU3	OPEN/
Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-066STS	RTU3	OPEN/
Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-062STS	RTU3	OPEN/
Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-061STS	RTU3	OPEN/
Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-036STS	RTU3	OPEN/
Mar 15 00:24:18 ALM DISC OPEN UNACK_ALM	1 VE-067STS	RTU3	OPEN/
Mar 15 00:24:20 ALM DISC OPEN UNACK_ALM	1 ZSH12100011	RTU5	OPEN/
Mar 15 00:24:23 RTN DISC TRIP ACK_RTN	1 XB-269A	RTU1	NORMA/
Mar 15 00:24:23 RTN DISC TRIP ACK_RTN	1 XB-263D	RTU1	NORMA/
Mar 15 00:24:23 RTN DISC TRIP ACK_RTN	1 XA-280A	RTU1	NORMA/
Mar 15 00:24:23 RTN DISC TRIP ACK_RTN	1 XE-159AA	RTU1	NORMA/
Mar 15 00:24:23 RTN DISC TRIP ACK_RTN	1 XE-159AB	RTU1	NORMA/
Mar 15 00:24:24 RTN DISC OPEN ACK_RTN	1 ZSH12330201	RTU2	NOT O/
Mar 15 00:24:24 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL12230109	RTU2	
Mar 15 00:24:27 ALM DISC OPEN UNACK_ALM	1 VE-002STS	RTU1	OPEN/
Mar 15 00:24:27 RTN DISC TRIP ACK_RTN	1 TG3FUELSOV2	RTU3	NORMA/
Mar 15 00:24:29 ALM DISC FAULT/FAULT UNACK_ALM	1 TG3FUELSOV2_F	RTU3	
Mar 15 00:24:29 RTN DISC C/CLOSE ACK_RTN	1 ZSL12100011	RTU5	NOT
Mar 15 00:24:32 RTN DISC NORMA/DISC ACK_RTN	1 SY12100011_VD	RTU5	
Mar 15 00:24:36 RTN DISC C/CLOSE ACK_RTN	1 ZSL51350001	RTU6	NOT
Mar 15 00:25:21 ALM DISC CLOSE/CLOSE UNACK_ALM	1 ZSL12330201	RTU2	
Mar 15 00:25:23 ALM DISC TRIP UNACK_ALM	1 XB-269A	RTU1	TRIP/
Mar 15 00:25:23 ALM DISC TRIP UNACK_ALM	1 XB-263D	RTU1	TRIP/
Mar 15 00:25:23 ALM DISC TRIP UNACK_ALM	1 XA-280A	RTU1	TRIP/
Mar 15 00:25:23 ALM DISC TRIP UNACK_ALM	1 XE-159AA	RTU1	TRIP/
Mar 15 00:25:23 ALM DISC TRIP UNACK_ALM	1 XE-159AB	RTU1	TRIP/
Mar 15 00:25:25 ALM DISC TRIP UNACK_ALM	1 XB-149B	RTU3	TRIP/
Mar 15 00:25:25 ALM DISC TRIP UNACK_ALM	1 XB-148D	RTU3	TRIP/
Mar 15 00:25:25 ALM DISC TRIP UNACK_ALM	1 XB-144B	RTU3	TRIP/
Mar 15 00:25:25 ALM DISC TRIP UNACK_ALM	1 TG3FUELSOV2	RTU3	TRIP/
Mar 15 00:25:25 ALM DISC TRIP UNACK_ALM	1 XA-428B	RTU3	TRIP/
Mar 15 00:25:26 RTN DISC NORMA/FAULT ACK_RTN	1 TG3FUELSOV2_F	RTU3	
Mar 15 00:25:26 ALM DISC ENERG/ENERG UNACK_ALM	1 XB-248A	RTU4	

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:25:26 ALM DISC	1 XB-148C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:25:27 RTN DISC	1 VE-002STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:03 RTN DISC	1 XB-269A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:03 RTN DISC	1 XB-263D	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:03 RTN DISC	1 XA-280A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:03 RTN DISC	1 XB-159AA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:03 RTN DISC	1 XB-159AB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:05 RTN DISC	1 XB-148A	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:26:05 RTN DISC	1 XB-148C	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:26:05 RTN DISC	1 XB-149B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:05 RTN DISC	1 XB-148D	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:05 RTN DISC	1 XB-144B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:06 RTN DISC	1 TG3FUELSOV2	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:06 RTN DISC	1 XA-428B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:26:07 ALM DISC	1 VE-002STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:26:07 ALM DISC	1 TG3FUELSOV2_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 00:26:26 ALM DISC	1 XB-265U	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-268K	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-268B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-263S	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-264G	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-266B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-266A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-265R	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-266F	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-276B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-274B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-149A	RTU1	
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-143A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-148B	RTU1	
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-144A	RTU1	
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-146A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XB-146D	RTU1	TRIP/
TRIP UNACK_ALM			

É CÓPIA DE DOCUMENTO ORIGINAL.

JOSE CARLOS POZENTEL GUSMÃO
DIRETOR
GABINETE DE SERVIÇOS CORPORATIVOS



Mar 15 00:26:27 ALM DISC	1 XB-146B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 SPARE_d9058_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 SPARE_d9059_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 FZ-002QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 FZ-005QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 FZ-006QB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XA-277	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XV-65002	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XA-280A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XE-159AA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XE-159AB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 SPARE_d9079_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XA-275B1	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:27 ALM DISC	1 XA-275B2	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:30 RTN DISC	1 VE-069STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 VE-071STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 VE-014STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 VE-072STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 XB-268K_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 XB-266B_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 XB-146A_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:26:31 RTN DISC	1 XB-146B_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:26:33 ALM DISC	1 YB-684CA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 YB-684HA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 SPARE_d9004_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 SPARE_d9005_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 YB-678A	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 YB-678C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 YB-678D	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 XB-148A	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 XB-148C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:33 ALM DISC	1 YB-684JA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:26:34 RTN DISC	1 VE-027STS	RTU3	CLOSE/
OPEN ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS

Mar 15 00:26:34 RTN DISC	1 VE-009STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:34 RTN DISC	1 VE-066STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:34 RTN DISC	1 VE-061STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:34 RTN DISC	1 VE-036STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:34 RTN DISC	1 VE-067STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:26:34 ALM DISC	1 XB-263G	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-266C	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263J	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-262B	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263L	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-262D	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-265M	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-265D	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263P	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-267E	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-265A	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-264A	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263N	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-262F	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-267F	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-266H	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263E	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-263B	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-262A	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-265Q	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:34 ALM DISC	1 XB-265P	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XE-159BA	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XB-149B	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XB-148D	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XB-144B	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XB-1385	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XB-146C	RTU3	TRIP/
TRIP UNACK_ALM			
Mar 15 00:26:35 ALM DISC	1 XA-275CA	RTU3	TRIP/
TRIP UNACK_ALM			



É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

TRIP/
 TRIP/
 TRIP/
 TRIP/
 TRIP/

JOSÉ CARLOS PIMENTEL GUSMÃO
 DIRETOR
 DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:26:35 ALM DISC	1	XA-275C2	RTU3	
TRIP UNACK_ALM				TRIP/
Mar 15 00:26:35 ALM DISC	1	VE-033STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-006GSS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-007GSS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-031STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-005GSS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-012GSS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-019STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-011STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-086STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-100STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	VE-099STS_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 ALM DISC	1	XB-146B_VD	RTU1	
DISCR/DISCR UNACK_ALM				
Mar 15 00:26:35 RTN DISC	1	YB-684JA_F	RTU4	
NORMA/FAULT ACK_RTN				
Mar 15 00:26:35 RTN DISC	1	XB-267E_F	RTU3	
NORMA/FAULT ACK_RTN				
Mar 15 00:26:36 RTN DISC	1	XB-185_F	RTU3	
NORMA/FAULT ACK_RTN				
Mar 15 00:27:03 ALM DISC	1	XB-269A	RTU1	TRIP/
TRIP UNACK_ALM				
Mar 15 00:27:03 ALM DISC	1	XB-263D	RTU1	TRIP/
TRIP UNACK_ALM				
Mar 15 00:27:04 ALM DISC	1	TG3FUELSOV2	RTU3	TRIP/
TRIP UNACK_ALM				
Mar 15 00:27:07 RTN DISC	1	VE-002STS	RTU1	CLOSE/
OPEN ACK_RTN				
Mar 15 00:27:10 RTN DISC	1	TG3FUELSOV2_F	RTU3	
NORMA/FAULT ACK_RTN				
Mar 15 00:27:15 RTN DISC	1	XB-269A	RTU1	NORMA/
TRIP ACK_RTN				
Mar 15 00:27:15 RTN DISC	1	XB-263D	RTU1	NORMA/
TRIP ACK_RTN				
Mar 15 00:27:18 RTN DISC	1	TG3FUELSOV2	RTU3	NORMA/
TRIP ACK_RTN				
Mar 15 00:27:19 ALM DISC	1	VE-002STS	RTU1	OPEN/
OPEN UNACK_ALM				
Mar 15 00:27:19 ALM DISC	1	TG3FUELSOV2_F	RTU3	
FAULT/FAULT UNACK_ALM				
Mar 15 00:27:31 ALM DISC	1	XB-269A	RTU1	
TRIP UNACK_ALM				
Mar 15 00:27:31 ALM DISC	1	XB-263D	RTU1	TRIP/
TRIP UNACK_ALM				
Mar 15 00:27:35 RTN DISC	1	VE-002STS	RTU1	CLOSE/
OPEN ACK_RTN				
Mar 15 00:27:47 RTN DISC	1	XB-269A	RTU1	NORMA/
TRIP ACK_RTN				
Mar 15 00:27:47 RTN DISC	1	XB-263D	RTU1	NORMA/
TRIP ACK_RTN				
Mar 15 00:27:51 ALM DISC	1	VE-002STS	RTU1	OPEN/
OPEN UNACK_ALM				
Mar 15 00:28:06 ALM DISC	1	PSLL1223074B	RTU2	
ALARM/ALARM UNACK_ALM				

ECOMAFER



Mar 15 00:31:27 RTN DISC	1 XB-144A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:27 RTN DISC	1 XB-146A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:27 RTN DISC	1 XE-146D	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XB-146B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 SPARE_d9058_RTU	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 SPARE_d9058_RTU	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 FZ-002QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 FZ-005QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 FZ-006QB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XA-277	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XV-65002	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XA-280A	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XE-159AA	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XE-159AB	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 SPARE_d9079_RTU	RTU1	OFF/
ON ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XA-275B1	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XA-275B2	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-033STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-005GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-007GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-031STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-005GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-012GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-019STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-011STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-086STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-100STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 VE-099STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:28 RTN DISC	1 XB-146B_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:31:29 RTN DISC	1 YB-684CA	RTU4	
EN/ENERG ACK_RTN			
Mar 15 00:31:29 RTN DISC	1 YB-684HA	RTU4	
EN/ENERG ACK_RTN			
Mar 15 00:31:30 RTN DISC	1 SPARE_d9004_RTU	RTU4	OFF/
ON ACK_RTN			
Mar 15 00:31:30 RTN DISC	1 SPARE_d9005_RTU	RTU4	OFF/
ON ACK_RTN			

É COPIA DO DOCUMENTO ORIGINAL

DE- **JOSÉ CARLOS PIMENTEL GUSMÃO**
DIRETOR

DE- **DIVISÃO DE SETORES CARTORARIOS**



Mar 15 00:31:32 RTN DISC	1 XB-159BA	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XB-149B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XB-148D	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XB-144B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XB-185	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XB-246C	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XA-275C1	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 RTN DISC	1 XA-275C2	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 00:31:32 ALM DISC	1 YB-684JA_F	RTU4	
FAULT/FAULT UNACK_ALM			
Mar 15 00:31:33 ALM DISC	1 XB-267E_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 00:31:33 ALM DISC	1 XB-185_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 00:31:43 RTN DISC	1 VE-038STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:31:43 ALM DISC	1 PSLL12230245	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:31:43 ALM DISC	1 PSLL12230345	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:31:47 RTN DISC	1 VE-076STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:31:58 ALM DISC	1 PSLL12230145	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:09 RTN DISC	1 VE-023GSS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 00:32:13 RTN DISC	1 LSHH12330006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:32:16 ALM DISC	1 LSHH12330006	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:22 RTN DISC	1 LSHH12330006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:32:27 RTN DISC	1 VE-071STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:32:28 ALM DISC	1 PSLL12230213	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:28 ALM DISC	1 LSHH12330006	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:29 ALM DISC	1 ZSL51350003	RTU6	
CLOSE/CLOSE UNACK_ALM			
Mar 15 00:32:29 RTN DISC	1 SYS1350001_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 00:32:31 RTN DISC	1 VE-013GSS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:32:33 ALM DISC	1 PSLL12230113	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:36 RTN DISC	1 LSHH12330006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:32:39 ALM DISC	1 LSHH12330006	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:46 ALM DISC	1 ESD-LVL2_RTU3	RTU3	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:47 ALM DISC	1 XB-269A	RTU1	
TRIP UNACK_ALM			
Mar 15 00:32:47 ALM DISC	1 XB-263D	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:47 ALM DISC	1 XB-263C	RTU1	TRIP/
TRIP UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS GASTOS



Mar 15 00:32:47	ALM DISC	1	XB-265G	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-265U	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-268K	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-265C	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-264C	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-265B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-264D	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-268B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-263S	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-264G	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-266B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-266A	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-265R	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-262M	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	VE-019GS	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-268H	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-266F	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-276B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-274B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-149A	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-143A	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-148B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-144A	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-146A	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XE-146D	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	XB-146B	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	SPARE_d9058_RTU	RTU1	ON/
ON UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	SPARE_d9059_RTU	RTU1	ON/
ON UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	FZ-002QB	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	FZ-005QB	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	FZ-006QB	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:47	ALM DISC	1	FZ-001QBA	RTU1	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:48	ALM DISC	1	XM-275AB	RTU1	TRIP/
TRIP UNACK_ALM					

É Cópia do Documento Original.

TRIP/
TRIP/
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:32:48 ALM DISC	1 XM-275BA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-277	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-65002	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59003	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59007	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59008	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59009	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59010	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XV-59032	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-280A	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-280B	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XE-159AA	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XE-159AB	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 SPARE_d9079_RTU	RTU1	ON/
ON UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-275A1	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-275A2	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-275B1	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 XA-275B2	RTU1	TRIP/
TRIP UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 HS12003333	RTU4	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:48 RTN DISC	1 XS12230380	RTU5	NORMA/
TRIP ACK_RTN			
Mar 15 00:32:48 ALM DISC	1 XS72009	RTU4	
ALARM/ALARM UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684AA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684CA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684HA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684TA	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 SPARE_d9004_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 SPARE_d9005_RTU	RTU4	ON/
ON UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-678A	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-678C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684P	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684Q	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:32:48 ALM DISC	1 YB-684BA	RTU4	
ENERG/ENERG UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL:

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 00:32:48 ALM DISC	1 YB-684DA	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 YA-678E	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 YB-678D	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 YB-684R	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 YB-684S	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 XB-148A	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 XB-148C	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:48 ALM DISC	1 YB-684NA	RTU4
ON UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 YB-684JA	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 ESD-LVL2_RTU5	RTU5
ALARM/ALARM UNACK_ALM		
Mar 15 00:32:49 RTN DISC	1 XS12105003	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS12105012	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS12230180	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250301	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250302	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250311	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250321	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250401	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250411	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250421	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68250711	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68251111	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 RTN DISC	1 XS68251121	RTU6
NORMA/TRIPP ACK_RTN		
Mar 15 00:32:49 ALM DISC	1 ESD-LVL4_RTU6	RTU6
ON UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-263T	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-262K	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-263U	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-262L	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-263G	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-266C	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-263Q	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-262H	RTU3
TRIP UNACK_ALM		
Mar 15 00:32:49 ALM DISC	1 XB-265J	RTU3
TRIP UNACK_ALM		

ON/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

ON/

TRIP/
JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DEPARTAMENTO DE SERVIÇOS CARTÓGRAFOS

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/

TRIP/



Mar 15 00:32:49	ALM DISC	1	XB-264E	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-263J	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-262B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-263L	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-262D	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-265M	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-265D	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-263P	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-267A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-266E	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-267E	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-268G	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-268F	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-265A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:49	ALM DISC	1	XB-264A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-263N	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-262F	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-265B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-264B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-267F	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-266H	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-263E	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-263B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-262A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-265Q	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-265P	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	VE-025-028GS	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-276A	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XE-159BA	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-149B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-143B	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-148D	RTU3	TRIP/
TRIP UNACK_ALM					
Mar 15 00:32:50	ALM DISC	1	XB-144B	RTU3	TRIP/
TRIP UNACK_ALM					

É Cópia do Documento Original

JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
TRILHA DE SERVIÇOS CARTORIAIS

DE-
DE-
DE- CARLOS PIMENTEL GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARTORIAS
DE-
DE-
DE-
DE-
DE-



Mar 15 00:32:53 RTN DISC	1 SPARE_d9056_RTU RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS30135 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS60132 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS43160 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS60131 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS42033 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS42036 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 SPARE_d9089_RTU RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS60108 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS43150 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS53360041 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS53360103 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS53360113 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS53360202 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS53360212 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 SPARE_d9208_RTU RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS30130 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 SOV41346 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 SOV41366 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS12230280 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS12230540 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS12330031 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS51240012 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS51240032 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:53 RTN DISC	1 XS60130 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS53360010 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS89001 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS89002 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 ALM DISC	1 XS72002 RTU2	
ENERG/ENERG UNACK_ALM		
Mar 15 00:32:54 RTN DISC	1 XS12230640 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS12330001 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS51210001 RTU2	DE-
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS51240022 RTU2	DE-
EN/ENERG ACK_RTN		

É Cópia Fiel do Documento Original:

JOSÉ CARLOS FONSECA GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 00:32:54 RTN DISC	1 XS51250041	RTU2
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS53360015	RTU2
EN/ENERG ACK_RTN		
Mar 15 00:32:54 RTN DISC	1 XS54120013	RTU2
EN/ENERG ACK_RTN		
Mar 15 00:32:55 ALM DISC	1 VE-008STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-004STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-022STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-024GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-024STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-033STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-006GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-007GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-031STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:55 ALM DISC	1 VE-005GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-012GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-019STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-011STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-086STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-075STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-100STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-099STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-101STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-009GSS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-047STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 VE-160STS_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 XB-146B_VD	RTU1
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 YB-684TAS_D	RTU4
DISCR/DISCR UNACK_ALM		
Mar 15 00:32:56 ALM DISC	1 YB-684NAS_D	RTU4
DISCR/DISCR UNACK_ALM		
Mar 15 00:33:45 RTN DISC	1 VE-032STS_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 00:33:47 ALM DISC	1 TSL51350006	RTU6
LOW UNACK_ALM		
Mar 15 00:33:54 ALM DISC	1 VE-032STS_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 00:34:44 ALM DISC	2 XL51114039N	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 00:34:44 RTN DISC	1 XL51114039R	RTU4
EN/ENERG ACK_RTN		
Mar 15 00:34:56 RTN DISC	1 PSL51350035	RTU6
LOW ACK_RTN		

DE-

DE-

DE-

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

LOW/

JOSE CARLOS PRUDENTE GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS

DE-

NORMA/



Mar 15 00:34:57 RTN DISC 1 XL51114039N RTU4
EN/ENERG ACK_RTN
Mar 15 00:34:57 ALM DISC 1 XL51114039R RTU4
ENERG/ENERG UNACK_ALM
Mar 15 00:35:39 RTN DISC 1 PSLLS1350016 RTU6
LOW ACK_RTN
Mar 15 00:37:40 RTN DISC 1 VE-022STS RTU1
OPEN ACK_RTN
Mar 15 00:37:40 RTN DISC 1 VE-022STS_VD RTU1
NORMA/DISCR ACK_RTN
Mar 15 00:37:40 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:37:44 ALM DISC 1 LSHH12330006 RTU2
ALARM/ALARM UNACK_ALM
Mar 15 00:37:48 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:37:49 ALM DISC 1 LSHH12330006 RTU2
ALARM/ALARM UNACK_ALM
Mar 15 00:38:13 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:38:17 ALM DISC 1 LSHH12330006 RTU2
ALARM/ALARM UNACK_ALM
Mar 15 00:38:23 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:39:01 ALM DISC 1 LSHH12330006 RTU2
ALARM/ALARM UNACK_ALM
Mar 15 00:39:07 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:39:11 ALM DISC 1 LSHH12330006 RTU2
ALARM/ALARM UNACK_ALM
Mar 15 00:39:19 RTN DISC 1 LSHH12330006 RTU2
NORMA/ALARM ACK_RTN
Mar 15 00:39:23 ALM DISC 1 LSL68250102 RTU6
LOW UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-012GSS RTU1
OPEN ACK_RTN
Mar 15 00:39:23 RTN DISC 1 LSHH68250201 RTU6
HIGH ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-071STS RTU1
OPEN UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-011STS RTU1
OPEN ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-037STS RTU1
OPEN UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-075STS RTU1
OPEN ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-076STS RTU1
OPEN UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-100STS RTU1
OPEN ACK_RTN
Mar 15 00:39:23 RTN DISC 1 VE-012GSS_VD RTU1
NORMA/DISCR ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-071STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-011STS_VD RTU1
NORMA/DISCR ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-037STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-075STS_VD RTU1
NORMA/DISCR ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-076STS_VD RTU1
DISCR/DISCR UNACK_ALM
Mar 15 00:39:23 RTN DISC 1 VE-100STS_VD RTU1
NORMA/DISCR ACK_RTN
Mar 15 00:39:23 ALM DISC 1 VE-006STS_F RTU1
FAULT/FAULT UNACK_ALM

DE-

NORMA/

CLOSE/

LOW/

CLOSE/

NORMA/

OPEN/

CLOSE/

OPEN/

CLOSE/

OPEN/

CLOSE/

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PRADO TEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAS



Mar 15 00:39:23 RTN DISC	1 VE-010STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:39:23 ALM DISC	1 VE-011STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:23 RTN DISC	1 VE-037STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:39:23 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:23 ALM DISC	1 VE-013GSS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:23 ALM DISC	1 YB-684HAS	RTU4	
RUNNI/RUNNI UNACK_ALM			
Mar 15 00:39:23 ALM DISC	1 YB-684HAS_D	RTU4	
DISCR/DISCR UNACK_ALM			
Mar 15 00:39:27 RTN DISC	1 VE-004STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 VE-024STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 VE-071STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:39:27 ALM DISC	1 VE-075STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:39:27 RTN DISC	1 VE-076STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 XB-146BS	RTU1	
STOPP/RUNNI ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 VE-004STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 VE-024STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 VE-071STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:27 ALM DISC	1 VE-075STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:39:27 RTN DISC	1 VE-076STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:27 RTN DISC	1 XB-146B_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:27 ALM DISC	1 VE-010STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:27 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:39:27 ALM DISC	1 VE-076STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:27 RTN DISC	1 LSL68250102	RTU6	NORMA/
LOW ACK_RTN			
Mar 15 00:39:27 ALM DISC	1 LSH68250201	RTU6	HIGH/
HIGH UNACK_ALM			
Mar 15 00:39:38 RTN DISC	1 XL51113039R	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:39:38 ALM DISC	1 XL51114039N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:39:38 RTN DISC	1 XL51114039R	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:39:38 ALM DISC	1 XL54230001T	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:39:38 ALM DISC	1 XL54230002T	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:39:38 ALM DISC	1 XL54230003T	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:39:38 ALM DISC	1 XL54230004T	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:39:38 ALM DISC	1 WWStatPortTGPri	System	
FAILE/FAILE UNACK_ALM			
Mar 15 00:39:39 RTN DISC	1 VE-075STS	RTU1	CLOSE/
OPEN ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSÉ CARLOS FUMANTEL DUSAN
DIRETOR
DIVISÃO DE SERVIÇOS CANTORIAN



Mar 15 00:39:39 RTN DISC	1 VE-075STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 00:39:39 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 00:39:46 ALM DISC	1 LSHH12330006	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:39:49 RTN DISC	1 LSHH12330006	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:39:53 RTN DISC	1 XL51113039N	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:39:53 RTN DISC	1 XL54230001T	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:39:53 RTN DISC	1 XL54230003T	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 00:40:08 ALM DISC	1 Heartbeat_RTO3	RTU3	
Faille/Faile UNACK_ALM			
Mar 15 00:40:20 ALM DISC	1 XL51113039R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:40:28 RTN DISC	1 XS12510042	RTU2	
NORMA/STOPP ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 AMY12101704	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 AWY12101705	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 COY12101707	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 RTU5_INH_8215	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 RTU5_INH_8216	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 RTU5_INH_8220	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:42 RTN DISC	1 RTU5_INH_8249	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:44 ALM DISC	1 XL51113039N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 00:40:47 RTN DISC	1 PMY12101702	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 00:40:48 RTN DISC	1 XS51110011	RTU5	NORMA/
TRIP ACK_RTN			
Mar 15 00:40:48 RTN DISC	1 XS51110015	RTU5	NORMA/
TRIP ACK_RTN			
Mar 15 00:40:48 RTN DISC	1 RTU5_INH_8386	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:48 RTN DISC	1 RTU5_INH_8387	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:48 RTN DISC	1 RTU5_INH_8392	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 00:40:51 ALM DISC	1 VE-075STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 00:40:51 ALM DISC	1 VE-075STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 00:40:51 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 00:40:56 ALM DISC	1 XS12510042	RTU2	
STOPP/STOPP UNACK_ALM			
Mar 15 00:41:14 RTN DISC	1 XS12510042	RTU2	
NORMA/STOPP ACK_RTN			
Mar 15 00:41:44 RTN DISC	1 SPARE_09972_RTU	RTU2	
ON ACK_RTN			
Mar 15 00:41:47 RTN DISC	1 XA80000005	RTU2	
ON ACK_RTN			
Mar 15 00:41:50 ALM DISC	1 TSHH52002	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 00:41:52 RTN DISC	1 SSSY12102201	RTU6	DE-
EN/ENERG ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUERINO
DIRETOR
UNIDADE DE SERVIÇOS CARTORIAIS



Mar 15 00:41:52 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:41:56 RTN DISC EN/ENERG ACK_RTN	2 BY51350003 RTU6	DE-
Mar 15 00:41:56 RTN DISC ON ACK_RTN	1 RTU6_INH_8308 RTU6_INHIBITS	OFF/
Mar 15 00:41:56 RTN DISC ON ACK_RTN	1 RTU6_INH_8309 RTU6_INHIBITS	OFF/
Mar 15 00:41:56 RTN DISC ON ACK_RTN	1 RTU6_INH_8312 RTU6_INHIBITS	OFF/
Mar 15 00:42:32 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:42:49 ALM DISC ON UNACK_ALM	1 XA80000005 RTU2	ON/
Mar 15 00:42:49 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:42:55 RTN DISC ON ACK_RTN	1 XA80000005 RTU2	OFF/
Mar 15 00:43:13 ALM DISC ON UNACK_ALM	1 XA80000005 RTU2	ON/
Mar 15 00:43:38 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:43:41 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:43:56 RTN DISC ON ACK_RTN	1 XA80000005 RTU2	OFF/
Mar 15 00:43:56 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:43:59 ALM DISC ON UNACK_ALM	1 XA80000005 RTU2	ON/
Mar 15 00:43:59 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:44:02 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:44:05 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:44:08 RTN DISC ON ACK_RTN	1 XA80000005 RTU2	OFF/
Mar 15 00:44:11 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:44:20 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:44:23 RTN DISC NORMA/ALARM ACK_RTN	1 PSLL52601 RTU2	
Mar 15 00:44:23 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:47:02 RTN DISC NORMA/ALARM ACK_RTN	1 LSHH12330102 RTU2	
Mar 15 00:47:52 RTN DISC LOW ACK_RTN	1 TSLL51350006 RTU6	NORMA/
Mar 15 00:47:52 ALM DISC DISCR/DISCR UNACK_ALM	1 BY51350003_VD RTU6	
Mar 15 00:48:23 ALM DISC ALARM/ALARM UNACK_ALM	1 LSHH52802 RTU2	
Mar 15 00:52:19 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:52:22 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	
Mar 15 00:52:25 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	
Mar 15 00:52:31 RTN DISC ON ACK_RTN	1 SPARE_d9972_RTU RTU2	OFF/
Mar 15 00:52:34 ALM DISC ON UNACK_ALM	1 SPARE_d9972_RTU RTU2	ON/
Mar 15 00:52:44 ALM DISC ON UNACK_ALM	1 XA80000005 RTU2	ON/

É COPIA DO DOCUMENTO ORIGINAL

ON/
JOSÉ CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS ADMINISTRATIVOS



Mar 15 00:53:32 RTN DISC	1 TSHH52002	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:54:35 ALM DISC	1 ZSH12230401	RTU5	OPEN/
OPEN UNACK_ALM			
Mar 15 00:55:05 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 00:55:25 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 00:57:20 RTN DISC	1 ZSL12230401	RTU5	NOT
C/CLOSE ACK_RTN			
Mar 15 00:59:06 RTN DISC	1 ZSH12100025	RTU5	NOT O/
OPEN ACK_RTN			
Mar 15 00:59:08 RTN DISC	1 PSL12230401	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 00:59:35 ALM DISC	1 ZSH68250801	RTU6	OPEN/
OPEN UNACK_ALM			
Mar 15 00:59:49 RTN DISC	1 PSL12100023	RTU5	NORMA/
LOW ACK_RTN			
Mar 15 01:02:38 ALM DISC	1 ZSH12230074	RTU2	OPEN/
OPEN UNACK_ALM			
Mar 15 01:02:38 RTN DISC	1 ZSL12230074	RTU2	NOT
C/CLOSE ACK_RTN			
Mar 15 01:03:16 ALM DISC	1 ZSL12100025	RTU5	
CLOSE/CLOSE UNACK_ALM			
Mar 15 01:03:16 ALM DISC	1 PSHH51350025	RTU6	HIGH/
HIGH UNACK_ALM			
Mar 15 01:03:16 RTN DISC	1 ZSL68250801	RTU6	NOT
C/CLOSE ACK_RTN			
Mar 15 01:07:24 ALM DISC	1 XL54230001C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 01:09:09 RTN DISC	1 XL54230001C	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 01:09:24 ALM DISC	1 XL54230003C	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 01:10:29 ALM DISC	1 PSL12330204	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 01:13:53 ALM DISC	1 PSHH51350015	RTU6	HIGH/
HIGH UNACK_ALM			
Mar 15 01:13:53 RTN DISC	1 SY68250801_VD	RTU6	
NORMA/DISCR ACK_RTN			
Mar 15 01:14:45 ALM DISC	1 YB-684JAS	RTU4	OPEN/
OPEN UNACK_ALM			
Mar 15 01:22:14 ALM DISC	1 PSL12230413	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 01:22:19 RTN DISC	1 SY12230401	RTU5	DE-
EN/ENERG ACK_RTN			
Mar 15 01:25:38 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:25:44 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:25:47 ALM DISC	1 SPARE_d9972_RTU	RTU2	ON/
ON UNACK_ALM			
Mar 15 01:25:50 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:26:14 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 01:26:29 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:31:27 RTN DISC	1 XL54230002T	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:31:27 RTN DISC	1 XL54230004T	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:31:39 RTN DISC	1 XL51114039N	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:31:39 ALM DISC	1 XL51114039R	RTU4	
ENERG/ENERG UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

DE-

DE-

JOSE CARLOS FONSECA GUSMÃO
DIRETOR
DIVISÃO DE SERÇOS CARTORIAS

Mar 15 01:32:09 RTN DISC EN/ENERG ACK_RTN	1 XL51113039R	RTU4	DE-
Mar 15 01:32:09 ALM DISC ENERG/ENERG UNACK_ALM	1 XL51114039N	RTU4	
Mar 15 01:32:09 RTN DISC EN/ENERG ACK_RTN	1 XL51114039R	RTU4	DE-
Mar 15 01:32:09 ALM DISC ENERG/ENERG UNACK_ALM	1 XL54230001T	RTU4	
Mar 15 01:32:09 ALM DISC ENERG/ENERG UNACK_ALM	1 XL54230002T	RTU4	
Mar 15 01:32:09 ALM DISC ENERG/ENERG UNACK_ALM	1 XL54230003T	RTU4	
Mar 15 01:32:09 ALM DISC ENERG/ENERG UNACK_ALM	1 XL54230004T	RTU4	
Mar 15 01:32:19 ALM DISC FAILE/FAILE UNACK_ALM	1 WWStatPortTGPri	\$System	
Mar 15 01:32:25 ALM DISC FAILE/FAILE UNACK_ALM	1 WWStatPortTGSec	\$System	
Mar 15 01:32:45 RTN DISC HEALT/FAILE ACK_RTN	1 WWStatPortTGSec	\$System	
Mar 15 01:33:00 ALM DISC FAILE/FAILE UNACK_ALM	1 WWStatPortTGSec	\$System	
Mar 15 01:36:21 RTN DISC HEALT/FAILE ACK_RTN	1 WWStatPortTGSec	\$System	
Mar 15 01:36:24 RTN DISC Healt/Faile ACK_RTN	1 Heartbeat_RTU3	RTU3	
Mar 15 01:36:25 RTN DISC HEALT/FAILE ACK_RTN	1 WWStatPortTGPri	\$System	
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE-016STS	RTU3	CLOSE/
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE-068STS	RTU3	CLOSE/
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE28ST&04GSS	RTU3	CLOSE/
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE11GS&92STS	RTU3	CLOSE/
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE-046STS	RTU3	CLOSE/
Mar 15 01:36:26 RTN DISC OPEN ACK_RTN	1 VE-040STS	RTU3	CLOSE/
Mar 15 01:36:26 ALM DISC OPEN UNACK_ALM	1 XV-65004S	RTU3	OPEN/
Mar 15 01:36:26 ALM DISC OPEN UNACK_ALM	1 XV-59019S	RTU3	OPEN/
Mar 15 01:36:27 RTN DISC EN/ENERG ACK_RTN	1 XL51113039N	RTU4	DE-
Mar 15 01:36:27 RTN DISC EN/ENERG ACK_RTN	1 XL54230003T	RTU4	DE-
Mar 15 01:36:51 ALM DISC FAILE/FAILE UNACK_ALM	1 WWStatPortTGSec	\$System	
Mar 15 01:36:51 ALM DISC ENERG/ENERG UNACK_ALM	1 XL51113039R	RTU4	
Mar 15 01:36:56 RTN DISC OPEN ACK_RTN	1 XV-59018S	RTU3	CLOSE/
Mar 15 01:37:16 ALM DISC ENERG/ENERG UNACK_ALM	1 XL51113039N	RTU4	
Mar 15 01:37:26 RTN DISC HEALT/FAILE ACK_RTN	1 WWStatPortTGSec	\$System	
Mar 15 01:37:47 ALM DISC OPEN UNACK_ALM	1 XV-59018S	RTU3	OPEN/
Mar 15 01:38:15 ALM DISC OPEN UNACK_ALM	1 XV-59013S	RTU3	OPEN/
Mar 15 01:38:23 RTN DISC OPEN ACK_RTN	1 XV-59013S	RTU3	CLOSE/
Mar 15 01:38:23 RTN DISC OPEN ACK_RTN	1 XV-59018S	RTU3	CLOSE/



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS FOMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS

Mar 15 01:38:51 ALM DISC	1 XV-59013S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:39:00 RTN DISC	1 XV-59013S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:39:09 ALM DISC	1 XV-59013S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:39:14 RTN DISC	1 XV-59013S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:39:21 ALM DISC	1 XV-59013S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:39:26 RTN DISC	1 XV-59013S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:39:39 ALM DISC	1 XV-59013S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:39:44 RTN DISC	1 XV-59013S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:40:00 ALM DISC	1 XV-59018S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:40:00 RTN DISC	1 XV-59019S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:40:17 RTN DISC	1 XV-59018S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:40:32 ALM DISC	1 XV-59018S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:40:36 RTN DISC	1 XV-59018S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:40:44 RTN DISC	1 VE-032STS_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 01:40:44 ALM DISC	1 XV-59013S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 01:40:48 RTN DISC	1 XV-59013S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 01:41:26 ALM DISC	1 XV-59019S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 01:42:12 RTN DISC	1 XV-59021S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 01:42:41 ALM DISC	1 WWStatPortTGSec	System	
FAILE/FAILE UNACK_ALM			
Mar 15 01:42:45 RTN DISC	1 WWStatPortTGSec	System	
HEALT/FAILE ACK_RTN			
Mar 15 01:43:08 RTN DISC	1 PSL52031	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 01:44:03 RTN DISC	1 HS12004444AP	RTU4	
NORMA/ALARM ACK_RTN			
Mar 15 01:44:03 RTN DISC	1 HS12004444CF	RTU4	
NORMA/ALARM ACK_RTN			
Mar 15 01:46:29 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 01:46:29 ALM DISC	1 XV-59033S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 01:46:33 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 01:46:33 RTN DISC	1 XV-59033S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 01:48:03 RTN DISC	1 XL51113039R	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:48:03 ALM DISC	1 XL54230003T	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 01:48:18 RTN DISC	1 XL51113039N	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:48:18 RTN DISC	1 XL54230003T	RTU4	
EN/ENERG ACK_RTN			
Mar 15 01:48:30 ALM DISC	1 XL51113039R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 01:48:36 ALM DISC	1 Heartbeat_RTU3	RTU3	
Faile/Faile UNACK_ALM			



É CÓPIA DE DOCUMENTO ORIGINAL

DE-
JOSE CARLOS POTENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS
DE-
DE-



Mar 15 01:49:00 ALM DISC	1 XL51113039N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 01:53:08 ALM DISC	1 LSHH52801	RTU2	
ALARM/ALARM UNACK_ALM			
Mar 15 01:53:38 ALM DISC	1 XA800000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 01:53:41 RTN DISC	1 XA800000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:54:53 ALM DISC	1 XA800000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 01:54:56 RTN DISC	1 XA800000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 ESD-LVL2_RTU5	RTU5	
NORMA/ALARM ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-075STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XB-263C	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XB-265G	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XB-262M	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-019GS	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XB-268H	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XV-59007	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XV-59008	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XV-59009	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XA-280B	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XA-275A1	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 XA-275A2	RTU1	NORMA/
TRIP ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-008STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-075STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-009GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 01:56:32 RTN DISC	1 VE-047STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 01:56:32 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 01:56:33 RTN DISC	1 XS72009	RTU4	
NORMA/ALARM ACK_RTN			
Mar 15 01:56:36 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 01:56:36 ALM DISC	1 XB-266F_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 01:56:36 ALM DISC	1 XB-243A_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 01:56:37 ALM DISC	1 XS89021	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:37 ALM DISC	1 XS80901	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:37 ALM DISC	1 XS80923	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:37 ALM DISC	1 XS80924	RTU2	
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:37 ALM DISC	1 XS89022	RTU2	
ENERG/ENERG UNACK_ALM			

É Cópia Fiel do Documento Original.

JOSÉ CARLOS POMERANTZ GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 01:56:37 ALM DISC	1 XS30133	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS42195	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS42200	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS42205	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 SPARE_d9056_RTU	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS30135	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS60132	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS43160	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS60131	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 SPARE_d9089_RTU	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS60108	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS43150	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360041	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360103	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360113	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360202	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360212	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 SPARE_d9208_RTU	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS30130	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 SOV41346	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 SOV41366	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS12230540	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS12330031	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS51240012	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS51240032	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS60130	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:37 ALM DISC	1 XS53360010	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:38 ALM DISC	1 XS53360025	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:38 ALM DISC	1 XS89001	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:38 ALM DISC	1 XS89002	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:38 RTN DISC	1 XS72002	RTU2
EN/ENERG ACK_RTN		
Mar 15 01:56:38 ALM DISC	1 XS12230640	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 01:56:38 ALM DISC	1 XS51210001	RTU2
ENERG/ENERG UNACK_ALM		

É Cópia Fiel do Documento Original

JOSÉ CARLOS PINHEIRO GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS
DE-



Mar 15 01:56:38 ALM DISC	1	XS51240022	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS51250041	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS53360015	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS54120013	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS12105003	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS12105012	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250301	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250302	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250311	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250321	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250401	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250411	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250421	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68250711	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68251111	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 ALM DISC	1	XS68251121	RTU6
TRIPP/TRIPP UNACK_ALM			
Mar 15 01:56:38 RTN DISC	1	ESD-LVL4_RTU6	RTU6
ON ACK_RTN			
Mar 15 01:56:43 ALM DISC	1	XS42033	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 01:56:43 ALM DISC	1	XS42036	RTU2
ENERG/ENERG UNACK_ALM			
Mar 15 02:02:17 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:02:20 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:02:44 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:02:47 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:02:51 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:02:51 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:02:53 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:02:53 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:02:54 RTN DISC	1	XL51114039N	RTU4
EN/ENERG ACK_RTN			
Mar 15 02:02:54 ALM DISC	1	XL51114039R	RTU4
ENERG/ENERG UNACK_ALM			
Mar 15 02:02:54 RTN DISC	1	XL54230002T	RTU4
EN/ENERG ACK_RTN			
Mar 15 02:04:09 ALM DISC	1	XL51114039N	RTU4
ENERG/ENERG UNACK_ALM			
Mar 15 02:04:09 RTN DISC	1	XL51114039R	RTU4
EN/ENERG ACK_RTN			
Mar 15 02:04:09 ALM DISC	1	XL54230002T	RTU4
ENERG/ENERG UNACK_ALM			

OFF/

ON/

OFF/

ON/

OFF/

ON/

ON/

OFF/

OFF/

É Cópia Fiel do Documento Original

DIRETOR CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS

DE-

Mar 15 02:06:00 ALM DISC 1 XA80000005 RTU2
 ON UNACK_ALM
 Mar 15 02:06:17 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:21 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:23 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:26 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:29 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:30 RTN DISC 1 PSL12100013 RTU5
 LOW ACK_RTN
 Mar 15 02:06:32 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:35 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:38 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:47 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:50 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:53 RTN DISC 1 XA80000005 RTU2
 ON ACK_RTN
 Mar 15 02:06:53 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:06:56 ALM DISC 1 XA80000005 RTU2
 ON UNACK_ALM
 Mar 15 02:06:56 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:06:59 RTN DISC 1 XA80000005 RTU2
 ON ACK_RTN
 Mar 15 02:06:59 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:07:03 ALM DISC 1 XA80000005 RTU2
 ON UNACK_ALM
 Mar 15 02:07:03 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:07:37 RTN DISC 1 XS53360025 RTU2
 EN/ENERG ACK_RTN
 Mar 15 02:07:58 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:08:02 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:08:02 ALM DISC 1 XS53360025 RTU2
 ENERG/ENERG UNACK_ALM
 Mar 15 02:08:23 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:08:26 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:08:30 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:08:32 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:08:41 RTN DISC 1 XA80000005 RTU2
 ON ACK_RTN
 Mar 15 02:08:41 RTN DISC 1 SPARE_d9972_RTU RTU2
 ON ACK_RTN
 Mar 15 02:08:44 ALM DISC 1 XA80000005 RTU2
 ON UNACK_ALM
 Mar 15 02:08:44 ALM DISC 1 SPARE_d9972_RTU RTU2
 ON UNACK_ALM
 Mar 15 02:08:47 RTN DISC 1 XA80000005 RTU2
 ON ACK_RTN

ON/
OFF/

ON/

OFF/

ON/

OFF/

NORMA/

ON/

OFF/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

DE-

OFF/

ON/

É Cópia do documento original

OFF/

JOSE CARLOS PEREIRA GUSMÃO
 DIRETOR
 CENTRO DE SERVIÇOS CARTÓGRAFOS

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFFX
ON/

ON

JOSE CARLOS PINHEIRO GOMES
OFF/ DIRETOR
DIVISAO DE SERVICOS CARTORARIOS
ON/



Mar 15 02:10:44 RTN DISC 1 XA80000005 RTU2
ON ACK_RTN
Mar 15 02:10:44 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:10:47 ALM DISC 1 XA80000005 RTU2
ON UNACK_ALM
Mar 15 02:10:47 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:10:50 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:10:53 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:10:57 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:10:59 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:11:29 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:11:32 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:11:41 RTN DISC 1 XA80000005 RTU2
ON ACK_RTN
Mar 15 02:11:41 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:11:44 ALM DISC 1 XA80000005 RTU2
ON UNACK_ALM
Mar 15 02:11:44 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:12:00 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:12:02 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:12:21 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:12:23 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:12:32 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:12:35 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:12:38 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:12:42 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:13:03 RTN DISC 1 XA80000005 RTU2
ON ACK_RTN
Mar 15 02:13:03 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:13:05 ALM DISC 1 XA80000005 RTU2
ON UNACK_ALM
Mar 15 02:13:05 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:13:06 RTN DISC 1 ZSH12100015 RTU5
OPEN ACK_RTN
Mar 15 02:13:08 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:13:11 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:13:14 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:13:17 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM
Mar 15 02:13:41 RTN DISC 1 SPARE_d9972_RTU RTU2
ON ACK_RTN
Mar 15 02:13:45 ALM DISC 1 SPARE_d9972_RTU RTU2
ON UNACK_ALM

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

ON/

OFF/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

NOT O/

OFF/

ECONOMIA DO DOCUMENTO

OFF/

JOSÉ CARLOS PIENDEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS

OFF/

ON/



Mar 15 02:14:09 ALM DISC	1 2SL12100015	RTU5
CLOSE/CLOSE UNACK_ALM		
Mar 15 02:14:16 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:14:16 RTN DISC	1 XS53360025	RTU2
EN/ENERG ACK_RTN		
Mar 15 02:14:20 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:14:20 ALM DISC	1 XS53360025	RTU2
ENERG/ENERG UNACK_ALM		
Mar 15 02:14:32 RTN DISC	1 PSL52001	RTU2
NORMA/ALARM ACK_RTN		
Mar 15 02:14:32 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:14:35 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:14:38 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		
Mar 15 02:14:41 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:14:50 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		
Mar 15 02:14:50 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:14:53 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:14:53 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:14:56 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		
Mar 15 02:14:56 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:14:59 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:14:59 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:02 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		
Mar 15 02:15:02 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:15:05 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:15:05 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:09 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:15:11 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:14 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		
Mar 15 02:15:14 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:15:17 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:15:17 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:20 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:15:23 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:26 RTN DISC	1 SPARE_d9972_RTU	RTU2
ON ACK_RTN		
Mar 15 02:15:30 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 02:15:41 RTN DISC	1 XA80000005	RTU2
ON ACK_RTN		

OFF/

DE-

ON/

OFF/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

É CÓPIA DO DOCUMENTO ORIGINAL

OFF/

JOSÉ CARLOS PIMENTEL GUSMÃO
ON/ DIRETOR
DIVISÃO DE SERVIÇOS CARTÓGRAFOS
OFF/

Mar 15 02:15:47 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:15:56 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:15:59 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:16:02 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:12 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:16:12 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:16:14 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:16:20 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:16:20 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:23 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:16:23 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:16:26 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:29 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:16:33 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:16:33 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:35 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:16:36 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:16:38 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:16:39 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:41 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:16:42 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:16:54 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:16:57 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:17:00 RTN DISC	1	XA80000005	RTU2
ON ACK_RTN			
Mar 15 02:17:00 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:17:03 ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM			
Mar 15 02:17:03 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:17:05 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:17:08 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:17:11 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:17:15 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			
Mar 15 02:17:17 RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN			
Mar 15 02:17:20 ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM			

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

OFF/

ON/

ON/

OFF/

ON/

OFF/

ON/

OFF/

ON/



É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARCERAIS



ONLY

OFF /

ON /

OFF/

OFF /

ON/

ON /

OFF/

OFF /

ON /

ONLY

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON/

ON/

OFF/

OFF/

ON A

OFF/

JOSE CARLOS PIMENTEL GUSMÃO
DRE/ DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS
ON/

OFF A

ON/

Mar 15 02:17:29	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:17:32	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:17:36	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:17:38	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:17:41	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:17:41	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:17:44	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:17:44	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:17:47	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:17:47	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:17:50	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:17:50	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:17:53	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:17:53	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:17:57	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:17:57	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:17:59	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:17:59	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:18:02	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:18:05	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:18:08	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:18:08	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:18:11	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:18:11	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:18:14	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:18:14	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:18:18	ALM DISC	1	XA80000005	RTU2
ON UNACK_ALM				
Mar 15 02:18:18	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:18:20	RTN DISC	1	XA80000005	RTU2
ON ACK_RTN				
Mar 15 02:18:26	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:18:29	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				
Mar 15 02:18:35	RTN DISC	1	SPARE_d9972_RTU	RTU2
ON ACK_RTN				
Mar 15 02:18:39	ALM DISC	1	SPARE_d9972_RTU	RTU2
ON UNACK_ALM				



Mar 15 02:18:41 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:18:56 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:18:56 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:00 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:00 ALM DISC	1 SPARE_d9972_RTU	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:02 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:02 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:08 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:14 ALM DISC	1 SPARE_d9972_RTU	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:17 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:17 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:21 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:21 ALM DISC	1 SPARE_d9972_RTU	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:23 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:24 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:26 ALM DISC	1 XA80000005	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:27 ALM DISC	1 SPARE_d9972_RTU	RTU2	ON/
ON UNACK_ALM			
Mar 15 02:19:29 RTN DISC	1 SPARE_d9972_RTU	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:32 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:19:56 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:20:08 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:20:12 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:20:16 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:20:28 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:20:31 ALM DISC	1 RTU5_INH_8214	RTU5_INHIBITS	ON/
ON UNACK_ALM			
Mar 15 02:20:32 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:20:50 RTN DISC	1 WWStatPortTGPri	\$System	
HEALT/FAILE ACK_RTN			
Mar 15 02:20:52 ALM DISC	1 WWStatPortTGPri	\$System	
FAILE/FAILE UNACK_ALM			
Mar 15 02:20:59 RTN DISC	1 ESD-LVL2_RTU3	RTU3	
NORMA/ALARM ACK_RTN			
Mar 15 02:20:59 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:20:59 ALM DISC	1 XB-268G_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:20:59 ALM DISC	1 XB-143B_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:02 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 02:21:04 RTN DISC	1 Heartbeat_RTU3	RTU3	
Healt/Faile ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XV-59012S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XV-59019S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-263T	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-262K	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-263U	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-262L	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-267A	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-266E	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-268G	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-268F	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 VE-025-028GS	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XB-143B	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 TG3FUELSOVI	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XS51400005	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 SPARE_d9097_RTU	RTU3	OFF/
ON ACK_RTN			
Mar 15 02:21:07 RTN DISC	1 XM-568	RTU3	NORMA/
TRIP ACK_RTN			
Mar 15 02:21:17 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:23 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:28 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:28 ALM DISC	1 XV-59019S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:32 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:32 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:32 RTN DISC	1 XV-59019S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:36 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:37 ALM DISC	1 XV-59013S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:46 RTN DISC	1 XV-59013S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:50 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:50 ALM DISC	1 XV-59019S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:21:59 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:21:59 RTN DISC	1 XV-59019S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:22:13 ALM DISC	1 XV-59013S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:22:13 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



Mar 15 02:22:13 ALM DISC	1 XV-59019S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:22:17 RTN DISC	1 XV-59013S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:22:23 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:22:23 RTN DISC	1 XV-59019S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:22:44 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:00 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:23:04 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:09 ALM DISC	1 XA800000005	RTU2
ON UNACK_ALM		
Mar 15 02:23:12 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:23:12 RTN DISC	1 XA800000005	RTU2
ON ACK_RTN		
Mar 15 02:23:13 ALM DISC	1 XV-59018S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:16 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:17 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:23:20 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:23:31 ALM DISC	1 XV-59018S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:35 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:23:44 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:44 ALM DISC	1 XV-59018S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:23:52 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:23:53 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:24:12 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:24:20 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:24:25 ALM DISC	1 XV-59018S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:24:29 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:25:00 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:25:08 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:25:12 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:25:17 ALM DISC	1 XV-59018S_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:25:23 RTN DISC	1 XV-59018S_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:25:24 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:25:36 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		
Mar 15 02:25:44 RTN DISC	1 VE-075STS_F	RTU1
NORMA/FAULT ACK_RTN		
Mar 15 02:25:52 ALM DISC	1 VE-075STS_F	RTU1
FAULT/FAULT UNACK_ALM		

ON/

OFF/

É Cópia Fiel do Documento Original

JOSE CARLOS COSTA DE OLIVEIRA
DIVISÃO DE



Mar 15 02:26:56 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:27:00 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:27:14 ALM DISC	1 XA80000005	RTU2	
ON UNACK_ALM			
Mar 15 02:27:17 RTN DISC	1 XA80000005	RTU2	OFF/
ON ACK_RTN			
Mar 15 02:27:22 ALM DISC	1 XV-59018S_F	RTU3	
FAULT/FAULT UNACK_ALM			
Mar 15 02:27:28 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:27:31 RTN DISC	1 XV-59018S_F	RTU3	
NORMA/FAULT ACK_RTN			
Mar 15 02:27:32 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:27:40 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:27:48 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:27:56 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:28:04 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:28:08 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:28:32 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:28:44 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:28:48 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:29:37 RTN DISC	1 XL51113039N	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 02:29:37 RTN DISC	1 XL51113039R	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 02:30:04 ALM DISC	1 XL51113039R	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 02:30:27 RTN DISC	1 RTU5_YMH_8214	RTU5_INHIBITS	OFF/
ON ACK_RTN			
Mar 15 02:30:31 ALM DISC	1 XL51113039N	RTU4	
ENERG/ENERG UNACK_ALM			
Mar 15 02:31:57 RTN DISC	1 LSHH52801	RTU2	
NORMA/ALARM ACK_RTN			
Mar 15 02:33:32 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 02:33:36 ALM DISC	1 VE-075STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 02:33:50 RTN DISC	1 XV-65004S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 02:34:20 ALM DISC	1 XV-65004S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 02:34:26 RTN DISC	1 XV-65004S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 02:36:58 ALM DISC	1 XV-65004S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 02:37:01 RTN DISC	1 XL51113039R	RTU4	DE-
EN/ENERG ACK_RTN			
Mar 15 02:37:28 ALM DISC	1 XV-59019S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 02:37:28 ALM DISC	1 XV-59033S	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 02:37:34 RTN DISC	1 XV-59033S	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 02:37:50 ALM DISC	1 XV-59033S	RTU3	OPEN/
OPEN UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

OPEN/
JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARTORARIAS

Mar 15 02:39:32 ALM DISC	1 XV-590138	RTU3
OPEN UNACK_ALM		
Mar 15 02:40:19 ALM DISC	1 XV-59018S	RTU3
OPEN UNACK_ALM		
Mar 15 02:40:38 ALM DISC	1 XV-59012S	RTU3
OPEN UNACK_ALM		
Mar 15 02:40:53 ALM DISC	1 XV-59021S	RTU3
OPEN UNACK_ALM		
Mar 15 02:41:10 ALM DISC	1 XB-149BS	RTU3
RUNNI/RUNNI UNACK_ALM		
Mar 15 02:41:55 RTN DISC	1 XB-143B_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:42:00 ALM DISC	1 XB-148DS	RTU3
RUNNI/RUNNI UNACK_ALM		
Mar 15 02:42:07 ALM DISC	1 XB-143B_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:42:11 RTN DISC	1 XB-148DS	RTU3
STOPP/RUNNI ACK_RTN		
Mar 15 02:43:08 RTN DISC	1 XB-143B_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:43:13 ALM DISC	1 XB-143B_F	RTU3
FAULT/FAULT UNACK_ALM		
Mar 15 02:43:25 RTN DISC	1 XB-143B_F	RTU3
NORMA/FAULT ACK_RTN		
Mar 15 02:43:35 ALM DISC	1 XB-148DS	RTU3
RUNNI/RUNNI UNACK_ALM		
Mar 15 02:45:28 ALM DISC	1 XB-143BS	RTU3
RUNNI/RUNNI UNACK_ALM		
Mar 15 02:48:49 RTN DISC	1 XL51113039N	RTU4
EN/ENERG ACK_RTN		
Mar 15 02:49:07 ALM DISC	1 XL51113039R	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 02:49:40 ALM DISC	1 XL51113039N	RTU4
ENERG/ENERG UNACK_ALM		
Mar 15 02:50:12 ALM DISC	1 LSHH12330206	RTU2
ALARM/ALARM UNACK_ALM		
Mar 15 02:50:42 ALM DISC	1 XA80000005	RTU2
ON UNACK_ALM		
Mar 15 02:57:12 RTN DISC	1 ZSL12330204	RTU2
C/CLOSE ACK_RTN		
Mar 15 02:57:54 RTN DISC	1 LSHH12330206	RTU2
NORMA/ALARM ACK_RTN		
Mar 15 03:04:18 ALM DISC	1 LSHH45022	RTU2
ALARM/ALARM UNACK_ALM		
Mar 15 03:04:36 ALM DISC	1 SPARE_d9972_RTU	RTU2
ON UNACK_ALM		
Mar 15 03:04:53 RTN DISC	1 XS30133	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS42195	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS42200	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS42205	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 SPARE_d9056_RTU	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS30135	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS43160	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS42033	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 XS42036	RTU2
EN/ENERG ACK_RTN		
Mar 15 03:04:53 RTN DISC	1 SPARE_d9089_RTU	RTU2
EN/ENERG ACK_RTN		

OPEN/
OPEN/
OPEN/
OPEN/



DE-

ON/

NOT

ON/

DE-

DE-

DE-

DE-

DE-

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

DE-

JOSE CARLOS MENDEL GUSMÃO
DIRETOR
UNIDADE DE SERVIÇOS CARTÓGRAFOS

DE-



Mar 15 03:04:53 RTN DISC	1 XS43150	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360041	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360103	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360113	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360202	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360212	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 SPARE_d9208_RTN	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS30130	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS12230540	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS12330031	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360010	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360025	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS12230640	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS53360015	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:53 RTN DISC	1 XS54120013	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS12105003	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS12105012	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250301	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250302	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250311	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250321	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250401	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250411	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250421	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68250711	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68251111	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:54 RTN DISC	1 XS68251121	RTU6	
NORMA/TRIPP ACK_RTN			
Mar 15 03:04:57 ALM DISC	1 XS12510042	RTU2	
STOPP/STOPP UNACK_ALM			
Mar 15 03:07:51 RTN DISC	1 XS12510042	RTU2	
NORMA/STOPP ACK_RTN			
Mar 15 03:08:00 ALM DISC	1 XS12510042	RTU2	
STOPP/STOPP UNACK_ALM			
Mar 15 03:17:25 RTN DISC	1 BY12230404	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:17:26 RTN DISC	1 BY12230110	RTU2	DE-
EN/ENERG ACK_RTN			
Mar 15 03:17:26 RTN DISC	1 BY12230210	RTU2	DE-
EN/ENERG ACK_RTN			

RECÓPIA RELATÓRIO DE EVENTOS

Mar 15 03:17:26 ALM DISC ON UNACK_ALM	1 RTU2_INH_8216	RTU2_INHIBITS	ON/
Mar 15 03:17:26 ALM DISC ON UNACK_ALM	1 RTU2_INH_8220	RTU2_INHIBITS	ON/
Mar 15 03:17:26 ALM DISC ON UNACK_ALM	1 RTU2_INH_8241	RTU2_INHIBITS	ON/
Mar 15 03:17:26 ALM DISC ON UNACK_ALM	1 RTU6_INH_8347	RTU6_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC OPEN UNACK_ALM	1 ZSH12230210	RTU2	OPEN/
Mar 15 03:17:30 RTN DISC C/CLOSE ACK_RTN	1 ZSL12230210	RTU2	NOT
Mar 15 03:17:30 ALM DISC OPEN UNACK_ALM	1 ZSH12230404	RTU2	OPEN/
Mar 15 03:17:30 RTN DISC C/CLOSE ACK_RTN	1 ZSL12230404	RTU2	NOT
Mar 15 03:17:30 ALM DISC OPEN UNACK_ALM	1 ZSH12230110	RTU2	OPEN/
Mar 15 03:17:30 RTN DISC EN/ENERG ACK_RTN	1 BY12330204	RTU2	DE-
Mar 15 03:17:30 RTN DISC EN/ENERG ACK_RTN	1 BY12230310	RTU2	DE-
Mar 15 03:17:30 RTN DISC EN/ENERG ACK_RTN	1 BY12230074	RTU2	DE-
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8123	RTU2_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8221	RTU2_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8251	RTU2_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8253	RTU2_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8363	RTU2_INHIBITS	ON/
Mar 15 03:17:30 ALM DISC ON UNACK_ALM	1 RTU2_INH_8365	RTU2_INHIBITS	ON/
Mar 15 03:17:33 ALM DISC OPEN UNACK_ALM	1 ZSH12230310	RTU2	OPEN/
Mar 15 03:17:33 RTN DISC C/CLOSE ACK_RTN	1 ZSL12230310	RTU2	NOT
Mar 15 03:17:33 ALM DISC OPEN UNACK_ALM	1 ZSH12330204	RTU2	OPEN/
Mar 15 03:18:08 ALM DISC OPEN UNACK_ALM	1 VE-020STS	RTU1	OPEN/
Mar 15 03:18:08 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-020STS_VD	RTU1	
Mar 15 03:18:48 ALM DISC OPEN UNACK_ALM	1 VE-042STS	RTU1	OPEN/
Mar 15 03:18:48 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-042STS_VD	RTU1	
Mar 15 03:20:09 ALM DISC ALARM/ALARM UNACK_ALM	1 PSL12230315	RTU2	
Mar 15 03:23:00 RTN DISC NORMA/FAULT ACK_RTN	1 VE-075STS_F	RTU1	
Mar 15 03:23:12 ALM DISC FAULT/FAULT UNACK_ALM	1 VE-075STS_F	RTU1	
Mar 15 03:24:46 RTN DISC EN/ENERG ACK_RTN	1 XL51113039R	RTU4	DE-
Mar 15 03:26:41 ALM DISC OPEN UNACK_ALM	1 VE-012GSS	RTU1	OPEN/
Mar 15 03:26:41 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-012GSS_VD	RTU1	
Mar 15 03:27:03 ALM DISC OPEN UNACK_ALM	1 VE11GS&92STS	RTU3	OPEN/
Mar 15 03:27:13 ALM DISC OPEN UNACK_ALM	1 VE-068STS	RTU3	OPEN/



É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

DE-

OPEN/

OPEN/

OPEN/

JOSÉ CARLOS PIMENTEL GUESSÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS



Mar 15 03:30:01 ALM DISC	1 VE-023STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:31:21 RTN DISC	1 VE-023STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 03:32:03 ALM DISC	1 VE-066STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:32:17 RTN DISC	1 VE-008STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:32:41 ALM DISC	1 VE-023STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:38:15 ALM DISC	1 VE-067STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:39:09 ALM DISC	1 VE-072STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:39:09 ALM DISC	1 VE-072STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:39:25 ALM DISC	1 VE-002STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:39:25 ALM DISC	1 VE-002STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:39:29 RTN DISC	1 VE-072STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:39:29 RTN DISC	1 VE-072STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 03:39:33 ALM DISC	1 VE-072STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:39:33 ALM DISC	1 VE-072STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:39:48 RTN DISC	1 VE-072STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:39:48 RTN DISC	1 VE-072STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 03:39:53 ALM DISC	1 VE-072STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:39:53 ALM DISC	1 VE-072STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:40:53 ALM DISC	1 VE-011STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:40:53 ALM DISC	1 VE-011STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:40:53 RTN DISC	1 VE-011STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:41:03 RTN DISC	1 VE-023STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 03:41:05 RTN DISC	1 VE-011STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:41:05 RTN DISC	1 VE-011STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 03:41:05 ALM DISC	1 VE-011STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 03:41:09 ALM DISC	1 VE-023STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:42:09 ALM DISC	1 VE-076STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:42:09 ALM DISC	1 VE-076STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:42:09 RTN DISC	1 VE-076STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:42:13 ALM DISC	1 VE-100STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:42:13 ALM DISC	1 VE-100STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			
Mar 15 03:42:21 ALM DISC	1 VE-075STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:42:21 ALM DISC	1 VE-075STS_VD	RTU1	
DISCR/DISCR UNACK_ALM			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORARIAS



Mar 15 03:42:21 RTN DISC	1 VE-075STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:42:29 RTN DISC	1 VE-076STS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:42:29 RTN DISC	1 VE-076STS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 03:42:29 ALM DISC	1 VE-076STS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 03:42:33 ALM DISC	2 VE-013GSS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:42:33 ALM DISC	1 VE-013GSS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:42:33 RTN DISC	1 VE-013GSS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:43:00 RTN DISC	1 VE-023STS	RTU3	CLOSE/
OPEN ACK_RTN			
Mar 15 03:43:00 ALM DISC	1 VE-061STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:43:09 ALM DISC	1 VE-010STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:43:09 ALM DISC	1 VE-010STS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:43:09 RTN DISC	1 VE-010STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:43:10 ALM DISC	1 VE-023STS	RTU3	OPEN/
OPEN UNACK_ALM			
Mar 15 03:44:04 ALM DISC	1 WWStatPortTG Pri	\$\$System	
FAILE/FAILE UNACK_ALM			
Mar 15 03:44:05 ALM DISC	1 VE-011STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:44:05 ALM DISC	1 VE-011STS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:44:05 RTN DISC	1 VE-011STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:44:21 ALM DISC	1 VE-006STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:44:21 ALM DISC	1 VE-006STS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:44:21 RTN DISC	1 VE-006STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:44:23 ALM DISC	1 WWStatPortTGSec	\$\$System	
FAILE/FAILE UNACK_ALM			
Mar 15 03:44:25 ALM DISC	1 Heartbeat_RTU3	RTU3	
FAILE/FAILE UNACK_ALM			
Mar 15 03:44:31 RTN DISC	1 WWStatPortTGSec	\$\$System	
HEALT/FAILE ACK_RTN			
Mar 15 03:44:44 ALM DISC	1 WWStatPortTGSec	\$\$System	
FAILE/FAILE UNACK_ALM			
Mar 15 03:46:05 ALM DISC	1 VE-076STS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:46:05 ALM DISC	1 VE-076STS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:46:05 RTN DISC	1 VE-076STS_F	RTU1	
NORMA/FAULT ACK_RTN			
Mar 15 03:46:12 RTN DISC	1 VE-013GSS	RTU1	CLOSE/
OPEN ACK_RTN			
Mar 15 03:46:13 RTN DISC	1 VE-013GSS_VD	RTU1	
NORMA/DISCR ACK_RTN			
Mar 15 03:46:13 ALM DISC	1 VE-013GSS_F	RTU1	
FAULT/FAULT UNACK_ALM			
Mar 15 03:46:16 ALM DISC	1 VE-013GSS	RTU1	OPEN/
OPEN UNACK_ALM			
Mar 15 03:46:16 ALM DISC	1 VE-013GSS_VD	RTU1	
DSCR/DSCR UNACK_ALM			
Mar 15 03:46:17 RTN DISC	1 VE-013GSS_F	RTU1	
NORMA/FAULT ACK_RTN			

É CÓPIA FIEL DO DOCUMENTO ORIGINAL

OPEN/

JOSE CARLOS PIMENTEL GUIMARÃES
DIRETOR
DIVISÃO DE SERVIÇOS CARTORÁRIOS

Mar 15 03:46:20 RTN DISC OPEN ACK_RTN	1 VE-010STS	RTU1
Mar 15 03:46:21 RTN DISC NORMA/DISCR ACK_RTN	1 VE-010STS_VD	RTU1
Mar 15 03:46:21 ALM DISC FAULT/FAULT UNACK_ALM	1 VE-010STS_F	RTU1
Mar 15 03:47:01 ALM DISC OPEN UNACK_ALM	1 VE-010STS	RTU1
Mar 15 03:47:01 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-010STS_VD	RTU1
Mar 15 03:47:01 RTN DISC NORMA/FAULT ACK_RTN	1 VE-010STS_F	RTU1
Mar 15 03:47:57 RTN DISC OPEN ACK_RTN	1 VE-011STS	RTU1
Mar 15 03:47:57 RTN DISC NORMA/DISCR ACK_RTN	1 VE-011STS_VD	RTU1
Mar 15 03:47:57 ALM DISC FAULT/FAULT UNACK_ALM	1 VE-011STS_F	RTU1
Mar 15 03:48:05 ALM DISC OPEN UNACK_ALM	1 VE-011STS	RTU1
Mar 15 03:48:05 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-011STS_VD	RTU1
Mar 15 03:48:05 RTN DISC NORMA/FAULT ACK_RTN	1 VE-011STS_F	RTU1
Mar 15 03:48:09 RTN DISC OPEN ACK_RTN	1 VE-011STS	RTU1
Mar 15 03:48:09 RTN DISC NORMA/DISCR ACK_RTN	1 VE-011STS_VD	RTU1
Mar 15 03:48:09 ALM DISC FAULT/FAULT UNACK_ALM	1 VE-011STS_F	RTU1
Mar 15 03:48:13 ALM DISC OPEN UNACK_ALM	1 VE-011STS	RTU1
Mar 15 03:48:13 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-011STS_VD	RTU1
Mar 15 03:48:13 RTN DISC NORMA/FAULT ACK_RTN	1 VE-011STS_F	RTU1
Mar 15 03:53:33 ALM DISC OPEN UNACK_ALM	1 VE-041STS	RTU1
Mar 15 03:53:33 ALM DISC DISCR/DISCR UNACK_ALM	1 VE-041STS_VD	RTU1
Mar 15 04:15:05 ALM DISC LOW UNACK_ALM	1 LSL51350002	RTU6

CLOSE/

OPEN/

CLOSE/

OPEN/

CLOSE/

OPEN/


OPEN/

LOW/



É CÓPIA FIEL DO DOCUMENTO ORIGINAL

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CARTORIAIS



CERTIDÃO

CERTIFICO que, nesta data, fui incumbido pelo Sr. Alvaro
do amor D. 24 de 2000 19489105
2.36

O referido é verdade e dou fé.

Ass. OS de Alvaro de 200 1.

É CÓPIA FIEL DO DOCUMENTO ORIGINAL.

JOSE CARLOS PIMENTEL GUSMÃO
DIRETOR
DIVISÃO DE SERVIÇOS CANTO